# LONDON ISD PAVING PROJECTS



Photo 01 - View east, excavation progress at HS-MS parent drive



Photo 02 - Installation of new storm drainage piping

Photo 03 - Installation of data/power conduit along loop road Photo 04 - Storm sewer installation in progress at stadium parking

## **CONSTRUCTION UPDATE**

- Data & Power conduit excavation &

## **LOOKING FORWARD**





