

Carmody Middle School		Resampled 4/30/19†	
SampleNumber	Description	Lead Result	Unit
64200-109X-S	Sink in Library Work Room	1.8*	ppb
64200-160-S1	Food Service Sink-Hand Sink	10.8**	ppb
64200-160-S2	Food Service Sink-Food Prep	4.9	ppb
64200-160-S3	Food Service Sink-Sanitize	5.0*	ppb
64200-160-S4	Food Service Sink-Sanitize	1.9*	ppb
64200-160-S5	Food Service Sink-Sprayer	10.6*	ppb
64200-159-DF	Drinking Fountain in Cafeteria	3.8	ppb
64200-159-WBFS	Water Bottle Filling Station in Cafeteria	4.1 [‡]	ppb
64200-168-S	Sink in Teacher's Lounge	2.5*	ppb
64200-168-IM	Ice Machine in Teacher's Lounge	0.5*	ppb
64200-114-S	Sink in Orchestra Classroom 114	6.5	ppb
64200-114-SWB	Sink with Bubbler in Orchestra Classroom 114	1.9*	ppb
64200-176-S	Sink in Custodial Office	0.4*	ppb
64200-179-S	Sink in Storage Room by Custodial Office	5.9**	ppb
64200-115-S1	Sink in Art Room 115	1.0*	ppb
64200-115-S2	Sink in Art Room 115	5.2*	ppb
64200-116-S1	Sink in Art Room 116	6.9*	ppb
64200-116-S2	Sink in Art Room 116	2.8*	ppb
64200-AUXGYM-DF	Drinking Fountain in Auxiliary Gym	2.8	ppb
64200-GYM-DF	Drinking Fountain in Large Gym	3.4	ppb
64200-144H-DF	Hallway Drinking Fountain near Elevator on 1st Floor	2.8	ppb
64200-112-S	Sink in Consumer Science Room 112	Repairs Pending	
64200-111-S	Sink in Kitchen Area of Classroom 111	24.4	ppb
64200-143H-DF	Hallway Drinking Fountain near Classrooms 104 and 105	0.6*	ppb
64200-107-S	Sink in Classroom 107	0.9*	ppb
64200-228-S1	Sink in Science Classroom 228	0.6*	ppb
64200-228-S2	Sink in Science Classroom 228	0.5*	ppb
64200-228-S3	Sink in Science Classroom 228	1.0*	ppb
64200-228-S4	Sink in Science Classroom 228	1.5*	ppb
64200-227-S1	Sink in Science Classroom 227	1.3*	ppb
64200-227-S2	Sink in Science Classroom 227	4.3*	ppb
64200-227-S3	Sink in Science Classroom 227	2.6*	ppb
64200-227-S4	Sink in Science Classroom 227	0.6*	ppb
64200-226-S1	Sink in Science Classroom 226	0.9*	ppb
64200-226-S2	Sink in Science Classroom 226	1.0*	ppb
64200-226-S3	Sink in Science Classroom 226	1.2*	ppb
64200-226-S4	Sink in Science Classroom 226	0.9*	ppb
64200-219XH-DFL	Hallway Drinking Fountain across from Stairs on 2nd Floor/Left	0.1	ppb
64200-219XH-DFR	Hallway Drinking Fountain across from Stairs on 2nd Floor/Right	0.1	ppb
64200-212-S1	Sink in Science Classroom 212	0.7*	ppb
64200-212-S2	Sink in Science Classroom 212	0.8*	ppb
64200-212-S3	Sink in Science Classroom 212	0.5*	ppb
64200-212-S4	Sink in Science Classroom 212	1.8*	ppb
64200-213-S1	Sink in Science Classroom 213	4.2*	ppb
64200-213-S2	Sink in Science Classroom 213	1.5*	ppb
64200-213-S3	Sink in Science Classroom 213	1.1*	ppb
64200-213-S4	Sink in Science Classroom 213	2.0*	ppb
64200-214-S1	Sink in Science Classroom 214	2.2*	ppb
64200-214-S2	Sink in Science Classroom 214	0.6*	ppb
64200-214-S3	Sink in Science Classroom 214	2.2*	ppb

64200-214-S4	Sink in Science Classroom 214	1.3*	ppb
64200-257H-DFL	Hallway Drinking Fountain near Elevator on 2nd Floor/Left	0.2	ppb
64200-257H-DFR	Hallway Drinking Fountain near Elevator on 2nd Floor/Right	0.1	ppb
64200-238-S1	Sink in Science Prep Room 238	6.6*	ppb
64200-238-S2	Sink in Science Prep Room 238	1.2*	ppb
* This fixture was sampled on 8/17/16.			
** This fixture was sampled on 1/31/17.			
‡ Sampled for first time on 4/30/19.			
† Resampling results as part of an ongoing rotation of lead testing.			