

Chatfield High School		Sampled 4/20/2022	Status
CustomerSampleNumber	Description	Lead results (ppb)	
73200-B102-S3	Food Service Sink-Food Prep	0.6	
73200-B194H-WBFS	Hallway Water Bottle Filling Station outside of Cafeteria and across from Large Gym	<0.1*	
73200-B194H-DF	Hallway Drinking Fountain outside of Cafeteria and across from Large Gym	<0.1*	
73200-D107XH-DF	Hallway Drinking Fountain across from Classroom D109 and D111	0.3	
73200-C107H-DF	Hallway Drinking Fountain near Art Rooms	1.2	
73200-E103-S1	Sink in Kitchen Classroom E103	0.1	
73200-E103-S2	Sink in Kitchen Classroom E103	0.1	
73200-E103-E3	Sink in Kitchen Classroom E103	<0.1*	
73200-E103-S4	Sink in Kitchen Classroom E103	<0.1*	
73200-E103-S5	Sink in Kitchen Classroom E103	<0.1*	
73200-E103-S6	Sink in Kitchen Classroom E103	<0.1*	
73200-E103-S7	Sink in Kitchen Classroom E103	<0.1*	
73200-2022-E103-S8	Sink in Kitchen Classroom E103	<0.1*	
73200-2022-E103-S9	Sink in Kitchen Classroom E103	0.1	
73200-2022-E103-S10	Sink in Kitchen Classroom E103	<0.1*	
73200-2022-E103-S11	Sink in Kitchen Classroom E103	0.1	
73200-2022-E103-S12	Sink in Kitchen Classroom E103	0.1	
73200-E105-S	Sink in Consumer Science Classroom E105	1	
73200-E112H-DFL	Hallway Drinking Fountain across from Office E107/Left	not in use	
73200-E108H-DFL	Hallway Drinking Fountain across from Classroom E105/Left	0.7	
73200-E108H-DFR	Hallway Drinking Fountain across from Classroom E105/Right	42.2	Repairs Pending
73200-A119H-DF	Hallway Drinking Fountain outside of Classroom A120	2.3	
73200-101.2-S	Sink in Gym	2.7	
73200-C131H-DF	Hallway Drinking Fountain outside of Dance Classroom C111	<0.1*	
73200-2022-C131H-WBFS	Water Bottle Filling Station outside of Dance Classroom C111	<0.1*	
73200-G200-DF	Drinking Fountain in Weight Room	0.2	
73200-C231H-DFL	Hallway Drinking Fountain outside of Weight Room/Left	0.6	
73200-C231H-DFR	Hallway Drinking Fountain outside of Weight Room/Right	0.2	
73200-C209.1-IM	Ice Machine in Training Room	<0.1*	
73200-C217H-DFL	Hallway Drinking Fountain by Vocal Music Room C219/Left	5.6	Repairs Pending
73200-C217H-DFR	Hallway Drinking Fountain by Vocal Music Room C219/Right	1.8	
73200-C221-DF	Drinking Fountain in Voc Lab C221	0.4	

73200-D207XH-DF	Hallway Drinking Fountain outside of Classroom D209	1.1	
73200-B285H-DF	Hallway Drinking Fountain outside of Classroom C214	3.2	
73200-A200H-DFL	Hallway Drinking Fountain outside of Laboratory A202/Left	<0.1*	
73200-A200H-DFR	Hallway Drinking Fountain outside of Laboratory A202/Right	0.1	
73200-E212H-DFL	Hallway Drinking Fountain across from Office E207/Left	0.2	
73200-E212H-DFR	Hallway Drinking Fountain across from Office E207/Right	0.2	
73200-E208H-DFL	Hallway Drinking Fountain across from Classroom E205/Left	0.3	
73200-E208H-DFR	Hallway Drinking Fountain across from Classroom E205/Right	0.3	
73200-A231-IM	Ice Machine in Science Prep Room A231	1.2	
73200-A215XH-DF	Hallway Drinking Fountain across from Laboratory A215	1.2	
73200-B287AH-DF	Drinking Fountain on 2nd Floor near restroom/stairs by Technology Lab C200	<0.1*	
73200-E113-S1	Sink in Store	1.4	
73200-E113-S2	Sink in Store	16.9	Repairs Pending
73200-E113-S3	Sink in Store	removed	
* This results is less than 0.1ppb, which is the lowest level that can be reported by the lab.			