

Evergreen High School		Sampled 7/9/20†		Resampled 7/31/20***	
CustomerSampleNumber	Description	Lead Result	Unit	Lead Result	Unit
74000-H307-S	Sink in Clinic	2.5	ppb		
74000-H316-S	Sink in Work Room H316	0.2*	ppb		
74000-A307H-DF	Hallway Drinking Fountain in Art Room Area	2.0	ppb		
74000-A301-S1	Sink in Art Room A301	1.7*	ppb		
74000-A301-S2	Sink in Art Room A301	5.4*	ppb		
74000-A301-S3	Sink in Art Room A301	1.2*	ppb		
74000-A308-S1	Sink in Art Room A308	7.2*	ppb		
74000-A308-S2	Sink in Art Room A308	4.3*	ppb		
74000-A308-S3	Sink in Art Room A308	8.4*	ppb		
74000-H302H-DF	Hallway Drinking Fountain outside of the Art Dept. Wing	0.2	ppb		
74000-D301H-DF	Hallway Drinking Fountain outside of Classroom G314	0.2*	ppb		
74000-F304-S	Sink in Library Work Room	1.0*	ppb		
74000-F320H-WBFS	Hallway Water Bottle Filling Station across from Classroom E300	<0.1†	ppb		
74000-F320H-DF	Hallway Drinking Fountain across from Classroom E300	<0.1†	ppb		
74000-E316-S1	Sink in Laboratory E316	0.5*	ppb		
74000-E316-S2	Sink in Laboratory E316	0.5*	ppb		
74000-E317-S	Sink in Science Prep Room E317	0.9*	ppb		
74000-E313-S1	Sink in Science Prep Room E313	1.4**	ppb		
74000-E313-S2	Sink in Science Prep Room E313	1.0*	ppb		
74000-E315-S1	Sink in Laboratory E315	0.8*	ppb		
74000-E315-S2	Sink in Laboratory E315	1.2*	ppb		
74000-E315-S3	Sink in Laboratory E315	0.8*	ppb		
74000-E315-S4	Sink in Laboratory E315	0.9*	ppb		
74000-E315-S5	Sink in Laboratory E315	0.7*	ppb		
74000-E315-S6	Sink in Laboratory E315	2.4*	ppb		
74000-E315-S7	Sink in Laboratory E315	0.4*	ppb		
74000-E314-S1	Sink in Laboratory E314	0.6*	ppb		
74000-E314-S2	Sink in Laboratory E314	1.0*	ppb		
74000-E314-S3	Sink in Laboratory E314	1.3*	ppb		
74000-E314-S5	Sink in Laboratory E314	2.3*	ppb		
74000-E314-S6	Sink in Laboratory E314	1.0*	ppb		
74000-E314-S7	Sink in Laboratory E314	0.4**	ppb		
74000-E314-S8	Sink in Laboratory E314	0.6*	ppb		
74000-E305-S1	Sink in Computer Room E305	Repairs pending			
74000-E305-S2	Sink in Computer Room E305	4.0*	ppb		
74000-D307-S	Sink in Custodial Office D307	0.7*	ppb		
74000-E321-S	Sink in Work Room E321	0.5*	ppb		
74000-J305-S1	Food Service Sink-Hand Sink	3.5*	ppb		
74000-J305-S2	Food Service Sink-Hand Sink	4.4*	ppb		
74000-J311-S1	Food Service Sink-Hand Sink	3.2*	ppb		
74000-J311-S2	Food Service Sink-Dish Wash Sprayer	2.1**	ppb		
74000-J311-S3	Food Service Sink-Wash/Rinse	3.5*	ppb		
74000-J311-S4	Food Service Sink-Rinse/Sanitize	2.3*	ppb		
74000-J311-S5	Food Service Sink-Hand Sink	1.4*	ppb		
74000-J311-S6	Food Service Sink-Food Prep	4.7	ppb		
74000-J311-S7	Food Service Sink-Food Prep Sprayer	3.5	ppb		
74000-J311-S8	Food Service Sink-Hand Sink	5.1*	ppb		
74000-J311-S9	Food Service Sink-Hand Sink	2.0*	ppb		
74000-C304-S	Sink in Dressing Room C304	6.7*	ppb		
74000-C316-S	Sink in Scene Shop	1.3*	ppb		
74000-C324-S	Sink in Dressing Room C324	8.4*	ppb		
74000-C322-S1	Sink in Store	11.5	ppb		
74000-C322-S2	Sink in Store	5.9	ppb		
74000-B308-S	Sink in restroom area B308	5.4*	ppb		
74000-B311-S1	Sink in Classroom B311	2.7*	ppb		
74000-B311-S2	Sink in Classroom B311	4.4*	ppb		
74000-B313H-WBFS	Hallway Water Bottle Filling Station across from Faculty Dining Area	<0.1†	ppb		
74000-B313H-DF	Hallway Drinking Fountain across from Faculty Dining Area	<0.1†	ppb		
74000-B309-S	Sink in Classroom Kitchen B309	51.1	ppb	2.1	ppb
74000-D307X-S1	Sink in Faculty Dining Area	1.5	ppb		
74000-D307X-S2	Sink in Faculty Dining Area	4.3	ppb		
74000-B205-S1	Sink in Photography Room	0.3*	ppb		
74000-B205-S2	Sink in Photography Room	0.5*	ppb		
74000-B205-S3	Sink in Photography Room	2.9*	ppb		

74000-B205-S4	Sink in Photography Room	0.3*	ppb		
74000-D202-S	Sink in Commons Area	97.7	ppb	8.5	ppb
74000-G202-S2	Sink in Restroom area outside of Small Gym	1.9*	ppb		
74000-213X-S	Sink in Concessions	4.9	ppb		
74000-A115-DFL	Hallway Drinking Fountain outside of Weight Room A115/Left	0.2	ppb		
74000-A115-DFR	Hallway Drinking Fountain outside of Weight Room A115/Right	0.2	ppb		
74000-A106-S	Sink in Dance Classroom	8.8*	ppb		
74000-A128-IM	Ice Machine in Training Room	<0.1 [†]	ppb		
74000-A123-DF	Drinking Fountain in Boy's Locker Room	0.8	ppb		
74000-A102-DF	Drinking Fountain in Weight Room A102	21.3	ppb	5.9	ppb
74000-A128-S	Sink in Training Room	3.6	ppb		
74000-A149-DF	Drinking Fountain Girl's Locker Room	2.7	ppb		
74000-A134-DF	Drinking Fountain in Boy's PE Locker Room	1.5	ppb		
74000-A142-DF	Drinking Fountain in Girl's PE Locker Room	1.8	ppb		
74000-G402H-DF	Hallway Drinking Fountain on 4th Floor next to Elevator	<0.1 [†]	ppb		
74000-G402H-WBFS	Hallway Water Bottle Filling Station on 4th Floor next to Elevator	<0.1 [†]	ppb		
74000-G416-S	Sink in Classroom G416	1.4	ppb		
74000-H403H-DF	Hallway Drinking Fountain in Science Wing on 4th Floor	<0.1 [†]	ppb		
74000-H402-S1	Sink in Science Classroom H402	4.4*	ppb		
74000-H402-S2	Sink in Science Classroom H402	3.8*	ppb		
74000-H402-S3	Sink in Science Classroom H402	2.2*	ppb		
74000-H402-S4	Sink in Science Classroom H402	3.2*	ppb		
74000-H403-S	Sink in Science Prep Room H403	8.8*	ppb		
74000-H404-S1	Sink in Science Classroom H404	1.7*	ppb		
74000-H404-S2	Sink in Science Classroom H404	3.3*	ppb		
74000-H404-S3	Sink in Science Classroom H404	5.1*	ppb		
74000-H404-S4	Sink in Science Classroom H404	1.9*	ppb		
74000-H408-S	Sink in Science Prep Room H408	14.2*	ppb		
74000-H405-S1	Sink in Science Classroom H405	4.2*	ppb		
74000-H405-S2	Sink in Science Classroom H405	2.9*	ppb		
74000-H405-S3	Sink in Science Classroom H405	3.5*	ppb		
74000-H405-S4	Sink in Science Classroom H405	9.2*	ppb		
74000-E406-S1	Sink in Science Classroom H406	3.8*	ppb		
74000-E406-S2	Sink in Science Classroom H406	4.4*	ppb		
74000-E406-S3	Sink in Science Classroom H406	0.4*	ppb		
74000-E406-S4	Sink in Science Classroom H406	2.0*	ppb		
74000-H413-S1	Sink in Science Classroom H413	3.1*	ppb		
74000-H413-S2	Sink in Science Classroom H413	3.9*	ppb		
74000-H413-S3	Sink in Science Classroom H413	2.0*	ppb		
74000-H413-S4	Sink in Science Classroom H413	2.4*	ppb		
74000-C309-S	Sink in Instrument/Band Office	24.3	ppb	11.4	ppb
* Sampled on 10/11/16.					
** Resampling results on 11/29/16 after elevated fixture was repaired or removed and replaced.					
*** Resampling results on 7/31/20 after elevated fixture was repaired.					
‡ This result is less than 0.1 ppb, which is the lowest level that can be reported by the lab.					
† Sampled as part of Jeffco's ongoing 5 year sampling program.					