

Little Elementary School		Sampled 6/25/20†		Resampled 10/9/20***	
CustomerSampleNumber	Description	Lead Result	Unit	Lead Result	Unit
23500-REC-067-DF	Drinking Fountain in TEMP REC-067	2.4	ppb		
23500-REC-114-DF	Drinking Fountain in TEMP REC-114	0.4	ppb		
23500-135H-DF	Hallway Drinking Fountain Outside of Art Room	0.9	ppb		
23500-135H-WBFS	Water Bottle Filling Station Outside of Art Room	1.0	ppb		
23500-101-S	Sink in Kindergarten Classroom 101	24.3	ppb	6.8	ppb
23500-101-SWB	Sink with Bubbler in Kindergarten Classroom 101	4.9	ppb		
23500-141-S	Sink in Kindergarten Classroom 141	5.6	ppb		
23500-141-SWB	Sink with Bubbler in Kindergarten Classroom 141	1.2	ppb		
23500-140H-S	Hallway Sink across from Main Office	6.1	ppb		
23500-140H-SWB	Hallway Sink with Bubbler across from Main Office	4.8	ppb		
23500-131AX-S	Sink in Clinic	5.1	ppb		
23500-131AX-SWB	Sink with Bubbler in Clinic	3.9	ppb		
23500-129-S	Sink in Planning Room 129	7.2**	ppb		
23500-105-S	Sink in Teacher's Lounge	1.4	ppb		
23500-165-S1	Food Service Sink-Hand Sink	3.7**	ppb		
23500-165-S2	Food Service Sink-Dish Wash/Sprayer		ppb		
23500-165-S3	Food Service Sink-Wash/Rinse	7.8*	ppb		
23500-165-S4	Food Service Sink-Rinse/Sanitize	8.0**	ppb		
23500-165-S5	Food Service Sink-Food Prep	7.1	ppb		
23500-165-S6	Food Service Sink-Food Prep/Hose Connector Spigot	Fixture Removed			
23500-176H-S1	Hallway Sink Outside of Kitchen	2.6	ppb		
23500-176H-SWB1	Hallway Sink with Bubbler Outside of Kitchen	2.3	ppb		
23500-176H-S2	Hallway Sink Outside of Kitchen	3.2	ppb		
23500-176H-SWB2	Hallway Sink with Bubbler Outside of Kitchen	3.1	ppb		
23500-182A-S	Sink in Classroom 182A	1.2	ppb		
23500-182A-SWB	Sink with Bubbler in Classroom 182A	1.1	ppb		
23500-167-S	Sink in Classroom 167	0.4	ppb		
23500-167-SWB	Sink with Bubbler in Classroom 167	0.2	ppb		
23500-168-S	Sink in Classroom 168	0.6	ppb		
23500-168-SWB	Sink with Bubbler in Classroom 168	0.2	ppb		
23500-124-S	Sink in Classroom 124	0.6	ppb		
23500-124-SWB	Sink with Bubbler in Classroom 124	0.3	ppb		
23500-137H-S	Hallway Sink across from Classroom 169	4.6	ppb		
23500-137H-SWB	Hallway Sink with Bubbler across from Classroom 169	6.1	ppb		
23500-111-S	Sink in Classroom 111	0.7	ppb		
23500-113-S	Sink in Classroom 113	0.8	ppb		
23500-177-S	Sink in Classroom 177	0.3	ppb		
23500-174H-S	Hallway Sink across from Classroom 169B	8.5	ppb		
23500-174H-SWB	Hallway Sink with Bubbler across from Classroom 169B	6.3	ppb		
23500-172-S	Sink in Classroom 172	1.4	ppb		
23500-138-S1	Art Room Sink	8.7*	ppb		
23500-138-S2	Art Room Sink	5.7*	ppb		
23500-147C-S	Sink in Library Work Room	2.6	ppb		
23500-149-S	Sink in Library Work Room	1.9	ppb		
*Sampled on 7/26/16					
** Results from 8/26/16 or 11/23/16 after elevated fixtures were repaired or removed and replaced.					
*** Result from 10/9/20 after elevated fixtures were replaced.					
† Sampled as part of Jeffco's ongoing 5 year sampling program.					