

Normandy Elementary School		Sampled 4/13/2022	Status
CustomerSampleNumber	Description	Lead results (ppb)	
29900-164X-S	Sink in Clinic	2.2	
29900-160X-SWB	Sink with Bubbler in Hallway near Classroom 2	9.4	Repairs Pending
29900-4-SWB	Sink with Bubbler in Classroom 4	5.8	Repairs Pending
29900-129-DFL	Hallway Drinking Fountain near Classroom 7/Left	0.2	
29900-129-DFR	Hallway Drinking Fountain near Classroom 7/Right	0.1	
29900-2022-129-WBFS	Water Bottle Filling Station near Classroom 7	0.1	
29900-2022-5H-S	Hallway Sink near Classroom 5	4.2	
29900-151X-DFL	Hallway Drinking Fountain near Classroom 10/Left	1.5	
29900-151X-DFR	Hallway Drinking Fountain near Classroom 10/Right	0.2	
29900-2022-151XH-S	Hallway Sink near Classroom 10	5.8	Repairs Pending
29900-12-SWB	Sink with Bubbler in Classroom 12	4.1	
29900-108H-DF	Hallway Drinking Fountain	0.1	
29900-14-SWB	Sink with Bubbler in Classroom 14	11.6	Repairs Pending
29900-C-1-SWB	Sink with Bubbler in Cafeteria	1	
29900-2022-109F-SWB	Sink with Bubbler in Room 109F	14	Repairs Pending
29900-109G-SWB	Sink with Bubbler in Room 109G	3.7	
29900-152-S	Sink in Teacher's Lounge	0.2	
29900-145X-DF	Hallway Drinking Fountain near PE Office	2.9	
29900-1-SWB-2	Sink with Bubbler in Music Room	1.9	
29900-106H-DF	Hallway Drinking Fountain near Office	<0.1*	
299009106H-WBFS	Water Bottle Filling Station near Office	<0.1*	
29900-156X-DF	Hallway Drinking Fountain	1.6	
29900-129A-DH-DF	Hallway Drinking Fountain	1.7	
29900-138-S	Sink in Clinic	0.3	

* This results is less than 0.1ppb, which is the lowest level that can be reported by the lab.