

Quail Complex Building 1 - Sampled 5/19/17			
CustomerSampleNumber	Description	Lead Result	Unit
80910-2017-N130-DF	Drinking Fountain across from Lockers	0.5	ppb
80910-2017-106-WF	Coffee Maker in Lounge 106	<0.1*	ppb
80910-2017-106-S	Sink in Lounge 106	<0.1*	ppb
80910-2017-106-IM	Ice Machine in Lounge 106	0.4	ppb
80910-2017-103-S2	Sink in Office 103	0.9	ppb
80910-2017-113X-S2	Sink in Reception Area	1.3	ppb
80910-2017-136X-S	Sink in Storage Area	0.5	ppb
80910-2017-103-CM	Coffee Maker in Lounge 103	0.2	ppb
80910-2017-113F-S1	Sink in Conference Room	0.2	ppb
80910-2017-113F-S2	Sink in Conference Room	0.8	ppb
80910-2017-113-S	Sink in Work Area	3.5	ppb
80910-2017-S114-S	Sink in Lounge S114	<0.1*	ppb
80910-2017-S114-CM	Coffee Maker in Lounge S114	0.2	ppb
80910-2017-S114-WF	Water Cooler in Lounge S114	<0.1*	ppb
80910-2017-166X-DF	Drinking Fountain in Hallway across from Computer Area	6.0	ppb
80910-2017-202N-DF2	Drinking Fountain in 202N	0.3	ppb
80910-2017-202N-WBFS	Water Bottle Filling Station in 202N	0.2	ppb
80910-2017-202N-DF1	Drinking Fountain in 202N	0.2	ppb
80910-2017-202K-S	Sink in Lounge 202K	0.9	ppb
80910-2017-202K-WM	Coffee Maker in Lounge 202K	3.5	ppb
* This result is less than 0.1 ppb, which is the lowest level that can be reported by the lab.			