

Slater Elementary School - Sampled 6/3/16				Resampled** 8/17/16		Resampled*** 4/28/17	
SampleNumber	Description	Lead Result	Unit	Lead Result	Unit	Lead Result	Unit
41000-001-DF	Kindergarten Drinking Fountain	25.7	ppb	Fixture Shut Off			
41000-001-S	Kindergarten Sink	2.4	ppb				
41000-005H-DF	Hallway Drinking Fountain	27.8	ppb	289.8	ppb	Fixture Shut Off	
41000-005-S	Conference Room Sink	5.0	ppb	459.7	ppb	7.8	ppb
41000-007-S	Teacher's Lounge Sink	0.6	ppb			0.8	ppb
41000-22-S1	Food Service Prep Sink	6.6	ppb			5.6	ppb
41000-22-S2	Food Service Rinse Sink	3.7	ppb			5.9	ppb
41000-22-S3	Food Service Sanitize Sink	1.8	ppb			12.7	ppb
41000-22-S4	Food Service Hand Sink	15.4	ppb	171.3	ppb	2.1	ppb
41000-23-DF	Cafeteria Drinking Fountain	31.9	ppb	43.0	ppb	Fixture Shut Off	
41000-25-S	Clinic Sink	0.4	ppb			0.8	ppb
41000-37H-DFL	B-Wing Hallway Drinking Fountain/L	9.0	ppb	17.0	ppb	Fixture Removed	
41000-37H-DFR	B-Wing Hallway Drinking Fountain/R	2.8	ppb	3.6	ppb	Fixture Removed	
41000-37H-DF	B-Wing Hallway Drinking Fountain	0.6*	ppb				
41000-37H-WBFS	B-Wing Hallway Water Bottle Filling Station	1.1*	ppb				
41000-41-DF	Classroom 41/A1 Drinking Fountain	6.6	ppb			12.0	ppb
41000-41-S	Classroom 41/A1 Sink	2.8	ppb				
41000-43-DF	Classroom 43/A2 Drinking Fountain	12.9	ppb	Fixture Shut Off			
41000-43-S	Classroom 43/A2 Sink	7.5	ppb				
41000-46-DF	Classroom 46/B1 Drinking Fountain	13.3	ppb			14.9	ppb
41000-46-S	Classroom 46/B1 Sink	12.5	ppb				
41000-47-DF	Classroom 47/B2 Drinking Fountain	14.7	ppb			12.8	ppb
41000-47-S	Classroom 47/B2 Sink	110.8	ppb	7.0	ppb		
41000-49-DF	Classroom 49/A3 Drinking Fountain	9.1	ppb			6.0	ppb
41000-49-S	Classroom 49/A3 Sink	26.2	ppb	4.3	ppb		
41000-52-DF	Classroom 52/B3 Drinking Fountain	5.7	ppb			7.2	ppb
41000-52-S	Classroom 52/B3 Sink	12.0	ppb				
41000-53-DF	Classroom 53/A4 Drinking Fountain	11.4	ppb			7.4	ppb
41000-53-S	Classroom 53/A4 Sink	10.7	ppb				
41000-56-DF	Classroom 56/B4 Drinking Fountain	3.8	ppb			3.9	ppb
41000-56-S	Classroom 56/B4 Sink	5.0	ppb				
41000-61A-S	Library Workroom Sink	105.9	ppb	34.7	ppb	14.5	ppb
41000-69-S2	Classroom 69/Art Sink	5.2	ppb				
41000-69-SI	Classroom 69/Art Sink	8.1	ppb				
41000-76H-DFL	C-Wing Hallway Drinking Fountain/L	19.1	ppb	1995.9	ppb	Fixture Removed	
41000-76H-DFR	C-Wing Hallway Drinking Fountain/R	4.3	ppb	6.1	ppb	Fixture Removed	
41000-76H-DF	C-Wing Hallway Drinking Fountain	0.9*	ppb				
41000-76H-WBFS	C-Wing Hallway Water Bottle Filling Station	1.7*	ppb				
41000-82H-DF	D-Wing Hallway Drinking Fountain	1.4	ppb			2.4	ppb
41000-85-DF	Classroom 85/C1 Drinking Fountain	5.3	ppb			9.5	ppb
41000-85-S	Classroom 85/C1 Sink	8.3	ppb				
41000-86-DF	Classroom 86/C2 Drinking Fountain	4.6	ppb			6.2	ppb
41000-86-S	Classroom 86/C2 Sink	7.5	ppb				
41000-91-DF	Classroom 91/C3 Drinking Fountain	6.4	ppb			8.1	ppb
41000-91-S	Classroom 91/C3 Sink	6.0	ppb				
41000-92-DF	Classroom 92/C Drinking Fountain	6.6	ppb			5.5	ppb
41000-92-S	Classroom 92/C4 Sink	13.8	ppb				
41000-93-S	Classroom 93/D1 Sink	3.7	ppb				
41000-94-S	Classroom 94/D2 Sink	2.1	ppb				

41000-95-S	Classroom 95/D3 Sink	3.1	ppb		
41000-96-S	Classroom 96/D4 Sink	1.4	ppb		
41000-R1-084-DF	Temp R1-084 Drinking Fountain	1.6	ppb		1.6 ppb
41000-RE-011-DF	Temp RE-011 Drinking Fountain	4.2	ppb		13.0 ppb
41000-RE-048-DF	Temp RE-048 Drinking Fountain	0.7	ppb		0.6 ppb
41000-REC-132-DF	Temp REC-132 Drinking Fountain	5.7	ppb		8.2 ppb
* These newly installed fixtures were sampled for the first time on 11/17/17.					
** Resampling results after elevated fixtures were repaired, or removed and replaced.					
*** Resampling results were from samples collected on 4/28/17 as part of an ongoing rotation of lead testing.					