

Ute Meadows Elementary School		Sampled 4/20/2022	Status
CustomerSampleNumber	Description	Lead results (ppb)	
44300-120-S	Sink in Office Workroom	11.2	Repairs pending
44300-118-S	Sink in Clinic	2	
44300-129-S	Sink in Teacher's Lounge	1.4	
44300-2022-106H-DF	Drinking Fountain Near Cafeteria	<0.1*	
44300-2022-106H-WBFS	Water Bottle Filling Station Near Cafeteria	<0.1*	
44300-C15-DF	Drinking Fountain in C-Pod Near Room C-7	14.9	Repairs pending
44300-C14-DF	Drinking Fountain in C-Pod Near Room C-1	3	
44300-B15-DF	Drinking Fountain in B-Pod	2	
44300-B14-DF	Drinking Fountain in B-Pod	10.5	Repairs pending
44300-A15-DF	Drinking Fountain in A-Pod	5.2	Repairs pending
44300-A14-DF	Drinking Fountain in A-Pod	3.9	
44300-126H-DF	Hallway Drinking Fountain	5.1	Repairs pending
44300-2K-SWB	Sink with Bubblers in Kindergarten Room 2	4.9	
44300-1K-SWB	Sink with Bubblers in Kindergarten Room 1	5.4	Repairs pending
44300-RE-037-DF	Drinking Fountain in Temp RE-037	4.1	
* This results is less than 0.1ppb, which is the lowest level that can be reported by the lab.			