

West Jefferson Middle School		Sampled 4/8/2022	Status
CustomerSampleNumber	Description	Lead Results (ppb)	
68000-C3H-DFL	Hallway Drinking Fountain across from Classrooms 305/Left	not in use	
68000-C3H-DFR	Hallway Drinking Fountain across from Classrooms 305/Right	0.9	
68000-C5H-DFL	Hallway Drinking Fountain across from Classroom 306/Left	0.4	
68000-C5H-DFR	Hallway Drinking Fountain across from Classroom 306/Right	0.4	
68000-2022-C5H-WBFS	Hallway Water Bottle Filling Station across from Classroom 306	0.4	
68000-2022-C6H-DF	Hallway Drinking Fountain on 1st Floor near Elevator	0.7	
68000-2022-C6H-WBFS	Hallway Water Bottle Filling Station on 1st Floor near Elevator	0.6	
68000-C8H-DFL	Hallway Drinking Fountain near Library/Left	4.2	
68000-C8H-DFR	Hallway Drinking Fountain near Library/Right	1.3	
68000-402-S1	Sink in FACS Kitchen Classroom	2.4	
68000-402-S2	Sink in FACS Kitchen Classroom	2.6	
68000-402-S3	Sink in FACS Kitchen Classroom	7	Repairs pending
68000-402-S4	Sink in FACS Kitchen Classroom	1.6	
68000-402-S5	Sink in FACS Kitchen Classroom	4.4	
68000-402-S6	Sink in FACS Kitchen Classroom	11.7	Repairs pending
68000-48-S	Sink in Teachers' Lounge	0.4	
68000-2022-79H-DF	Hallway Drinking Fountain near Restrooms near Band Room	0.5	
68000-2022-79H-WBFS	Hallway Water Bottle Filling Station near Restrooms near Band Room	0.5	
68000-61-UPPER-DF	Drinking Fountain in 2nd Floor Locker Room	26.6	Repairs pending
68000-403-SWB	Sink with Bubbler in Instrument/Band Room 403	3.6	
68000-90-S	Sink in Clinic	1.2	
68000-94H-DF	Hallway Drinking Fountain near Cafeteria	1.2	
68000-416-SWB	Sink with Bubbler in Industrial Lab 416	not in use	
68000-102-S1	Food Service Sink - Food Prep	426.4	Repairs pending
68000-102-S2	Food Service Sink - Food Prep	25.6	Repairs pending
68000-C2H-DFL	Hallway Drinking Fountain on 2nd Floor near Elevator/Left	0.5	
68000-C2H-DFR	Hallway Drinking Fountain on 2nd Floor near Elevator/Right	0.4	
68000-2022-C2H-WBFS	Hallway Water Bottle Filling Station on 2nd Floor near Elevator	0.4	