



Safety Inspection Photos

Staples High School

Auditorium
70 North Avenue
Westport, CT 06880



870 Bunting Lane, Bldg A
Primos, PA 19018

800-727-7471

www.sapsis-rigging.com


Requested By:	Steve Hamelin
Inspection Date:	September 22, 2022
Inspector:	Stu Cox




1




2




3



4



5



6



7




8




9



10




11



12



13



14




15



16



17



18



19



20



21



22



23



24



25



26



27



28



29



30



31



32



33



34



35



36



37



38



39



40



41



42



43



44



45



46



47



48



49




50



51



52



53



54



55



56



57



58



59




60



61




62



63



64




65



66



67



68




69




70



71



72



73