

Quail Complex Building 4 - Sampled 5/19/17			
CustomerSampleNumber	Description	Lead Result	Unit
80940-2017-W11A-S	Sink in FSD Kitchen Area	2.4	ppb
80940-2017-W130-S	Sink in Custodial Kitchen Area	<0.1*	ppb
80940-2017-W131-WBFS	Custodial Hallway Water Bottle Filling Station	<0.1*	ppb
80940-2017-W131-DF	Custodial Hallway Drinking Fountain	<0.1*	ppb
80940-2017-W144-S	Sink in Vending Area	0.2	ppb
80940-2017-W144-IM	Ice Machine in Vending Area	0.4	ppb
80940-2017-C131H-DFL	Landscape Hallway Drinking Fountain/Left	<0.1*	ppb
80940-2017-C131H-DFR	Landscape Hallway Drinking Fountain/Right	<0.1*	ppb
80940-2017-S110-S	Sink in Directors Kitchen Area	0.5	ppb
80940-2017-E142-S	Sink in Construction Management Kitchen Area	1.3	ppb
80940-2017-E108-DFR	Drinking Fountain near Laundry Area/Right	<0.1*	ppb
80940-2017-E108-DFL	Drinking Fountain near Laundry Area/Left	<0.1*	ppb
80940-2017-C132-S	Sink in Landscape Kitchen Area	0.2	ppb
80940-2017-C132-S2	Sink in Landscape Kitchen Area	0.2	ppb
* This result is less than 0.1 ppb, which is the lowest level that can be reported by the lab.			