

Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

| | | | | | | | | |
|--------------|---------------|---------------|--|--|--|--|--|--|
| Heim | | | | | | | | |
| Location | Room 142 Sink | Room 146 Sink | | | | | | |
| Test results | 16.60 | 16.80 | | | | | | |
| Remediation | | | | | | | | |
| Results | | | | | | | | |
| Results 2 | | | | | | | | |
| Back in use | | | | | | | | |
| | | | | | | | | |
| Location | | | | | | | | |
| Test results | | | | | | | | |
| Remediation | | | | | | | | |
| Results | | | | | | | | |
| Results | | | | | | | | |
| Results | | | | | | | | |
| Back in use | | | | | | | | |

Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

| | | | | | | | | |
|------------------|----------------------|------------------------|-------------------------|---------------------------|--------------------|-------------------|-------------------|-------------------|
| East high | | | | | | | | |
| Location | Pool Room Eye Wash | Kitchen Sink # 5 | Kitchen Sink # 8 | Room 102 Sink #1 | Room 103 Sink # 4 | Kiln Room Sink | Room 117 Sink # 4 | Room 117 Sink # 6 |
| Test results | 2080 | 20.2 | 27.5 | 18.6 | 20.4 | 30.4 | 52.6 | 97.2 |
| Remediation | | | | | | | | |
| Back in svc. | | | | | | | | |
| Location | Room 117 Sink #7 | Room 117 Sink # 8 | Room 119 Sink # 1 | Room 119 Sink # 2 | Room 119 Sink # 3 | Room 119 Sink # 4 | Room 119 Sink # 5 | Room 113 Sink |
| Test results | 101 | 44.9 | 32.6 | 23 | 71.2 | 50.4 | 15.4 | 38.3 |
| Remediation | | | | | | | | |
| Back in svc. | | | | | | | | |
| Location | Mens Lav by Aud Sink | Health Office Sink # 1 | Coaches Office Lav Sink | Boys Red locker Room Sink | Kiln Room Sink # 2 | | | |
| Test results | 29.2 | 21.8 | 21.2 | 19.2 | 30.4 | | | |
| Remediation | | | | | | | | |
| Back in svc. | | | | | | | | |
| Location | | | | | | | | |
| Test results | | | | | | | | |
| Remediation | | | | | | | | |
| Back in svc. | | | | | | | | |
| Location | | | | | | | | |
| Test results | | | | | | | | |
| Test results | | | | | | | | |
| Test results | | | | | | | | |
| Remediation | | | | | | | | |
| Back in svc. | | | | | | | | |

