

Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Transporation								
Location	mens Staff Room Skink # 2							
Test results	17.1							
Remediation								
Test results								
Back in use								
Location								
Test results								
Remediation								
Back in use								
AIM building								
Location								
Test results								
Remediation								
Back in use								

Hose bib: A hose bib is a faucet that is used to connect a hose for cleaning purposes. These faucets are not meant for use as a source of drinking water.

Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Casey middle									
	Location	Room 114 Sink	Room 129 Sink	Room 132 Sink # 2	Room 132 Sink # 5	Stage Sink	Room 139 Sink # 1	Faculty Bathroom Sink # 1	Mezzaninne Sink
	Test results	22.2	20.5	15.6	17.8	96.8	21.3	37.8	65.6
	Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing
	Test results	20.00	20.80	13.10	18.00	29.00	24.4	7.42	34.80
	Back in use			9/29/2021				9/29/2021	
	Location								
	Test results								
	Remediation								
	Results								
	Back in use								
	Location								
	Test results								
	Remediation								
	Back in use								
	Location								
	Test results								
	Remediation								
	Back in use								
	Location								
	Test results								
	Remediation								
	Back in use								
	Location								
	Test results								

Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Country Parkway								
Location	101 Classroom Sink # 1	102 Classroom Sink #1	107 Classroom Sink	108 Classroom Sink	110 Classroom Sink	Speech Office Sink	116 Classroom Sink	117 Classroom Sink
Results	18.10	25.60	18.20	19.40	25.00	19.60	16.00	29.00
Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing
Results	4.12	5.51	6.26	7.89	4.6	8.57	18.4	35.8
Results								
Results								
Back in use	9/29/2021	9/29/2021	9/29/2021	9/29/2021	9/29/2021	9/29/2021		
Location	121 Classroom Sink	123 Classroom Sink	122 Classroom Sink	124 Classroom Sink	125 Classroom Sink	127 Classroom Sink	12 Kitchen Bathroom Sink	
Results	19.70	18.90	24.60	15.60	20.00	15.50	35.90	
Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	
Results	12.4	9.01	13.8	12.7	23.2	14.8	20.4	
Back in use						9/29/2021		
Back in use								

Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Dodge Location Results Remediation Results Back in use Location Results Remediation Results Back in use								
	105 Bathroom Sink	144 Bathroom Sink	Basement Source	Basement Sink				
	18.10	18.50	42.70	43.50				
	Flushing	Flushing	Flushing	Flushing				
	19.80	27.40	12.30	3.25				
			9/29/2021	9/29/2021				

Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

East high	Location	Pool Room Eye Wash	Kitchen Sink # 5	Kitchen Sink # 8	Room 102 Sink #1	Room 103 Sink # 4	Kiln Room Sink	Room 117 Sink # 4	Room 117 Sink # 6
	Test results	2080	20.2	27.5	18.6	20.4	30.4	52.6	97.2
	Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing
	Test results	133	3.68	3.9	3.76	3.52	3.03	2.52	4.21
	Back in svc.		9/29/2021	9/29/2021	9/29/2021	9/29/2021	9/29/2021	9/29/2021	9/29/2021
	Location	Room 117 Sink #7	Room 117 Sink # 8	Room 119 Sink # 1	Room 119 Sink # 2	Room 119 Sink # 3	Room 119 Sink # 4	Room 119 Sink # 5	Room 113 Sink
	Test results	101	44.9	32.6	23	71.2	50.4	15.4	38.3
	Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing
	Test results	6.99	ND	8.07	1.99	3.19	3.79	2.29	2.26
	Back in svc.	9/29/2021	9/29/2021	9/29/2021	9/29/2021	9/29/2021	9/29/2021	9/29/2021	9/29/2021
	Location	Mens Lav by Aud Sink	Health Office Sink # 1	Coaches Office Lav Sink	Boys Red locker Room Sink	Kiln Room Sink # 2			
	Test results	29.2	21.8	21.2	19.2	30.4			
	Remediation	Flushing	Flushing	Flushing	Flushing	Flushing			
	Test results	88	14.6	236	20.3	2.77			
	Back in svc.		9/29/2021			9/29/2021			
	Location								
	Test results								
	Remediation								
	Test results								
	Back in svc.								
	Location								
	Test results								
	Test results								
	Test results								
	Remediation								
	Back in svc.								

EMSL Analytical, Inc.

200 Route 130 North, Cinnaminson, NJ 08077

Phone: (856) 303-2500 Fax: (856) 858-4571 Email: EnvChemistry2@emsl.com

Attn: **Keith Langlotz**
Williamsville CSD - Facilities Dept
480 Lawrence Bell Dr.
Williamsville, NY 14221

9/28/2021

Phone: (716) 626-8860


Fax:

The following analytical report covers the analysis performed on samples submitted to EMSL Analytical, Inc. on 8/27/2021. The results are tabulated on the attached data pages for the following client designated project:

Lead in Water Testing 2021

The reference number for these samples is EMSL Order #012109963. Please use this reference when calling about these samples. If you have any questions, please do not hesitate to contact me at (856) 303-2500.

Approved By:



Phillip Worby, Environmental Chemistry
Laboratory Director



The test results contained within this report meet the requirements of NELAP and/or the specific certification program that is applicable, unless otherwise noted.
NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, CA ELAP 1877

The samples associated with this report were received in good condition unless otherwise noted. This report relates only to those items tested as received by the laboratory. The QC data associated with the sample results meet the recovery and precision requirements established by the NELAP, unless specifically indicated. All results for soil samples are reported on a dry weight basis, unless otherwise noted. This report may not be reproduced except in full and without written approval by EMSL Analytical, Inc.

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>EnvChemistry2@emsl.com

EMSL Order: 012109963

CustomerID: WCSD21A

CustomerPO: 20-04919

ProjectID:

Attn: **Keith Langlotz**
Williamsville CSD - Facilities Dept
480 Lawrence Bell Dr.
Williamsville, NY 14221

Phone: (716) 626-8860
 Fax:
 Received: 8/27/2021 10:00 AM

Project: **Lead in Water Testing 2021****Analytical Results**

Client Sample Description CP-200
 101 Classroom Sink #1
Collected: 8/21/2021 6:15:00 AM
Lab ID: 012109963-0001

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	4.12	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 18:03

Client Sample Description CP-201
 102 Classroom Sink #1
Collected: 8/21/2021 6:17:00 AM
Lab ID: 012109963-0002

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	5.51	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 18:07

Client Sample Description CP-202
 107 Classroom Sink
Collected: 8/21/2021 6:18:00 AM
Lab ID: 012109963-0003

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	6.26	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 18:09

Client Sample Description CP-203
 108 Classroom Sink
Collected: 8/21/2021 6:19:00 AM
Lab ID: 012109963-0004

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	7.89	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 18:10

Client Sample Description CP-204
 110 Classroom Sink
Collected: 8/21/2021 6:22:00 AM
Lab ID: 012109963-0005

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	4.60	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 18:15

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>EnvChemistry2@emsl.com

EMSL Order: 012109963

CustomerID: WCSD21A

CustomerPO: 20-04919

ProjectID:

Attn: **Keith Langlotz**
Williamsville CSD - Facilities Dept
480 Lawrence Bell Dr.
Williamsville, NY 14221

Phone: (716) 626-8860
 Fax:
 Received: 8/27/2021 10:00 AM

Project: **Lead in Water Testing 2021****Analytical Results**

Client Sample Description CP-205
Speech Office Sink
Collected: 8/21/2021 6:23:00 AM
Lab ID: 012109963-0006

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	8.57	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 18:16

Client Sample Description CP-206
116 Classroom Sink
Collected: 8/21/2021 6:27:00 AM
Lab ID: 012109963-0007

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	18.4	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 18:18

Client Sample Description CP-207
117 Classroom Sink
Collected: 8/21/2021 6:28:00 AM
Lab ID: 012109963-0008

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	35.8	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 18:19

Client Sample Description CP-208
121 Classroom Sink
Collected: 8/21/2021 6:29:00 AM
Lab ID: 012109963-0009

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	12.4	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 18:20

Client Sample Description CP-209
123 Classroom Sink
Collected: 8/21/2021 6:31:00 AM
Lab ID: 012109963-0010

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	9.01	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 18:22

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>EnvChemistry2@emsl.com

EMSL Order: 012109963

CustomerID: WCSD21A

CustomerPO: 20-04919

ProjectID:

Attn: **Keith Langlotz**
Williamsville CSD - Facilities Dept
480 Lawrence Bell Dr.
Williamsville, NY 14221

Phone: (716) 626-8860
 Fax:
 Received: 8/27/2021 10:00 AM

Project: **Lead in Water Testing 2021****Analytical Results**

Client Sample Description CP-210
122 Classroom Sink
Collected: 8/21/2021 6:32:00 AM
Lab ID: 012109963-0011

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	13.8	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 18:23

Client Sample Description CP-211
124 Classroom Sink
Collected: 8/21/2021 6:34:00 AM
Lab ID: 012109963-0012

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	12.7	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 18:28

Client Sample Description CP-212
125 Classroom Sink
Collected: 8/21/2021 6:35:00 AM
Lab ID: 012109963-0013

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	23.2	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 18:32

Client Sample Description CP-213
127 Classroom Sink
Collected: 8/21/2021 6:36:00 AM
Lab ID: 012109963-0014

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	14.8	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 18:34

Client Sample Description CP-214
Kitchen Bathroom Sink
Collected: 8/21/2021 6:38:00 AM
Lab ID: 012109963-0015

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	20.4	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 18:35

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>EnvChemistry2@emsl.com

EMSL Order: 012109963

CustomerID: WCSD21A

CustomerPO: 20-04919

ProjectID:

Attn: **Keith Langlotz**
Williamsville CSD - Facilities Dept
480 Lawrence Bell Dr.
Williamsville, NY 14221

Phone: (716) 626-8860
 Fax:
 Received: 8/27/2021 10:00 AM

Project: **Lead in Water Testing 2021****Analytical Results**

Client Sample Description DE-200
105 Bathroom Sink # 1
Collected: 8/21/2021 6:27:00 AM
Lab ID: 012109963-0016

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	19.8	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 18:37

Client Sample Description DE-201
144 Bathroom Sink
Collected: 8/21/2021 6:33:00 AM
Lab ID: 012109963-0017

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	27.4	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 18:38

Client Sample Description DE-202
Basement Source
Collected: 8/21/2021 6:18:00 AM
Lab ID: 012109963-0018

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	12.3	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 18:40

Client Sample Description DE-203
Basement Sink
Collected: 8/21/2021 6:15:00 AM
Lab ID: 012109963-0019

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	3.25	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 18:41

Client Sample Description FE-200
38 Bathroom Sink # 1
Collected: 8/21/2021 7:32:00 AM
Lab ID: 012109963-0020

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	29.8	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 18:42

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>EnvChemistry2@emsl.com

EMSL Order: 012109963

CustomerID: WCSD21A

CustomerPO: 20-04919

ProjectID:

Attn: **Keith Langlotz**
Williamsville CSD - Facilities Dept
480 Lawrence Bell Dr.
Williamsville, NY 14221

Phone: (716) 626-8860
 Fax:
 Received: 8/27/2021 10:00 AM

Project: **Lead in Water Testing 2021****Analytical Results**

Client Sample Description FE-201
 36 Bathroom Sink
Collected: 8/21/2021 7:28:00 AM
Lab ID: 012109963-0021

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	22.1	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 18:51

Client Sample Description FE-202
 20 Classroom Sink # 3
Collected: 8/21/2021 7:25:00 AM
Lab ID: 012109963-0022

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	3.66	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 18:56

Client Sample Description FE-203
 19 Classroom Sink
Collected: 8/21/2021 7:22:00 AM
Lab ID: 012109963-0023

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	16.7	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 18:57

Client Sample Description FE-204
 12 Classroom Sink
Collected: 8/21/2021 7:20:00 AM
Lab ID: 012109963-0024

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	20.8	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 18:59

Client Sample Description FE-205
 9 Bathroom Sink
Collected: 8/21/2021 7:17:00 AM
Lab ID: 012109963-0025

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	18.1	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 19:00

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>EnvChemistry2@emsl.com

EMSL Order: 012109963

CustomerID: WCSD21A

CustomerPO: 20-04919

ProjectID:

Attn: **Keith Langlotz**
Williamsville CSD - Facilities Dept
480 Lawrence Bell Dr.
Williamsville, NY 14221

Phone: (716) 626-8860
 Fax:
 Received: 8/27/2021 10:00 AM

Project: **Lead in Water Testing 2021****Analytical Results**

Client Sample Description FE-206
1 Classroom Sink
Collected: 8/21/2021 7:00:00 AM
Lab ID: 012109963-0026

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	2.42	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 19:02

Client Sample Description FE-207
Library Offcie Sink
Collected: 8/21/2021 6:57:00 AM
Lab ID: 012109963-0027

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	6.85	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 19:03

Client Sample Description HE-200
Room 142 Sink
Collected: 8/21/2021 6:45:00 AM
Lab ID: 012109963-0028

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	12.9	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 19:07

Client Sample Description HE-201
Room 146 Sink
Collected: 8/21/2021 6:46:00 AM
Lab ID: 012109963-0029

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	43.3	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 19:09

Client Sample Description ME-200
Boiler Room Sample
Collected: 8/21/2021 7:09:00 AM
Lab ID: 012109963-0030

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	12.1	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 19:10

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>EnvChemistry2@emsl.com

EMSL Order: 012109963
 CustomerID: WCSD21A
 CustomerPO: 20-04919
 ProjectID:

Attn: **Keith Langlotz**
Williamsville CSD - Facilities Dept
480 Lawrence Bell Dr.
Williamsville, NY 14221

Phone: (716) 626-8860
 Fax:
 Received: 8/27/2021 10:00 AM

Project: **Lead in Water Testing 2021****Analytical Results**

Client Sample Description ME-201
Boiler Room Eyewash
Collected: 8/21/2021 7:08:00 AM
Lab ID: 012109963-0031

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	1.99	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 19:12

Client Sample Description ME-202
Girl's ShBathroom Sink
Collected: 8/21/2021 7:05:00 AM
Lab ID: 012109963-0032

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	3.55	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 19:16

Client Sample Description ME-203
42 Classroom Sink
Collected: 8/21/2021 7:03:00 AM
Lab ID: 012109963-0033

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	10.9	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 19:18

Client Sample Description ME-204
29 Classroom Sink # 3
Collected: 8/21/2021 7:00:00 AM
Lab ID: 012109963-0034

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	14.9	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 19:19

Client Sample Description ME-205
22 Classroom Sink
Collected: 8/21/2021 6:52:00 AM
Lab ID: 012109963-0035

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	9.70	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 19:21

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>EnvChemistry2@emsl.com

EMSL Order: 012109963

CustomerID: WCSD21A

CustomerPO: 20-04919

ProjectID:

Attn: **Keith Langlotz**
Williamsville CSD - Facilities Dept
480 Lawrence Bell Dr.
Williamsville, NY 14221

Phone: (716) 626-8860
 Fax:
 Received: 8/27/2021 10:00 AM

Project: **Lead in Water Testing 2021****Analytical Results**

Client Sample Description ME-206
Library Office Sink
Collected: 8/21/2021 6:52:00 AM
Lab ID: 012109963-0036

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	2.78	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 19:25

Client Sample Description MW-200
109 Classroom Sink # 1
Collected: 8/21/2021 7:32:00 AM
Lab ID: 012109963-0037

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	14.7	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 19:27

Client Sample Description MW-201
Library Office Sink
Collected: 8/21/2021 7:52:00 AM
Lab ID: 012109963-0038

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	18.9	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 19:28

Client Sample Description MW-202
102 Classroom Sink
Collected: 8/21/2021 7:27:00 AM
Lab ID: 012109963-0039

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	17.3	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 19:30

Client Sample Description MW-203
Boiler Room Eyewash
Collected: 8/21/2021 7:42:00 AM
Lab ID: 012109963-0040

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	67.8	1.00 µg/L	9/22/2021 KG	9/23/2021 JW 19:00

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>EnvChemistry2@emsl.com

EMSL Order: 012109963

CustomerID: WCSD21A

CustomerPO: 20-04919

ProjectID:

Attn: **Keith Langlotz**
Williamsville CSD - Facilities Dept
480 Lawrence Bell Dr.
Williamsville, NY 14221

Phone: (716) 626-8860
 Fax:
 Received: 8/27/2021 10:00 AM

Project: **Lead in Water Testing 2021****Analytical Results**

Client Sample Description		MW-204 Boiler Room Sample	Collected:	8/21/2021 7:45:00 AM	Lab ID:	012109963-0041		
Method	Parameter	Result	RL Units		Prep Date & Analyst		Analysis Date & Analyst	
METALS								
200.8	Lead	43.6	1.00 µg/L		9/23/2021	KG	9/24/2021 13:58	JW
Client Sample Description		MW-205 102 Classroom Sink # 2	Collected:	8/21/2021 7:26:00 AM	Lab ID:	012109963-0042		
Method	Parameter	Result	RL Units		Prep Date & Analyst		Analysis Date & Analyst	
METALS								
200.8	Lead	16.7	1.00 µg/L		9/27/2021	VD	9/27/2021 19:31	VD
Client Sample Description		MW-206 101 Classroom Sink # 2	Collected:	8/21/2021 7:24:00 AM	Lab ID:	012109963-0043		
Method	Parameter	Result	RL Units		Prep Date & Analyst		Analysis Date & Analyst	
METALS								
200.8	Lead	16.1	1.00 µg/L		9/24/2021	VD	9/27/2021 14:32	VD
Client Sample Description		MW-207 Kitchen Pot Filler	Collected:	8/21/2021 7:47:00 AM	Lab ID:	012109963-0044		
Method	Parameter	Result	RL Units		Prep Date & Analyst		Analysis Date & Analyst	
METALS								
200.8	Lead	5.65	1.00 µg/L		9/27/2021	VD	9/27/2021 19:37	VD
Client Sample Description		CM-300 Room 114 Sink	Collected:	8/21/2021 8:06:00 AM	Lab ID:	012109963-0045		
Method	Parameter	Result	RL Units		Prep Date & Analyst		Analysis Date & Analyst	
METALS								
200.8	Lead	20.0	1.00 µg/L		9/27/2021	VD	9/27/2021 19:44	VD

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>EnvChemistry2@emsl.com

EMSL Order: 012109963
 CustomerID: WCSD21A
 CustomerPO: 20-04919
 ProjectID:

Attn: **Keith Langlotz**
Williamsville CSD - Facilities Dept
480 Lawrence Bell Dr.
Williamsville, NY 14221

Phone: (716) 626-8860
 Fax:
 Received: 8/27/2021 10:00 AM

Project: **Lead in Water Testing 2021****Analytical Results**

Client Sample Description		CM-301 Room 129 Sink	Collected:		8/21/2021 8:17:00 AM	Lab ID:		012109963-0046
Method	Parameter	Result	RL Units		Prep Date & Analyst		Analysis Date & Analyst	
METALS								
200.8	Lead	20.8	1.00 µg/L		9/27/2021	VD	9/27/2021 19:46	VD
Client Sample Description		CM-302 Room 132 Sink # 2	Collected:		8/21/2021 7:51:00 AM	Lab ID:		012109963-0047
Method	Parameter	Result	RL Units		Prep Date & Analyst		Analysis Date & Analyst	
METALS								
200.8	Lead	13.1	1.00 µg/L		9/27/2021	VD	9/27/2021 19:47	VD
Client Sample Description		CM-303 Room 132 Sink # 5	Collected:		8/21/2021 7:52:00 AM	Lab ID:		012109963-0048
Method	Parameter	Result	RL Units		Prep Date & Analyst		Analysis Date & Analyst	
METALS								
200.8	Lead	18.0	1.00 µg/L		9/27/2021	VD	9/27/2021 19:49	VD
Client Sample Description		CM-304 Stage Sink	Collected:		8/21/2021 7:58:00 AM	Lab ID:		012109963-0049
Method	Parameter	Result	RL Units		Prep Date & Analyst		Analysis Date & Analyst	
METALS								
200.8	Lead	29.0	1.00 µg/L		9/27/2021	VD	9/27/2021 19:50	VD
Client Sample Description		CM-305 Room 139 Sink # 1	Collected:		8/21/2021 7:55:00 AM	Lab ID:		012109963-0050
Method	Parameter	Result	RL Units		Prep Date & Analyst		Analysis Date & Analyst	
METALS								
200.8	Lead	24.4	1.00 µg/L		9/27/2021	VD	9/27/2021 19:52	VD

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>EnvChemistry2@emsl.com

EMSL Order: 012109963
 CustomerID: WCSD21A
 CustomerPO: 20-04919
 ProjectID:

Attn: **Keith Langlotz**
Williamsville CSD - Facilities Dept
480 Lawrence Bell Dr.
Williamsville, NY 14221

Phone: (716) 626-8860
 Fax:
 Received: 8/27/2021 10:00 AM

Project: **Lead in Water Testing 2021****Analytical Results**

Client Sample Description CM-306
 Faculty Bathroom Sink # 1
Collected: 8/21/2021 8:25:00 AM
Lab ID: 012109963-0051

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	7.42	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 19:53

Client Sample Description CM-307
 Mezzanine Sink
Collected: 8/21/2021 7:47:00 AM
Lab ID: 012109963-0052

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	34.8	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 19:54

Client Sample Description HM-300
 Room D6 Sink # 1
Collected: 8/21/2021 7:31:00 AM
Lab ID: 012109963-0053

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	48.9	1.00 µg/L	9/22/2021 KG	9/23/2021 JW 19:02

Client Sample Description HM-301
 Boys Locker Room Sink # 1
Collected: 8/21/2021 7:04:00 AM
Lab ID: 012109963-0054

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	5.30	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 19:56

Client Sample Description HM-302
 Room C-13 Eye Wash
Collected: 8/21/2021 7:26:00 AM
Lab ID: 012109963-0055

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	4.29	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 20:00

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>EnvChemistry2@emsl.com

EMSL Order: 012109963
 CustomerID: WCSD21A
 CustomerPO: 20-04919
 ProjectID:

Attn: **Keith Langlotz**
Williamsville CSD - Facilities Dept
480 Lawrence Bell Dr.
Williamsville, NY 14221

Phone: (716) 626-8860
 Fax:
 Received: 8/27/2021 10:00 AM

Project: **Lead in Water Testing 2021****Analytical Results**

Client Sample Description HM-303
Room C-11 Eyewash
Collected: 8/21/2021 7:08:00 AM
Lab ID: 012109963-0056

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	3.84	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 20:05

Client Sample Description HM-304
Room A-11 Eyewash
Collected: 8/21/2021 7:05:00 AM
Lab ID: 012109963-0057

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	11.1	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 20:06

Client Sample Description HM-305
Womens Lav by Aud Sink # 2
Collected: 8/21/2021 7:03:00 AM
Lab ID: 012109963-0058

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	8.45	1.00 µg/L	9/22/2021 KG	9/23/2021 JW 19:04

Client Sample Description HM-306
Outlet by Steamer in Kitchen
Collected: 8/21/2021 7:00:00 AM
Lab ID: 012109963-0059

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	69.2	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 20:08

Client Sample Description HM-307
Boiler Room Eye Wash
Collected: 8/21/2021 6:58:00 AM
Lab ID: 012109963-0060

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	29.7	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 20:09



EMSL Analytical, Inc.

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>

EnvChemistry2@emsl.com

EMSL Order:	012109963
CustomerID:	WCSD21A
CustomerPO:	20-04919
ProjectID:	

Definitions:

MDL - method detection limit

J - Result was below the reporting limit, but at or above the MDL

ND - indicates that the analyte was not detected at the reporting limit

RL - Reporting Limit (Analytical)

D - Dilution Sample required a dilution which was used to calculate final results

EMSL Analytical, Inc.

200 Route 130 North, Cinnaminson, NJ 08077

Phone: (856) 303-2500 Fax: (856) 858-4571 Email: EnvChemistry2@emsl.com

Attn: **Keith Langlotz**
Williamsville CSD - Facilities Dept
480 Lawrence Bell Dr.
Williamsville, NY 14221

9/28/2021

Phone: (716) 626-8860


Fax:

The following analytical report covers the analysis performed on samples submitted to EMSL Analytical, Inc. on 8/27/2021. The results are tabulated on the attached data pages for the following client designated project:

Lead in Water Testing 2021

The reference number for these samples is EMSL Order #012109969. Please use this reference when calling about these samples. If you have any questions, please do not hesitate to contact me at (856) 303-2500.

Approved By:



Phillip Worby, Environmental Chemistry
Laboratory Director



The test results contained within this report meet the requirements of NELAP and/or the specific certification program that is applicable, unless otherwise noted.
NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, CA ELAP 1877

The samples associated with this report were received in good condition unless otherwise noted. This report relates only to those items tested as received by the laboratory. The QC data associated with the sample results meet the recovery and precision requirements established by the NELAP, unless specifically indicated. All results for soil samples are reported on a dry weight basis, unless otherwise noted. This report may not be reproduced except in full and without written approval by EMSL Analytical, Inc.

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>EnvChemistry2@emsl.com

EMSL Order: 012109969

CustomerID: WCSD21A

CustomerPO: 20-04919

ProjectID:

Attn: **Keith Langlotz**
Williamsville CSD - Facilities Dept
480 Lawrence Bell Dr.
Williamsville, NY 14221

Phone: (716) 626-8860
 Fax:
 Received: 8/27/2021 10:00 AM

Project: **Lead in Water Testing 2021****Analytical Results**

Client Sample Description MM-300
Principals Offcie Lav Sink
Collected: 8/21/2021 8:09:00 AM
Lab ID: 012109969-0001

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	6.03	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 16:23

Client Sample Description MM-301
Storage Room by AP Sink
Collected: 8/21/2021 8:14:00 AM
Lab ID: 012109969-0002

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	12.8	1.00 µg/L	9/27/2021 VD	9/28/2021 VD 09:55

Client Sample Description MM-302
Clinic Bathroom Sink
Collected: 8/21/2021 8:15:00 AM
Lab ID: 012109969-0003

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	176 D	10.0 µg/L	9/27/2021 VD	9/28/2021 VD 09:56

Client Sample Description MM-303
Room A-1 Sink
Collected: 8/21/2021 8:17:00 AM
Lab ID: 012109969-0004

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	43.3	1.00 µg/L	9/27/2021 VD	9/28/2021 VD 09:58

Client Sample Description MM-304
Room A-6 Sink
Collected: 8/21/2021 8:20:00 AM
Lab ID: 012109969-0005

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	39.7	1.00 µg/L	9/27/2021 VD	9/28/2021 VD 09:59

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>EnvChemistry2@emsl.com

EMSL Order: 012109969
 CustomerID: WCSD21A
 CustomerPO: 20-04919
 ProjectID:

Attn: **Keith Langlotz**
Williamsville CSD - Facilities Dept
480 Lawrence Bell Dr.
Williamsville, NY 14221

Phone: (716) 626-8860
 Fax:
 Received: 8/27/2021 10:00 AM

Project: **Lead in Water Testing 2021****Analytical Results**

Client Sample Description		MM-305 Room A-8 Sink	Collected:		8/21/2021 8:22:00 AM	Lab ID:		012109969-0006
Method	Parameter	Result	RL Units	Prep Date & Analyst		Analysis Date & Analyst		
METALS								
200.8	Lead	56.7	1.00 µg/L	9/27/2021	VD	9/28/2021 10:01	VD	
Client Sample Description		MM-306 Girls Lav by Room A-11 Sink	Collected:		8/21/2021 8:23:00 AM	Lab ID:		012109969-0007
Method	Parameter	Result	RL Units	Prep Date & Analyst		Analysis Date & Analyst		
METALS								
200.8	Lead	6.17	1.00 µg/L	9/27/2021	VD	9/28/2021 10:02	VD	
Client Sample Description		MM-307 Room A-11 Sink	Collected:		8/21/2021 8:23:00 AM	Lab ID:		012109969-0008
Method	Parameter	Result	RL Units	Prep Date & Analyst		Analysis Date & Analyst		
METALS								
200.8	Lead	50.6	1.00 µg/L	9/27/2021	VD	9/28/2021 10:04	VD	
Client Sample Description		MM-308 Room A-10 Sink	Collected:		8/21/2021 8:25:00 AM	Lab ID:		012109969-0009
Method	Parameter	Result	RL Units	Prep Date & Analyst		Analysis Date & Analyst		
METALS								
200.8	Lead	49.3	1.00 µg/L	9/27/2021	VD	9/28/2021 10:05	VD	
Client Sample Description		MM-309 Room A-13 Sink	Collected:		8/21/2021 8:26:00 AM	Lab ID:		012109969-0010
Method	Parameter	Result	RL Units	Prep Date & Analyst		Analysis Date & Analyst		
METALS								
200.8	Lead	29.0	1.00 µg/L	9/27/2021	VD	9/28/2021 10:06	VD	

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>EnvChemistry2@emsl.com

EMSL Order: 012109969

CustomerID: WCSD21A

CustomerPO: 20-04919

ProjectID:

Attn: **Keith Langlotz**
Williamsville CSD - Facilities Dept
480 Lawrence Bell Dr.
Williamsville, NY 14221

Phone: (716) 626-8860
 Fax:
 Received: 8/27/2021 10:00 AM

Project: **Lead in Water Testing 2021****Analytical Results**

Client Sample Description MM-310
 Handicapped Lav by Library Sink
Collected: 8/21/2021 8:36:00 AM
Lab ID: 012109969-0011

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	28.9	1.00 µg/L	9/27/2021 VD	9/28/2021 VD 10:11

Client Sample Description MM-311
 Room B-6 Sink
Collected: 8/21/2021 8:35:00 AM
Lab ID: 012109969-0012

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	30.2	1.00 µg/L	9/27/2021 VD	9/28/2021 VD 10:15

Client Sample Description MM-313
 Bays Lav by A-11 Sink #1
Collected: 8/21/2021 8:41:00 AM
Lab ID: 012109969-0013

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	8.53	1.00 µg/L	9/27/2021 VD	9/28/2021 VD 10:17

Client Sample Description MM-314
 Hallway Fountain by A-11 Sink #1
Collected: 8/21/2021 8:45:00 AM
Lab ID: 012109969-0014

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	ND	1.00 µg/L	9/27/2021 VD	9/28/2021 VD 10:18

Client Sample Description MM-315
 Girls Lav by A-11 Sink #1
Collected: 8/21/2021 8:45:00 AM
Lab ID: 012109969-0015

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	4.41	1.00 µg/L	9/27/2021 VD	9/28/2021 VD 10:20

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>EnvChemistry2@emsl.com

EMSL Order: 012109969
CustomerID: WCSD21A
CustomerPO: 20-04919
ProjectID:

Attn: **Keith Langlotz**
Williamsville CSD - Facilities Dept
480 Lawrence Bell Dr.
Williamsville, NY 14221

Phone: (716) 626-8860
Fax:
Received: 8/27/2021 10:00 AM

Project: **Lead in Water Testing 2021****Analytical Results**

Client Sample Description		MM-320 Room E-3 Storage Sink	Collected:	8/21/2021 9:01:00 AM	Lab ID:	012109969-0016	
Method	Parameter	Result	RL Units	Prep Date & Analyst		Analysis Date & Analyst	
METALS							
200.8	Lead	22.4	1.00 µg/L	9/27/2021	VD	9/28/2021 10:21	VD
Client Sample Description		MM-321 Room E-5 Sink #3	Collected:	8/21/2021 9:02:00 AM	Lab ID:	012109969-0017	
Method	Parameter	Result	RL Units	Prep Date & Analyst		Analysis Date & Analyst	
METALS							
200.8	Lead	8.33	1.00 µg/L	9/27/2021	VD	9/28/2021 10:23	VD
Client Sample Description		MM-322 Room E-2 Sink #1	Collected:	8/21/2021 8:51:00 AM	Lab ID:	012109969-0018	
Method	Parameter	Result	RL Units	Prep Date & Analyst		Analysis Date & Analyst	
METALS							
200.8	Lead	16.5	1.00 µg/L	9/27/2021	VD	9/28/2021 10:24	VD
Client Sample Description		MM-323 Room E-2 Sink #2	Collected:	8/21/2021 8:51:00 AM	Lab ID:	012109969-0019	
Method	Parameter	Result	RL Units	Prep Date & Analyst		Analysis Date & Analyst	
METALS							
200.8	Lead	15.4	1.00 µg/L	9/27/2021	VD	9/27/2021 17:04	VD
Client Sample Description		MM-324 Room E-2 Sink #3	Collected:	8/21/2021 8:51:00 AM	Lab ID:	012109969-0020	
Method	Parameter	Result	RL Units	Prep Date & Analyst		Analysis Date & Analyst	
METALS							
200.8	Lead	29.2	1.00 µg/L	9/27/2021	VD	9/27/2021 17:05	VD

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>EnvChemistry2@emsl.com

EMSL Order: 012109969

CustomerID: WCSD21A

CustomerPO: 20-04919

ProjectID:

Attn: **Keith Langlotz**
Williamsville CSD - Facilities Dept
480 Lawrence Bell Dr.
Williamsville, NY 14221

Phone: (716) 626-8860
Fax:
Received: 8/27/2021 10:00 AM

Project: **Lead in Water Testing 2021****Analytical Results**

Client Sample Description		MM-325 Room E-2 Sink #4	Collected: 8/21/2021 8:51:00 AM		Lab ID: 012109969-0021		
Method	Parameter	Result	RL Units	Prep Date & Analyst		Analysis Date & Analyst	
METALS							
200.8	Lead	13.5	1.00 µg/L	9/27/2021	VD	9/27/2021 17:11	VD
Client Sample Description		MM-326 Room E-4 Sink	Collected: 8/21/2021 8:57:00 AM		Lab ID: 012109969-0022		
Method	Parameter	Result	RL Units	Prep Date & Analyst		Analysis Date & Analyst	
METALS							
200.8	Lead	18.1	1.00 µg/L	9/27/2021	VD	9/27/2021 17:16	VD
Client Sample Description		MM-327 Room E-7 Sink # 1	Collected: 8/21/2021 9:05:00 AM		Lab ID: 012109969-0023		
Method	Parameter	Result	RL Units	Prep Date & Analyst		Analysis Date & Analyst	
METALS							
200.8	Lead	29.3	1.00 µg/L	9/27/2021	VD	9/27/2021 17:17	VD
Client Sample Description		MM-329 Boys Locker Room Sink	Collected: 8/21/2021 9:08:00 AM		Lab ID: 012109969-0024		
Method	Parameter	Result	RL Units	Prep Date & Analyst		Analysis Date & Analyst	
METALS							
200.8	Lead	18.4	1.00 µg/L	9/27/2021	VD	9/27/2021 17:22	VD
Client Sample Description		MM-330 Girls Locker Room Sink #2	Collected: 8/21/2021 9:10:00 AM		Lab ID: 012109969-0025		
Method	Parameter	Result	RL Units	Prep Date & Analyst		Analysis Date & Analyst	
METALS							
200.8	Lead	21.7	1.00 µg/L	9/27/2021	VD	9/27/2021 17:23	VD

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>EnvChemistry2@emsl.com

EMSL Order: 012109969
 CustomerID: WCSD21A
 CustomerPO: 20-04919
 ProjectID:

Attn: **Keith Langlotz**
Williamsville CSD - Facilities Dept
480 Lawrence Bell Dr.
Williamsville, NY 14221

Phone: (716) 626-8860
 Fax:
 Received: 8/27/2021 10:00 AM

Project: **Lead in Water Testing 2021****Analytical Results**

Client Sample Description MM-331 **Collected:** 8/21/2021 **Lab ID:** 012109969-0026
 Girls Locker Room Sink #3 9:10:00 AM

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	25.1	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 17:25

Client Sample Description MM-332 **Collected:** 8/21/2021 **Lab ID:** 012109969-0027
 Basement Storage Sink # 1 9:15:00 AM

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	9.55	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 17:26

Client Sample Description TM-317 **Collected:** 8/21/2021 **Lab ID:** 012109969-0028
 Source Sample Boiler Room 8:14:00 AM

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	ND	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 17:28

Client Sample Description EH-300 **Collected:** 8/21/2021 **Lab ID:** 012109969-0029
 Pool Room Eye Wash 7:34:00 AM

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	133 D	10.0 µg/L	9/27/2021 VD	9/28/2021 VD 09:33

Client Sample Description EH-301 **Collected:** 8/21/2021 **Lab ID:** 012109969-0030
 Kitchen Sink # 5 7:38:00 AM

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	3.68	1.00 µg/L	9/27/2021 VD	9/28/2021 VD 09:34

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>EnvChemistry2@emsl.com

EMSL Order: 012109969

CustomerID: WCSD21A

CustomerPO: 20-04919

ProjectID:

Attn: **Keith Langlotz**
Williamsville CSD - Facilities Dept
480 Lawrence Bell Dr.
Williamsville, NY 14221

Phone: (716) 626-8860
 Fax:
 Received: 8/27/2021 10:00 AM

Project: **Lead in Water Testing 2021****Analytical Results**

Client Sample Description EH-302
 Kitchen Sink # 8
Collected: 8/21/2021 7:39:00 AM
Lab ID: 012109969-0031

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	3.90	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 17:32

Client Sample Description EH-303
 Room 102 Sink # 1
Collected: 8/21/2021 7:40:00 AM
Lab ID: 012109969-0032

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	3.76	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 17:39

Client Sample Description EH-304
 Room 103 Sink # 4
Collected: 8/21/2021 7:41:00 AM
Lab ID: 012109969-0033

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	3.52	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 17:41

Client Sample Description EH-305
 Kiln Room Sink
Collected: 8/21/2021 7:43:00 AM
Lab ID: 012109969-0034

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	3.03	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 17:42

Client Sample Description EH-306
 Room 117 Sink #4
Collected: 8/21/2021 7:45:00 AM
Lab ID: 012109969-0035

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	2.52	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 17:44

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>EnvChemistry2@emsl.com

EMSL Order: 012109969

CustomerID: WCSD21A

CustomerPO: 20-04919

ProjectID:

Attn: **Keith Langlotz**
Williamsville CSD - Facilities Dept
480 Lawrence Bell Dr.
Williamsville, NY 14221

Phone: (716) 626-8860
 Fax:
 Received: 8/27/2021 10:00 AM

Project: **Lead in Water Testing 2021****Analytical Results**

Client Sample Description EH-307
 Room 117 Sink #6
Collected: 8/21/2021 7:46:00 AM
Lab ID: 012109969-0036

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	4.21	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 17:45

Client Sample Description EH-308
 Room 117 Sink #7
Collected: 8/21/2021 7:46:00 AM
Lab ID: 012109969-0037

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	6.99	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 17:47

Client Sample Description EH-309
 Room 117 Sink #8
Collected: 8/21/2021 7:47:00 AM
Lab ID: 012109969-0038

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	ND	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 17:48

Client Sample Description EH-310
 Room 119 Sink #1
Collected: 8/21/2021 7:48:00 AM
Lab ID: 012109969-0039

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	8.07	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 17:50

Client Sample Description EH-311
 Room 119 Sink #2
Collected: 8/21/2021 7:48:00 AM
Lab ID: 012109969-0040

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	1.99	1.00 µg/L	9/27/2021 VD	9/27/2021 VD 17:51

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>EnvChemistry2@emsl.com

EMSL Order: 012109969

CustomerID: WCSD21A

CustomerPO: 20-04919

ProjectID:

Attn: **Keith Langlotz**
Williamsville CSD - Facilities Dept
480 Lawrence Bell Dr.
Williamsville, NY 14221

Phone: (716) 626-8860
 Fax:
 Received: 8/27/2021 10:00 AM

Project: **Lead in Water Testing 2021****Analytical Results**

Client Sample Description EH-312
Room 119 Sink #3
Collected: 8/21/2021 7:49:00 AM
Lab ID: 012109969-0041

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	3.19	1.00 µg/L	9/28/2021 VD	9/27/2021 VD 11:31

Client Sample Description EH-313
Room 119 Sink #4
Collected: 8/21/2021 7:49:00 AM
Lab ID: 012109969-0042

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	3.79	1.00 µg/L	9/28/2021 VD	9/27/2021 VD 11:36

Client Sample Description EH-314
Room 119 Sink #5
Collected: 8/21/2021 7:50:00 AM
Lab ID: 012109969-0043

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	2.29	1.00 µg/L	9/28/2021 VD	9/27/2021 VD 11:37

Client Sample Description EH-315
Room 113 Sink
Collected: 8/21/2021 7:52:00 AM
Lab ID: 012109969-0044

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	2.67	1.00 µg/L	9/28/2021 VD	9/27/2021 VD 11:39

Client Sample Description EH-316
Mens Lav by Aud Sink
Collected: 8/21/2021 7:54:00 AM
Lab ID: 012109969-0045

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	88.0	1.00 µg/L	9/28/2021 VD	9/27/2021 VD 11:43

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>EnvChemistry2@emsl.com

EMSL Order: 012109969

CustomerID: WCSD21A

CustomerPO: 20-04919

ProjectID:

Attn: **Keith Langlotz**
Williamsville CSD - Facilities Dept
480 Lawrence Bell Dr.
Williamsville, NY 14221

Phone: (716) 626-8860
 Fax:
 Received: 8/27/2021 10:00 AM

Project: **Lead in Water Testing 2021****Analytical Results**

Client Sample Description EH-317
 Health Office Sink # 1
Collected: 8/21/2021
 7:56:00 AM
Lab ID: 012109969-0046

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	14.6	1.00 µg/L	9/28/2021 VD	9/27/2021 VD 11:45

Client Sample Description EH-318
 Womens PE Coaches Office Lav Sink
Collected: 8/21/2021
 7:58:00 AM
Lab ID: 012109969-0047

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	236 D	10.0 µg/L	9/28/2021 VD	9/27/2021 VD 12:57

Client Sample Description EH-319
 Boys Red locker Room Sink
Collected: 8/21/2021
 7:59:00 AM
Lab ID: 012109969-0048

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	20.3	1.00 µg/L	9/28/2021 VD	9/27/2021 VD 12:58

Client Sample Description EH-320
 Kiln Room Sink # 2
Collected: 8/21/2021
 7:44:00 AM
Lab ID: 012109969-0049

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	2.77	1.00 µg/L	9/28/2021 VD	9/27/2021 VD 11:49

Client Sample Description NH-300
 Boiler Room Source
Collected: 8/21/2021
 8:46:00 AM
Lab ID: 012109969-0050

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	ND	1.00 µg/L	9/28/2021 VD	9/27/2021 VD 11:50

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>EnvChemistry2@emsl.com

EMSL Order: 012109969

CustomerID: WCSD21A

CustomerPO: 20-04919

ProjectID:

Attn: **Keith Langlotz**
Williamsville CSD - Facilities Dept
480 Lawrence Bell Dr.
Williamsville, NY 14221

Phone: (716) 626-8860
 Fax:
 Received: 8/27/2021 10:00 AM

Project: **Lead in Water Testing 2021****Analytical Results**

Client Sample Description NH-301
 Conference Room Sink # 1
Collected: 8/21/2021 9:28:00 AM
Lab ID: 012109969-0051

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	2.86	1.00 µg/L	9/28/2021 VD	9/27/2021 VD 11:52

Client Sample Description NH-302
 Kitchen Dish room Sink # 2
Collected: 8/21/2021 9:24:00 AM
Lab ID: 012109969-0052

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	11.5	1.00 µg/L	9/28/2021 VD	9/27/2021 VD 11:56

Client Sample Description NH-303
 Womens Lav by C-108 Sink # 3
Collected: 8/21/2021 8:53:00 AM
Lab ID: 012109969-0053

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	10.8	1.00 µg/L	9/28/2021 VD	9/27/2021 VD 12:01

Client Sample Description NH-304
 Room C-108 Sink #1
Collected: 8/21/2021 8:55:00 AM
Lab ID: 012109969-0054

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	26.9	1.00 µg/L	9/28/2021 VD	9/27/2021 VD 12:02

Client Sample Description NH-305
 Room C-108 Sink #2
Collected: 8/21/2021 8:56:00 AM
Lab ID: 012109969-0055

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	18.4	1.00 µg/L	9/28/2021 VD	9/27/2021 VD 12:04

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>EnvChemistry2@emsl.com

EMSL Order: 012109969

CustomerID: WCSD21A

CustomerPO: 20-04919

ProjectID:

Attn: **Keith Langlotz**
Williamsville CSD - Facilities Dept
480 Lawrence Bell Dr.
Williamsville, NY 14221

Phone: (716) 626-8860
 Fax:
 Received: 8/27/2021 10:00 AM

Project: **Lead in Water Testing 2021****Analytical Results**

Client Sample Description NH-306
Room C-105 Sink #1
Collected: 8/21/2021 9:07:00 AM
Lab ID: 012109969-0056

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	4.87	1.00 µg/L	9/28/2021 VD	9/27/2021 VD 12:05

Client Sample Description NH-307
Room C-152 Sink #1
Collected: 8/21/2021 9:17:00 AM
Lab ID: 012109969-0057

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	5.01	1.00 µg/L	9/28/2021 VD	9/27/2021 VD 12:07

Client Sample Description NH-308
Room C-162 Sink #2
Collected: 8/21/2021 9:00:00 AM
Lab ID: 012109969-0058

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	30.4	1.00 µg/L	9/28/2021 VD	9/27/2021 VD 12:08

Client Sample Description NH-309
Mens Lav by C-130 Sink #1
Collected: 8/21/2021 9:10:00 AM
Lab ID: 012109969-0059

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	16.9	1.00 µg/L	9/28/2021 VD	9/27/2021 VD 12:10

Client Sample Description NH-310
Mens Lav by C-130 Sink #2
Collected: 8/21/2021 9:11:00 AM
Lab ID: 012109969-0060

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	15.5	1.00 µg/L	9/28/2021 VD	9/27/2021 VD 12:11

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>EnvChemistry2@emsl.com

EMSL Order: 012109969
 CustomerID: WCSD21A
 CustomerPO: 20-04919
 ProjectID:

Attn: **Keith Langlotz**
Williamsville CSD - Facilities Dept
480 Lawrence Bell Dr.
Williamsville, NY 14221

Phone: (716) 626-8860
 Fax:
 Received: 8/27/2021 10:00 AM

Project: **Lead in Water Testing 2021****Analytical Results**

Client Sample Description NH-311 **Collected:** 8/21/2021 **Lab ID:** 012109969-0061
 Mens Lav by C-130 Sink #3 9:12:00 AM

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	264 D	5.00 µg/L	9/24/2021 VD	9/27/2021 VD 13:01

Client Sample Description NH-312 **Collected:** 8/21/2021 **Lab ID:** 012109969-0062
 Womens 1st Floor Coaches Office Sink 9:15:00 AM

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	13.7	1.00 µg/L	9/24/2021 VD	9/27/2021 VD 13:03

Client Sample Description NH-313 **Collected:** 8/21/2021 **Lab ID:** 012109969-0063
 Pump Room Eye Wash 8:43:00 AM

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	23.2	1.00 µg/L	9/24/2021 VD	9/27/2021 VD 12:26

Client Sample Description SH-300 **Collected:** 8/21/2021 **Lab ID:** 012109969-0064
 Room 134 Sink #1 6:35:00 AM

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	57.4	1.00 µg/L	9/24/2021 VD	9/27/2021 VD 12:27

Client Sample Description SH-301 **Collected:** 8/21/2021 **Lab ID:** 012109969-0065
 Room 134 Sink #2 6:35:00 AM

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	5.69	1.00 µg/L	9/24/2021 VD	9/27/2021 VD 12:29

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>EnvChemistry2@emsl.com

EMSL Order: 012109969

CustomerID: WCSD21A

CustomerPO: 20-04919

ProjectID:

Attn: **Keith Langlotz**
Williamsville CSD - Facilities Dept
480 Lawrence Bell Dr.
Williamsville, NY 14221

Phone: (716) 626-8860
 Fax:
 Received: 8/27/2021 10:00 AM

Project: **Lead in Water Testing 2021****Analytical Results**

Client Sample Description		SH-302 Room E-6 Sink	Collected:	8/21/2021 6:47:00 AM	Lab ID:	012109969-0066	
Method	Parameter	Result	RL Units	Prep Date & Analyst		Analysis Date & Analyst	
METALS							
200.8	Lead	5.46	1.00 µg/L	9/24/2021	VD	9/27/2021 12:30	VD
Client Sample Description		SH-303 Room 129 P Dark Room Sink	Collected:	8/21/2021 6:53:00 AM	Lab ID:	012109969-0067	
Method	Parameter	Result	RL Units	Prep Date & Analyst		Analysis Date & Analyst	
METALS							
200.8	Lead	15.1	1.00 µg/L	9/24/2021	VD	9/27/2021 12:32	VD
Client Sample Description		SH-304 Room 129 D Sink #1	Collected:	8/21/2021 6:55:00 AM	Lab ID:	012109969-0068	
Method	Parameter	Result	RL Units	Prep Date & Analyst		Analysis Date & Analyst	
METALS							
200.8	Lead	61.2	1.00 µg/L	9/24/2021	VD	9/27/2021 12:36	VD
Client Sample Description		SH-305 Room 129 D Sink #2	Collected:	8/21/2021 6:55:00 AM	Lab ID:	012109969-0069	
Method	Parameter	Result	RL Units	Prep Date & Analyst		Analysis Date & Analyst	
METALS							
200.8	Lead	14.8	1.00 µg/L	9/24/2021	VD	9/27/2021 12:38	VD
Client Sample Description		SH-306 Room 129 D Sink #3	Collected:	8/21/2021 6:55:00 AM	Lab ID:	012109969-0070	
Method	Parameter	Result	RL Units	Prep Date & Analyst		Analysis Date & Analyst	
METALS							
200.8	Lead	20.7	1.00 µg/L	9/24/2021	VD	9/27/2021 12:39	VD

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>EnvChemistry2@emsl.com

EMSL Order: 012109969
 CustomerID: WCSD21A
 CustomerPO: 20-04919
 ProjectID:

Attn: **Keith Langlotz**
Williamsville CSD - Facilities Dept
480 Lawrence Bell Dr.
Williamsville, NY 14221

Phone: (716) 626-8860
 Fax:
 Received: 8/27/2021 10:00 AM

Project: **Lead in Water Testing 2021****Analytical Results**

Client Sample Description SH-307 **Collected:** 8/21/2021 **Lab ID:** 012109969-0071
 Room 129 D Sink #4 6:55:00 AM

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	134 D	5.00 µg/L	9/24/2021 VD	9/27/2021 VD 13:04

Client Sample Description MM-317 **Collected:** 8/25/2021 **Lab ID:** 012109969-0072
 Room C-11 Sink 6:13:00 AM

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	44.8	1.00 µg/L	9/24/2021 VD	9/27/2021 VD 13:06

Client Sample Description MM-318 **Collected:** 8/25/2021 **Lab ID:** 012109969-0073
 Room C-10 Sink 6:12:00 AM

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	29.0	1.00 µg/L	9/24/2021 VD	9/27/2021 VD 12:47

Client Sample Description MM-319 **Collected:** 8/25/2021 **Lab ID:** 012109969-0074
 Room C-13 Sink 6:10:00 AM

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	49.0	1.00 µg/L	9/24/2021 VD	9/27/2021 VD 12:48

Definitions:

MDL - method detection limit

J - Result was below the reporting limit, but at or above the MDL

ND - indicates that the analyte was not detected at the reporting limit

RL - Reporting Limit (Analytical)

D - Dilution Sample required a dilution which was used to calculate final results

Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Forest									
	Location	38 Bathroom Sink # 1	36 Classroom Sink	20 Classroom Sink # 3	19 Classroom Sink	12 Classroom Sink	9 Bathroom Sink	1 Classroom Sink	Library Offcie Sink
	Test results	98.10	16.80	20.50	15.10	21.60	15.60	138.00	140.00
	Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing
	Results	29.80	22.10	3.66	16.70	20.80	18.10	2.42	6.85
	Back in use			9/29/2021				9/29/2021	9/29/2021
	Location								
	Test results								
	Remediation								
	Results								
	Back in use								

Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occuring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Heim middle								
	Location	Room D6 Sink # 1	Boys Locker Room Sink # 1	Room C-13 Eye Wash	Room C-11 Eyewash	Room A-11 Eyewash	Womens Lav by Aud Sink # 2	Wet by Steamer in Kitchen
	Test results	28.8	16.7	51.7	93.9	232	19	119
	Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing
	Test results	48.9						
	Back in svc.		9/29/2021	9/29/2021	9/29/2021	9/29/2021	9/29/2021	
	Location							
	Test results							
	Remediation							
	Back in svc.							
	Location							
	Test results							
	Remediation							
	Results							
	Back in svc.							
	Location							
	Test results							
	Remediation							
	Results							
	Back in svc.							
	Location							
	Test results							
	Remediation							
	Back in svc.							
	Location							
	Test results							
	Remediation							
	Back in svc.							
	Location							

Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Heim								
Location	Room 142 Sink	Room 146 Sink						
Test results	16.60	16.80						
Remediation	Flushing	Flushing						
Results	12.90	43.30						
Results 2								
Back in use	9/29/2021							
Location								
Test results								
Remediation								
Results								
Results								
Results								
Back in use								

Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occuring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Maple East								
	Location	Boiler Room Sample	Boiler Room Eyewash	Girl's ShBathroom Sink	42 Classroom Sink	29 Classroom Sink # 3	22 Classroom Sink	Library Office Sink
	Test results	18.10	47.40	1220.00	16.20	52.30	17.30	22.30
	Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing
	Results	12.10	1.99	3.55	10.90	14.90	9.70	2.78
	Back in use	9/29/2021	9/29/2021	9/29/2021	9/29/2021	9/29/2021	9/29/2021	9/29/2021
	Location							
	Test results							
	Remediation							
	Results							
	Results							
	Back in use							

Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Maple West									
	Location	109 Classroom Sink # 1	Library Office Sink	102 Classroom Sink	Boiler Room Eyewash	Boiler Room Sample	102 Classroom Sink # 2	101 Classroom Sink # 2	Kitchen Pot Filler
	Test results	15.40	18.10	16.20	200.00	15.80	22.40	76.00	28.30
	Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing
	Results	14.70	18.90	17.30	67.80	43.60	16.70	16.10	5.65
	Test results								
	Back in use	9/29/2021							9/29/2021
	Location								
	Test results								
	Remediation								
	Results								
	Results								
	Back in use								

Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Mill middle	Location	Principals Offcie Lav Sink	Storage Room by AP Sink	Clinic Bathroom Sink	Room A-1 Sink	Room A-6 Sink	Room A-8 Sink	Girls Lav by Room A-11 Sink	Room A-11 Sink
	Test results	30.3	202	26.4	36.2	40.2	56.8	22.3	48.4
	Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing
	Test results	6.03	12.8	176	43.3	39.7	56.7	6.17	50.6
	Back in svc.	9/29/2021	9/29/2021					9/29/2021	
	Location	Room A-10 Sink	Room A-13 Sink	apped Lav by Library Sink	Room B-6 Sink	Storage Room by AP Sink # 2	Boys Lav by A-11 Sink #1	allway Fountain by A-11 #1	Girls Lav by A-11 Sink # 1
	Test results	46.2	27.9	26.1	18.1	28	49.2	42.3	19.5
	Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing
	Test results	49.3	29	28.9	30.2	12.8	8.53	ND	4.41
	Back in svc.					9/29/2021	9/29/2021	9/29/2021	9/29/2021
	Location	m A-11 Classroom Sink # 2	m A-11 Classroom Sink # 2	Room C-11 Sink	Room C-10 Sink	Room C-13 Sink	Room E-3 Storage Sink	Room E-5 Sink # 3	Room E-2 Sink # 1
	Test results	36.8	53	63.9	41.4	56.4	19.1	17.8	19.3
	Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing
	Test results	48.3	48.3	44.8	29	49	22.4	8.33	16.5
	Back in svc.							9/29/2021	
	Location	Room E-2 Sink # 2	Room E-2 Sink # 3	Room E-2 Sink # 4	Room E-4 Sink	Room E-7 Sink # 1	Room E-7 Sink # 2	Boys Locker Room Sink	Girls Locker Room Sink # 2
	Test results	53.5	20	34.3	17.9	45.9	19.4	16.1	40.5
	Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing
	Test results	15.4	29.2		18.1	29.3		18.4	21.7
	Back in svc.			9/29/2021			9/29/2021		
	Location	Girls Locker Room Sink # 3	Basement Storage Sink # 1						
	Test results	15.7	15.7						
	Remediation	Flushing	Flushing						
	Test results	25.1	9.55						
	Back in svc.		9/29/2021						
	Location								
	Test results								
	Remediation								
	Back in svc.								

Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

North high									
	Location	Boiler Room Source	Conference Room Sink # 1	itchen Dish room Sink # 2	mens Lav by C-108 Sink # 3	Room C-108 Sink # 1	Room C-108 Sink # 2	Room C-105 Sink # 1	Room C-152 Sink # 1
	Test results	23.5	21.3	21.9	21.4	24.6	17.1	53.6	19.2
	Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing
	Results	ND	2.86	11.5	10.8	26.9	18.4	4.87	5.01
	Back in use	9/29/2021	9/29/2021	9/29/2021	9/29/2021			9/29/2021	9/29/2021
	Location	Room C-162 Sink # 2	Mens Lav by C-130 Sink # 1	Mens Lav by C-130 Sink # 2	Mens Lav by C-130 Sink # 3	1st Floor Coaches Office Sink	Pump Room Eye Wash		
Test results	92.2	28	16.2	15.7	305	30.4			
Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing			
Test results							23.2		
Back in use					9/29/2021				
Location									
Test results									
Remediation									
Back in use									
Location									
Test results									
Remediation									
Results									
Back in use									
Location									
Test results									
Remediation									
Back in use									

Williamsville Central School District
New York State Public School District
Water Testing for Lead

School	Number of Samples Tested (1)	Number of Samples Not Addressed	Location of Samples Tested above 15ppb (2)										Received All Results Yes - No	Number of Samples Taken on 1st Retest		Number of Samples Above 15 ppb on 1st Re-Test
			Hallway Drinking Fountains	Student Lavatories	Classroom Faucets	Classroom Fountains	Student-staff Showers/ Locker rooms	Office Sinks	Staff Lavatories	Custodial Outlets	Child Nutrition Faucets	Outdoor Faucets				
Country Parkway	81	0	0	0	13	0	0	1	1	0	0	0	Yes	15	15	4
Dodge	91	0	0	2	0	0	0	0	0	2	0	0	Yes	4	4	2
Forest	93	0	0	2	5	0	0	1	0	0	0	0	Yes	8	8	5
Heim	78	0	0	0	2	0	0	0	0	0	0	0	Yes	2	2	1
Maple East	96	0	0	0	3	0	1	1	0	2	0	0	Yes	7	7	0
Maple West	82	0	0	0	4	0	0	1	0	2	1	0	Yes	8	8	6
Casey middle	94	0	0	0	4	0	0	1	1	1	0	0	Yes	7	7	6
Heim middle	83	0	0	1	3	0	1	0	1	1	1	0	Yes	8	8	3
Mill middle	98	0	1	8	20	0	0	3	1	1	0	0	Yes	34	30	21
Transit middle	118	0	0	0	21	0	1	0	0	1	0	0	Yes	23	1	0
East high	101	0	0	0	14	0	1	1	2	1	2	0	Yes	21	21	4
North high	121	0	0	0	3	0	0	2	6	2	1	0	Yes	14	14	7
South high	110	0	0	0	8	0	1	0	0	0	0	0	Yes	9	8	5
AIM building	5	0	0	0	0	0	0	0	0	0	0	0	Yes	0	0	0
Transportation	12	0	0	0	0	0	0	0	1	0	0	0	Yes	1	0	0
Lawrence Bell Dr.	16	0	0	0	0	0	0	0	0	0	0	0	Yes	0	0	0
District office	12	0	0	0	0	0	0	0	0	0	0	0	Yes	0	0	0
Total Samples	1291	0	1	13	100	0	5	11	13	13	5	0		161	133	64
												161				

- (1) New York State water testing parameters for lead require all water outlets to be tested after water has been stagnant in the water pipes and faucets for a minimum of eight hours. Flushing water through the water outlet is not permitted per the test.
- (2) A failed test results in immediate remediation efforts by the District. The water supply is turned off and the most common repair is to replace the fixture and retest the water from the location.
- (3) The District utilized apprved NYS remediation included replacement of fixtures, additional testing, signage indicating that the outlet is not to be used for drinking water and in certain situations, removal from service.

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

South high									
	Location	Room 134 Sink # 1	Room 134 Sink # 2	Room E-6 Sink	om 129 P Dark Room Sink	Room 129 D Sink # 1	Room 129 D Sink # 2	Room 129 D Sink # 3	Room 129 D Sink # 4
	Test results	23.5	31.3	18.6	15.8	59.4	16.1	16.8	34
	Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing
	Test results	57.4	5.69	5.46	15.1	61.2	14.8	20.7	134
	Back in use		9/29/2021	9/29/2021			9/29/2021		
	Location	v Coaches Girls Off Shower							
	Test results	193							
Remediation	Shower, non-potable								
Test results	8/30/2021								
Back in use									
Location									
Test results									
Remediation									
Back in use									
Location									
Test results									
Remediation									
Back in use									
Location									
Test results									
Remediation									
Back in use									
Location									
Test results									
Remediation									
Back in use									

Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occuring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Transit middle Location Test results Test results Remediation Back in svc.								
	Room B229 Sink #6	Room B229 Sink # 7	Room B227 Sink # 1	Room B227 Sink # 2	Room A212 Sink # 1	Room A212 Sink # 2	Room A212 Sink # 3	Room A214 Sink # 1
	19.2	76.4	18.1	73.2	21.6	29.3	46.7	79.7
	Science Room	Science Room	Science Room	Science Room	Science Room	Science Room	Science Room	Science Room
	8/30/2021	8/30/2021	8/30/2021	8/30/2021	8/30/2021	8/30/2021	8/30/2021	8/30/2021
Location Test results Remediation Back in svc.								
	Room A214 Sink # 2	Room A214 Sink # 3	Room A214 Sink # 4	Room A214 Sink # 5	Room A214 Sink # 6	Room A214 Sink # 7	Room A214 Sink # 8	Room A214 Sink # 9
	47.9	78.4	56.3	47.5	33.4	44.8	43.1	29.4
	Science Room	Science Room	Science Room	Science Room	Science Room	Science Room	Science Room	Science Room
	8/30/2021	8/30/2021	8/30/2021	8/30/2021	8/30/2021	8/30/2021	8/30/2021	8/30/2021
Location Test results Remediation Test results Back in svc.	Room A 214 Sink # 11	Boiler Room Sample	er Room Coaches Shower	Room B123 Sink # 1	Room B123 Sink # 3	Room B123 Sink # 4	Room B123 Sink # 5	
	63.5	39.9	69.4	15.5	25.2	17.6	168	
	Science Room	Flushing	Science Room	Science Room	Science Room	Science Room	Science Room	Science Room
		ND						
	8/30/2021	9/29/2021	8/30/2021	8/30/2021	8/30/2021	8/30/2021	8/30/2021	8/30/2021
Location Test results Remediation Back in svc.								
Location Test results Remediation Back in svc.								
Location Test results Remediation Back in svc.								
Location Test results Remediation Back in svc.								

Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Country Parkway								
Location	101 Classroom Sink # 1	102 Classroom Sink #1	107 Classroom Sink	108 Classroom Sink	110 Classroom Sink	Speech Office Sink	116 Classroom Sink	117 Classroom Sink
Results	18.10	25.60	18.20	19.40	25.00	19.60	16.00	29.00
Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing
Results	4.12	5.51	6.26	7.89	4.6	8.57	18.4	35.8
Results								
Results								
Back in use	9/29/2021	9/29/2021	9/29/2021	9/29/2021	9/29/2021	9/29/2021		
Location	121 Classroom Sink	123 Classroom Sink	122 Classroom Sink	124 Classroom Sink	125 Classroom Sink	127 Classroom Sink	12 Kitchen Bathroom Sink	
Results	19.70	18.90	24.60	15.60	20.00	15.50	35.90	
Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	
Results	12.4	9.01	13.8	12.7	23.2	14.8	20.4	
Back in use						9/29/2021		
Back in use								

Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Dodge Location Results Remediation Results Back in use Location Results Remediation Results Back in use								
	105 Bathroom Sink	144 Bathroom Sink	Basement Source	Basement Sink				
	18.10	18.50	42.70	43.50				
	Flushing	Flushing	Flushing	Flushing				
	19.80	27.40	12.30	3.25				
			9/29/2021	9/29/2021				

Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Forest									
	Location	38 Bathroom Sink # 1	36 Classroom Sink	20 Classroom Sink # 3	19 Classroom Sink	12 Classroom Sink	9 Bathroom Sink	1 Classroom Sink	Library Offcie Sink
	Test results	98.10	16.80	20.50	15.10	21.60	15.60	138.00	140.00
	Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing
	Results	29.80	22.10	3.66	16.70	20.80	18.10	2.42	6.85
	Back in use			9/29/2021				9/29/2021	9/29/2021
	Location								
	Test results								
	Remediation								
	Results								
	Back in use								

Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Heim								
Location	Room 142 Sink	Room 146 Sink						
Test results	16.60	16.80						
Remediation	Flushing	Flushing						
Results	12.90	43.30						
Results 2								
Back in use	9/29/2021							
Location								
Test results								
Remediation								
Results								
Results								
Results								
Back in use								

Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occuring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Maple East								
	Location	Boiler Room Sample	Boiler Room Eyewash	Girl's ShBathroom Sink	42 Classroom Sink	29 Classroom Sink # 3	22 Classroom Sink	Library Office Sink
	Test results	18.10	47.40	1220.00	16.20	52.30	17.30	22.30
	Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing
	Results	12.10	1.99	3.55	10.90	14.90	9.70	2.78
	Back in use	9/29/2021	9/29/2021	9/29/2021	9/29/2021	9/29/2021	9/29/2021	9/29/2021
	Location							
	Test results							
	Remediation							
	Results							
	Results							
	Back in use							

Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Maple West									
	Location	109 Classroom Sink # 1	Library Office Sink	102 Classroom Sink	Boiler Room Eyewash	Boiler Room Sample	102 Classroom Sink # 2	101 Classroom Sink # 2	Kitchen Pot Filler
	Test results	15.40	18.10	16.20	200.00	15.80	22.40	76.00	28.30
	Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing
	Results	14.70	18.90	17.30	67.80	43.60	16.70	16.10	5.65
	Test results								
	Back in use	9/29/2021							9/29/2021
	Location								
	Test results								
	Remediation								
	Results								
	Results								
	Back in use								

Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Casey middle								
	Room 114 Sink	Room 129 Sink	Room 132 Sink # 2	Room 132 Sink # 5	Stage Sink	Room 139 Sink # 1	Faculty Bathroom Sink # 1	Mezzanine Sink
Location	Room 114 Sink	Room 129 Sink	Room 132 Sink # 2	Room 132 Sink # 5	Stage Sink	Room 139 Sink # 1	Faculty Bathroom Sink # 1	Mezzanine Sink
Test results	22.2	20.5	15.6	17.8	96.8	21.3	37.8	65.6
Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing
Test results	20.00	20.80	13.10	18.00	29.00	24.4	7.42	34.80
Back in use			9/29/2021				9/29/2021	
Location								
Test results								
Remediation								
Results								
Back in use								
Location								
Test results								
Remediation								
Back in use								
Location								
Test results								
Remediation								
Back in use								

Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Heim middle								
Location	Room D6 Sink # 1	Boys Locker Room Sink # 1	Room C-13 Eye Wash	Room C-11 Eyewash	Room A-11 Eyewash	Womens Lav by Aud Sink # 2	Wet by Steamer in Kitchen	Boiler Room Eye Wash
Test results	28.8	16.7	51.7	93.9	232	19	119	46.9
Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing
Test results	48.9						69.2	29.7
Back in svc.		9/29/2021	9/29/2021	9/29/2021	9/29/2021	9/29/2021		
Location								
Test results								
Remediation								
Back in svc.								
Location								
Test results								
Remediation								
Results								
Back in svc.								
Location								
Test results								
Remediation								
Back in svc.								
Location								
Test results								
Remediation								
Back in svc.								

Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Mill middle	Location	Principals Offcie Lav Sink	Storage Room by AP Sink	Clinic Bathroom Sink	Room A-1 Sink	Room A-6 Sink	Room A-8 Sink	Girls Lav by Room A-11 Sink	Room A-11 Sink
	Test results	30.3	202	26.4	36.2	40.2	56.8	22.3	48.4
	Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing
	Test results	6.03	12.8	176	43.3	39.7	56.7	6.17	50.6
	Back in svc.	9/29/2021	9/29/2021					9/29/2021	
	Location	Room A-10 Sink	Room A-13 Sink	apped Lav by Library Sink	Room B-6 Sink	Storage Room by AP Sink # 2	Boys Lav by A-11 Sink #1	allway Fountain by A-11 #1	Girls Lav by A-11 Sink # 1
	Test results	46.2	27.9	26.1	18.1	28	49.2	42.3	19.5
	Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing
	Test results	49.3	29	28.9	30.2	12.8	8.53	ND	4.41
	Back in svc.					9/29/2021	9/29/2021	9/29/2021	9/29/2021
	Location	m A-11 Classroom Sink # 2	m A-11 Classroom Sink # 2	Room C-11 Sink	Room C-10 Sink	Room C-13 Sink	Room E-3 Storage Sink	Room E-5 Sink # 3	Room E-2 Sink # 1
	Test results	36.8	53	63.9	41.4	56.4	19.1	17.8	19.3
	Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing
	Test results	48.3	48.3	44.8	29	49	22.4	8.33	16.5
	Back in svc.							9/29/2021	
	Location	Room E-2 Sink # 2	Room E-2 Sink # 3	Room E-2 Sink # 4	Room E-4 Sink	Room E-7 Sink # 1	Room E-7 Sink # 2	Boys Locker Room Sink	Girls Locker Room Sink # 2
	Test results	53.5	20	34.3	17.9	45.9	19.4	16.1	40.5
	Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing
	Test results	15.4	29.2		18.1	29.3		18.4	21.7
	Back in svc.			9/29/2021			9/29/2021		
	Location	Girls Locker Room Sink # 3	Basement Storage Sink # 1						
	Test results	15.7	15.7						
	Remediation	Flushing	Flushing						
	Test results	25.1	9.55						
	Back in svc.		9/29/2021						
	Location								
	Test results								
	Remediation								
	Back in svc.								

Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Mill middle								
Location								
Test results								
Remediation								
Test results								
Test results								
Back in svc.								
Location								
Test results								
Remediation								
Test results								
Test results								
Back in svc.								
Location								
Test results								
Remediation								
Back in svc.								
Location								
Test results								
Remediation								
Test results								
Test results								
Test results								
Back in svc.								
Location								
Test results								
Remediation								
Back in svc.								

Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Transit middle								
Location	Room B229 Sink #6	Room B229 Sink # 7	Room B227 Sink # 1	Room B227 Sink # 2	Room A212 Sink # 1	Room A212 Sink # 2	Room A212 Sink # 3	Room A214 Sink # 1
Test results	19.2	76.4	18.1	73.2	21.6	29.3	46.7	79.7
Test results								
Remediation	Science Room	Science Room	Science Room	Science Room	Science Room	Science Room	Science Room	Science Room
Back in svc.	8/30/2021	8/30/2021	8/30/2021	8/30/2021	8/30/2021	8/30/2021	8/30/2021	8/30/2021
Location	Room A214 Sink # 2	Room A214 Sink # 3	Room A214 Sink # 4	Room A214 Sink # 5	Room A214 Sink # 6	Room A214 Sink # 7	Room A214 Sink # 8	Room A214 Sink # 9
Test results	47.9	78.4	56.3	47.5	33.4	44.8	43.1	29.4
Remediation	Science Room	Science Room	Science Room	Science Room	Science Room	Science Room	Science Room	Science Room
Back in svc.	8/30/2021	8/30/2021	8/30/2021	8/30/2021	8/30/2021	8/30/2021	8/30/2021	8/30/2021
Location	Room A 214 Sink # 11	Boiler Room Sample	er Room Coaches Shower	Room B123 Sink # 1	Room B123 Sink # 3	Room B123 Sink # 4	Room B123 Sink # 5	
Test results	63.5	39.9	69.4	15.5	25.2	17.6	168	
Remediation	Science Room	Flushing	Science Room	Science Room	Science Room	Science Room	Science Room	Science Room
Test results		ND						
Back in svc.	8/30/2021	9/29/2021	8/30/2021	8/30/2021	8/30/2021	8/30/2021	8/30/2021	8/30/2021
Location								
Test results								
Remediation								
Back in svc.								
Location								
Test results								
Remediation								
Back in svc.								
Location								
Test results								
Remediation								
Back in svc.								
Location								
Test results								
Remediation								
Back in svc.								

Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

East high	Location	Pool Room Eye Wash	Kitchen Sink # 5	Kitchen Sink # 8	Room 102 Sink #1	Room 103 Sink # 4	Kiln Room Sink	Room 117 Sink # 4	Room 117 Sink # 6
	Test results	2080	20.2	27.5	18.6	20.4	30.4	52.6	97.2
	Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing
	Test results	133	3.68	3.9	3.76	3.52	3.03	2.52	4.21
	Back in svc.		9/29/2021	9/29/2021	9/29/2021	9/29/2021	9/29/2021	9/29/2021	9/29/2021
	Location	Room 117 Sink #7	Room 117 Sink # 8	Room 119 Sink # 1	Room 119 Sink # 2	Room 119 Sink # 3	Room 119 Sink # 4	Room 119 Sink # 5	Room 113 Sink
	Test results	101	44.9	32.6	23	71.2	50.4	15.4	38.3
	Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing
	Test results	6.99	ND	8.07	1.99	3.19	3.79	2.29	2.26
	Back in svc.	9/29/2021	9/29/2021	9/29/2021	9/29/2021	9/29/2021	9/29/2021	9/29/2021	9/29/2021
	Location	Mens Lav by Aud Sink	Health Office Sink # 1	Coaches Office Lav Sink	Boys Red locker Room Sink	Kiln Room Sink # 2			
	Test results	29.2	21.8	21.2	19.2	30.4			
	Remediation	Flushing	Flushing	Flushing	Flushing	Flushing			
	Test results	88	14.6	236	20.3	2.77			
	Back in svc.		9/29/2021			9/29/2021			
	Location								
	Test results								
	Remediation								
	Test results								
	Back in svc.								
	Location								
	Test results								
	Test results								
	Test results								
	Remediation								
	Back in svc.								

Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

<u>East high</u>								
Location								
Test results								
Test results								
Test results								
Remediation								
Back in svc.								
Location								
Test results								
Remediation								
Back in svc.								
Location								
Test results								
Remediation								
Back in svc.								
Location								
Test results								
Remediation								
Back in svc.								
Location								
Test results								
Remediation								
Back in svc.								
Location								
Test results								
Test results								
Remediation								
Back in svc.								

Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

<u>East high</u>								
Location								
Test results								
Test results								
Remediation								
Back in svc.								
Location								
Test results								
Remediation								
Back in svc.								

Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occuring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

North high									
	Location	Boiler Room Source	Conference Room Sink # 1	itchen Dish room Sink # 2	mens Lav by C-108 Sink # 3	Room C-108 Sink # 1	Room C-108 Sink # 2	Room C-105 Sink # 1	Room C-152 Sink # 1
	Test results	23.5	21.3	21.9	21.4	24.6	17.1	53.6	19.2
	Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing
	Results	ND	2.86	11.5	10.8	26.9	18.4	4.87	5.01
	Back in use	9/29/2021	9/29/2021	9/29/2021	9/29/2021			9/29/2021	9/29/2021
	Location	Room C-162 Sink # 2	Mens Lav by C-130 Sink # 1	Mens Lav by C-130 Sink # 2	Mens Lav by C-130 Sink # 3	1st Floor Coaches Office Sink	Pump Room Eye Wash		
Test results	92.2	28	16.2	15.7	305	30.4			
Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing			
Test results							23.2		
Back in use					9/29/2021				
Location									
Test results									
Remediation									
Back in use									
Location									
Test results									
Remediation									
Results									
Back in use									
Location									
Test results									
Remediation									
Back in use									

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

South high									
	Location	Room 134 Sink # 1	Room 134 Sink # 2	Room E-6 Sink	om 129 P Dark Room Sink	Room 129 D Sink # 1	Room 129 D Sink # 2	Room 129 D Sink # 3	Room 129 D Sink # 4
	Test results	23.5	31.3	18.6	15.8	59.4	16.1	16.8	34
	Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing
	Test results	57.4	5.69	5.46	15.1	61.2	14.8	20.7	134
	Back in use		9/29/2021	9/29/2021			9/29/2021		
	Location	v Coaches Girls Off Shower							
	Test results	193							
Remediation	Shower, non-potable								
Test results	8/30/2021								
Back in use									
Location									
Test results									
Remediation									
Back in use									
Location									
Test results									
Remediation									
Back in use									
Location									
Test results									
Remediation									
Back in use									
Location									
Test results									
Remediation									
Back in use									

Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

South high								
	Location							
	Test results							
	Remediation							
	Back in use							
	Location							
	Test results							
	Remediation							
	Back in use							
	Location							
	Test results							
	Remediation							
	Back in service							
	Location							
	Test results							
	Remediation							
	Back in use							
	Location							
	Test results							
	Remediation							
	Back in service							
	Location							
	Test results							
	Remediation							
	Back in use							
	Location							
	Test results							
	Remediation							
	Back in use							

Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Transporation								
Location	mens Staff Room Skink # 2							
Test results	17.1							
Remediation								
Test results								
Back in use								
Location								
Test results								
Remediation								
Back in use								
AIM building								
Location								
Test results								
Remediation								
Back in use								

Hose bib: A hose bib is a faucet that is used to connect a hose for cleaning purposes. These faucets are not meant for use as a source of drinking water.