

**Hendrick Hudson School District - Elementary Schools Flush Water Samples**  
**Buchanan-Verplanck Elementary School**

<b>Buchanan-Verplanck Elementary School</b>				
Sample #	Location	1 <sup>st</sup> Draw (ppb)	Flush Draw (ppb)	Immediate Remediation Plan
BV-01	Kitchen sink hall	84.4	83.1	Signage – Not Drinking Water
BV-09	Kitchen sink by café	20.2	20.7	Signage – Not Drinking Water
BV-10	Kitchen sink by serving line	25.6	26.9	Signage – Not Drinking Water
BV-18	Gym office sink	26.4	8.2	Signage – Not Drinking Water
BV-19	Gym office shower	216.0	14.9	Signage – Not Drinking Water
BV-22	Outside water fountain by playground	132.0	18.4	Taken out of service
BV-25	Nurse office sink (2)	177.0	395	To be removed permanently
BV-47	Classroom 20 Bubbler	20.6	<1.0	Taken out of service
BV-48	Classroom 20 Sink	17.9	1.5	Signage – Not Drinking Water
BV-49	Classroom 21 Bubbler	24.1	3.2	Taken out of service
BV-51	Classroom 22 Bubbler	71.2	1.0	Taken out of service
BV-52	Classroom 22 Sink	191	2.5	Signage – Not Drinking Water
BV-54	Service (server) Closet Sink	707	N/A	To be removed permanently
BV-62	Classroom 4 Sink	31.5	2.3	Signage – Not Drinking Water

## Hendrick Hudson School District - Elementary Schools Flush Water Samples

### Frank G. Lindsey Elementary School

Frank G. Lindsey Elementary School				
Sample #	Location	1 <sup>st</sup> Draw (ppb)	Flush Draw (ppb)	Immediate Remediation Plan
FGL-17	Classroom 16 Sink	76.4	<1.0	Signage – Not Drinking Water
FGL-41	Copy Room Sink	37.9	50.5	Signage – Not Drinking Water
FGL-43	Nurse Office Bathroom Sink	21.1	1.2	Signage – Not Drinking Water
FGL-52	Room SW 1 Sink	83.6	5.0	Signage – Not Drinking Water
FGL-53	Classroom 1 Sink	162	31.2	Signage – Not Drinking Water
FGL-55	Classroom 1 Sink RT	15.7	<1.0	Signage – Not Drinking Water
FGL-57	SP 1 Custodian Sink	28.8	<1.0	Signage – Not Drinking Water
FGL-60	Classroom 2 Sink RT	700	1.4	Signage – Not Drinking Water
FGL-61	Classroom 2 Fountain	18.0	N/A	Taken out of service
FGL-62	Classroom 2 Sink	21.3	<1.0	Signage – Not Drinking Water
FGL-64	Classroom 6 Sink	24.8	<1.0	Signage – Not Drinking Water
FGL-66	Classroom 7 Sink	616	<1.0	Signage – Not Drinking Water
FGL-75	Classroom 4 Sink	29.2	3.2	Signage – Not Drinking Water
FGL-81	Classroom 5 Fountain	17.1	N/A	Taken out of service
FGL-97	Library Sink	31.0	<1.0	Signage – Not Drinking Water
FGL-100	Hose Bib Hot Box	2020	21.3	Taken out of service
FGL-101	Hose Bib Trolley Road	34.5	<1.0	Signage – Not Drinking Water

## Hendrick Hudson School District - Elementary Schools Flush Water Samples

### Furnace Woods Elementary School

Furnace Woods Elementary School				
Sample #	Location	1 <sup>st</sup> Draw (ppb)	2 <sup>nd</sup> Draw (ppb)	Immediate Remediation Plan
FW-04	Gym Bathroom Sink	27.6	1.3	Signage – Not Drinking Water
FW-09	Kitchen Sink	23.1	6.3	Signage – Not Drinking Water
FW-10	Kitchen Bathroom Sink	27.3	1.7	Signage – Not Drinking Water
FW-20	Women's Room Sink Right	30.6	14.4	Signage – Not Drinking Water
FW-23	Classroom 20 Bubbler	17.4	1.3	Signage – Not Drinking Water
FW-27	Classroom 21 Sink	23.3	<1.0	Signage – Not Drinking Water
FW-28	Classroom 21 Bubbler	15.5	3.8	Signage – Not Drinking Water
FW-44	Classroom 1 Bubbler	43.2	N/A	Taken out of service
FW-46	Classroom 1 Bathroom Sink	1080	76.8	Signage – Not Drinking Water
FW-52	Classroom 3 Bathroom Sink	1270	N/A	Taken out of service
FW-53	Classroom 4 Sink	62.2	<1.0	Signage – Not Drinking Water
FW-55	Library Sink	29.7	13.3	Signage – Not Drinking Water
FW-62	Main Office Bathroom	65.0	332	Signage – Not Drinking Water
FW-71	Classroom 9 Sink	41.4	2.4	Signage – Not Drinking Water
FW-81	Outside Sink LT (1)	469	4.3	Signage – Not Drinking Water
FW-82	Outside Sink Middle (2)	156	4.5	Signage – Not Drinking Water
FW-83	Outside Sink Middle (3)	90.9	71.2	Signage – Not Drinking Water
FW-84	Outside Sink RT (4)	109	48.9	Signage – Not Drinking Water
FW-85	Outside Hose Bib Loading Dock	460	<1.0	Signage – Not Drinking Water