

Radon test result report for:  
**BUTTERNUT CREEK**  
**MAIN**

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
9119739	CAFETERIA 1	2018-10-23 @ 12:00 pm	2018-10-26 @ 12:00 pm	< 0.3	2018-10-29
9119738	CAFETERIA 2	2018-10-23 @ 12:00 pm	2018-10-26 @ 12:00 pm	0.5 ± 0.2	2018-10-29
9119749	CUSTODIAN 10A	2018-10-23 @ 12:00 pm	2018-10-26 @ 12:00 pm	0.6 ± 0.3	2018-10-29
9119388	GYM OFFICE	2018-10-23 @ 12:00 pm	2018-10-26 @ 12:00 pm	< 0.3	2018-10-29
9119743	HEALTH ROOM	2018-10-23 @ 12:00 pm	2018-10-26 @ 12:00 pm	0.7 ± 0.3	2018-10-29
9119745	LIBR. OFFICE DUP	2018-10-23 @ 12:00 pm	2018-10-26 @ 12:00 pm	0.7 ± 0.3	2018-10-29
9119740	LIBR. WORK ROOM	2018-10-23 @ 12:00 pm	2018-10-26 @ 12:00 pm	0.5 ± 0.3	2018-10-29
9119742	LIBRARY 1	2018-10-23 @ 12:00 pm	2018-10-26 @ 12:00 pm	< 0.3	2018-10-29
9119741	LIBRARY 2	2018-10-23 @ 12:00 pm	2018-10-26 @ 12:00 pm	0.6 ± 0.3	2018-10-29
9119734	LIBRARY OFFICE	2018-10-23 @ 12:00 pm	2018-10-26 @ 12:00 pm	0.6 ± 0.3	2018-10-29
9119736	MAIN OFFICE	2018-10-23 @ 12:00 pm	2018-10-26 @ 12:00 pm	< 0.3	2018-10-29
9119756	MUSIC	2018-10-23 @ 1:00 pm	2018-10-26 @ 12:00 pm	0.8 ± 0.3	2018-10-29
9119755	MUSIC DUP	2018-10-23 @ 1:00 pm	2018-10-26 @ 12:00 pm	< 0.3	2018-10-29
9119771	PORT 1	2018-10-23 @ 1:00 pm	2018-10-26 @ 12:00 pm	< 0.3	2018-10-29
9119772	PORT 1 BLANK	2018-10-23 @ 1:00 pm	2018-10-26 @ 12:00 pm	< 0.3	2018-10-29
9119764	PORT 2	2018-10-23 @ 1:00 pm	2018-10-26 @ 12:00 pm	< 0.3	2018-10-29
9119766	PORT 2 DUP	2018-10-23 @ 1:00 pm	2018-10-26 @ 12:00 pm	< 0.3	2018-10-29
9119735	PRINCIPAL OFFICE	2018-10-23 @ 12:00 pm	2018-10-26 @ 12:00 pm	0.6 ± 0.3	2018-10-29
9119747	ROOM 1	2018-10-23 @ 1:00 pm	2018-10-26 @ 12:00 pm	< 0.3	2018-10-29
9119716	ROOM 10	2018-10-23 @ 12:00 pm	2018-10-26 @ 12:00 pm	0.7 ± 0.3	2018-10-29
9119757	ROOM 11	2018-10-23 @ 1:00 pm	2018-10-26 @ 12:00 pm	0.6 ± 0.3	2018-10-29
9119758	ROOM 12	2018-10-23 @ 1:00 pm	2018-10-26 @ 12:00 pm	0.5 ± 0.2	2018-10-29
9119761	ROOM 13	2018-10-23 @ 1:00 pm	2018-10-26 @ 12:00 pm	0.5 ± 0.3	2018-10-29
9119767	ROOM 14	2018-10-23 @ 1:00 pm	2018-10-26 @ 12:00 pm	0.7 ± 0.3	2018-10-29
9119763	ROOM 15	2018-10-23 @ 1:00 pm	2018-10-26 @ 12:00 pm	0.5 ± 0.3	2018-10-29
9119760	ROOM 16	2018-10-23 @ 1:00 pm	2018-10-26 @ 12:00 pm	0.5 ± 0.2	2018-10-29
9119762	ROOM 17	2018-10-23 @ 1:00 pm	2018-10-26 @ 12:00 pm	0.6 ± 0.3	2018-10-29
9119768	ROOM 18	2018-10-23 @ 1:00 pm	2018-10-26 @ 12:00 pm	0.9 ± 0.3	2018-10-29
9119714	ROOM 19	2018-10-23 @ 1:00 pm	2018-10-26 @ 12:00 pm	0.8 ± 0.3	2018-10-29
9119744	ROOM 2	2018-10-23 @ 12:00 pm	2018-10-26 @ 12:00 pm	0.6 ± 0.3	2018-10-29
9119759	ROOM 3	2018-10-23 @ 12:00 pm	2018-10-26 @ 12:00 pm	0.5 ± 0.2	2018-10-29
9119397	ROOM 4	2018-10-23 @ 12:00 pm	2018-10-26 @ 12:00 pm	0.6 ± 0.3	2018-10-29
9119398	ROOM 5	2018-10-23 @ 12:00 pm	2018-10-26 @ 12:00 pm	< 0.3	2018-10-29
9119748	ROOM 6	2018-10-23 @ 12:00 pm	2018-10-26 @ 12:00 pm	0.5 ± 0.2	2018-10-29
9119753	ROOM 6 BLANK	2018-10-23 @ 12:00 pm	2018-10-26 @ 12:00 pm	< 0.3	2018-10-29
9119751	ROOM 7	2018-10-23 @ 12:00 pm	2018-10-26 @ 12:00 pm	0.6 ± 0.2	2018-10-29
9119752	ROOM 8	2018-10-23 @ 12:00 pm	2018-10-26 @ 12:00 pm	< 0.3	2018-10-29

---

October 29, 2018

**\*\* LABORATORY ANALYSIS REPORT \*\***

---

Radon test result report for:  
**BUTTERNUT CREEK  
MAIN**

---

<b>Kit #</b>	<b>Room Id</b>	<b>Started</b>	<b>Ended</b>	<b>pCi/L</b>	<b>Analyzed</b>
9119750	ROOM 8 DUP	2018-10-23 @ 12:00 pm	2018-10-26 @ 12:00 pm	0.6 ± 0.2	2018-10-29
9119746	ROOM 9	2018-10-23 @ 12:00 pm	2018-10-26 @ 12:00 pm	0.6 ± 0.3	2018-10-29
9119754	SCC	2018-10-23 @ 1:00 pm	2018-10-26 @ 12:00 pm	0.7 ± 0.3	2018-10-29
9119737	STAFF ROOM	2018-10-23 @ 12:00 pm	2018-10-26 @ 12:00 pm	< 0.3	2018-10-29
9119765	WELLNESS PORTABL	2018-10-23 @ 1:00 pm	2018-10-26 @ 12:00 pm	0.6 ± 0.3	2018-10-29

---

Air Chek 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498