



November 13, 2018

Dave Peterson
Hillsboro School District
4901 SE Witch Hazel Road
Hillsboro, Oregon 97123

Via email: petersod@hsd.k12.or.us

Regarding: District Wide Radon Testing
 Hillsboro High School
 3285 SE Rood Bridge Road
 Hillsboro, Oregon
 PBS Project 23440.024, Phase 0003

Dear Mr. Peterson:

From October 22 to October 25, 2018, PBS Engineering and Environmental Inc. (PBS) performed short term radon testing at Hillsboro High School located at 3285 SE Rood Bridge Road in Hillsboro, Oregon.

The Environmental Protection Agency (EPA) and Oregon Health Authority (OHA) recommend that buildings be tested for radon and that any radon concentrations be maintained below 4.0 picocuries per liter (pCi/L) of air. PBS used AirChek, Inc. brand single-use, short-term radon test kits to measure radon levels in frequently-occupied rooms that are in contact with the ground or above unoccupied basements or crawlspaces.

Laboratory results indicate all short-term radon tests at Hillsboro High School tested below 4.0 pCi/L. with the exception of the Wood Shop building.

The following table lists all samples in which radon levels were found to be above the EPA action level.

Test Kits with Radon 4.0 pCi/L or Above

Test Kit Number	Sample location	Radon Level (pCi/L)
9119321	Wood Shop classroom duplicate	4.7
9119322	Wood Shop classroom	4.9
9119317	Wood Shop	4.9
9119323	Wood Shop office	6.0

The areas in the Wood Shop listed above will require follow-up testing with long-term radon detector kits.

See the attached Laboratory Analysis Report for more details.

In addition to the EPA recommendation that radon concentrations not exceed 4.0 pCi/L, OHA recommends the following steps be conducted based on the results of a room's initial short-term test:

- **If the result is less than 2.0 pCi/L**, school districts are required to test again every 10 years, per Oregon Revised Statute 332.166-167.
- **If the result is between 2.0 pCi/L and 4.0 pCi/L**, consider fixing (i.e., lowering) the radon in that room.
- **If the result is from 4.0 pCi/L to 8.0 pCi/L**, perform a follow-up measurement of that room using a long-term test. This test should be conducted over as much of a nine-month school year as possible, when the room is likely to be occupied. If that result is equal to or greater than 4.0 pCi/L, the radon in the room should be fixed (i.e., lowered).
- **If the initial short-term test result is equal to or greater than 8.0 pCi/L**, conduct a second short-term test and average its result with the initial short-term test result. If the average of the two is equal to or greater than 4.0 pCi/L, radon in the room should be fixed (i.e., lowered).

Note: A great difference in the results of the short-term tests may indicate a flaw in the testing process. Investigate and consider retesting. For situations in which one of the test results is equal to or greater than 4.0 pCi/L, if the higher result is two or more times the lower result, repeat the test.

LIMITATIONS OF SCOPE

This study was limited to the tests and locations as previously indicated. The site as a whole may have other environmental concerns that will not be characterized by this study. The findings and conclusions of this work are not scientific certainties, but probabilities based on professional judgment concerning the significance of the data gathered during the course of this investigation. PBS is not able to represent conditions on the site or adjoining sites beyond those detected or observed by PBS.

Please feel free to contact me at 503.935.5484 or dale.voeller@pbsusa.com with any questions or comments.

Sincerely,

Dale Voeller, CHMM, CSP
Senior Project Manager

Attachment: AirChek, Inc Laboratory Analysis Report

SG::dsv

Radon test result report for:

**HILLSBORO HIGH SCHOOL
ADMIN**

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
9119567	ADMIN CORRIDOR	2018-10-22 @ 3:00 pm	2018-10-25 @ 4:00 pm	< 0.3	2018-10-29
9119561	ALICE HART	2018-10-22 @ 3:00 pm	2018-10-25 @ 4:00 pm	0.7 ± 0.3	2018-10-29
9119571	AMI WALLBERG	2018-10-22 @ 3:00 pm	2018-10-25 @ 4:00 pm	< 0.3	2018-10-29
9119562	CAMP SECURE DUP	2018-10-22 @ 3:00 pm	2018-10-25 @ 4:00 pm	0.6 ± 0.3	2018-10-29
9119555	CAMPUS SECURITY	2018-10-22 @ 3:00 pm	2018-10-25 @ 4:00 pm	0.6 ± 0.3	2018-10-29
9119560	CAREER COMMON	2018-10-22 @ 3:00 pm	2018-10-25 @ 4:00 pm	< 0.3	2018-10-29
9119543	COU. CENTER COMM	2018-10-22 @ 3:00 pm	2018-10-25 @ 4:00 pm	< 0.3	2018-10-29
9119551	COUNC. COMM DUP	2018-10-22 @ 3:00 pm	2018-10-25 @ 4:00 pm	< 0.3	2018-10-29
9119534	DAVID VICKERY	2018-10-22 @ 3:00 pm	2018-10-25 @ 4:00 pm	< 0.3	2018-10-29
9119559	HERRERA	2018-10-22 @ 3:00 pm	2018-10-25 @ 4:00 pm	< 0.3	2018-10-29
9119563	JENNIFER BAILEY	2018-10-22 @ 3:00 pm	2018-10-25 @ 4:00 pm	0.6 ± 0.3	2018-10-29
9119545	JOHN MATSUO	2018-10-22 @ 3:00 pm	2018-10-25 @ 4:00 pm	0.6 ± 0.3	2018-10-29
9119553	JOSE CAMPUZANO	2018-10-22 @ 3:00 pm	2018-10-25 @ 4:00 pm	< 0.3	2018-10-29
9119540	KELLY COX	2018-10-22 @ 3:00 pm	2018-10-25 @ 4:00 pm	0.6 ± 0.3	2018-10-29
9119536	KORI SAKAMOTO	2018-10-22 @ 3:00 pm	2018-10-25 @ 4:00 pm	< 0.3	2018-10-29
9119547	LAURA KOSAK	2018-10-22 @ 3:00 pm	2018-10-25 @ 4:00 pm	0.8 ± 0.3	2018-10-29
9119554	LESLIE LUTTRELL	2018-10-22 @ 3:00 pm	2018-10-25 @ 4:00 pm	0.6 ± 0.3	2018-10-29
9119556	LORRIE MCKEDY	2018-10-22 @ 3:00 pm	2018-10-25 @ 4:00 pm	0.6 ± 0.3	2018-10-29
9119544	MARLA LYLE	2018-10-22 @ 3:00 pm	2018-10-25 @ 4:00 pm	0.6 ± 0.3	2018-10-29
9119548	MATEO CAMPOS	2018-10-22 @ 3:00 pm	2018-10-25 @ 4:00 pm	< 0.3	2018-10-29
9119552	MIGUEL CHO BLANK	2018-10-22 @ 3:00 pm	2018-10-25 @ 4:00 pm	< 0.3	2018-10-29
9119570	MIGUEL CHOLULA	2018-10-22 @ 3:00 pm	2018-10-25 @ 4:00 pm	0.7 ± 0.3	2018-10-29
9119546	NATHAN BUCK	2018-10-22 @ 3:00 pm	2018-10-25 @ 4:00 pm	< 0.3	2018-10-29
9119532	OFFICE CONFERENC	2018-10-22 @ 3:00 pm	2018-10-25 @ 4:00 pm	0.6 ± 0.3	2018-10-29
9119539	PUBLIC LOBBY	2018-10-22 @ 3:00 pm	2018-10-25 @ 4:00 pm	0.6 ± 0.3	2018-10-29
9119526	REGISTRAR	2018-10-22 @ 3:00 pm	2018-10-25 @ 4:00 pm	0.6 ± 0.4	2018-10-29
9119538	SHERRILL FRANK	2018-10-22 @ 3:00 pm	2018-10-25 @ 4:00 pm	< 0.3	2018-10-29
9119533	STAFF RESOURCE R	2018-10-22 @ 3:00 pm	2018-10-25 @ 4:00 pm	0.8 ± 0.3	2018-10-29
9119537	STEPHANIE WINTER	2018-10-22 @ 3:00 pm	2018-10-25 @ 4:00 pm	< 0.3	2018-10-29

Radon test result report for:

**HILLSBORO HIGH SCHOOL
BUSINESS EDUCATION**

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
9119463	BE CONF OFFICE	2018-10-22 @ 6:00 pm	2018-10-25 @ 5:00 pm	0.6 ± 0.3	2018-10-29
9119462	BE CONFERENCE	2018-10-22 @ 6:00 pm	2018-10-25 @ 5:00 pm	0.7 ± 0.3	2018-10-29
9119460	CLASS 4 BLANK	2018-10-22 @ 6:00 pm	2018-10-25 @ 5:00 pm	< 0.3	2018-10-29
9119452	CLASSROOM 1	2018-10-22 @ 6:00 pm	2018-10-25 @ 5:00 pm	0.6 ± 0.3	2018-10-29
9119450	CLASSROOM 2	2018-10-22 @ 6:00 pm	2018-10-25 @ 5:00 pm	< 0.3	2018-10-29
9119457	CLASSROOM 3	2018-10-22 @ 6:00 pm	2018-10-25 @ 5:00 pm	< 0.3	2018-10-29
9119459	CLASSROOM 3 DUP	2018-10-22 @ 6:00 pm	2018-10-25 @ 8:00 pm	< 0.3	2018-10-29
9119458	CLASSROOM 4	2018-10-22 @ 6:00 pm	2018-10-25 @ 5:00 pm	< 0.3	2018-10-29
9119455	CLASSROOM 5	2018-10-22 @ 6:00 pm	2018-10-25 @ 5:00 pm	< 0.3	2018-10-29
9119453	CLASSROOM 6	2018-10-22 @ 6:00 pm	2018-10-25 @ 5:00 pm	< 0.3	2018-10-29
9119456	CLASSROOM 7	2018-10-22 @ 6:00 pm	2018-10-25 @ 5:00 pm	< 0.3	2018-10-29
9119454	CLASSROOM 8	2018-10-22 @ 6:00 pm	2018-10-25 @ 5:00 pm	< 0.3	2018-10-29
9119461	COMPUTER DEPOT	2018-10-22 @ 6:00 pm	2018-10-25 @ 5:00 pm	< 0.3	2018-10-29

Radon test result report for:
HILLSBORO HIGH SCHOOL
CAFETERIA\KITCHEN

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
9119470	ACTIV. OFFICE	2018-10-22 @ 6:00 pm	2018-10-25 @ 5:00 pm	< 0.3	2018-10-29
9119464	CAFETERIA 1	2018-10-22 @ 6:00 pm	2018-10-25 @ 6:00 pm	< 0.3	2018-10-29
9119465	CAFETERIA 2	2018-10-22 @ 6:00 pm	2018-10-25 @ 6:00 pm	< 0.3	2018-10-29
9119467	COMMONS 2	2018-10-22 @ 6:00 pm	2018-10-25 @ 5:00 pm	0.5 ± 0.3	2018-10-29
9119469	COMMONSCLASSROOM	2018-10-22 @ 6:00 pm	2018-10-25 @ 6:00 pm	< 0.3	2018-10-29
9119466	CONF ROOM	2018-10-22 @ 6:00 pm	2018-10-25 @ 5:00 pm	0.6 ± 0.3	2018-10-29
9119473	CONF WRKRM OFFIC	2018-10-22 @ 6:00 pm	2018-10-25 @ 5:00 pm	< 0.3	2018-10-29
9119474	KITCHEN OFFICE	2018-10-22 @ 6:00 pm	2018-10-25 @ 6:00 pm	< 0.3	2018-10-29
9119471	TEACH LOUNGE DUP	2018-10-22 @ 6:00 pm	2018-10-25 @ 6:00 pm	0.5 ± 0.3	2018-10-29
9119472	TEACHERS LOUNGE	2018-10-22 @ 6:00 pm	2018-10-25 @ 6:00 pm	< 0.3	2018-10-29

October 29, 2018

**** LABORATORY ANALYSIS REPORT ****

Radon test result report for:

**HILLSBORO HIGH SCHOOL
CREATIVE ARTS**

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
9119447	CLASS 1 OFF DUP	2018-10-22 @ 6:00 pm	2018-10-25 @ 5:00 pm	0.5 ± 0.3	2018-10-29
9119449	CLASS 1 OFFICE	2018-10-22 @ 6:00 pm	2018-10-25 @ 5:00 pm	0.6 ± 0.3	2018-10-29
9119443	CLASSROOM 1	2018-10-22 @ 6:00 pm	2018-10-25 @ 5:00 pm	< 0.3	2018-10-29
9119444	CLASSROOM 2	2018-10-22 @ 6:00 pm	2018-10-25 @ 5:00 pm	0.6 ± 0.3	2018-10-29
9119448	DAYCARE A	2018-10-22 @ 6:00 pm	2018-10-25 @ 5:00 pm	< 0.3	2018-10-29
9119446	DAYCARE OFFICE	2018-10-22 @ 6:00 pm	2018-10-25 @ 5:00 pm	< 0.3	2018-10-29
9119445	FOOD LAB	2018-10-22 @ 6:00 pm	2018-10-25 @ 5:00 pm	0.8 ± 0.3	2018-10-29
9119439	ROOM 3	2018-10-22 @ 5:00 pm	2018-10-25 @ 5:00 pm	0.6 ± 0.3	2018-10-29

Air Chek 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498

October 29, 2018

**** LABORATORY ANALYSIS REPORT ****

Radon test result report for:
HILLSBORO HIGH SCHOOL
DRAMA AND MUSIC

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
9119566	BAND DIRECTOR	2018-10-22 @ 4:00 pm	2018-10-25 @ 4:00 pm	0.7 ± 0.3	2018-10-29
9119558	BAND ROOM	2018-10-22 @ 4:00 pm	2018-10-25 @ 4:00 pm	< 0.3	2018-10-29
9119565	CHOIR DIRECTOR	2018-10-22 @ 4:00 pm	2018-10-25 @ 4:00 pm	0.7 ± 0.3	2018-10-29
9119557	CHOIR ROOM	2018-10-22 @ 4:00 pm	2018-10-25 @ 4:00 pm	0.6 ± 0.3	2018-10-29
9119575	DM 5 OFFICE	2018-10-22 @ 4:00 pm	2018-10-25 @ 4:00 pm	0.6 ± 0.3	2018-10-29
9119577	DM5	2018-10-22 @ 4:00 pm	2018-10-25 @ 4:00 pm	0.5 ± 0.3	2018-10-29
9119583	DM5 OFFICE DUP	2018-10-22 @ 4:00 pm	2018-10-25 @ 4:00 pm	0.6 ± 0.3	2018-10-29
9119578	DM6	2018-10-22 @ 4:00 pm	2018-10-25 @ 4:00 pm	0.5 ± 0.3	2018-10-29
9119576	DM6 BLANK	2018-10-22 @ 4:00 pm	2018-10-25 @ 4:00 pm	< 0.3	2018-10-29
9119572	DRAMA DIRECTOR	2018-10-22 @ 4:00 pm	2018-10-25 @ 4:00 pm	< 0.3	2018-10-29

Air Chek 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498

Radon test result report for:

**HILLSBORO HIGH SCHOOL
HEALTH EDUCATION/GYM**

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
9119330	COACH OFFICE 2	2018-10-22 @ 8:00 pm	2018-10-25 @ 6:00 pm	0.7 ± 0.3	2018-10-29
9119329	COACH OFFICE 3	2018-10-22 @ 8:00 pm	2018-10-25 @ 6:00 pm	< 0.3	2018-10-29
9119328	COACH OFFICE 4	2018-10-22 @ 8:00 pm	2018-10-25 @ 6:00 pm	< 0.3	2018-10-29
9119326	COACHES OFFICE 1	2018-10-22 @ 7:00 pm	2018-10-25 @ 6:00 pm	< 0.3	2018-10-29
9119340	EAST GYM 1	2018-10-22 @ 8:00 pm	2018-10-25 @ 7:00 pm	0.7 ± 0.3	2018-10-29
9119341	EAST GYM 2	2018-10-22 @ 8:00 pm	2018-10-25 @ 7:00 pm	0.7 ± 0.3	2018-10-29
9119327	GIRLS LOCKER OFF	2018-10-22 @ 7:00 pm	2018-10-25 @ 6:00 pm	< 0.3	2018-10-29
9119336	HEALTH 2	2018-10-22 @ 8:00 pm	2018-10-25 @ 6:00 pm	0.6 ± 0.3	2018-10-29
9119334	HEALTH 3	2018-10-22 @ 8:00 pm	2018-10-25 @ 6:00 pm	< 0.3	2018-10-29
9119331	HEALTH ROOM	2018-10-22 @ 8:00 pm	2018-10-25 @ 6:00 pm	< 0.3	2018-10-29
9119332	HEALTH ROOM DUP	2018-10-22 @ 8:00 pm	2018-10-25 @ 6:00 pm	< 0.3	2018-10-29
9119333	MAIN GYM 1	2018-10-22 @ 8:00 pm	2018-10-25 @ 7:00 pm	< 0.3	2018-10-29
9119337	MAIN GYM 2	2018-10-22 @ 8:00 pm	2018-10-25 @ 7:00 pm	0.6 ± 0.3	2018-10-29
9119339	MID GYM 2	2018-10-22 @ 8:00 pm	2018-10-25 @ 7:00 pm	< 0.3	2018-10-29
9119324	TRAINING OFFICE	2018-10-22 @ 7:00 pm	2018-10-25 @ 6:00 pm	< 0.3	2018-10-29
9119325	TRAINING ROOM	2018-10-22 @ 7:00 pm	2018-10-25 @ 6:00 pm	< 0.3	2018-10-29
9119345	WEIGHT ROOM	2018-10-22 @ 8:00 pm	2018-10-25 @ 7:00 pm	< 0.3	2018-10-29
9119344	WEIGHT ROOM BLAN	2018-10-22 @ 8:00 pm	2018-10-25 @ 7:00 pm	< 0.3	2018-10-29
9119343	WEIGHT ROOM DUP	2018-10-22 @ 8:00 pm	2018-10-25 @ 7:00 pm	< 0.3	2018-10-29

Radon test result report for:

**HILLSBORO HIGH SCHOOL
LANGUAGE ARTS**

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
9119414	CLASS 14 OFF DUP	2018-10-22 @ 5:00 pm	2018-10-25 @ 4:00 pm	0.6 ± 0.3	2018-10-29
9119402	CLASS 14 OFFICE	2018-10-22 @ 5:00 pm	2018-10-25 @ 4:00 pm	< 0.3	2018-10-29
9119415	CLASS 18 BLANK	2018-10-22 @ 5:00 pm	2018-10-25 @ 4:00 pm	< 0.3	2018-10-29
9119410	CLASS 3 DUP	2018-10-22 @ 5:00 pm	2018-10-25 @ 4:00 pm	< 0.3	2018-10-29
9119412	CLASSROOM 10	2018-10-22 @ 5:00 pm	2018-10-25 @ 4:00 pm	< 0.3	2018-10-29
9119413	CLASSROOM 11	2018-10-22 @ 5:00 pm	2018-10-25 @ 4:00 pm	< 0.3	2018-10-29
9119403	CLASSROOM 12	2018-10-22 @ 5:00 pm	2018-10-25 @ 4:00 pm	< 0.3	2018-10-29
9119408	CLASSROOM 13	2018-10-22 @ 5:00 pm	2018-10-25 @ 4:00 pm	< 0.3	2018-10-29
9119407	CLASSROOM 14	2018-10-22 @ 5:00 pm	2018-10-25 @ 4:00 pm	< 0.3	2018-10-29
9119401	CLASSROOM 15	2018-10-22 @ 5:00 pm	2018-10-25 @ 4:00 pm	< 0.3	2018-10-29
9119404	CLASSROOM 17	2018-10-22 @ 5:00 pm	2018-10-25 @ 4:00 pm	0.7 ± 0.3	2018-10-29
9119409	CLASSROOM 18	2018-10-22 @ 5:00 pm	2018-10-25 @ 4:00 pm	0.6 ± 0.3	2018-10-29
9119596	CLASSROOM 3	2018-10-22 @ 4:00 pm	2018-10-25 @ 4:00 pm	< 0.3	2018-10-29
9119597	CLASSROOM 4	2018-10-22 @ 4:00 pm	2018-10-25 @ 4:00 pm	< 0.3	2018-10-29
9119598	CLASSROOM 5	2018-10-22 @ 4:00 pm	2018-10-25 @ 4:00 pm	< 0.3	2018-10-29
9119600	CLASSROOM 6	2018-10-22 @ 4:00 pm	2018-10-25 @ 4:00 pm	< 0.3	2018-10-29
9119411	CLASSROOM 7	2018-10-22 @ 4:00 pm	2018-10-25 @ 4:00 pm	< 0.3	2018-10-29
9119406	CLASSROOM 8	2018-10-22 @ 4:00 pm	2018-10-25 @ 4:00 pm	< 0.3	2018-10-29
9119405	CLASSROOM 9	2018-10-22 @ 5:00 pm	2018-10-25 @ 4:00 pm	< 0.3	2018-10-29
9119421	LRC OFFICE	2018-10-22 @ 5:00 pm	2018-10-25 @ 4:00 pm	< 0.3	2018-10-29
9119418	OFFICE 1 A	2018-10-22 @ 5:00 pm	2018-10-25 @ 4:00 pm	< 0.3	2018-10-29
9119419	OFFICE 10A	2018-10-22 @ 5:00 pm	2018-10-25 @ 4:00 pm	< 0.3	2018-10-29
9119417	OFFICE 2 A	2018-10-22 @ 5:00 pm	2018-10-25 @ 4:00 pm	0.6 ± 0.3	2018-10-29
9119416	OFFICE 5A	2018-10-22 @ 5:00 pm	2018-10-25 @ 4:00 pm	< 0.3	2018-10-29
9119420	OFFICE 6A	2018-10-22 @ 5:00 pm	2018-10-25 @ 4:00 pm	< 0.3	2018-10-29
9119422	OFFICE 9A	2018-10-22 @ 5:00 pm	2018-10-25 @ 4:00 pm	< 0.3	2018-10-29

October 29, 2018

**** LABORATORY ANALYSIS REPORT ****

Radon test result report for:

**HILLSBORO HIGH SCHOOL
LIBRARY**

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
9119480	CAREER CENTER	2018-10-22 @ 6:00 pm	2018-10-25 @ 6:00 pm	< 0.3	2018-10-29
9119485	CAREER CTR CONF	2018-10-22 @ 6:00 pm	2018-10-25 @ 6:00 pm	< 0.3	2018-10-29
9119481	LEARN CTR BLANK	2018-10-22 @ 6:00 pm	2018-10-25 @ 6:00 pm	< 0.3	2018-10-29
9119479	LEARNING CENTER	2018-10-22 @ 6:00 pm	2018-10-25 @ 6:00 pm	< 0.3	2018-10-29
9119482	LEARNING CTR DUP	2018-10-22 @ 6:00 pm	2018-10-25 @ 6:00 pm	0.6 ± 0.3	2018-10-29
9119483	LIBRARY 1	2018-10-22 @ 6:00 pm	2018-10-25 @ 6:00 pm	0.5 ± 0.3	2018-10-29
9119475	LIBRARY 2	2018-10-22 @ 6:00 pm	2018-10-25 @ 6:00 pm	0.5 ± 0.3	2018-10-29
9119476	NORTH OFFICE	2018-10-22 @ 6:00 pm	2018-10-25 @ 6:00 pm	< 0.3	2018-10-29
9119484	PENDERGRASS OFFI	2018-10-22 @ 6:00 pm	2018-10-25 @ 6:00 pm	0.5 ± 0.3	2018-10-29
9119477	WORK ROOM	2018-10-22 @ 6:00 pm	2018-10-25 @ 6:00 pm	< 0.3	2018-10-29

Air Chek 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498

Radon test result report for:

**HILLSBORO HIGH SCHOOL
MATH AND SCIENCE**

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
9119428	CLASS 12 BLANK	2018-10-22 @ 5:00 pm	2018-10-25 @ 5:00 pm	< 0.3	2018-10-29
9119435	CLASSROOM 1	2018-10-22 @ 5:00 pm	2018-10-25 @ 5:00 pm	< 0.3	2018-10-29
9119425	CLASSROOM 10	2018-10-22 @ 5:00 pm	2018-10-25 @ 5:00 pm	0.5 ± 0.3	2018-10-29
9119424	CLASSROOM 11	2018-10-22 @ 5:00 pm	2018-10-25 @ 5:00 pm	< 0.3	2018-10-29
9119426	CLASSROOM 12	2018-10-22 @ 5:00 pm	2018-10-25 @ 5:00 pm	< 0.3	2018-10-29
9119437	CLASSROOM 4	2018-10-22 @ 5:00 pm	2018-10-25 @ 5:00 pm	< 0.3	2018-10-29
9119438	CLASSROOM 5	2018-10-22 @ 5:00 pm	2018-10-25 @ 5:00 pm	< 0.3	2018-10-29
9119431	CLASSROOM 6	2018-10-22 @ 5:00 pm	2018-10-25 @ 5:00 pm	< 0.3	2018-10-29
9119430	CLASSROOM 7	2018-10-22 @ 5:00 pm	2018-10-25 @ 5:00 pm	< 0.3	2018-10-29
9119429	CLASSROOM 8	2018-10-22 @ 5:00 pm	2018-10-25 @ 5:00 pm	< 0.3	2018-10-29
9119423	CLASSROOM 9	2018-10-22 @ 5:00 pm	2018-10-25 @ 5:00 pm	0.6 ± 0.3	2018-10-29
9119433	OFFICE 2A	2018-10-22 @ 5:00 pm	2018-10-25 @ 5:00 pm	< 0.3	2018-10-29
9119442	OFFICE 7A	2018-10-22 @ 5:00 pm	2018-10-25 @ 5:00 pm	0.5 ± 0.3	2018-10-29
9119441	OFFICE 8A	2018-10-22 @ 5:00 pm	2018-10-25 @ 5:00 pm	0.9 ± 0.3	2018-10-29
9119440	OFFICE 9A	2018-10-22 @ 5:00 pm	2018-10-25 @ 5:00 pm	0.6 ± 0.3	2018-10-29
9119434	ROOM 1 DUP	2018-10-22 @ 5:00 pm	2018-10-25 @ 5:00 pm	< 0.3	2018-10-29
9119427	ROOM 10 DUP	2018-10-22 @ 5:00 pm	2018-10-25 @ 5:00 pm	< 0.3	2018-10-29

October 29, 2018

**** LABORATORY ANALYSIS REPORT ****

Radon test result report for:

**HILLSBORO HIGH SCHOOL
PERFORMANCE CENTER**

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
9119550	AUDITORIUM 1	2018-10-22 @ 4:00 pm	2018-10-25 @ 4:00 pm	0.8 ± 0.3	2018-10-29
9119569	AUDITORIUM 2	2018-10-22 @ 4:00 pm	2018-10-25 @ 4:00 pm	0.8 ± 0.3	2018-10-29
9119568	AUDITORIUM 2 DUP	2018-10-22 @ 4:00 pm	2018-10-25 @ 4:00 pm	0.9 ± 0.3	2018-10-29
9119549	DRAMA CLASSROOM	2018-10-22 @ 4:00 pm	2018-10-25 @ 4:00 pm	< 0.3	2018-10-29
9119542	GALLERY	2018-10-22 @ 4:00 pm	2018-10-25 @ 4:00 pm	0.5 ± 0.3	2018-10-29
9119541	MAKE UP ROOM	2018-10-22 @ 4:00 pm	2018-10-25 @ 4:00 pm	< 0.3	2018-10-29
9119564	N STAGEE STORAGE	2018-10-22 @ 4:00 pm	2018-10-25 @ 4:00 pm	0.8 ± 0.3	2018-10-29

Air Chek 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498

Radon test result report for:

**HILLSBORO HIGH SCHOOL
SOCIAL STUDIES**

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
9119594	CLASS 5 OFFICE	2018-10-22 @ 4:00 pm	2018-10-25 @ 5:00 pm	0.7 ± 0.3	2018-10-29
9119587	CLASSROOM 1	2018-10-22 @ 4:00 pm	2018-10-25 @ 5:00 pm	< 0.3	2018-10-29
9119573	CLASSROOM 1 DUP	2018-10-22 @ 4:00 pm	2018-10-25 @ 5:00 pm	< 0.3	2018-10-29
9119586	CLASSROOM 10	2018-10-22 @ 4:00 pm	2018-10-25 @ 5:00 pm	< 0.3	2018-10-29
9119593	CLASSROOM 12	2018-10-22 @ 4:00 pm	2018-10-25 @ 5:00 pm	0.7 ± 0.3	2018-10-29
9119574	CLASSROOM 12 DUP	2018-10-22 @ 4:00 pm	2018-10-25 @ 5:00 pm	< 0.3	2018-10-29
9119584	CLASSROOM 2	2018-10-22 @ 4:00 pm	2018-10-25 @ 5:00 pm	< 0.3	2018-10-29
9119585	CLASSROOM 4	2018-10-22 @ 4:00 pm	2018-10-25 @ 5:00 pm	< 0.3	2018-10-29
9119591	CLASSROOM 5	2018-10-22 @ 4:00 pm	2018-10-25 @ 5:00 pm	< 0.3	2018-10-29
9119579	CLASSROOM 6	2018-10-22 @ 4:00 pm	2018-10-25 @ 5:00 pm	< 0.3	2018-10-29
9119580	CLASSROOM 7	2018-10-22 @ 4:00 pm	2018-10-25 @ 5:00 pm	< 0.3	2018-10-29
9119599	CLASSROOM 8	2018-10-22 @ 4:00 pm	2018-10-25 @ 5:00 pm	< 0.3	2018-10-29
9119592	CLASSROOM 9	2018-10-22 @ 4:00 pm	2018-10-25 @ 5:00 pm	< 0.3	2018-10-29
9119581	SSRC	2018-10-22 @ 4:00 pm	2018-10-25 @ 5:00 pm	0.6 ± 0.3	2018-10-29
9119588	SSRC BLANK	2018-10-22 @ 4:00 pm	2018-10-25 @ 5:00 pm	< 0.3	2018-10-29
9119582	SSRC OFFICE	2018-10-22 @ 4:00 pm	2018-10-25 @ 5:00 pm	0.7 ± 0.3	2018-10-29

Radon test result report for:

**HILLSBORO HIGH SCHOOL
TECHNICAL ED**

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
9119310	AUTO CLASSROOM	2018-10-22 @ 7:00 pm	2018-10-25 @ 6:00 pm	0.6 ± 0.3	2018-10-29
9119311	AUTO OFFICE	2018-10-22 @ 7:00 pm	2018-10-25 @ 6:00 pm	1.0 ± 0.3	2018-10-29
9119309	AUTO SHOP 1	2018-10-22 @ 7:00 pm	2018-10-25 @ 6:00 pm	< 0.3	2018-10-29
9119308	AUTO SHOP 2	2018-10-22 @ 7:00 pm	2018-10-25 @ 6:00 pm	0.7 ± 0.3	2018-10-29
9119486	CISCO	2018-10-22 @ 7:00 pm	2018-10-25 @ 6:00 pm	0.6 ± 0.3	2018-10-29
9119499	COMP RM OFFICE	2018-10-22 @ 7:00 pm	2018-10-25 @ 6:00 pm	< 0.3	2018-10-29
9119488	ELEC STRUT	2018-10-22 @ 7:00 pm	2018-10-25 @ 6:00 pm	< 0.3	2018-10-29
9119490	ELEC STRUT OFFIC	2018-10-22 @ 7:00 pm	2018-10-25 @ 6:00 pm	0.8 ± 0.3	2018-10-29
9119307	FABSHOP	2018-10-22 @ 7:00 pm	2018-10-25 @ 6:00 pm	1.6 ± 0.3	2018-10-29
9119304	FABSHOP OFFICE	2018-10-22 @ 7:00 pm	2018-10-25 @ 6:00 pm	0.8 ± 0.3	2018-10-29
9119497	FOUNDATION OFFIC	2018-10-22 @ 7:00 pm	2018-10-25 @ 6:00 pm	< 0.3	2018-10-29
9119498	FOUNDATIONS ROOM	2018-10-22 @ 7:00 pm	2018-10-25 @ 6:00 pm	< 0.3	2018-10-29
9119319	PLANT LAB	2018-10-22 @ 7:00 pm	2018-10-25 @ 6:00 pm	< 0.3	2018-10-29
9119316	PLANT SCI DUP	2018-10-22 @ 7:00 pm	2018-10-25 @ 6:00 pm	0.6 ± 0.3	2018-10-29
9119315	PLANT SCI OFFICE	2018-10-22 @ 7:00 pm	2018-10-25 @ 6:00 pm	0.8 ± 0.3	2018-10-29
9119318	PLANT SCIENCE	2018-10-22 @ 7:00 pm	2018-10-25 @ 6:00 pm	0.6 ± 0.3	2018-10-29
9119494	PUB. WORK STUDIO	2018-10-22 @ 7:00 pm	2018-10-25 @ 6:00 pm	0.9 ± 0.3	2018-10-29
9119493	PUBLICATION OFFI	2018-10-22 @ 7:00 pm	2018-10-25 @ 6:00 pm	0.7 ± 0.3	2018-10-29
9119491	PUBLICATIONS	2018-10-22 @ 7:00 pm	2018-10-25 @ 6:00 pm	< 0.3	2018-10-29
9119492	PUBLICATIONS DUP	2018-10-22 @ 7:00 pm	2018-10-25 @ 6:00 pm	0.6 ± 0.3	2018-10-29
9119489	SMT ELECTRONICS	2018-10-22 @ 7:00 pm	2018-10-25 @ 6:00 pm	0.7 ± 0.3	2018-10-29
9119301	TE 10 A DUP	2018-10-22 @ 7:00 pm	2018-10-25 @ 6:00 pm	< 0.3	2018-10-29
9119303	TE 10A	2018-10-22 @ 7:00 pm	2018-10-25 @ 6:00 pm	0.6 ± 0.3	2018-10-29
9119487	TE-3 STRUT	2018-10-22 @ 7:00 pm	2018-10-25 @ 6:00 pm	0.6 ± 0.3	2018-10-29
9119312	TECH ED 13	2018-10-22 @ 7:00 pm	2018-10-25 @ 6:00 pm	0.7 ± 0.3	2018-10-29
9119313	TECH ED 13 OFFIC	2018-10-22 @ 7:00 pm	2018-10-25 @ 6:00 pm	0.6 ± 0.3	2018-10-29
9119302	TRANSPORT BLANK	2018-10-22 @ 7:00 pm	2018-10-25 @ 6:00 pm	< 0.3	2018-10-29
9119306	TRANSPORT OFFICE	2018-10-22 @ 7:00 pm	2018-10-25 @ 6:00 pm	< 0.3	2018-10-29
9119495	TV STUDIO	2018-10-22 @ 7:00 pm	2018-10-25 @ 6:00 pm	0.5 ± 0.3	2018-10-29

October 29, 2018

**** LABORATORY ANALYSIS REPORT ****

Radon test result report for:

**HILLSBORO HIGH SCHOOL
WOOD SHOP**

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
9119321	CLASS DUP	2018-10-22 @ 7:00 pm	2018-10-25 @ 6:00 pm	4.7 ± 0.4	2018-10-29
9119320	OFFICE BLANK	2018-10-22 @ 7:00 pm	2018-10-25 @ 6:00 pm	< 0.3	2018-10-29
9119322	WOOD CLASSROOM	2018-10-22 @ 7:00 pm	2018-10-25 @ 6:00 pm	4.9 ± 0.4	2018-10-29
9119317	WOOD SHOP	2018-10-22 @ 7:00 pm	2018-10-25 @ 6:00 pm	4.9 ± 0.4	2018-10-29
9119323	WOOD SHOP OFFICE	2018-10-22 @ 7:00 pm	2018-10-25 @ 6:00 pm	6.0 ± 0.4	2018-10-29

Air Chek 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498