

Update on FCPS Construction / Renovation Projects







> Architect:

JRA Architects

- General Contractor:Rising Sun Developing Co.
- ➤ GC Contract Sum:

\$69,964,000.00

➤ Total Project Cost:

\$82,680,000.00

➤ Change Orders to Date (4):

(\$2.053.17)




Completed Work:

- O ICF Area E final lift
- O CMU Area B and grouting CMU Area E and B.
- O Structural Steel finish roof at Areas A and C.
- O Roofing delivery for Areas A and C.
- O Metal Stud Framing at Areas F and C second floor.
- O Air Barrier continuing at Area C and Area A.
- O MEP and Sprinkler rough-in overhead and in wall at multiple buildings.
- O Geothermal underground piping install nearly complete.


Upcoming Work/Look Ahead:

- O Pour final lift at Area C.
- O Begin Stala and ICF at remaining Area D walls.
- O Finish roof structure Area A.
- Finish CMU Areas B and D.
- O Continue CMU Area E.
- Continue steel Area C.
- O Continue MEP rough-ins and inspections.
- O Continue metal stud framing.
- O Continue geothermal.
- O Set switch gear in Mechanical Room.






Area A – Stud Framing Above CMU Partitions





Area B – CMU Continues at 2nd Floor Corridor






Area B – CMU Continues on 2nd Floor






Area C – Air Barrier Continuing Around Building





Area C – Roof Soffit Framing






Area C – Wood Fascia Installation at Roof Edge






Areas D – Roof Work Continues





Area F – Exterior Stud Framing at Mezzanine





> Architect:

FOP Architects

D.W. Wilburn Inc.

> GC Contract Sum:

> General Contractor:

\$50,700,288.00

➤ Total Project Cost:

\$64,712,240.00

> Change Orders to Date (6):

\$646,787.73

Completed Work:

- CMU work on all floors continued.
- Ceilings continued on Levels 4 and 3.
- Metal stud and drywall work continuing on all levels.
- Window glazing continued on all levels.
- Electrical devices and lighting continued on Levels 4 and 3.
- Plumbing above ceiling continued on all floors.

Upcoming Work/Look Ahead:

- CMU work should near completion.
- Ceilings to continue on Levels 4 and 3.
- Curtain walls and glazing to continue.
- Ductwork installation to continue.
- Electrical and plumbing wall rough-ins to continue with masonry and electrical devices being installed.
- Drilling for the geothermal wells is scheduled to continue.

Metal Stud Work and Exterior Work Progressing



Curtain Wall Framing




Geothermal Well Drilling Progressing



Metal Stud Work Progressing Below Curtain Wall




Culinary Arts Equipment



Open Ceiling Paint at Level 4



Metal Stud Work in Commons Area



Lights Being Energized on Level 4





Thank you!