

Lead Tests - Lone Pine Elementary School - Main Building - # 20480700						
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20480700-001SF	20480700-001SF23A	Office Conference Room - Sink	03/16/22	2.38	None.
2	20480700-002NS	20480700-002NS23A	Health Room - Sink	03/16/22	3.51	None.
3	20480700-003BF	20480700-003BF23A	Health Room Restroom - Sink	03/16/22	3.34	None.
4	20480705-004SF	20480705-004SF23A	Staff Work Room - Sink (Main Fixture)	03/16/22	3.22	None.
5	20480705-005SF	20480705-005SF23A	Staff Work Room - Sink (Insta-Hot)	03/16/22	0.93	None.
6	20480700-006BF	20480700-006BF23A	Main Office Restroom - Sink	03/16/22	2.05	None.
7	20480700-007DW	20480700-007DW23A	Room 1 - Drinking Fountain	03/16/22	0.93	None.
8	20480700-008CF	20480700-008CF23A	Room 1 - Sink	03/16/22	1.57	None.
9	20480700-009BF	20480700-009BF23A	Room 1 Restroom - Sink	03/16/22	2.24	None.
10	20480700-010DW	20480700-010DW23A	Room 2 - Drinking Fountain	03/16/22	1.74	None.
11	20480700-011CF	20480700-011CF23A	Room 2 - Sink	03/16/22	1.26	None.
12	20480700-012DW	20480700-012DW23A	Room 3 - Drinking Fountain	03/16/22	1.23	None.
13	20480700-013CF	20480700-013CF23A	Room 3 - Sink	03/16/22	0.74	None.
14	20480700-014BF	20480700-014BF23A	Unisex Restroom Near Room 3 - Sink	03/16/22	2.41	None.
15	20480700-015BF	20480700-015BF23A	Boys/Girls Restroom Near Room 3 - Trough Sink	03/16/22	5.23	None.
16	20480700-016DW	20480700-016DW23A	Room 4 - Drinking Fountain	03/16/22	0.74	None.
17	20480700-017CF	20480700-017CF23A	Room 4 - Sink	03/16/22	ND	None.
18	20480700-018DW	20480700-018DW23A	Room 5 - Drinking Fountain	03/16/22	ND	None.
19	20480700-019CF	20480700-019CF23A	Room 5 - Sink	03/16/22	1.08	None.
20	20480700-020DW	20480700-020DW23A	Room 6 - Drinking Fountain	03/16/22	0.98	None.
21	20480700-021CF	20480700-021CF23A	Room 6 - Sink	03/16/22	0.93	None.
22	20480700-022DW	20480700-022DW23A	Room 7 - Drinking Fountain	03/16/22	2.91	None.
23	20480700-023CF	20480700-023CF23A	Room 7 - Sink	03/16/22	0.82	This fixture has a lead filter on it for sediment.
24	20480700-024BF	20480700-024BF23A	Boys/Girls Restroom Near Room 7 - Trough Sink	03/16/22	2.93	None.
25	20480700-025DW	20480700-025DW23A	Room 8 - Drinking Fountain	03/16/22	3.63	None.
26	20480700-026CF	20480700-026CF23A	Room 8 - Sink	03/16/22	1.55	This fixture has a lead filter on it for sediment.
27	20480700-027DW	20480700-027DW23A	Room 9 - Drinking Fountain	03/16/22	ND	None.
28	20480700-028CF	20480700-028CF23A	Room 9 - Sink	03/16/22	1.32	This fixture has a lead filter on it for sediment.
29	20480700-029BF	20480700-029BF23A	Staff Unisex Restroom Near Room 9 - Sink	03/16/22	4.42	None.
Lead Tests - Lone Pine Elementary School - Rooms 23-24 Building - # 20480701						
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20480701-001DW	20480701-001DW23A	Room 23 - Drinking Fountain	03/16/22	ND	None.
2	20480701-002CF	20480701-002CF23A	Room 23 - Sink	03/16/22	ND	None.
3	20480701-003BF	20480701-003BF23A	Room 23 Restroom - Sink	03/16/22	ND	None.
4	20480701-004DW	20480701-004DW23A	Room 24 - Drinking Fountain	03/16/22	ND	None.
5	20480701-005CF	20480701-005CF23A	Room 24 - Sink	03/16/22	ND	None.
6	20480701-006BF	20480701-006BF23A	Room 24 Restroom - Sink	03/16/22	ND	None.
Lead Tests - Lone Pine Elementary School - Rooms 25-26 Building - # 20480702						
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20480702-001DW	20480702-001DW23A	Room 25 - Drinking Fountain	03/16/22	ND	None.
2	20480702-002CF	20480702-002CF23A	Room 25 - Sink	03/16/22	ND	None.
3	20480702-003BF	20480702-003BF23A	Room 25 Restroom - Sink	03/16/22	ND	None.
4	20480702-004DW	20480702-004DW23A	Room 26 - Drinking Fountain	03/16/22	ND	None.
5	20480702-005CF	20480702-005CF23A	Room 26 - Sink	03/16/22	ND	None.
6	20480702-006BF	20480702-006BF23A	Room 26 Restroom - Sink	03/16/22	ND	None.
Lead Tests - Lone Pine Elementary School - C Building - # 20480703						
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20480703-001DW	20480703-001DW23A	Room 10 - Drinking Fountain	03/16/22	1.21	None.
2	20480703-002CF	20480703-002CF23A	Room 10 - Sink	03/16/22	0.93	None.
3	20480703-003DW	20480703-003DW23A	Room 11 - Drinking Fountain	03/16/22	1.14	None.
4	20480703-004CF	20480703-004CF23A	Room 11 - Sink	03/16/22	0.65	None.
5	20480703-005DW	20480703-005DW23A	Room 12 - Drinking Fountain	03/16/22	ND	None.
6	20480703-006CF	20480703-006CF23A	Room 12 - Sink	03/16/22	ND	None.
7	20480703-007DW	20480703-007DW23A	Room 13 - Drinking Fountain	03/16/22	0.60	None.
8	20480703-008CF	20480703-008CF23A	Room 13 - Sink	03/16/22	ND	None.
9	20480703-009DW	20480703-009DW23A	Room 14 - Drinking Fountain	03/16/22	2.60	None.
10	20480703-010CF	20480703-010CF23A	Room 14 - Sink	03/16/22	0.83	None.
11	20480703-011DW	20480703-011DW23A	Room 15 - Drinking Fountain	03/16/22	0.80	None.
12	20480703-012CF	20480703-012CF23A	Room 15 - Sink	03/16/22	ND	None.
13	20480703-013DW	20480703-013DW23A	Room 16 - Drinking Fountain	03/16/22	1.49	None.
14	20480703-014CF	20480703-014CF23A	Room 16 - Sink	03/16/22	0.81	None.
15	20480703-015BF	20480703-015BF23A	Room 16 Unisex Restroom - Sink	03/16/22	1.45	None.
16	20480703-016DW	20480703-016DW23A	Room 17 - Drinking Fountain	03/16/22	1.44	None.
17	20480703-017CF	20480703-017CF23A	Room 17 - Sink	03/16/22	1.00	None.
18	20480703-018BF	20480703-018BF23A	Room 17 Unisex Restroom - Sink	03/16/22	0.96	None.
Lead Tests - Lone Pine Elementary School - B Building - # 20480704						
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20480704-001DW	20480704-001DW23A	Room 18 - Drinking Fountain	03/16/22	1.54	None.
2	20480704-002CF	20480704-002CF23A	Room 18 - Sink	03/16/22	1.05	None.
3	20480704-003BF	20480704-003BF23A	Outside Room 18 Boy's/Girl's - Trough Sink (NE Corner)	03/16/22	4.09	None.
4	20480704-004BF	20480704-004BF23A	Outside Room 18 (North Side) Staff Unisex Restroom - Sink	03/16/22	4.63	None.
5	20480704-005BF	20480704-005BF23A	Outside Room 18 (West Side) Staff Unisex Restroom - Sink	03/16/22	4.61	None.
6	20480704-006DW	20480704-006DW23A	Room 19 - Drinking Fountain	03/16/22	0.97	None.
7	20480704-007CF	20480704-007CF23A	Room 19 - Sink	03/16/22	0.98	None.
8	20480704-008DW	20480704-008DW23A	Room 20 - Drinking Fountain	03/16/22	1.57	None.
9	20480704-009CF	20480704-009CF23A	Room 20 - Sink	03/16/22	0.81	None.
10	20480704-010DW	20480704-010DW23A	Room 21 - Drinking Fountain	03/16/22	0.82	None.

11	20480704-011CF	20480704-011CF23A	Room 21 - Sink	03/16/22	0.99	None.
12	20480704-012DW	20480704-012DW23A	Room 22 - Drinking Fountain	03/16/22	0.60	None.
13	20480704-013CF	20480704-013CF23A	Room 22 - Sink	03/16/22	0.71	None.

**Lead Tests - Lone Pine Elementary School - H Building - # 20480705**

#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20480705-001WB	20480705-001WB23A	Cafeteria - Bottle Filler (Upper?)	03/16/22	ND	This fixture shares a lead/sediment filter with drinking fountain.
2	20480705-002DW	20480705-002DW23A	Cafeteria - Drinking Fountain (Lower?)	03/16/22	ND	This fixture shares a lead/sediment filter with drinking fountain.
3	20480705-003DW	20480705-003DW23A	Gym Lobby - Drinking Fountain (Lower?)	03/16/22	ND	This fixture shares a lead/sediment filter with drinking fountain.
4	20480705-004WB	20480705-004WB23A	Gym Lobby - Bottle Filler (Upper?)	03/16/22	ND	This fixture shares a lead/sediment filter with drinking fountain.
5	20480705-005SF	20480705-005SF23A	Staff Break Room - Sink (Main Fixture)	03/16/22	0.83	None.
6	20480705-006SF	20480705-006SF23A	Staff Break Room - Sink (Insta-Hot)	03/16/22	0.59	None.
7	20480705-007IM	20480705-007IM23A	Staff Break Room Refrigerator - Ice Maker (Left)	04/20/22	7.42	Installed Lead Filter 4/20/22.
8	20480705-008IM	20480705-008IM23A	Staff Break Room Refrigerator - Ice Maker (Right)	06/29/16	2.50	Installed a New Refridgerator without a ice maker, date ?.
9	20480705-009BF	20480705-009BF23A	Unisex Restroom Outside Staff Break Room (Left) - Sink	03/16/22	1.65	None.
10	20480705-010BF	20480705-010BF23A	Unisex Restroom Outside Staff Break Room (Right) - Sink	03/16/22	2.47	None.
11	20480705-011BF	20480705-011BF23A	Across From The Gym Boys/Girls Restroom - Trough Sink	03/16/22	2.33	None.
12	20480705-012KF	20480705-012KF23A	Kitchen - Sink (Pre-rinse) [Left Side - South Wall]	03/16/22	1.52	None.
13	20480705-013KF	20480705-013KF23A	Kitchen - Sink (Pre-rinse) [Right Side - South Wall]	03/16/22	8.09	None.
14	20480705-014KF	20480705-014KF23A	Kitchen - Island Sink	03/16/22	3.48	None.
15	20480705-015KF	20480705-015KF23A	Kitchen - Hand Sink/Eye Wash (On Island)	07/01/22	ND	Lead filter added 5/19/22. Then Faucet Replaced 7/1/22.
16	20480705-016KF	20480705-016KF23A	Kitchen - Hand Sink/Eye Wash (On North Wall)	03/16/22	12.70	None.
17	20480705-017KF	20480705-017KF23A	Kitchen - Food Prep Sink (On North Wall)	03/16/22	2.34	None.
18	20480705-018DW	20480705-018DW23A	Music Room - Drinking Fountain	03/16/22	1.19	None.
19	20480705-019CF	20480705-019CF23A	Music Room - Sink	03/16/22	2.13	None.

**Lead Tests - Lone Pine Elementary School - G Building - # 20480706**

#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20480706-001DW	20480706-001DW23A	Media Center (2nd Floor) Lobby - Drinking Fountain	03/16/22	2.43	None.
2	20480706-002SF	20480706-002SF23A	Media Center (2nd Floor) Work Room - Sink	03/16/22	6.54	None.
3	20480706-003SF	20480706-003SF23A	Media Center (2nd Floor) Conference Room (G) - Sink	03/16/22	3.43	None.
4	20480706-004BF	20480706-004BF23A	Media Center (2nd Floor) Boy's Restroom - Sink	03/16/22	5.32	None.
5	20480706-005BF	20480706-005BF23A	Media Center (2nd Floor) Girl's Restroom - Sink	03/16/22	6.98	None.
6	20480706-006BF	20480706-006BF23A	Media Center (2nd Floor) Unisex Staff Restroom - Sink	03/16/22	3.16	None.
7	20480706-007SF	20480706-007SF23A	Media Center (1st Floor) - Sink	03/16/22	3.68	None.
8	20480706-008BF	20480706-008BF23A	Media Center (1st Floor) Unisex Restroom - Sink	03/16/22	5.08	None.
9	20480706-009BF	20480706-009BF23A	Media Center (1st Floor) Boy's/Girls Restroom - Trough Sink	03/16/22	2.36	None.
10	20480706-010DW	20480706-010DW23A	Media Center (1st Floor) - Drinking Fountain (Upper) [Outdoor]	03/16/22	3.42	None.
11	20480706-011DW	20480706-011DW23A	Media Center (1st Floor) - Drinking Fountain (Lower) [Outdoor]	03/16/22	2.62	None.

\*None Detected (ND) = 0.10 Or Less PPB

  = Fixture Where Water Has The Potential of Being Consumed (All of These Will Be Tested When Testing The Whole School)

\*ODE's required action level is 15 parts per billion (PPB)

\*The E.P.A.'s recommended action level for lead in schools is 20 PPB Oregon's action level for schools changed to 15 PPB in 2019 in accordance with OAR 333-061-0400. In 2021, ODE changed the unit of measurement for reporting to parts per billion (PPB).

\*The E.P.A. action level for copper is 1.30

\*Lead test results will be posted on the MSD/Facilities website within 5 days minus the school map for security purposes.