

## Special Education Facilities

<b>Building Name</b>		<b>Room #</b>
Leighton Area Elementary Center		C153
<b>School Building</b>		<b>Building Description</b>
		A building in which general education programs are operated
<b>Classroom Measurements</b>	<b>Classroom Area Measurement</b>	<b>Max # of students in classroom</b>
35 feet, 0 inches x 23 feet, 0 inches	805sqft	28
<b>Implementation Date</b>		
2022-06-22		
<b>Uploaded Files</b>		

### 1Assurance Check

Assurance Check	Yes	No
The class is maintained as close as appropriate to the ebb and flow of usual school activities	Yes	
The class is located where noise will not interfere with instruction	Yes	
The class is located only in space that is designed for purposes of instruction	Yes	
The class is readily accessible	Yes	
The class is composed of at least 28 square feet per student	Yes	
The location of the class has been maintained for at least 3 school years.		No

<b>Building Name</b>		<b>Room #</b>
Leighton Area Elementary Center		A117
<b>School Building</b>		<b>Building Description</b>
		A building in which general education programs are operated
<b>Classroom Measurements</b>	<b>Classroom Area Measurement</b>	<b>Max # of students in classroom</b>
35 feet, 0 inches x 23 feet, 0 inches	805sqft	28
<b>Implementation Date</b>		

2022-06-22
<b>Uploaded Files</b>

### 2Assurance Check

Assurance Check	Yes	No
The class is maintained as close as appropriate to the ebb and flow of usual school activities	Yes	
The class is located where noise will not interfere with instruction	Yes	
The class is located only in space that is designed for purposes of instruction	Yes	
The class is readily accessible	Yes	
The class is composed of at least 28 square feet per student	Yes	
The location of the class has been maintained for at least 3 school years.		No

<b>Building Name</b>		<b>Room #</b>
Leighton Area MS		C219B
<b>School Building</b>		<b>Building Description</b>
		A building in which general education programs are operated
<b>Classroom Measurements</b>	<b>Classroom Area Measurement</b>	<b>Max # of students in classroom</b>
20 feet, 0 inches x 25 feet, 0 inches	500sqft	17
<b>Implementation Date</b>		
2022-06-22		
<b>Uploaded Files</b>		

### 3Assurance Check

Assurance Check	Yes	No
The class is maintained as close as appropriate to the ebb and flow of usual school activities	Yes	
The class is located where noise will not interfere with instruction	Yes	

The class is located only in space that is designed for purposes of instruction	Yes	
The class is readily accessible	Yes	
The class is composed of at least 28 square feet per student	Yes	
The location of the class has been maintained for at least 3 school years.		No

<b>Building Name</b>		<b>Room #</b>
Leighton Area MS		C123
<b>School Building</b>		<b>Building Description</b>
		A building in which general education programs are operated
<b>Classroom Measurements</b>	<b>Classroom Area Measurement</b>	<b>Max # of students in classroom</b>
25 feet, 0 inches x 31 feet, 0 inches	775sqft	27
<b>Implementation Date</b>		
2022-06-22		
<b>Uploaded Files</b>		

#### 4Assurance Check

Assurance Check	Yes	No
The class is maintained as close as appropriate to the ebb and flow of usual school activities	Yes	
The class is located where noise will not interfere with instruction	Yes	
The class is located only in space that is designed for purposes of instruction	Yes	
The class is readily accessible	Yes	
The class is composed of at least 28 square feet per student	Yes	
The location of the class has been maintained for at least 3 school years.		No

<b>Building Name</b>	<b>Room #</b>
Leighton Area Elementary Center	A215

<b>School Building</b>		<b>Building Description</b>
		A building in which general education programs are operated
<b>Classroom Measurements</b>	<b>Classroom Area Measurement</b>	<b>Max # of students in classroom</b>
35 feet, 0 inches x 23 feet, 0 inches	805sqft	28
<b>Implementation Date</b>		
2022-06-22		
<b>Uploaded Files</b>		

#### 5Assurance Check

Assurance Check	Yes	No
The class is maintained as close as appropriate to the ebb and flow of usual school activities		No
The class is located where noise will not interfere with instruction		No
The class is located only in space that is designed for purposes of instruction		No
The class is readily accessible		No
The class is composed of at least 28 square feet per student		No
The location of the class has been maintained for at least 3 school years.		No

<b>Building Name</b>		<b>Room #</b>
Leighton Area Elementary Center		A210
<b>School Building</b>		<b>Building Description</b>
		A building in which general education programs are operated
<b>Classroom Measurements</b>	<b>Classroom Area Measurement</b>	<b>Max # of students in classroom</b>
35 feet, 0 inches x 23 feet, 0 inches	805sqft	28
<b>Implementation Date</b>		
2022-06-15		
<b>Uploaded Files</b>		

**6Assurance Check**

Assurance Check	Yes	No
The class is maintained as close as appropriate to the ebb and flow of usual school activities	Yes	
The class is located where noise will not interfere with instruction	Yes	
The class is located only in space that is designed for purposes of instruction	Yes	
The class is readily accessible	Yes	
The class is composed of at least 28 square feet per student	Yes	
The location of the class has been maintained for at least 3 school years.		No

<b>Building Name</b>		<b>Room #</b>	
Lehighton Area Elementary Center		C162	
<b>School Building</b>		<b>Building Description</b>	
		A building in which general education programs are operated	
<b>Classroom Measurements</b>	<b>Classroom Area Measurement</b>	<b>Max # of students in classroom</b>	
35 feet, 0 inches x 23 feet, 0 inches	805sqft	28	
<b>Implementation Date</b>			
2022-06-22			
<b>Uploaded Files</b>			

**7Assurance Check**

Assurance Check	Yes	No
The class is maintained as close as appropriate to the ebb and flow of usual school activities	Yes	
The class is located where noise will not interfere with instruction	Yes	
The class is located only in space that is designed for purposes of instruction	Yes	
The class is readily accessible	Yes	
The class is composed of at least 28 square feet per student	Yes	
The location of the class has been maintained for at least 3 school years.		No

<b>Building Name</b>		<b>Room #</b>
Leighton Area Elementary Center		C116
<b>School Building</b>		<b>Building Description</b>
		A building in which general education programs are operated
<b>Classroom Measurements</b>	<b>Classroom Area Measurement</b>	<b>Max # of students in classroom</b>
17 feet, 0 inches x 23 feet, 0 inches	391sqft	13
<b>Implementation Date</b>		
2022-06-22		
<b>Uploaded Files</b>		

#### 8 Assurance Check

Assurance Check	Yes	No
The class is maintained as close as appropriate to the ebb and flow of usual school activities	Yes	
The class is located where noise will not interfere with instruction	Yes	
The class is located only in space that is designed for purposes of instruction	Yes	
The class is readily accessible	Yes	
The class is composed of at least 28 square feet per student	Yes	
The location of the class has been maintained for at least 3 school years.		No

<b>Building Name</b>		<b>Room #</b>
Leighton Area HS		C205
<b>School Building</b>		<b>Building Description</b>
		A building in which general education programs are operated
<b>Classroom Measurements</b>	<b>Classroom Area Measurement</b>	<b>Max # of students in classroom</b>
33 feet, 0 inches x 24 feet, 0 inches	792sqft	28

<b>Implementation Date</b>
2022-06-16
<b>Uploaded Files</b>

**9 Assurance Check**

Assurance Check	Yes	No
The class is maintained as close as appropriate to the ebb and flow of usual school activities	Yes	
The class is located where noise will not interfere with instruction	Yes	
The class is located only in space that is designed for purposes of instruction	Yes	
The class is readily accessible	Yes	
The class is composed of at least 28 square feet per student	Yes	
The location of the class has been maintained for at least 3 school years.		No

<b>Building Name</b>		<b>Room #</b>
Lehighon Area Elementary Center		C239
<b>School Building</b>		<b>Building Description</b>
		A building in which general education programs are operated
<b>Classroom Measurements</b>	<b>Classroom Area Measurement</b>	<b>Max # of students in classroom</b>
35 feet, 0 inches x 23 feet, 0 inches	805sqft	28
<b>Implementation Date</b>		
2022-06-22		
<b>Uploaded Files</b>		

**10 Assurance Check**

Assurance Check	Yes	No
The class is maintained as close as appropriate to the ebb and flow of usual school activities	Yes	

The class is located where noise will not interfere with instruction	Yes	
The class is located only in space that is designed for purposes of instruction	Yes	
The class is readily accessible	Yes	
The class is composed of at least 28 square feet per student	Yes	
The location of the class has been maintained for at least 3 school years.		No

<b>Building Name</b>		<b>Room #</b>
Leighton Area Elementary Center		C252
<b>School Building</b>		<b>Building Description</b>
		A building in which general education programs are operated
<b>Classroom Measurements</b>	<b>Classroom Area Measurement</b>	<b>Max # of students in classroom</b>
35 feet, 0 inches x 23 feet, 0 inches	805sqft	28
<b>Implementation Date</b>		
2022-06-22		
<b>Uploaded Files</b>		

11 Assurance Check

Assurance Check	Yes	No
The class is maintained as close as appropriate to the ebb and flow of usual school activities	Yes	
The class is located where noise will not interfere with instruction	Yes	
The class is located only in space that is designed for purposes of instruction	Yes	
The class is readily accessible	Yes	
The class is composed of at least 28 square feet per student	Yes	
The location of the class has been maintained for at least 3 school years.		No

<b>Building Name</b>	<b>Room #</b>
----------------------	---------------



Lehigh Area HS		D230
<b>School Building</b>		<b>Building Description</b>
		A building in which general education programs are operated
<b>Classroom Measurements</b>	<b>Classroom Area Measurement</b>	<b>Max # of students in classroom</b>
33 feet, 0 inches x 24 feet, 0 inches	792sqft	28
<b>Implementation Date</b>		
2022-06-16		
<b>Uploaded Files</b>		

**12Assurance Check**

Assurance Check	Yes	No
The class is maintained as close as appropriate to the ebb and flow of usual school activities	Yes	
The class is located where noise will not interfere with instruction	Yes	
The class is located only in space that is designed for purposes of instruction	Yes	
The class is readily accessible	Yes	
The class is composed of at least 28 square feet per student	Yes	
The location of the class has been maintained for at least 3 school years.		No

<b>Building Name</b>		<b>Room #</b>
Lehigh Area Elementary Center		A113
<b>School Building</b>		<b>Building Description</b>
		A building in which general education programs are operated
<b>Classroom Measurements</b>	<b>Classroom Area Measurement</b>	<b>Max # of students in classroom</b>
35 feet, 0 inches x 23 feet, 0 inches	805sqft	28
<b>Implementation Date</b>		
2022-06-22		
<b>Uploaded Files</b>		

**13 Assurance Check**

Assurance Check	Yes	No
The class is maintained as close as appropriate to the ebb and flow of usual school activities	Yes	
The class is located where noise will not interfere with instruction	Yes	
The class is located only in space that is designed for purposes of instruction	Yes	
The class is readily accessible	Yes	
The class is composed of at least 28 square feet per student	Yes	
The location of the class has been maintained for at least 3 school years.		No

<b>Building Name</b>		<b>Room #</b>
Leighton Area MS		D203
<b>School Building</b>		<b>Building Description</b>
		A building in which general education programs are operated
<b>Classroom Measurements</b>	<b>Classroom Area Measurement</b>	<b>Max # of students in classroom</b>
16 feet, 0 inches x 35 feet, 0 inches	560sqft	20
<b>Implementation Date</b>		
2022-06-22		
<b>Uploaded Files</b>		

**14 Assurance Check**

Assurance Check	Yes	No
The class is maintained as close as appropriate to the ebb and flow of usual school activities	Yes	
The class is located where noise will not interfere with instruction	Yes	
The class is located only in space that is designed for purposes of instruction	Yes	
The class is readily accessible	Yes	
The class is composed of at least 28 square feet per student	Yes	

The location of the class has been maintained for at least 3 school years.		No
--	--	----

<b>Building Name</b>		<b>Room #</b>
Lehigh Area Elementary Center		C118
<b>School Building</b>		<b>Building Description</b>
		A building in which general education programs are operated
<b>Classroom Measurements</b>	<b>Classroom Area Measurement</b>	<b>Max # of students in classroom</b>
17 feet, 0 inches x 23 feet, 0 inches	391sqft	13
<b>Implementation Date</b>		
2022-06-22		
<b>Uploaded Files</b>		

15 Assurance Check

Assurance Check	Yes	No
The class is maintained as close as appropriate to the ebb and flow of usual school activities	Yes	
The class is located where noise will not interfere with instruction	Yes	
The class is located only in space that is designed for purposes of instruction	Yes	
The class is readily accessible	Yes	
The class is composed of at least 28 square feet per student	Yes	
The location of the class has been maintained for at least 3 school years.		No

<b>Building Name</b>		<b>Room #</b>
Lehigh Area MS		C126
<b>School Building</b>		<b>Building Description</b>
		A building in which general education programs are operated
<b>Classroom Measurements</b>	<b>Classroom Area Measurement</b>	<b>Max # of students in classroom</b>

32 feet, 0 inches x 27 feet, 0 inches	864sqft	30
<b>Implementation Date</b>		
2022-06-22		
<b>Uploaded Files</b>		

**16 Assurance Check**

Assurance Check	Yes	No
The class is maintained as close as appropriate to the ebb and flow of usual school activities	Yes	
The class is located where noise will not interfere with instruction	Yes	
The class is located only in space that is designed for purposes of instruction	Yes	
The class is readily accessible	Yes	
The class is composed of at least 28 square feet per student	Yes	
The location of the class has been maintained for at least 3 school years.		No

<b>Building Name</b>		<b>Room #</b>
Leighton Area Elementary Center		A204
<b>School Building</b>		<b>Building Description</b>
		A building in which general education programs are operated
<b>Classroom Measurements</b>	<b>Classroom Area Measurement</b>	<b>Max # of students in classroom</b>
27 feet, 0 inches x 31 feet, 0 inches	837sqft	29
<b>Implementation Date</b>		
2022-06-22		
<b>Uploaded Files</b>		

**17 Assurance Check**

Assurance Check	Yes	No
-----------------	-----	----

The class is maintained as close as appropriate to the ebb and flow of usual school activities	Yes	
The class is located where noise will not interfere with instruction	Yes	
The class is located only in space that is designed for purposes of instruction	Yes	
The class is readily accessible	Yes	
The class is composed of at least 28 square feet per student	Yes	
The location of the class has been maintained for at least 3 school years.		No

<b>Building Name</b>		<b>Room #</b>
Lehighton Area HS		C101
<b>School Building</b>		<b>Building Description</b>
		A building in which general education programs are operated
<b>Classroom Measurements</b>	<b>Classroom Area Measurement</b>	<b>Max # of students in classroom</b>
33 feet, 0 inches x 19 feet, 0 inches	627sqft	22
<b>Implementation Date</b>		
2022-06-16		
<b>Uploaded Files</b>		

**18Assurance Check**

Assurance Check	Yes	No
The class is maintained as close as appropriate to the ebb and flow of usual school activities	Yes	
The class is located where noise will not interfere with instruction	Yes	
The class is located only in space that is designed for purposes of instruction	Yes	
The class is readily accessible	Yes	
The class is composed of at least 28 square feet per student	Yes	
The location of the class has been maintained for at least 3 school years.		No

<b>Building Name</b>		<b>Room #</b>
Lehigh Area MS		C219A
<b>School Building</b>		<b>Building Description</b>
		A building in which general education programs are operated
<b>Classroom Measurements</b>	<b>Classroom Area Measurement</b>	<b>Max # of students in classroom</b>
20 feet, 0 inches x 25 feet, 0 inches	500sqft	17
<b>Implementation Date</b>		
2022-06-22		
<b>Uploaded Files</b>		

**19 Assurance Check**

Assurance Check	Yes	No
The class is maintained as close as appropriate to the ebb and flow of usual school activities	Yes	
The class is located where noise will not interfere with instruction	Yes	
The class is located only in space that is designed for purposes of instruction	Yes	
The class is readily accessible	Yes	
The class is composed of at least 28 square feet per student	Yes	
The location of the class has been maintained for at least 3 school years.		No

<b>Building Name</b>		<b>Room #</b>
Lehigh Area MS		A125
<b>School Building</b>		<b>Building Description</b>
		A building in which general education programs are operated
<b>Classroom Measurements</b>	<b>Classroom Area Measurement</b>	<b>Max # of students in classroom</b>
27 feet, 0 inches x 34 feet, 0 inches	918sqft	32
<b>Implementation Date</b>		
2022-06-22		
<b>Uploaded Files</b>		

20 Assurance Check

Assurance Check	Yes	No
The class is maintained as close as appropriate to the ebb and flow of usual school activities	Yes	
The class is located where noise will not interfere with instruction	Yes	
The class is located only in space that is designed for purposes of instruction	Yes	
The class is readily accessible	Yes	
The class is composed of at least 28 square feet per student	Yes	
The location of the class has been maintained for at least 3 school years.		No

<b>Building Name</b>		<b>Room #</b>
Leighton Area HS		D134
<b>School Building</b>		<b>Building Description</b>
		A building in which general education programs are operated
<b>Classroom Measurements</b>	<b>Classroom Area Measurement</b>	<b>Max # of students in classroom</b>
32 feet, 6 inches x 24 feet, 0 inches	780sqft	27
<b>Implementation Date</b>		
2022-06-16		
<b>Uploaded Files</b>		

21 Assurance Check

Assurance Check	Yes	No
The class is maintained as close as appropriate to the ebb and flow of usual school activities	Yes	
The class is located where noise will not interfere with instruction	Yes	
The class is located only in space that is designed for purposes of instruction	Yes	
The class is readily accessible	Yes	
The class is composed of at least 28 square feet per student	Yes	

The location of the class has been maintained for at least 3 school years.		No
--	--	----

<b>Building Name</b>		<b>Room #</b>
Leighton Area MS		D211
<b>School Building</b>		<b>Building Description</b>
		A building in which general education programs are operated
<b>Classroom Measurements</b>	<b>Classroom Area Measurement</b>	<b>Max # of students in classroom</b>
15 feet, 0 inches x 23 feet, 0 inches	345sqft	12
<b>Implementation Date</b>		
2022-06-22		
<b>Uploaded Files</b>		

22Assurance Check

Assurance Check	Yes	No
The class is maintained as close as appropriate to the ebb and flow of usual school activities	Yes	
The class is located where noise will not interfere with instruction	Yes	
The class is located only in space that is designed for purposes of instruction	Yes	
The class is readily accessible	Yes	
The class is composed of at least 28 square feet per student	Yes	
The location of the class has been maintained for at least 3 school years.		No

<b>Building Name</b>		<b>Room #</b>
Leighton Area HS		C215
<b>School Building</b>		<b>Building Description</b>
		A building in which general education programs are operated
<b>Classroom Measurements</b>	<b>Classroom Area Measurement</b>	<b>Max # of students in classroom</b>



27 feet, 0 inches x 24 feet, 0 inches	648sqft	23
<b>Implementation Date</b>		
2022-06-16		
<b>Uploaded Files</b>		

**23Assurance Check**

Assurance Check	Yes	No
The class is maintained as close as appropriate to the ebb and flow of usual school activities	Yes	
The class is located where noise will not interfere with instruction	Yes	
The class is located only in space that is designed for purposes of instruction	Yes	
The class is readily accessible	Yes	
The class is composed of at least 28 square feet per student	Yes	
The location of the class has been maintained for at least 3 school years.		No