

Lead Sample Test Results and Actions

LONGFELLOW ELEMENTARY SCHOOL

| Fixture Number | Location | Part of Sampling Plan | Sampling Results (ppm) | Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter (µg/L) – fixture must be immediately removed from service | Bin 2 - Lead concentrations greater than 5.0 µg/L less than 15.0 µg/L – fixture must be fixed, replaced or removed from service | Bin 3 - Lead concentrations less than 5.0 µg/L – no action is required. |
|----------------|--------------------------|-----------------------|------------------------|--|---|---|
| FX 001 | Bottle filler by Rm 107 | Yes | 0.0009 | | | No action |
| FX 002 | Lo fountain by Rm 107 | Yes | 0.0009 | | | No action |
| FX 003 | Hi fountain by Rm 107 | Yes | 0.002 | | | No action |
| FX 004 | Bottle filler TL wing | Yes | 0.0009 | | | No action |
| FX 005 | Lo fountain TL wing | Yes | 0.0009 | | | No action |
| FX 006 | Hi fountain TL wing | Yes | 0.0009 | | | No action |
| FX 007 | Bottle filler by gym | Yes | 0.0009 | | | No action |
| FX 008 | Lo fountain by gym | Yes | 0.0009 | | | No action |
| FX 009 | Hi fountain by gym | Yes | 0.0009 | | | No action |
| FX 010 | Bottle filler K-1 wing | Yes | 0.0009 | | | No action |
| FX 011 | Fountain K-1 wing | Yes | 0.0009 | | | No action |
| FX 012 | Bottle filler 4-6 wing | Yes | 0.0009 | | | No action |
| FX 013 | Lo fountain 4-6 wing | Yes | 0.0009 | | | No action |
| FX 014 | Hi fountain 4-6 wing | Yes | 0.0009 | | | No action |
| FX 015 | Bottle filler by library | Yes | 0.0009 | | | No action |
| FX 016 | Lo fountain by library | Yes | 0.0009 | | | No action |
| FX 017 | Hi fountain by library | Yes | 0.0009 | | | No action |
| FX 018 | Bottle filler 2-3 wing | Yes | 0.0009 | | | No action |
| FX 019 | Lo fountain 2-3 wing | Yes | 0.0009 | | | No action |
| FX 020 | Hi fountain 2-3 wing | Yes | 0.0009 | | | No action |
| FX 021 | | No | | | | |
| FX 022 | | No | | | | |
| FX 023 | | No | | | | |
| FX 024 | | No | | | | |
| FX 025 | | No | | | | |
| FX 026 | | No | | | | |
| FX 027 | | No | | | | |
| FX 028 | | No | | | | |
| FX 029 | | No | | | | |
| FX 030 | | No | | | | |
| FX 031 | | No | | | | |
| FX 032 | | No | | | | |
| FX 033 | Room 107 sink | Yes | 0.0009 | | | No action |
| FX 034 | | No | | | | |
| FX 035 | | No | | | | |
| FX 036 | | No | | | | |
| FX 037 | | No | | | | |

Lead Sample Test Results and Actions

LONGFELLOW ELEMENTARY SCHOOL

| Fixture Number | Location | Part of Sampling Plan | Sampling Results (ppm) | Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter (µg/L) – fixture must be immediately removed from service | Bin 2 - Lead concentrations greater than 5.0 µg/L less than 15.0 µg/L – fixture must be fixed, replaced or removed from service | Bin 3 - Lead concentrations less than 5.0 µg/L – no action is required. |
|----------------|-------------------|-----------------------|------------------------|--|---|---|
| FX 038 | | No | | | | |
| FX 039 | | No | | | | |
| FX 040 | | No | | | | |
| FX 041 | Room 119 sink | Yes | 0.0009 | | | No action |
| FX 042 | | No | | | | |
| FX 043 | | No | | | | |
| FX 044 | | No | | | | |
| FX 045 | | No | | | | |
| FX 046 | | No | | | | |
| FX 047 | | No | | | | |
| FX 048 | | No | | | | |
| FX 049 | | No | | | | |
| FX 050 | | No | | | | |
| FX 051 | | No | | | | |
| FX 052 | | No | | | | |
| FX 053 | | No | | | | |
| FX 054 | | No | | | | |
| FX 055 | | No | | | | |
| FX 056 | Room 204 sink | Yes | 0.002 | | | No action |
| FX 057 | | No | | | | |
| FX 058 | | No | | | | |
| FX 059 | | No | | | | |
| FX 060 | Room 212 sink | Yes | 0.0009 | | | No action |
| FX 061 | | No | | | | |
| FX 062 | | No | | | | |
| FX 063 | | No | | | | |
| FX 064 | | No | | | | |
| FX 065 | | No | | | | |
| FX 066 | | No | | | | |
| FX 067 | | No | | | | |
| FX 068 | | No | | | | |
| FX 069 | | No | | | | |
| FX 070 | | No | | | | |
| FX 071 | | No | | | | |
| FX 072 | | No | | | | |
| FX 073 | | No | | | | |
| FX 074 | Kitchen hand sink | Yes | 0.002 | | | No action |

Lead Sample Test Results and Actions

LONGFELLOW ELEMENTARY SCHOOL

| Fixture Number | Location | Part of Sampling Plan | Sampling Results (ppm) | Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter ($\mu\text{g/L}$) – fixture must be immediately removed from service | Bin 2 - Lead concentrations greater than 5.0 $\mu\text{g/L}$ less than 15.0 $\mu\text{g/L}$ – fixture must be fixed, replaced or removed from service | Bin 3 - Lead concentrations less than 5.0 $\mu\text{g/L}$ – no action is required. |
|----------------|---------------------------|-----------------------|------------------------|---|---|--|
| FX 075 | Kitchen sink left | Yes | 0.002 | | | No action |
| FX 076 | Kitchen sink right | Yes | 0.002 | | | No action |
| FX 077 | Kit hand sink serv lin | Yes | 0.003 | | | No action |
| FX 078 | Kit. serve line left frnt | Yes | 0.0009 | | | No action |
| FX 079 | | No | | | | |
| FX 080 | Kit. Dish room left | Yes | 0.001 | | | No action |
| FX 081 | Kit. Dish room right | Yes | 0.0009 | | | No action |
| FX 082 | Kit. Dish room hand sink | Yes | 0.002 | | | No action |
| FX 083 | Kit. Dish room sink | Yes | 0.0009 | | | No action |
| FX 084 | Kit. Dish room sprayer | Yes | 0.001 | | | No action |