

# Lead Sample Test Results and Actions

## VALLEY VIEW ELEMENTARY SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter ( $\mu\text{g/L}$ ) – fixture must be immediately removed from service	Bin 2 - Lead concentrations greater than 5.0 $\mu\text{g/L}$ less than 15.0 $\mu\text{g/L}$ – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 $\mu\text{g/L}$ – no action is required.
FX 001	Room A1 drinking fountain	Yes	0.0009			No action required
FX 002		No				
FX 003		No				
FX 004	Room A2 Sink	Yes	0.0009			No action required
FX 005	Room A3 drinking fountain	Yes	0.0009			No action required
FX 006		No				
FX 007	Room A4 drinking fountain	Yes	0.001			No action required
FX 008		No				
FX 009	Room A5 drinking fountain	Yes	0.001			No action required
FX 010		No				
FX 011	Room A6 drinking fountain	Yes	0.0009			No action required
FX 012		No				
FX 013	Main Entrance bottle filler	Yes	0.0009			No action required
FX 014	Main Entrance drinking fountain	Yes	0.0009			No action required
FX 015		No				
FX 016		No				
FX 017		No				
FX 018		No				
FX 019		No				
FX 020		No				
FX 021	Room K1 sink	Yes	0.003			No action required
FX 022		No				
FX 023		No				
FX 024		No				
FX 025	Kitchen sink	Yes	0.0009			No action required
FX 026	Kitchen Sprayer	Yes	0.0009			No action required

# Lead Sample Test Results and Actions

## VALLEY VIEW ELEMENTARY SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter (µg/L) – fixture must be immediately removed from service	Bin 2 - Lead concentrations greater than 5.0 µg/L less than 15.0 µg/L – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 µg/L – no action is required.
FX 027		No				
FX 028		No				
FX 029		No				
FX 030		No				
FX 031		No				
FX 032		No				
FX 033		No				
FX 034		No				
FX 035	Room B1 drinking fountain	Yes	0.001			No action required
FX 036		No				
FX 037	Room B1 drinking fountain	Yes	0.001			No action required
FX 038		No				
FX 039	Room B3 drinking fountain	Yes	0.001			No action required
FX 040		No				
FX 041	Room B4 drinking fountain	Yes	0.0009			No action required
FX 042		No				
FX 043	Room C1 drinking fountain	Yes	0.001			No action required
FX 044		No				
FX 045	Room C2 drinking fountain	Yes	0.002			No action required
FX 046		No				
FX 047	Room C3 drinking fountain	Yes	0.002			No action required
FX 048		No				
FX 049	Room C4 drinking fountain	Yes	0.001			No action required
FX 050						
FX 051	Room C5 drinking fountain	Yes	0.0009			No action required

## Lead Sample Test Results and Actions

### VALLEY VIEW ELEMENTARY SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter ( $\mu\text{g/L}$ ) – fixture must be immediately removed from service	Bin 2 - Lead concentrations greater than 5.0 $\mu\text{g/L}$ less than 15.0 $\mu\text{g/L}$ – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 $\mu\text{g/L}$ – no action is required.
FX 052		No				
FX 053		No				
FX 054		No				
FX 055		No				
FX 056		No				
FX 057		No				
FX 058		No				
FX 059		No				
FX 060	Library drinking fountain	Yes	0.003			No action required
FX 061		No				
FX 062	Room B5 drinking fountain	Yes	0.0009			No action required
FX 063		No				
FX 064		No				
FX 065		No				
FX 066	Main Entrance drinking fountain	Yes	0.0009			No action required
FX 067	C wing hall drinking fountain	Yes	0.001			No action required
FX 068	C wing hall drinking fountain	Yes	0.0009			No action required
FX 069	B wing hall drinking fountain	Yes	0.003			No action required