

# Lead Sample Test Results and Actions

## NORTH MIDDLE SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter (µg/L) – fixture must be immediately removed from service	Bin 2 - Lead concentrations greater than 5.0 µg/L less than 15.0 µg/L – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 µg/L – no action is required.
FX 001		No				
FX 002		No				
FX 003		No				
FX 004		No				
FX 005		No				
FX 006	Kitchen hand sink	Yes	0.0009			No action
FX 007	Kitchen sink	Yes	0.0009			No action
FX 008	Kitchen sink	Yes	0.0009			No action
FX 009		No				
FX 010		No				
FX 011		No				
FX 012		No				
FX 013		No				
FX 014		No				
FX 015		No				
FX 016		No				
FX 017		No				
FX 018		No				
FX 019		No				
FX 020	Room 101 sink	Yes	0.0009			No action
FX 021		No				
FX 022		No				
FX 023	Room 101 sink	Yes	0.0009			No action
FX 024		No				
FX 025		No				
FX 026	Main office sink nurse	Yes	0.003			No action
FX 027		No				
FX 028		No				
FX 029	Room 117 sink	Yes	0.0009			No action
FX 030		No				
FX 031		No				
FX 032		No				
FX 033		No				
FX 034	Room 116 sink	Yes	0.0009			No action
FX 035		No				
FX 036		No				
FX 037		No				

# Lead Sample Test Results and Actions

## NORTH MIDDLE SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter (µg/L) – fixture must be immediately removed from service	Bin 2 - Lead concentrations greater than 5.0 µg/L less than 15.0 µg/L – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 µg/L – no action is required.
FX 038		No				
FX 039		No				
FX 040	Hi fountain 1/F west	Yes	0.001			No action
FX 041	Low fountain 1/F west	Yes	0.002			No action
FX 042		No				
FX 043	Hi fountain by café	Yes	0.0009			No action
FX 044	Low fountain by café	Yes	0.0009			No action
FX 045	Bottle filler by café	Yes	0.0009			No action
FX 046		No				
FX 047		No				
FX 048	Hi fnt griz den east	Yes	0.0009			No action
FX 049	Low fnt griz den east	Yes	0.0009			No action
FX 050		No				
FX 051		No				
FX 052		No				
FX 053	Bottle filler griz den E	Yes	0.0009			No action
FX 054		No				
FX 055		No				
FX 056		No				
FX 057		No				
FX 058		No				
FX 059		No				
FX 060		No				
FX 061		No				
FX 062		No				
FX 063		No				
FX 064		No				
FX 065		No				
FX 066		No				
FX 067		No				
FX 068		No				
FX 069		No				
FX 070		No				
FX 071		No				
FX 072		No				
FX 073		No				
FX 074		No				

# Lead Sample Test Results and Actions

## NORTH MIDDLE SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter (µg/L) – fixture must be immediately removed from service	Bin 2 - Lead concentrations greater than 5.0 µg/L less than 15.0 µg/L – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 µg/L – no action is required.
FX 075		No				
FX 076		No				
FX 077		No				
FX 078	Hi fountain east gym	Yes	0.0009			No action
FX 079	Low fountain east gym	Yes	0.0009			No action
FX 080	Bottle filler east gym	Yes	0.0009			No action
FX 081	Fountain west gym	Yes	0.0009			No action
FX 082	Bottle filler west gym	Yes	0.0009			No action
FX 083		No				
FX 084		No				
FX 085		No				
FX 086		No				
FX 087		No				
FX 088		No				
FX 089		No				
FX 090		No				
FX 091		No				
FX 092		No				
FX 093		No				
FX 094		No				
FX 095		No				
FX 096		No				
FX 097	Room 311 sink	Yes	0.0009			No action
FX 098		No				
FX 099		No				
FX 100		No				
FX 101		No				
FX 102		No				
FX 103	Fountain extreme hall	Yes	0.0009			No action
FX 104		No				
FX 105		No				
FX 106	Hi fnt griz den west	Yes	0.0009			No action
FX 107	Low fnt griz den west	Yes	0.0009			No action
FX 108	Bottle filler griz den W	Yes	0.0009			No action
FX 109		No				
FX 110		No				
FX 111		No				

## Lead Sample Test Results and Actions

### NORTH MIDDLE SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter ( $\mu\text{g/L}$ ) – fixture must be immediately removed from service	Bin 2 - Lead concentrations greater than 5.0 $\mu\text{g/L}$ less than 15.0 $\mu\text{g/L}$ – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 $\mu\text{g/L}$ – no action is required.
FX 112		No				
FX 113		No				
FX 114		No				
FX 115		No				
FX 116		No				
FX 117		No				
FX 118		No				
FX 119		No				
FX 120	Room 203 sink	Yes	0.002			No action
FX 121		No				
FX 122		No				
FX 123		No				
FX 124	Room 204 sink	Yes	0.001			No action
FX 125	Room 205 sink	Yes	0.001			No action
FX 126		No				
FX 127		No				
FX 128	Room 206 sink	Yes	0.002			No action
FX 129		No				
FX 130	Room 207 sink	Yes	0.001			No action
FX 131		No				
FX 132		No				
FX 133		No				
FX 134		No				
FX 135		No				
FX 136	2/F hi fountain	Yes	0.0009			No action
FX 137	2/F low fountain	Yes	0.0009			No action
FX 138	2/F bottle filler	Yes	0.0009			No action