

DISTRICT WIDE LEAD IN DRINKING WATER
SAYVILLE UNION FREE SCHOOL DISTRICT
SUMMARY REPORT AS OF
12/8/2016

CHERRY AVENUE ELEMENTARY SCHOOL	
First Draw Samples Collected	96
First Draw Samples > 15 Parts Per Billion	7
Number of Sources Capped or Taken Off Line	1
Post Remediation Samples <= 15 PPB	0
Number of Sources Pending For Remediation	6
<i>Maximum Pb Concentration Observed</i>	<i>76</i>

Lead in Drinking Water Test Results

As of 12/8/16

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
WF Outside Nurses Office	WF	<2.5	-	-	None	-	-
Café	WF	<2.5	-	-	None	-	-
WF Outside Faculty Room	WF	<2.5	-	-	None	-	-
WF Outside Room 103	WF	<2.5	-	-	None	-	-
Room 103	WF	<2.5	-	-	None	-	-
Room 104	WF	<2.5	-	-	None	-	-
Room 102	WF	9.5	-	-	None	-	-
Room 106	WF	7.7	-	-	None	-	-
WF Outside Gym	WF	<2.5	-	-	None	-	-
Room 111B	WF	<2.5	-	-	None	-	-
Room 113	WF	<2.5	-	-	None	-	-
Room 112	WF	<2.5	-	-	None	-	-
Room 115	WF	<2.5	-	-	None	-	-
Room 117	WF	<2.5	-	-	None	-	-
Room 116	WF	<2.5	-	-	None	-	-
Room 114	WF	<2.5	-	-	None	-	-
Room 121	WF	<2.5	-	-	None	-	-
Room 120	WF	<2.5	-	-	None	-	-
Room 123	WF	15	-	-	None	-	-
WF Outside Room 123	WF	<2.5	-	-	None	-	-
Room 125	WF	7.9	-	-	None	-	-
Room 127	WF	7.5	-	-	None	-	-
Room 126	WF	<2.5	-	-	None	-	-

Lead in Drinking Water Test Results

As of 12/8/16

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room 128	WF	<2.5	-	-	None	-	-
Kitchen Pot Filler by Serving Line	SK	6	-	-	None	-	-
Kitchen Pot Filler in Back	SK	5.8	-	-	None	-	-
Faculty Room	SK	5.6	-	-	None	-	-
Room 105	SK	3.3	-	-	None	-	-
Room 101	SK	9.5	-	-	None	-	-
Nurse's Office	SK	11	-	-	None	-	-
Room 109	SK	4.2	-	-	None	-	-
Room 108	SK	76			FR	SIGN	45 (7/28/2016)
Room 124	SK	6	-	-	None	-	-
Room 129	SK	17	<2.5	<2.5	FR	Flush/Clean Aerator	Pending Retest
Room 111A	WF	3.1	-	-	None	-	-
Room 110	WF	15	<2.5	<2.5	None	-	-
Room 122	WF	17	12	4.7	FR	TBD	
Main Custodial Office BR	SK	2	-	-	None	-	-
Main Custodial Office	SS	<1.0	-	-	None	-	-
Kitchen BR	SK	12	-	-	None	-	-
Kitchen Prep @ (A)	SK	1.1	-	-	None	-	-
Kitchen Prep @ (B)	SK	<1.0	-	-	None	-	-
Kitchen Prep @ (C)	SK	48			FR		
Kitchen Island	SK	1.7	-	-	None	-	-
Kitchen Dishwash	SP	<1.0	-	-	None	-	-
Art Room	SK	<1.0	-	-	None	-	-

Lead in Drinking Water Test Results

As of 12/8/16

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Nurse's Office BR	SK	2.6	-	-	None	-	-
Faculty BR by Cafe	SK	2.6	-	-	None	-	-
Faculty BR by MPR	SK	4.2	-	-	None	-	-
BR by Main Office	SK	<1.0	-	-	None	-	-
Principal's Office BR	SK	<1.0	-	-	None	-	-
Speech Language Room	SK	21			FR		
Room 101	WF	3.1	-	-	None	-	-
Room 101 BR	SK	24			FR		
Room 102	SK	3.7	-	-	None	-	-
Room 102 BR	SK	7.1	-	-	None	-	-
Room 104	SK	1.4	-	-	None	-	-
Room 103	SK	3.4	-	-	None	-	-
Room 103 BR	SK	3.4	-	-	None	-	-
Room 105	WF	<1.0	-	-	None	-	-
Room 105 BR	SK	1.9	-	-	None	-	-
Room 106	SK	2.9	-	-	None	-	-
Room 106 BR	SK	5.4	-	-	None	-	-
Girl's BR by RM 111 @ (A)	SK	<1.0	-	-	None	-	-
Girl's BR by RM 111 @ (B)	SK	2.5	-	-	None	-	-
Girl's BR by RM 111 @ (C)	SK	1.7	-	-	None	-	-
Girl's BR by RM 111 @ (D)	SK	7.1	-	-	None	-	-
Boy's BR by RM 111 @ (A)	SK	2.5	-	-	None	-	-
Boy's BR by RM 111 @ (B)	SK	3.6	-	-	None	-	-

Lead in Drinking Water Test Results

As of 12/8/16

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Boy's BR by RM 111 @ (C)	SK	12	-	-	None	-	-
Boy's BR by RM 111 @ (D)	SK	6.8	-	-	None	-	-
Room 111B	SK	11	-	-	None	-	-
Room 110	SK	17			FR		
Room 113	SK	1.7	-	-	None	-	-
Room 112	SK	1.7	-	-	None	-	-
Room 115	SK	<1.0	-	-	None	-	-
Room 114	SK	2.4	-	-	None	-	-
Room 117	SK	1.3	-	-	None	-	-
Room 116	SK	5	-	-	None	-	-
BR by Library	SK	2	-	-	None	-	-
Room 121	SK	6.2	-	-	None	-	-
Room 120	SK	3.3	-	-	None	-	-
Room 123	SK	5.4	-	-	None	-	-
Girl's BR by RM 123 @ (A)	SK	5.5	-	-	None	-	-
Girl's BR by RM 123 @ (B)	SK	6.3	-	-	None	-	-
Girl's BR by RM 123 @ (C)	SK	5.2	-	-	None	-	-
Boy's BR by RM 123 @ (A)	SK	2.2	-	-	None	-	-
Boy's BR by RM 123 @ (C)	SK	3.9	-	-	None	-	-
Room 125	SK	4.8	-	-	None	-	-
Room 122	SK	2.7	-	-	None	-	-
Room 127	SK	3.3	-	-	None	-	-
Room 124	WF	2.4	-	-	None	-	-

Lead in Drinking Water Test Results

As of 12/8/16

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room 129	WF	1.2	-	-	None	-	-
Room 126	SK	3	-	-	None	-	-
Room 128	SK	8.5	-	-	None	-	-
Gym Coaches Office BR	SK	8.3	-	-	None	-	-

DISTRICT WIDE LEAD IN DRINKING WATER
SAYVILLE UNION FREE SCHOOL DISTRICT
SUMMARY REPORT AS OF
12/8/2016

GARFIELD AVENUE MAINTENANCE SHOP	
First Draw Samples Collected	6
First Draw Samples > 15 Parts Per Billion	0
Number of Sources Capped or Taken Off Line	0
Post Remediation Samples <= 15 PPB	0
Number of Sources Pending For Remediation	0
<i>Maximum Pb Concentration Observed</i>	<i>6.9</i>

Lead in Drinking Water Test Results

As of 12/8/16

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Kitchenette	SK	<2.5	-	-	None	-	-
Women's BR	SK	<2.5	-	-	None	-	-
Men's BR	SK	<2.5	-	-	None	-	-
Garage @ (A)	WF	<2.5	-	-	None	-	-
Garage @ (B)	WF	3.6	-	-	None	-	-
Garage	SS	6.9	-	-	None	-	-

DISTRICT WIDE LEAD IN DRINKING WATER
SAYVILLE UNION FREE SCHOOL DISTRICT
SUMMARY REPORT AS OF
12/8/2016

LINCOLN AVENUE ELEMENTARY SCHOOL	
First Draw Samples Collected	117
First Draw Samples > 15 Parts Per Billion	6
Number of Sources Capped or Taken Off Line	0
Post Remediation Samples <= 15 PPB	0
Number of Sources Pending For Remediation	6
<i>Maximum Pb Concentration Observed</i>	<i>34</i>

Lead in Drinking Water Test Results

As of 12/8/16

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Café	WF	<2.5	-	-	None	-	-
Room 134	WF	<2.5	-	-	None	-	-
Room 133	WF	<2.5	-	-	None	-	-
Room 136	WF	4	-	-	None	-	-
Room 138	WF	2.7	-	-	None	-	-
Room 135	WF	6.8	-	-	None	-	-
Room 137	WF	3.2	-	-	None	-	-
Room 140	WF	5.8	-	-	None	-	-
Room 142	WF	<2.5	-	-	None	-	-
Room 139	WF	<2.5	-	-	None	-	-
Room 141	WF	<2.5	-	-	None	-	-
Library	WF	<2.5	-	-	None	-	-
Room 152	WF	<2.5	-	-	None	-	-
Room 151	WF	<2.5	-	-	None	-	-
Girls LR	WF	<2.5	-	-	None	-	-
Boys LR	WF	<2.5	-	-	None	-	-
Room 121	WF	<2.5	-	-	None	-	-
Room 123	WF	8.4	-	-	None	-	-
Room 119	WF	<2.5	-	-	None	-	-
Room 117	WF	<2.5	-	-	None	-	-
Room 118	WF	<2.5	-	-	None	-	-
Room 120	WF	<2.5	-	-	None	-	-
Room 115	WF	<2.5	-	-	None	-	-

Lead in Drinking Water Test Results

As of 12/8/16

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room 113	WF	8.9	-	-	None	-	-
Room 114	WF	<2.5	-	-	None	-	-
Room 116	WF	<2.5	-	-	None	-	-
Room 111	WF	2.9	-	-	None	-	-
Room 110	WF	<2.5	-	-	None	-	-
Room 112	WF	4.8	-	-	None	-	-
Room 130 SK (Left)	SK	6.2	-	-	None	-	-
Room 155	SK	<1.0	-	-	None	-	-
Room 154	SK	<1.0	-	-	None	-	-
Room 153	SK	2.3	-	-	None	-	-
Room 124	SK	3.6	-	-	None	-	-
Room 125	SK	1.9	-	-	None	-	-
Main Office	SK	3.4	-	-	None	-	-
Nurses Office	SK	6.5	-	-	None	-	-
Kitchen Prep SK (Left)	SK	1.9	-	-	None	-	-
Kitchen Prep SK (Right)	SK	1.9	-	-	None	-	-
Room 132	WF	3.1	-	-	None	-	-
Room 131	WF	6.9	-	-	None	-	-
Kindergarten Rotunda	WF	1.4	-	-	None	-	-
WF by Room 130	WF	14	-	-	None	-	-
North Hallway Ladies BR @ (A)	SK	1.9	-	-	None	-	-
North Hallway Ladies BR @ (B)	SK	2.4	-	-	None	-	-
Room 109	SK	7.9	-	-	None	-	-

Lead in Drinking Water Test Results

As of 12/8/16

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Teacher's Lounge	SK	3.9	-	-	None	-	-
Art Room @ (A)	SK	<1.0	-	-	None	-	-
Art Room @ (B)	SK	<1.0	-	-	None	-	-
Art Room @ (C)	SK	<1.0	-	-	None	-	-
Nurse's Office BR	SK	<1.0	-	-	None	-	-
Main Office BR	SK	2.2	-	-	None	-	-
Library Staff BR	SK	4.6	-	-	None	-	-
Library Student BR	SK	2.4	-	-	None	-	-
Room 106	SK	6.6	-	-	None	-	-
Room 130 (right)	SK	11	-	-	None	-	-
Boy's BR by RM 129 @ (A)	SK	2.5	-	-	None	-	-
Girl's BR by RM 129 @ (A)	SK	2.8	-	-	None	-	-
Girl's BR by RM 129 @ (B)	SK	2.3	-	-	None	-	-
Girl's BR by RM 129 @ (C)	SK	1	-	-	None	-	-
Girl's BR by RM 129 @ (D)	SK	2.1	-	-	None	-	-
CC by RM 129	SS	1.8	-	-	None	-	-
Room 131	SK	5.7	-	-	None	-	-
Room 132	SK	8.5	-	-	None	-	-
Room 133	SK	3.6	-	-	None	-	-
Room 134	SK	3.4	-	-	None	-	-
Room 135	SK	2.2	-	-	None	-	-
Room 136	SK	1.7	-	-	None	-	-
Room 137	SK	4	-	-	None	-	-

Lead in Drinking Water Test Results

As of 12/8/16

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room 138	SK	8.5	-	-	None	-	-
Room 139	SK	5.8	-	-	None	-	-
Room 140	SK	4.3	-	-	None	-	-
Room 141	SK	4.9	-	-	None	-	-
Room 142	SK	5.9	-	-	None	-	-
Room 155 BR	SK	2.9	-	-	None	-	-
Room 151 Counter @ (A)	SK	2.7	-	-	None	-	-
Room 151 Counter @ (B)	SK	4.9	-	-	None	-	-
Room 152	SK	6	-	-	None	-	-
Room 152 BR	SK	30			FR		
Room 153	WF	1.1	-	-	None	-	-
Room 154 BR	SK	4	-	-	None	-	-
CC by RM 154	SS	34			FR		
Kindergarten Rotunda	SK	4.4	-	-	None	-	-
South Hallway Men's BR	SK	1.7	-	-	None	-	-
South Hallway Women's BR @ (A)	SK	3.3	-	-	None	-	-
South Hallway Women's BR @ (B)	SK	3.3	-	-	None	-	-
Coach's Office	SK	20			FR		
Girl's LR @ (A)	SK	6.3	-	-	None	-	-
Girl's LR @ (B)	SK	8.9	-	-	None	-	-
Boy's LR @ (A)	SK	7.6	-	-	None	-	-
Boy's LR @ (B)	SK	23			FR		
Room 124 BR	SK	3	-	-	None	-	-

Lead in Drinking Water Test Results

As of 12/8/16

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room 125 BR	SK	1.6	-	-	None	-	-
Room 123	SK	1.9	-	-	None	-	-
Room 121	SK	4.2	-	-	None	-	-
Room 117	SK	1.8	-	-	None	-	-
Room 118	SK	<1.0	-	-	None	-	-
Room 119	SK	2.6	-	-	None	-	-
Room 120	SK	2.1	-	-	None	-	-
Room 113	SK	4	-	-	None	-	-
Room 114	SK	2	-	-	None	-	-
Room 115	SK	2.9	-	-	None	-	-
Room 116	SK	2.2	-	-	None	-	-
Room 110	SK	4.6	-	-	None	-	-
Room 111	SK	5.2	-	-	None	-	-
Room 112	SK	17			FR		
East Hallway Men's BR @ (A)	SK	11	-	-	None	-	-
East Hallway Men's BR @ (B)	SK	2.1	-	-	None	-	-
CC by Dining Room	SS	2.5	-	-	None	-	-
Library CC	SS	<1.0	-	-	None	-	-
Custodian's Office CC	SS	7.8	-	-	None	-	-
Custodian's Office Children's BR by Basement	SK	<1.0	-	-	None	-	-
Custodian's Office Children's BR by Storage	SK	<1.0	-	-	None	-	-
Boiler Room	SK	18			FR		
Kitchen Sanitizer Station	SPRAY	2.2	-	-	None	-	-

Lead in Drinking Water Test Results

As of 12/8/16

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Kitchen Island Handwash	SK	3.2	-	-	None	-	-
Kitchen Warewashing Station	SK	3.5	-	-	None	-	-

DISTRICT WIDE LEAD IN DRINKING WATER
SAYVILLE UNION FREE SCHOOL DISTRICT
SUMMARY REPORT AS OF
12/8/2016

OLD JUNIOR HIGH SCHOOL	
First Draw Samples Collected	19
First Draw Samples > 15 Parts Per Billion	5
Number of Sources Capped or Taken Off Line	5
Post Remediation Samples <= 15 PPB	0
Number of Sources Pending For Remediation	0
<i>Maximum Pb Concentration Observed</i>	<i>451</i>

Lead in Drinking Water Test Results

As of 12/8/16

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
WF by Auditorium	WF	<1.0	-	-	None	-	-
RM 130	SK	9.9	-	-	None	-	-
WF by RM 119	WF	<1.0	-	-	None	-	-
WF by RM 156	WF	1	-	-	None	-	-
Kitchen Prep	SK	451			FR	CAP	-
WF by RM 211A	WF	1.1	-	-	None	-	-
WF by RM 204	WF	<1.0	-	-	None	-	-
WF by RM 321	WF	<1.0	-	-	None	-	-
RM 320	SK	12	-	-	None	-	-
WF by RM 303	WF	1.2	-	-	None	-	-
Kitchen BR	SK	29			FR	SIGN	-
IMC BR in Old Gym	SK	11	-	-	None	-	-
IMC BR in Hall-Left	SK	13	-	-	None	-	-
IMC BR in Hall-Right	SK	9	-	-	None	-	-
IMC CC	SS	14	-	-	None	-	-
Upper LR BR	SK	10	-	-	None	-	-
Upper LR Office	SK	21			FR	CAP	-
Lower LR BR @ (A)	SK	36			FR	SIGN	-
Lower LR BR @ (B)	SK	48			FR	SIGN	-

DISTRICT WIDE LEAD IN DRINKING WATER
SAYVILLE UNION FREE SCHOOL DISTRICT
SUMMARY REPORT AS OF
12/8/2016

SAYVILLE ADMINISTRATION BUILDING	
First Draw Samples Collected	10
First Draw Samples > 15 Parts Per Billion	2
Number of Sources Capped or Taken Off Line	2
Post Remediation Samples <= 15 PPB	0
Number of Sources Pending For Remediation	0
<i>Maximum Pb Concentration Observed</i>	<i>232</i>

Lead in Drinking Water Test Results

As of 12/8/16

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
1st Floor Kitchen	SK	<2.5	-	-	None	-	-
Basement Kitchen Conference Room	SK	232			FR	SIGN	31 (7/28/2016)
Men's Main BR @ (A)	SK	<2.5	-	-	None	-	-
Men's Main BR @ (B)	SK	<2.5	-	-	None	-	-
Women's Main BR @ (A)	SK	4	-	-	None	-	-
Women's Main BR @ (B)	SK	<2.5	-	-	None	-	-
Superintendant's Office BR	SK	5.8	-	-	None	-	-
Lower Level Men's BR	SK	3.6	-	-	None	-	-
Lower Level Women's BR	SK	<2.5	-	-	None	-	-
Print Shop Kitchen	SK	140			FR	SIGN	-

DISTRICT WIDE LEAD IN DRINKING WATER
SAYVILLE UNION FREE SCHOOL DISTRICT
SUMMARY REPORT AS OF
12/8/2016

SAYVILLE HIGH SCHOOL	
First Draw Samples Collected	254
First Draw Samples > 15 Parts Per Billion	49
Number of Sources Capped or Taken Off Line	0
Post Remediation Samples <= 15 PPB	0
Number of Sources Pending For Remediation	49
<i>Maximum Pb Concentration Observed</i>	<i>1193</i>

Lead in Drinking Water Test Results

As of 12/8/16

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Gym Main Entrance	WF	<1.0	-	-	None	-	-
Boys LR Entrance	WF	<1.0	-	-	None	-	-
Wellness Center (Left)	WF	<1.0	-	-	None	-	-
Wellness Center (Right)	WF	<1.0	-	-	None	-	-
Girls LR	WF	1.3	-	-	None	-	-
Girls Dugout	WF	5.1	-	-	None	-	-
Boys Dugout	WF	2	-	-	None	-	-
Hall by Room 134	WF	<1.0	-	-	None	-	-
Hall by Room 134 (Left)	WF	<1.0	-	-	None	-	-
Hall by Room 134 (Right)	WF	<1.0	-	-	None	-	-
Hall by Room 122 (Left)	WF	<1.0	-	-	None	-	-
Hall by Room 122 (Right)	WF	<1.0	-	-	None	-	-
Café A/B (Left)	WF	<1.0	-	-	None	-	-
Café A/B (Right)	WF	<1.0	-	-	None	-	-
Hall by Room 104 (Left)	WF	<1.0	-	-	None	-	-
Hall by Room 104 (Right)	WF	<1.0	-	-	None	-	-
Hall by Room 110 (Left)	WF	<1.0	-	-	None	-	-
Hall by Room 110 (Right)	WF	<1.0	-	-	None	-	-
Hall by Room 98 (Left)	WF	<1.0	-	-	None	-	-
Hall by Room 98 (Right)	WF	<1.0	-	-	None	-	-
Outside Auditorium	WF	<1.0	-	-	None	-	-
Hall by Room 127 (Left)	WF	<1.0	-	-	None	-	-
Hall by Room 127 (Right)	WF	<1.0	-	-	None	-	-
Hall by Room 125 (Left)	WF	<1.0	-	-	None	-	-

Lead in Drinking Water Test Results

As of 12/8/16

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Hall by Room 125 (Right)	WF	<1.0	-	-	None	-	-
Hall by Room 200A (Left)	WF	<1.0	-	-	None	-	-
Hall by Room 200A (Right)	WF	<1.0	-	-	None	-	-
Hall by Room 206 (Left)	WF	<1.0	-	-	None	-	-
Hall by Room 206 (Right)	WF	<1.0	-	-	None	-	-
Hall by Room 213 (Left)	WF	<1.0	-	-	None	-	-
Hall by Room 213 (Right)	WF	<1.0	-	-	None	-	-
Hall by Room 220 (Left)	WF	<1.0	-	-	None	-	-
Hall by Room 220 (Right)	WF	<1.0	-	-	None	-	-
Hall by Room 234 (Left)	WF	<1.0	-	-	None	-	-
Hall by Room 234 (Right)	WF	<1.0	-	-	None	-	-
Boys Coaches Office BR	SK	<1.0	-	-	None	-	-
Boys LR	SK	2.2	-	-	None	-	-
Girls Coaches Office BR	SK	6.8	-	-	None	-	-
Faculty Dining 1st Fl	SK	1.5	-	-	None	-	-
Kitchen Prep	SK	4.4	-	-	None	-	-
2nd Fl Faculty Room	SK	3	-	-	None	-	-
2nd Fl Teachers Room	SK	4.8	-	-	None	-	-
Nurse's Office	SK	16	5.9	1.5	FR	Completed FR	Pending Retest
Room 200D	SK	1.8	-	-	None	-	-
Football Field	SP	1.8	-	-	None	-	-
Girls' Softball (Outside Dugout)	SP	1.5	-	-	None	-	-
Baseball Field/Tennis Court	SP	6.3	-	-	None	-	-
Hall by Room L30	WF	<1.0	-	-	None	-	-

Lead in Drinking Water Test Results

As of 12/8/16

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Hall by Room 113 (Left)	WF	7.2	-	-	None	-	-
Hall by Room 113 (Right)	WF	3	-	-	None	-	-
Café C	WF	14	-	-	None	-	-
Girl's BR in Lote Hall @ (A)	SK	3.4	-	-	None	-	-
Girl's BR in Lote Hall @ (B)	SK	5	-	-	None	-	-
Girl's BR in Lote Hall @ (C)	SK	8.3	-	-	None	-	-
Girl's BR in Lote Hall @ (D)	SK	12	-	-	None	-	-
Girl's BR in Lote Hall @ (E)	SK	3.2	-	-	None	-	-
Boy's BR in Lote Hall @ (A)	SK	1.5	-	-	None	-	-
Boy's BR in Lote Hall @ (B)	SK	5	-	-	None	-	-
Boy's BR in Lote Hall @ (C)	SK	8.2	-	-	None	-	-
Boy's BR in Lote Hall @ (E)	SK	8.7	-	-	None	-	-
Library Prep Room	SK	5.8	-	-	None	-	-
CC by RM in Science Hall	SS	<1.0	-	-	None	-	-
Trainer's Room	SK	6.9	-	-	None	-	-
Trainer's Room	SPRAY	17			FR		
Trainer's Room	IM	<1.0	-	-	None	-	-
Men's BR in Gym Area	SK	7.3	-	-	None	-	-
CC #1	SS	<1.0	-	-	None	-	-
Boy's LR BR @ (A)	SK	1	-	-	None	-	-
Boy's LR BR @ (B)	SK	5.5	-	-	None	-	-
Women's BR in Wellness Center @ (A)	SK	2.4	-	-	None	-	-
Women's BR in Wellness Center @ (B)	SK	29			FR		
Women's BR in Wellness Center @ (C)	SK	1.7	-	-	None	-	-

Lead in Drinking Water Test Results

As of 12/8/16

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Men's BR in Wellness Center @ (A)	SK	4.1	-	-	None	-	-
Men's BR in Wellness Center @ (B)	SK	1.2	-	-	None	-	-
Men's BR in Wellness Center @ (C)	SK	4.3	-	-	None	-	-
CC in Wellnes Center	SS	<1.0	-	-	None	-	-
Girl's LR BR @ (A)	SK	3.2	-	-	None	-	-
Girl's LR BR @ (C)	SK	4.3	-	-	None	-	-
CC # 2 in Gym Area	SS	<1.0	-	-	None	-	-
Women's BR in Gym Area	SK	10	-	-	None	-	-
Faculty Room near Art Hall	SK	<1.0	-	-	None	-	-
Women's Faculty BR in Art Hall	SK	6.5	-	-	None	-	-
Men's Faculty BR in Art Hall	SK	11	-	-	None	-	-
Boy's BR in Art Hall @ (A)	SK	25			FR		
Boy's BR in Art Hall @ (B)	SK	12	-	-	None	-	-
Boy's BR in Art Hall @ (C)	SK	14	-	-	None	-	-
Boy's BR in Art Hall @ (D)	SK	38			FR		
Girl's BR in Art Hall @ (A)	SK	6.7	-	-	None	-	-
Girl's BR in Art Hall @ (B)	SK	4.5	-	-	None	-	-
Girl's BR in Art Hall @ (C)	SK	4.7	-	-	None	-	-
CC in Art Hall	SS	13	-	-	None	-	-
Room 135 @ (A)	SK	<1.0	-	-	None	-	-
Room 135 @ (B)	SK	<1.0	-	-	None	-	-
Room 137 @ (A)	SK	2.3	-	-	None	-	-
Room 137 @ (B)	SK	<1.0	-	-	None	-	-
Room 138 @ (A)	SK	<1.0	-	-	None	-	-

Lead in Drinking Water Test Results

As of 12/8/16

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room 138 @ (B)	SK	1	-	-	None	-	-
Room 112 Teacher's Station 1 @ (A)	SK	23			FR		
Room 112 Teacher's Station 2 @ (A)	SK	20			FR		
Room 112 Teacher's Station 2 @ (B)	SK	28			FR		
Room 112 Counter	SK	13	-	-	None	-	-
Room 112 Storage	SK	1.8	-	-	None	-	-
Room 111 Teacher's Station @ (A)	SK	62			FR		
Room 111 Teacher's Station @ (B)	SK	17			FR		
Room 111 Counter @ (A)	SK	110			FR		
Room 111 Counter @ (B)	SK	15	-	-	None	-	-
Room 110 Pod 4 @ (A)	SK	9	-	-	None	-	-
Room 110 Pod 4 @ (B)	SK	3.5	-	-	None	-	-
Room 110 Pod 5 @ (A)	SK	6.6	-	-	None	-	-
Room 110 Pod 5 @ (B)	SK	4.6	-	-	None	-	-
Room 110 Counter	SK	6.6	-	-	None	-	-
Room 109 Counter @ (A)	SK	23			FR		
Room 109 Counter @ (B)	SK	9.2	-	-	None	-	-
Room 108 Teacher's Station @ (A)	SK	17			FR		
Room 108 Teacher's Station @ (B)	SK	15	-	-	None	-	-
Room 108 Island @ (A)	SK	2.8	-	-	None	-	-
Room 108 Island @ (B)	SK	7.5	-	-	None	-	-
Room 108 Island @ (C)	SK	5	-	-	None	-	-
Room 108 Counter 1	SK	12	-	-	None	-	-
Room 108 Counter 2 @ (A)	SK	2.9	-	-	None	-	-

Lead in Drinking Water Test Results

As of 12/8/16

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room 108 Counter 2 @ (B)	SK	16			FR		
Room 107 Pod 1 @ (A)	SK	43			FR		
Room 107 Pod 1 @ (B)	SK	66			FR		
Room 107 Pod 2 @ (A)	SK	65			FR		
Room 107 Pod 2 @ (B)	SK	52			FR		
Room 107 Pod 3 @ (A)	SK	40			FR		
Room 107 Pod 3 @ (B)	SK	36			FR		
Room 107 Counter	SK	8.8	-	-	None	-	-
Room 104 Counter 1 @ (B)	SK	8.2	-	-	None	-	-
Room 104 Counter 2 @ (A)	SK	7.7	-	-	None	-	-
Room 104 Counter 2 @ (B)	SK	12	-	-	None	-	-
Room 104 Counter 3	SK	16			FR		
Room 103 Teacher's Station	SK	53			FR		
Room 103 Pod 1 @ (A)	SK	62			FR		
Room 103 Pod 1 @ (B)	SK	31			FR		
Room 103 Pod 2 @ (B)	SK	52			FR		
Room 103 Pod 3 @ (A)	SK	58			FR		
Room 103 Pod 3 @ (B)	SK	53			FR		
Room 103 Counter	SK	25			FR		
Room 101	SK	31			FR		
Room 102 Teacher's Station	SK	5.1	-	-	None	-	-
Room 102 Counter @ (A)	SK	5.9	-	-	None	-	-
Room 102 Counter @ (B)	SK	3.9	-	-	None	-	-
Men's BR by RM 98	SK	<1.0	-	-	None	-	-

Lead in Drinking Water Test Results

As of 12/8/16

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Women's BR by RM 98	SK	<1.0	-	-	None	-	-
CC by RM 98	SS	<1.0	-	-	None	-	-
Room 98 Counter 1	SK	2.4	-	-	None	-	-
Room 98 Counter 2	SK	3.2	-	-	None	-	-
Room 98 Counter 3	SK	14	-	-	None	-	-
Room 98 Counter 4	SK	5.1	-	-	None	-	-
Room 98 Counter 5	SK	2.5	-	-	None	-	-
Room 98 Island @ (B)	SK	2.6	-	-	None	-	-
Room 96 Teacher's Station	SK	798			FR		
Room 96 Pod 1 @ (A)	SK	55			FR		
Room 96 Pod 1 @ (B)	SK	41			FR		
Room 96 Pod 2 @ (A)	SK	18			FR		
Room 96 Pod 2 @ (B)	SK	13	-	-	None	-	-
Room 96 Pod 3 @ (A)	SK	23			FR		
Room 96 Pod 3 @ (B)	SK	21			FR		
Room 96 Pod 4 @ (A)	SK	21			FR		
Room 96 Pod 4 @ (B)	SK	29			FR		
Room 96 Counter 1 @ (A)	SK	488			FR		
Room 96 Counter 1 @ (B)	SK	17			FR		
Room 96 Handwash	SK	2.2	-	-	None	-	-
Room 96 Counter 2	SK	4.8	-	-	None	-	-
Science Office	SK	1.3	-	-	None	-	-
Band Room 94	SK	<1.0	-	-	None	-	-
Nurse's Office BR 1	SK	1.2	-	-	None	-	-

Lead in Drinking Water Test Results

As of 12/8/16

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Nurse's Office BR 2	SK	7.2	-	-	None	-	-
Attendance Office BR	SK	<1.0	-	-	None	-	-
Boy's BR in Main Hall @ (A)	SK	2.6	-	-	None	-	-
Boy's BR in Main Hall @ (B)	SK	2.6	-	-	None	-	-
Concession Stand	SK	4.2	-	-	None	-	-
CC-Stage Crew Paint Closet	SS	29			FR		
Girl's BR in Main Hall @ (A)	SK	1.3	-	-	None	-	-
Girl's BR in Main Hall @ (B)	SK	<1.0	-	-	None	-	-
CC by Main Hall Boy's BR	SS	2.6	-	-	None	-	-
Men's BR by Auditorium	SK	3.2	-	-	None	-	-
Women's BR by Auditorium	SK	<1.0	-	-	None	-	-
Principal's Office BR	SK	<1.0	-	-	None	-	-
Custodian's BR	SK	<1.0	-	-	None	-	-
CC in Custodial Area	SS	1.5	-	-	None	-	-
Custodial Break Room	SK	1.4	-	-	None	-	-
Kitchen BR @ (A)	SK	2.8	-	-	None	-	-
Kitchen BR @ (B)	SK	1.6	-	-	None	-	-
Kitchen Prep @ (B)	SK	4	-	-	None	-	-
Kitchen Pot Filler 1	SK	14	-	-	None	-	-
Kitchen Island	SK	14	-	-	None	-	-
Kitchen Handwash @ (A)	SK	22			FR		
Kitchen Sanitizer @ (A)	SK	8.1	-	-	None	-	-
Kitchen Sanitizer @ (B)	SK	3.8	-	-	None	-	-
Kitchen Sanitizer	SPRAY	<1.0	-	-	None	-	-

Lead in Drinking Water Test Results

As of 12/8/16

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Kitchen Sanitizer @ (C)	SK	186			FR		
Kitchen Sanitizer @ (D)	SK	7.3	-	-	None	-	-
Kitchen Handwash @ (B) by Pot Filler 2	SK	<1.0	-	-	None	-	-
Kitchen Pot Filler 2 by ovens	SK	6.7	-	-	None	-	-
Kitchen Dishwasher Room @ (A)	SK	<1.0	-	-	None	-	-
Kitchen Dishwasher Room @ (B)	SK	53			FR		
Kitchen Serving Line Handwash	SK	<1.0	-	-	None	-	-
Kitchen Serving Line by Cafeteria	SK	4.2	-	-	None	-	-
Room 121	SK	4.4	-	-	None	-	-
Boy's Dugout @ (A)	SK	3.8	-	-	None	-	-
Boy's Dugout @ (B)	SK	2.8	-	-	None	-	-
CC in Boy's Dugout	SS	15	-	-	None	-	-
Girl's Dugout @ (A)	SK	9.4	-	-	None	-	-
CC in Girl's Dugout	SS	12	-	-	None	-	-
Room L10 @ (A)	SK	<1.0	-	-	None	-	-
Room L10 @ (B)	SK	1.1	-	-	None	-	-
Room L10 @ (C)	SK	<1.0	-	-	None	-	-
Room L10 @ (D)	SK	<1.0	-	-	None	-	-
Men's BR in Lower Hall	SK	<1.0	-	-	None	-	-
Women's BR in Lower Hall	SK	4.2	-	-	None	-	-
CC in Lower Hall	SS	<1.0	-	-	None	-	-
Room L30 Teacher's Station	SK	8.5	-	-	None	-	-
Room L30 Counter 1 @ (A)	SK	8	-	-	None	-	-
Room L30 Counter 1 @ (B)	SK	12	-	-	None	-	-

Lead in Drinking Water Test Results

As of 12/8/16

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room L30 Counter 1 @ (C)	SK	5.1	-	-	None	-	-
Room L30 Counter 2 @ (A)	SK	14	-	-	None	-	-
Room L30 Counter 2 @ (B)	SK	8.2	-	-	None	-	-
Room L40	SK	16			FR		
Room L60	SK	<1.0	-	-	None	-	-
Women's BR in English Hall	SK	1.6	-	-	None	-	-
Men's BR in English Hall	SK	1.1	-	-	None	-	-
Boy's BR in English Hall @ (A)	SK	14	-	-	None	-	-
Boy's BR in English Hall @ (B)	SK	10	-	-	None	-	-
Boy's BR in English Hall @ (C)	SK	12	-	-	None	-	-
CC in English Hall	SS	<1.0	-	-	None	-	-
Girl's BR in English Hall @ (A)	SK	7.1	-	-	None	-	-
Girl's BR in English Hall @ (B)	SK	1.7	-	-	None	-	-
Girl's BR in English Hall @ (C)	SK	16			FR		
CC in Math Hall	SS	1.4	-	-	None	-	-
Room 200D	SK	<1.0	-	-	None	-	-
Room 200A @ (A)	SK	6.5	-	-	None	-	-
Room 200A @ (B)	SK	21			FR		
Room 200A @ (C)	SK	33			FR		
Boy's BR in Social Studies Hall @ (B)	SK	3.8	-	-	None	-	-
Boy's BR in Social Studies Hall @ (C)	SK	2.9	-	-	None	-	-
Boy's BR in Social Studies Hall @ (D)	SK	3.6	-	-	None	-	-
Boy's BR in Social Studies Hall @ (F)	SK	11	-	-	None	-	-
Girl's BR in Social Studies Hall @ (A)	SK	<1.0	-	-	None	-	-

Lead in Drinking Water Test Results

As of 12/8/16

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Girl's BR in Social Studies Hall @ (B)	SK	4.2	-	-	None	-	-
Girl's BR in Social Studies Hall @ (C)	SK	5.6	-	-	None	-	-
Girl's BR in Social Studies Hall @ (D)	SK	5.2	-	-	None	-	-
Girl's BR in Social Studies Hall @ (E)	SK	10	-	-	None	-	-
Girl's BR in Social Studies Hall @ (F)	SK	6.6	-	-	None	-	-
Auditorium Fan House	SS	48			FR		
Women's Faculty BR in Social Studies Hall @ (A)	SK	3.3	-	-	None	-	-
Women's Faculty BR in social Studies Hall @ (B)	SK	11	-	-	None	-	-
Men's Faculty BR in Social Studies Hall	SK	2.7	-	-	None	-	-
Green House	SK	5.4	-	-	None	-	-
Green House	SP	4.4	-	-	None	-	-
Green House Courtyard	SP	5.6	-	-	None	-	-
Snack Room	SK	1	-	-	None	-	-
Snack Room Storage	SK	1193			FR		

DISTRICT WIDE LEAD IN DRINKING WATER
SUMMARY REPORT AS OF
12/8/2016

SAYVILLE MIDDLE SCHOOL	
First Draw Samples Collected	205
First Draw Samples > 15 Parts Per Billion	71
Number of Sources Capped or Taken Off Line	1
Post Remediation Samples <= 15 PPB	2
Number of Sources Pending For Remediation	68
<i>Maximum Pb Concentration Observed</i>	<i>9053</i>

Lead in Drinking Water Test Results

As of 12/8/16

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
WF Nearby Room 113 (Right)	WF	2.9	-	-	None	-	-
WF Nearby Room 113 (Left)	WF	3.4	-	-	None	-	-
Girls LR by Office	WF	9	-	-	None	-	-
Girls LR by BR WF (Right)	WF	<2.5	-	-	None	-	-
Girls LR by BR WF (Left)	WF	3.2	-	-	None	-	-
Boys LR by Office	WF	<2.5	-	-	None	-	-
WF Across Room 103 (Right)	WF	4.8	-	-	None	-	-
WF Across Room 103 (Left)	WF	9.4	-	-	None	-	-
WF Across Technology Room (Right)	WF	6.6	-	-	None	-	-
WF Across Technology Room (Left)	WF	8	-	-	None	-	-
Boys LR by Pool	WF	7.2	-	-	None	-	-
WF by Faculty Room	WF	<2.5	-	-	None	-	-
Cafeteria "A"	WF	<2.5	-	-	None	-	-
Cafeteria "B"	WF	<2.5	-	-	None	-	-
WF by Room 235 (Right)	WF	3.6	-	-	None	-	-
WF by Room 235 (Left)	WF	3	-	-	None	-	-
WF Across Room 204 (Right)	WF	4.8	-	-	None	-	-
WF Across Room 204 (Left)	WF	6.9	-	-	None	-	-
Kitchen Island Sink	SK	7.5	-	-	None	-	-
Kitchen Pot Filler (Right)	SK	43			FR	CAP	
Kitchen Pot Filler (Left)	SK	110			FR	Completed FR	7.4
Kitchen Prep Sink	SK	7.9	-	-	None	-	-
Boy's LR by Pool	SK	2.4	-	-	None	-	-

Lead in Drinking Water Test Results

As of 12/8/16

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Girl's LR by Pool	SK	5.4	-	-	None	-	-
Room 112	SK	32	1.4	1.4	FR	Flushed/Clean Aerator	Pending Retest
Faculty Room	SK	2.6	-	-	None	-	-
Nurse's Office	SK	5.9	-	-	None	-	-
Nurse's Office BR	SK	6.3	-	-	None	-	-
Work Room Kitchen	SK	14	-	-	None	-	-
Room 247	SK	295			FR	Completed FR	12
Girl's LR by Pool	WF	17			FR	Completed FR	Pending Retest
WF by Room 229	WF	7.5	-	-	None	-	-
Room 116 Station 1	SK	3.5	-	-	None	-	-
Room 116 Station 2	SK	4.9	-	-	None	-	-
Room 116 Station 3	SK	<1.0	-	-	None	-	-
Room 116 Station 4	SK	23			FR		
Room 116 Station 5	SK	5	-	-	None	-	-
Room 115 Station 1	SK	16			FR		
Room 115 Station 2	SK	4.7	-	-	None	-	-
Room 115 Station 3	SK	6.6	-	-	None	-	-
Room 115 Station 4	SK	5.3	-	-	None	-	-
Room 115 Station 5	SK	14	-	-	None	-	-
Room 114	SK	7.3	-	-	None	-	-
Ladies BR by Cafe @ (D)	SK	5.2	-	-	None	-	-
Ladies BR by Cafe @ (E)	SK	<1.0	-	-	None	-	-
Ladies BR by Cafe @ (F)	SK	1	-	-	None	-	-
Men's BR by Cafe @ (B)	SK	<1.0	-	-	None	-	-

Lead in Drinking Water Test Results

As of 12/8/16

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Men's BR by Cafe @ (D)	SK	3.5	-	-	None	-	-
Men's BR by Cafe @ (E)	SK	1.2	-	-	None	-	-
Boy's BR by Auditorium @ (A)	SK	8.1	-	-	None	-	-
Boy's BR by Auditorium @ (B)	SK	7.8	-	-	None	-	-
Boy's BR by Auditorium @ (C)	SK	16			FR		
Girl's BR by Auditorium @ (A)	SK	14	-	-	None	-	-
Girl's BR by Auditorium @ (B)	SK	25			FR		
Girl's BR by Auditorium @ (C)	SK	21			FR		
Girl's LR BR @ (A)	SK	5.4	-	-	None	-	-
Girl's LR BR @ (B)	SK	5.6	-	-	None	-	-
Girl's LR Office BR	SK	9.7	-	-	None	-	-
Boy's LR Office BR	SK	2.7	-	-	None	-	-
Boy's LR Office	IM	<1.0	-	-	None	-	-
Boy's LR BR @ (A)	SK	<1.0	-	-	None	-	-
Room 112	SK	5.4	-	-	None	-	-
Men's BR in Tech Hallway @ (A)	SK	5.2	-	-	None	-	-
Men's BR in Tech Hallway @ (B)	SK	12	-	-	None	-	-
Room 110	SK	4.7	-	-	None	-	-
Room 111	SK	12	-	-	None	-	-
Room 108	SK	12	-	-	None	-	-
Girl's LR by Pool @ (B)	SK	<1.0	-	-	None	-	-
Boy's LR by Pool @ (B)	SK	<1.0	-	-	None	-	-
Coach's BR by Pool	SK	1.8	-	-	None	-	-

Lead in Drinking Water Test Results

As of 12/8/16

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Pool BR	SK	1.5	-	-	None	-	-
Pool Chemical Storage Room	SS	1	-	-	None	-	-
Men's BR by Music Room	SK	4.1	-	-	None	-	-
Women's BR by Music Room	SK	1.4	-	-	None	-	-
Room 106 @ (A)	SK	29			FR		
Room 106 @ (B)	SK	25			FR		
Room 105 @ (A)	SK	7.8	-	-	None	-	-
Room 105 @ (B)	SK	11	-	-	None	-	-
Room 104 Unit @ (A)	SK	14	-	-	None	-	-
Room 104 Unit @ (B)	SK	34			FR		
Room 104 Counter	SK	17			FR		
Room 103 @ (A)	SK	2	-	-	None	-	-
Room 103 @ (B)	SK	1.6	-	-	None	-	-
Girl's BR by RM 103 @ (A)	SK	16			FR		
Girl's BR by RM 103 @ (B)	SK	35			FR		
Girl's BR by RM 103 @ (C)	SK	144			FR		
Room 102	SK	11	-	-	None	-	-
Office Copy Room	SK	6	-	-	None	-	-
Men's BR by Main Office	SK	<1.0	-	-	None	-	-
Women's BR by Main Office	SK	<1.0	-	-	None	-	-
Kitchen BR @ (A)	SK	3.8	-	-	None	-	-
Kitchen BR @ (B)	SK	5.2	-	-	None	-	-
Kitchen Handwash by Ovens	SK	14	-	-	None	-	-

Lead in Drinking Water Test Results

As of 12/8/16

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Kitchen Sanitizer @ (A)	SK	<1.0	-	-	None	-	-
Kitchen Sanitizer	SPRAY	<1.0	-	-	None	-	-
Kitchen Sanitizer @ (B)	SK	4.1	-	-	None	-	-
Kitchen Dishwasher Handwash by Prep SK	SK	4.5	-	-	None	-	-
Kitchen Dishwasher by Prep SK	SPRAY	6	-	-	None	-	-
Kitchen Dishwasher Handwash by desk	SK	26			FR		
Kitchen Dishwasher by desk	SPRAY	41			FR		
Kitchen Serving Line A Handwash	SK	11	-	-	None	-	-
Kitchen Serving Line B Handwash	SK	6	-	-	None	-	-
Boiler Room	SS	22			FR		
Custodial Office	SS	<1.0	-	-	None	-	-
Custodial BR	SK	<1.0	-	-	None	-	-
CC by RM 103	SS	4.1	-	-	None	-	-
CC by RM 112	SS	4.2	-	-	None	-	-
Outside Spigot by Girl's Lobby North	SP	219			FR		
Outside Spigot by Girl's Gym LR East	SP	6.8	-	-	None	-	-
Outside Spigot by Boy's LR South	SP	5.3	-	-	None	-	-
Outside Spigot by Metal Shop East	SP	407			FR		
Outside Spigot by Filter Room East	SP	17			FR		
Outside Spigot by Choral Room South	SP	15	-	-	None	-	-
Outside Spigot by Art Room West	SP	606			FR		
Outside Spigot by Room 103 West	SP	192			FR		
Outside Spigot by Main Office West	SP	308			FR		

Lead in Drinking Water Test Results

As of 12/8/16

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Outside Spigot by Boiler Room	SP	247			FR		
Teachers Men's BR by RM 238 @ (A)	SK	6.2	-	-	None	-	-
Teachers Men's BR by RM 238 @ (B)	SK	13	-	-	None	-	-
Teachers Men's BR by RM 238 @ (C)	SK	23			FR		
Teachers Men's BR by RM 238 @ (D)	SK	15	-	-	None	-	-
Teachers Women's BR by RM 238 @ (A)	SK	1.9	-	-	None	-	-
Teachers Women's BR by RM 238 @ (B)	SK	4.5	-	-	None	-	-
Teachers Women's BR by RM 238 @ (C)	SK	<1.0	-	-	None	-	-
Room 239 Table 1 @ (A)	SK	11	-	-	None	-	-
Room 239 Table 1 @ (B)	SK	13	-	-	None	-	-
Room 239 Table 2 @ (A)	SK	7.9	-	-	None	-	-
Room 239 Table 2 @ (B)	SK	6.2	-	-	None	-	-
Room 239 Table 3 @ (A)	SK	13	-	-	None	-	-
Room 239 Table 3 @ (B)	SK	25			FR		
Room 240 Teacher's Station	SK	2386			FR		
Room 240 Table 1 @ (A)	SK	594			FR		
Room 240 Table 1 @ (B)	SK	492			FR		
Room 240 Table 2 @ (A)	SK	33			FR		
Room 240 Table 2 @ (B)	SK	20			FR		
Room 240 Table 3 @ (A)	SK	50			FR		
Room 240 Table 3 @ (B)	SK	330			FR		
Room 243 Teacher's Station	SK	45			FR		
Room 243 Table 1 @ (A)	SK	32			FR		

Lead in Drinking Water Test Results

As of 12/8/16

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room 243 Table 1 @ (B)	SK	27			FR		
Room 243 Table 2 @ (A)	SK	33			FR		
Room 243 Table 2 @ (B)	SK	27			FR		
Room 243 Table 3 @ (A)	SK	9053			FR		
Room 243 Table 3 @ (B)	SK	62			FR		
Room 206 Teacher's Station	SK	386			FR		
Room 206 Table 2 @ (A)	SK	8.6	-	-	None	-	-
Room 206 Table 2 @ (B)	SK	8.4	-	-	None	-	-
Room 206 Table 3 @ (A)	SK	38			FR		
Room 206 Table 3 @ (B)	SK	32			FR		
Room 207 Table 1 @ (A)	SK	26			FR		
Room 207 Table 1 @ (B)	SK	17			FR		
Room 207 Table 3 @ (A)	SK	3.4	-	-	None	-	-
Room 207 Table 3 @ (B)	SK	6.2	-	-	None	-	-
Room 245 Teacher's Station	SK	17			FR		
Room 245 Table 1 @ (A)	SK	12	-	-	None	-	-
Room 245 Table 1 @ (B)	SK	7.8	-	-	None	-	-
Room 245 Table 2 @ (A)	SK	17			FR		
Room 245 Table 2 @ (B)	SK	14	-	-	None	-	-
Room 245 Table 2 @ (C)	SK	18			FR		
Room 245 Table 3 @ (A)	SK	13	-	-	None	-	-
Room 245 Table 3 @ (B)	SK	4.8	-	-	None	-	-
Room 245 Table 4 @ (A)	SK	3.3	-	-	None	-	-

Lead in Drinking Water Test Results

As of 12/8/16

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room 245 Table 4 @ (B)	SK	3.9	-	-	None	-	-
Room 246 Teacher's Station	SK	57			FR		
Room 246 Table 1 @ (A)	SK	101			FR		
Room 246 Table 1 @ (B)	SK	20			FR		
Room 246 Table 2 @ (A)	SK	160			FR		
Room 246 Table 2 @ (B)	SK	38			FR		
Room 246 Table 3 @ (A)	SK	8.5	-	-	None	-	-
Room 246 Table 3 @ (B)	SK	6.1	-	-	None	-	-
Room 246 Table 4 @ (B)	SK	9.3	-	-	None	-	-
Room 231 Table 1 @ (A)	SK	5.9	-	-	None	-	-
Room 231 Table 1 @ (B)	SK	5.7	-	-	None	-	-
Room 231 Table 3 @ (A)	SK	159			FR		
Room 231 Table 3 @ (B)	SK	26			FR		
Room 231 Table 4 @ (A)	SK	12	-	-	None	-	-
Room 231 Table 4 @ (B)	SK	15	-	-	None	-	-
Prep RM Counter by RM 207	SK	7.7	-	-	None	-	-
Prep RM Counter by RM 243	SK	27			FR		
Prep RM Counter by RM 239	SK	7.6	-	-	None	-	-
Prep RM Island 1 by Storage RM	SK	1014			FR		
Prep RM Island 2 by RM 231	SK	11	-	-	None	-	-
CC by RM 233	SS	5.4	-	-	None	-	-
Girl's BR by RM 244 @ (A)	SK	39			FR		
Girl's BR by RM 244 @ (B)	SK	1098			FR		

Lead in Drinking Water Test Results

As of 12/8/16

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Girl's BR by RM 244 @ (C)	SK	671			FR		
Girl's BR by RM 244 @ (D)	SK	445			FR		
Boy's BR by RM 244 @ (A)	SK	1520			FR		
Boy's BR by RM 244 @ (B)	SK	1488			FR		
Boy's BR by RM 244 @ (C)	SK	160			FR		
Boy's BR by RM 244 @ (D)	SK	206			FR		
CC by RM 205	SS	6.7	-	-	None	-	-
CC by RM 212	SS	2.8	-	-	None	-	-
Teachers Men's BR by RM 213	SK	8.8	-	-	None	-	-
Teachers Women's BR by RM 213 @ (A)	SK	4.7	-	-	None	-	-
Teachers Women's BR by RM 213 @ (B)	SK	11	-	-	None	-	-
Girl's BR by RM 213 @ (A)	SK	25			FR		
Girl's BR by RM 213 @ (B)	SK	169			FR		
WF by RM 229 (Upper)	WF	2.1	-	-	None	-	-
Boy's BR by RM 229	SK	5.8	-	-	None	-	-
Teachers Women's BR by RM 229 @ (A)	SK	3.1	-	-	None	-	-
Teachers Women's BR by RM 229 @ (B)	SK	17			FR		
Teachers Men's BR by RM 229	SK	15	-	-	None	-	-
CC by RM 229	SS	4.3	-	-	None	-	-
Library Office	SK	3.8	-	-	None	-	-

DISTRICT WIDE LEAD IN DRINKING WATER
SAYVILLE UNION FREE SCHOOL DISTRICT
SUMMARY REPORT AS OF
12/8/2016

SUNRISE DRIVE ELEMENTARY SCHOOL	
First Draw Samples Collected	114
First Draw Samples > 15 Parts Per Billion	11
Number of Sources Capped or Taken Off Line	2
Post Remediation Samples <= 15 PPB	0
Number of Sources Pending For Remediation	9
<i>Maximum Pb Concentration Observed</i>	<i>31</i>

Lead in Drinking Water Test Results

As of 12/8/16

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
RM 103	WF	9.9	-	-	None	-	-
RM 104	WF	5.1	-	-	None	-	-
RM 108	WF	10	-	-	None	-	-
RM 110	WF	2.3	-	-	None	-	-
WF Outside Main Office	WF	11	-	-	None	-	-
WF by RM 120 B (Lower)	WF	<1.0	-	-	None	-	-
RM 122	WF	7.2	-	-	None	-	-
RM 123A	WF	6.1	-	-	None	-	-
RM 125	WF	6.4	-	-	None	-	-
RM 127	WF	5.6	-	-	None	-	-
RM 126	WF	5.2	-	-	None	-	-
Rm 128	WF	4.5	-	-	None	-	-
RM 129	WF	6.8	-	-	None	-	-
WF by RM 132	WF	13	-	-	None	-	-
RM 134	WF	7.6	-	-	None	-	-
RM 133	WF	4.7	-	-	None	-	-
RM 138	WF	<1.0	-	-	None	-	-
RM 137	WF	7.5	-	-	None	-	-
RM 139	WF	10	-	-	None	-	-
RM 142	WF	12	-	-	None	-	-
RM 102	WF	3.3	-	-	None	-	-
RM 105	WF	<1.0	-	-	None	-	-
RM 106	WF	5.8	-	-	None	-	-

Lead in Drinking Water Test Results

As of 12/8/16

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
RM 107	WF	<1.0	-	-	None	-	-
RM 109	WF	<1.0	-	-	None	-	-
RM 112	WF	<1.0	-	-	None	-	-
RM 124	WF	3	-	-	None	-	-
RM 130	WF	3.3	-	-	None	-	-
RM 136	WF	5.1	-	-	None	-	-
RM 140	WF	1.4	-	-	None	-	-
RM 135	WF	<1.0	-	-	None	-	-
Kitchen Pot Filler	SK	<1.0	-	-	None	-	-
Kitchen Prep	SK	<1.0	-	-	None	-	-
Main Office	SK	2.8	-	-	None	-	-
Faculty Room	SK	<1.0	-	-	None	-	-
Room 101	SK	3.3	-	-	None	-	-
Nurse's Office	SK	<1.0	-	-	None	-	-
Library Office	SK	4.8	-	-	None	-	-
Kitchen Prep SK (Center)	SK	21	8.4	2.1	FR	SIGN	
Kitchen Prep SK (Right)	SK	19	1.5	<1.0	FR	SIGN	
Room 121	WF	16	3.6	2.6	FR	TBD	
Room 132	WF	<1.0	6	1.9	None	-	-
Room 112	SK	21			FR		
Room 112 BR	SK	7.6	-	-	None	-	-
Room 109	SK	1.3	-	-	None	-	-
Room 109 BR	SK	3.7	-	-	None	-	-

Lead in Drinking Water Test Results

As of 12/8/16

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room 110	SK	15	-	-	None	-	-
Room 110 BR	SK	3.4	-	-	None	-	-
CC 100 Wing	SS	17			FR		
Room 108	SK	4.9	-	-	None	-	-
Room 108 BR	SK	<1.0	-	-	None	-	-
Room 107	SK	<1.0	-	-	None	-	-
Room 107 BR	SK	6.6	-	-	None	-	-
Room 106	SK	16			FR		
Room 106 BR	SK	4	-	-	None	-	-
Room 105	SK	6.6	-	-	None	-	-
Room 105 BR	SK	2.9	-	-	None	-	-
Room 104	SK	5.4	-	-	None	-	-
Room 104 BR	SK	4.1	-	-	None	-	-
Room 103	SK	4.2	-	-	None	-	-
Room 103 BR	SK	3.9	-	-	None	-	-
Room 102	SK	22			FR		
Room 102 BR	SK	5.8	-	-	None	-	-
CC by Main Office	SS	<1.0	-	-	None	-	-
Room 101 BR	SK	7.7	-	-	None	-	-
Men's Faculty BR @ (A)	SK	4.4	-	-	None	-	-
Men's Faculty BR @ (B)	SK	5.5	-	-	None	-	-
Ladies Faculty BR @ (A)	SK	1.9	-	-	None	-	-
Ladies Faculty BR @ (B)	SK	1.8	-	-	None	-	-

Lead in Drinking Water Test Results

As of 12/8/16

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Nurse"s Office BR	SK	4.8	-	-	None	-	-
Toni Fabian BR	SK	31			FR		
WF by Room 120B	WF	<1.0	-	-	None	-	-
Room 119	SK	<1.0	-	-	None	-	-
Room 121	SK	5.1	-	-	None	-	-
CC 120 Wing	SS	<1.0	-	-	None	-	-
Boy's BR in 120 Wing @ (A)	SK	24			FR		
Boy's BR in 120 Wing @ (B)	SK	1.5	-	-	None	-	-
Boy's BR in 120 Wing @ (C)	SK	1.8	-	-	None	-	-
Ladies BR in 120 Wing @ (A)	SK	2.2	-	-	None	-	-
Ladies BR in 120 Wing @ (B)	SK	1.2	-	-	None	-	-
Ladies BR in 120 Wing @ (C)	SK	2.2	-	-	None	-	-
Room 123 (A)	SK	4.4	-	-	None	-	-
Room 122	SK	1.5	-	-	None	-	-
Room 125	SK	5.2	-	-	None	-	-
Room 124	SK	9.9	-	-	None	-	-
Room 127	SK	11	-	-	None	-	-
Room 126	SK	5.7	-	-	None	-	-
Room 129	SK	4.6	-	-	None	-	-
Room 128	SK	5.6	-	-	None	-	-
Women faculty BR in 130 Wing	SK	<1.0	-	-	None	-	-
Men Faculty BR in 130 Wing	SK	1.8	-	-	None	-	-
Room 130	SK	1.4	-	-	None	-	-

Lead in Drinking Water Test Results

As of 12/8/16

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Boy's BR in 130 Wing @ (A)	SK	4.3	-	-	None	-	-
Boy's BR in 130 Wing @ (B)	SK	3.5	-	-	None	-	-
Boy's BR in 130 Wing @ (C)	SK	4.4	-	-	None	-	-
CC 130 Wing	SS	20			FR		
Girl's BR in 130 Wing @ (A)	SK	2.3	-	-	None	-	-
Girl's BR in 130 Wing @ (B)	SK	3.7	-	-	None	-	-
Girl's BR in 130 Wing @ (C)	SK	4.5	-	-	None	-	-
Room 132	SK	5.3	-	-	None	-	-
Room 134	SK	3.6	-	-	None	-	-
Room 133	SK	7.4	-	-	None	-	-
Room 136	SK	2.9	-	-	None	-	-
Room 135	SK	3.4	-	-	None	-	-
Room 138	SK	4.2	-	-	None	-	-
Room 137	SK	5.1	-	-	None	-	-
Room 140	SK	7	-	-	None	-	-
Room 139	SK	6.5	-	-	None	-	-
Room 142	SK	4.9	-	-	None	-	-
Kitchen Sanitizer	SK	1.8	-	-	None	-	-
Kitchen Island	SK	4.5	-	-	None	-	-
Kitchen Dishwashing Station	SK	3.1	-	-	None	-	-
Kitchen Dishwashing Station Spray	SPRAY	<1.0	-	-	None	-	-
Kitchen BR	SK	22			FR		