

Attachment C – Drinking Water Outlet Inventory

Name of School: Selover

Grade Levels: Administration Year School Constructed: 1954 Renovated/Additions: 1959

Individual school project officer Name/Signature: Richard Cierpriel Date Completed: 12/15/16

#	Type	Location	Code	Operational ² (Y/N)	Signs of Corrosion ³ (Y/N)	Filter ⁴ (Y/N)	Brass Fittings, Faucets or valves? (Y/N)	Aerator/ Screen (Y/N)	Motion Activated (Y/N)	Chiller (Y/N)	Water Cooler		Comments
											Make	Model	
0	Test												
1	Water cooler	Room 7	1	Yes	No	Yes	No	No	No	Yes	Quench	XFTUS	
2	Water cooler	Room 12	2	Yes	No	Yes	No	No	No	Yes	Quench	12chcu	
3	Sink	Room 23	3	Yes	No	No	Yes	Yes	No	No			
4	Sink	Room 14	4	Yes	No	No	Yes	Yes	No	No			
5	Water fountain	Hall room 7	5	No	Yes	No	Yes	Yes	No	8			Out of service
6	Water fountain	Hall room 21	6	No	Yes	No	Yes	Yes	No	No			Out of service

¹ Number outlets starting at the closest outlet to the Point of Entry (POE).

² Document if permanently or temporarily out of service on the Attachment B- Plumbing Profile.

³ Signs of corrosion detected, such as but not limited to frequent leaks, rust-colored water, or stained fixtures, dishes, or laundry.

⁴ Document on Attachment D- Filter Inventory.

7	Water fountain	Hall room 28	7	No	Yes	No	Yes	Yes	No	No			Out of service