Construction Status Update

Farmington Public Schools 2020 Bond Issue

Bid Package #1 – East Middle School Remodeling Project June 22nd, 2021









Before





After







Before After







Media Center


Ceiling Tiles have been removed.
Prepping for sheet metal install. Flooring protection installed.














Vocal and Band Rooms have had flooring protection and scaffolding installed. Celling tiles were removed and grid is painted. New ceiling tiles are being installed currently.












Before After










Before



After







Cafeteria

Ceiling Tiles have been removed. Grid has been painted. New lighting fixtures being installed.









The Look Ahead

- Exterior Asphalt and Concrete Demo
- Continue Installing New Lighting Fixtures
- Layout and Install Media Center Ductwork
- Begin Roof Joist Reinforcement





