

## Farmington Public Schools 2020 Bond Issue

### Bid Package #3 Farmington High School



# Progress Overview – Farmington High School



New pool deck tile has been installed and grouted.



Pool base and walls have been acid washed to prep various areas for new grout.



# Progress Overview – Farmington High School

Before



After



Old pool bleachers have been removed and new bleachers have been installed. New epoxy flooring has been installed underneath the bleachers.



# Progress Overview – Farmington High School

Before



After



Selective existing stadium bleacher concrete foundations have been removed. New concrete foundations are being placed.



# Progress Overview – Farmington High School



Selective classroom ceiling tile demolition is ongoing and new lighting fixtures are being installed.




Existing unit ventilators are being removed and new unit ventilators are being installed.



# Progress Overview – Farmington High School




Various bathrooms new tile installation has begun



Selective exterior windows are being removed and replaced



# Progress Overview – Farmington High School



Various classroom existing casework has been removed and prepared for new replacement.

# The Look Ahead – Farmington High School

- Continue selective bathroom new tile installation and being grouting
- Continue install of new unit ventilator controls
- Continue architectural demolition
- Continue electrical rough-in and lighting installation