


Completed Work:

- Pour Storm Shelter Roof (5/16/24)
- Continue Interior CMU and Brick Veneer
- Continue Joist and Decking at E Area and Structural Steel at Gym Entrance
- Roofing at B and D Area starting 5/16/24, Delayed due to Rain
- Standing Seam Roofing starting 5/20/24 Area A
- Continue Exterior Framing and Sheetrock in Area A second floor.
- Start Priming and first coat of classrooms at Area A
- Continue MEP and Sprinkler Rough Ins


Upcoming Work/Look Ahead:

- Finish Decking Area E, Structural Steel and Decking at Gym Entrance
- Finish CMU at Plumbing Chase Walls
- Continue Brick Veneer at Cafeteria and ACM Panels at Area F
- Continue Roofing Area B and D Flat Roofs and Standing Seam Trim out at Area A
- Continue Painting Area A (Prime and First Coat at Classrooms)
- Continue Terrazzo Area A First Floor
- Finish Installing Sheetrock Area A Second Floor
- Exterior Wall Furring/Framing Continuing
- Start Installing Sheetrock Area C First Floor
- Mechanical and Plumbing Rough In Continuing at Area E and Area D





Area A – Classroom Accent Wall Paint





Area A – Window Boxouts Complete






Area B – Metal Panel Furring has begun






Area E – Storm Shelter Roof Ready to Pour





Area F – ACM Panels on Gym





Area F – Bus Canopy Framing





Area F – Kitchen Brick Veneer





Area F — Loading Dock Ready to Pour

