

Lead Tests - Jackson Elementary School - Main Building - # 20480400

#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20480400-001NS	20480400-001NS25A	Health Room - Sink (Left - Fixture)	04/10/24	ND	None.
2	20480400-002WB	20480400-002WB25A	Health Room - Sink (Right - Bottle Filler)	04/10/24	ND	None.
3	20480400-003BF	20480400-003BF25A	Health Room Unisex Restroom - Sink	04/10/24	1.6	None.
4	20480400-004BF	20480400-004BF25A	Near Office Staff Unisex Restroom (Left) - Sink	04/10/24	3.8	None.
5	20480400-005BF	20480400-005BF25A	Near Office Staff Unisex Restroom (Right) - Sink	04/10/24	3.3	None.
6	20480400-006SF	20480400-006SF25A	Staff Break Room (101D) - Sink	04/10/24	ND	None.
7	20480400-007SF	20480400-007SF25A	Staff Break Room (101D) - Insta Hot	04/10/24	ND	None.
8	20480400-008DW	20480400-008DW25A	Room 120 - South Drinking Fountain (A)	04/10/24	10.5	None.
9	20480400-009CF	20480400-009CF25A	Room 120 - South Sink (A)	04/10/24	ND	None.
10	20480400-010DW	20480400-010DW25A	Room 120 - North East Drinking Fountain (B)	04/10/24	0.5	None.
11	20480400-011CF	20480400-011CF25A	Room 120 - North East Sink (B)	04/10/24	0.5	None.
12	20480400-012DW	20480400-012DW25A	Room 120 - North West Drinking Fountain (C)	04/10/24	1.0	None.
13	20480400-013CF	20480400-013CF25A	Room 120 - North West Sink (C)	04/10/24	1.3	None.
N/A	N/A	N/A	South Outdoor Closet Outside Room 120	N/A	N/A	Water should not be consumed out of this sink.
14	20480400-014DW	20480400-014DW25A	Room 121 - Drinking Fountain	04/10/24	ND	None.
15	20480400-015CF	20480400-015CF25A	Room 121 - Sink	04/10/24	ND	None.
16	20480400-016DW	20480400-016DW25A	Room 122 - Drinking Fountain	04/10/24	1.0	None.
17	20480400-017CF	20480400-017CF25A	Room 122 - Sink	04/10/24	ND	None.
18	20480400-018DW	20480400-018DW25A	Room 123 - Drinking Fountain	04/10/24	ND	None.
19	20480400-019CF	20480400-019CF25A	Room 123 - Sink	04/10/24	ND	None.
20	20480400-020DW	20480400-020DW25A	Behind Sliding Door In Front of Room 110 - Drinking Fountain	04/10/24	0.9	None.
21	20480400-021OT	20480400-021OT25A	Behind Sliding Door In Front of Room 110 - Sink	04/10/24	0.9	None.
22	20480400-022DW	20480400-022DW25A	Room 110 - West Drinking Fountain (A)	04/10/24	0.6	None.
23	20480400-023CF	20480400-023CF25A	Room 110 - West Sink (A)	04/10/24	0.7	None.
24	20480400-024DW	20480400-024DW25A	Room 110 - East Drinking Fountain (B)	04/10/24	0.7	None.
25	20480400-025CF	20480400-025CF25A	Room 110 - East Sink (B)	04/10/24	0.7	None.
26	20480400-026BF	20480400-026BF25A	Room 110 Boys/Girl's Restroom - Trough Sink	04/10/24	0.7	None.
27	20480400-027OT	20480400-027OT25A	West Outdoor Closet Outside Room 110 - Sink	04/30/24	14.2	Removed May 2024.
28	20480400-028DW	20480400-028DW25A	Room 111 - Drinking Fountain	04/10/24	ND	None.
29	20480400-029CF	20480400-029CF25A	Room 111 - Sink	04/10/24	ND	None.
30	20480400-030DW	20480400-030DW25A	Room 112 - Drinking Fountain	04/10/24	ND	None.
31	20480400-031CF	20480400-031CF25A	Room 112 - Sink	04/10/24	ND	None.
32	20480400-032DW	20480400-032DW25A	Room 113 - Drinking Fountain	04/10/24	ND	None.
33	20480400-033CF	20480400-033CF25A	Room 113 - Sink	04/10/24	ND	None.
34	20480400-034BF	20480400-034BF25A	Outside Room 105D Boy's Restroom - Trough Sink	04/10/24	5.3	None.
35	20480400-035BF	20480400-035BF25A	Outside Room 105D Girl's Restroom - Trough Sink	04/10/24	1.7	None.
36	20480400-036WB	20480400-036WB25A	Near 1st Floor Elevator - Bottle Filler (Upper)	04/10/24	ND	Installed Elkay Bottle Filler Unit with Filter. 01/15/2023.
37	20480400-037DW	20480400-037DW25A	Near 1st Floor Elevator - Drinking Fountain (Lower)	04/10/24	ND	Installed Elkay Bottle Filler Unit with Filter. 01/15/2023.
38	20480400-038DW	20480400-038DW25A	Room 141 - Drinking Fountain	04/10/24	ND	None.
39	20480400-039CF	20480400-039CF25A	Room 141 - Sink	04/10/24	ND	None.
40	20480400-040DW	20480400-040DW25A	Room 142 - Drinking Fountain	04/10/24	ND	None.
41	20480400-041CF	20480400-041CF25A	Room 142 - Sink	04/10/24	0.6	None.
42	20480400-042DW	20480400-042DW25A	Room 143 - Drinking Fountain	04/10/24	ND	None.
43	20480400-043CF	20480400-043CF25A	Room 143 - Sink	04/10/24	ND	None.
44	20480400-044CF	20480400-044CF25A	Room 132 - Sink	04/10/24	1.1	This sink has a lead filter on the cold side.
45	20480400-045DW	20480400-045DW25A	Playground - Drinking Fountain (Outside)	04/10/24	ND	This drinking fountain has a lead filter on it.
46	20480400-046DW	20480400-046DW25A	Room 220 - South Drinking Fountain (A)	04/10/24	ND	None.
47	20480400-047CF	20480400-047CF25A	Room 220 - South Sink (A)	04/10/24	0.7	None.
48	20480400-048DW	20480400-048DW25A	Room 220 - North East Drinking Fountain (B)	04/10/24	ND	None.
49	20480400-049CF	20480400-049CF25A	Room 220 - North East Sink (B)	04/10/24	0.9	None.
50	20480400-050DW	20480400-050DW25A	Room 220 - North West Drinking Fountain (C)	04/10/24	ND	None.
51	20480400-051CF	20480400-051CF25A	Room 220 - North West Sink (C)	04/10/24	1.2	None.
52	20480400-052DW	20480400-052DW25A	Room 221 - Drinking Fountain	04/10/24	ND	None.
53	20480400-053CF	20480400-053CF25A	Room 221 - Sink	04/10/24	ND	None.
54	20480400-054DW	20480400-054DW25A	Room 222 - Drinking Fountain	04/10/24	ND	None.

55	20480400-055CF	20480400-055CF25A	Room 222 - Sink	04/10/24	ND	None.
56	20480400-056DW	20480400-056DW25A	Room 223 - Drinking Fountain	04/10/24	ND	None.
57	20480400-057CF	20480400-057CF25A	Room 223 - Sink	04/10/24	ND	None.
58	20480400-058DW	20480400-058DW25A	Room 224 - Drinking Fountain	04/10/24	ND	None.
59	20480400-059CF	20480400-059CF25A	Room 224 - Sink	04/10/24	ND	None.
60	20480400-060DW	20480400-060DW25A	Room 211 - Drinking Fountain	04/10/24	ND	None.
61	20480400-061CF	20480400-061CF25A	Room 211 - Sink	04/10/24	ND	None.
62	20480400-062DW	20480400-062DW25A	Room 212 - Drinking Fountain	04/10/24	ND	None.
63	20480400-063CF	20480400-063CF25A	Room 212 - Sink	04/10/24	0.7	None.
64	20480400-064DW	20480400-064DW25A	Room 210 - West Drinking Fountain (A)	04/10/24	ND	None.
65	20480400-065CF	20480400-065CF25A	Room 210 - West Sink (A)	04/10/24	ND	None.
66	20480400-066DW	20480400-066DW25A	Room 210 - East Drinking Fountain (B)	04/10/24	1.4	None.
67	20480400-067CF	20480400-067CF25A	Room 210 - East Sink (B)	04/10/24	0.5	None.
68	20480400-068DW	20480400-068DW25A	Room 210 - North Drinking Fountain (C)	04/10/24	6.0	None.
69	20480400-069CF	20480400-069CF25A	Room 210 - North Sink (C)	04/10/24	2.3	None.
70	20480400-070DW	20480400-070DW25A	Room 213 - Drinking Fountain	04/10/24	0.5	None.
71	20480400-071CF	20480400-071CF25A	Room 213 - Sink	04/10/24	ND	None.
72	20480400-072DW	20480400-072DW25A	Room 214 - Drinking Fountain	04/10/24	0.7	None.
73	20480400-073CF	20480400-073CF25A	Room 214 - Sink	04/10/24	0.6	None.
74	20480400-074BF	20480400-074BF25A	Outside Room 214 Boy's Restroom - Trough Sink	04/10/24	0.8	None.
75	20480400-075BF	20480400-075BF25A	Outside Room 214 Girl's Restroom - Trough Sink	04/10/24	1.7	None.
76	20480400-076WB	20480400-076WB25A	Near 2nd Floor Elevator - Bottle Filler (Upper)	04/10/24	ND	Installed Elkay Bottle Filler Unit with Filter. 01/15/2023.
77	20480400-077DW	20480400-077DW25A	Near 2nd Floor Elevator - Drinking Fountain (Lower)	04/10/24	ND	Installed Elkay Bottle Filler Unit with Filter. 01/15/2023.
78	20480400-078BF	20480400-078BF25A	Outside Room 240 Men's Restroom - Sink	04/10/24	3.2	None.
79	20480400-079BF	20480400-079BF25A	Outside Room 240 A Women's Restroom - Sink	04/10/24	5.5	None.
80	20480400-080DW	20480400-080DW25A	Room 241 - Drinking Fountain	04/10/24	ND	None.
81	20480400-081CF	20480400-081CF25A	Room 241 - Sink	04/10/24	0.8	None.
82	20480400-082DW	20480400-082DW25A	Room 242 - Drinking Fountain	04/10/24	0.7	None.
83	20480400-083CF	20480400-083CF25A	Room 242 - Sink	04/10/24	0.6	None.
84	20480400-084DW	20480400-084DW25A	Room 243 - Drinking Fountain	04/10/24	ND	None.
85	20480400-085CF	20480400-085CF25A	Room 243 - Sink	04/10/24	ND	None.
N/A	N/A	N/A	2" Backflow At The Meter	08/15/16	0.2	Water should not be consumed from this backflow.
N/A	N/A	N/A	Fire Vault - Backflow	08/10/16	10.9	Water should not be consumed from this backflow.
N/A	N/A	N/A	Mechanical Room - Main Drain From PRV	08/15/16	1.7	Water should not be consumed from this drain.
N/A	N/A	N/A	Room 104 - Mechanical Room - 2nd Drain	06/22/17	1.0	Water should not be consumed from this drain.

Lead Tests - Jackson Elementary School - Rooms 144-145 Building - # 20480401

#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20480401-001DW	20480401-001DW25A	Modular Room 144 - Drinking Fountain	04/10/24	ND	None.
2	20480401-002CF	20480401-002CF25A	Modular Room 144 - Sink	04/10/24	ND	None.
3	20480401-003BF	20480401-003BF25A	Modular Room 144 - Restroom - Sink	04/10/24	ND	None.
4	20480401-004DW	20480401-004DW25A	Modular Room 145 - Drinking Fountain	04/10/24	ND	None.
5	20480401-005CF	20480401-005CF25A	Modular Room 145 - Sink	04/10/24	ND	None.
6	20480401-006BF	20480401-006BF25A	Modular Room 145 - Restroom - Sink	04/10/24	ND	None.

Lead Tests - Jackson Elementary School - Cafeteria - # 20480402

#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20480402-001DW	20480402-001DW25A	Cafeteria - Drinking Fountain (Upper)	04/10/24	0.8	None.
2	20480402-002DW	20480402-002DW25A	Cafeteria - Drinking Fountain (Lower)	04/10/24	ND	None.
3	20480402-003BF	20480402-003BF25A	Cafeteria Boy's Restroom - Sink (Left)	04/10/24	2.0	None.
4	20480402-004BF	20480402-004BF25A	Cafeteria Boy's Restroom - Sink (Right)	04/10/24	1.3	None.
5	20480402-005BF	20480402-005BF25A	Cafeteria Girl's Restroom - Sink (Left)	04/10/24	1.3	None.
6	20480402-006BF	20480402-006BF25A	Cafeteria Girl's Restroom - Sink (Right)	04/10/24	4.3	None.
7	20480402-007KF	20480402-007KF25A	Kitchen - Sink (Pre-rinse/Dishwasher)	04/10/24	1.3	None.
8	20480402-008KF	20480402-008KF25A	Kitchen - Sink (Hand Wash)	04/10/24	ND	None.
9	20480402-009KF	20480402-009KF25A	Kitchen - Sink (Food Prep)	04/10/24	ND	This drinking fountain has a lead filter on it.
N/A	N/A	N/A	Cafeteria - Drinking Fountain (Bottle Filler)	08/09/16	9.7	This bottle filler was removed permanently.

Lead Tests - Jackson Elementary School - Gymnasium - # 20480403

#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20480403-001DW	20480403-001DW25A	Gym - Drinking Fountain (Upper)	04/10/24	ND	This drinking fountain has a lead filter on it.
2	20480403-002DW	20480403-002DW25A	Gym - Drinking Fountain (Lower)	04/10/24	ND	This drinking fountain has a lead filter on it.
3	20480403-003BF	20480403-003BF25A	Gym Boy's Restroom - Sink	04/10/24	ND	None.
4	20480403-004BF	20480403-004BF25A	Gym Girl's Restroom - Sink	04/10/24	ND	None.
Lead Tests - Jackson Elementary School - Kids Health Connection - # 20480404						
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20480404-001BF	20480404-001BF25A	La Clinica Restroom - Sink	04/10/24	ND	None.
2	20480404-002NS	20480404-002NS25A	La Clinica Exam Room 1 - Sink	04/10/24	1.0	None.
3	20480404-003NS	20480404-003NS25A	La Clinica Exam Room 2 - Sink	04/10/24	1.7	None.
4	20480404-004NS	20480404-004NS25A	La Clinica Exam Room 3 - Sink	04/10/24	3.0	None.
5	20480404-005NS	20480404-005NS25A	La Clinica Hallway By Back Door - Sink	04/10/24	1.1	None.
6	20480404-006SF	20480404-006SF25A	La Clinica Break Room - Sink	04/10/24	ND	None.

*None Detected (ND) = 0.10 Or Less PPB

= Fixture Where Water Has The Potential of Being Consumed (All of These Will Be Tested When Testing The Whole School)

*ODE's required action level is 15 parts per billion (PPB)

*The E.P.A.'s recommended action level for lead in schools is 20 PPB. Oregon's action level for schools changed to 15 PPB in 2019 in accordance with OAR 333-061-0400.

In 2021, ODE changed the unit of measurement for reporting to parts per billion (PPB).

*The E.P.A. action level for copper is 1.30

*Lead test results will be posted on the MSD/Facilities website within 5 days minus the school map for security purposes.