

Lead Tests - Roosevelt Elementary School - Main Building - # 20481000						
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20481000-001DW	20481000-001DW25A	Room 110 - South Drinking Fountain (A)	04/11/24	ND	None.
2	20481000-002CF	20481000-002CF25A	Room 110 - South Sink (A)	04/11/24	ND	None.
3	20481000-003DW	20481000-003DW25A	Room 110 - NW Drinking Fountain (B)	04/11/24	ND	None.
4	20481000-004CF	20481000-004CF25A	Room 110 - NW Sink (B)	04/11/24	1.3	None.
5	20481000-005DW	20481000-005DW25A	Room 110 - NE Drinking Fountain (C)	04/11/24	ND	None.
6	20481000-006CF	20481000-006CF25A	Room 110 - NE Sink (C)	04/11/24	0.6	None.
7	20481000-007OT	20481000-007OT25A	Outside Room 110 In South Outdoor Storage Closet - Sink	04/30/24	26.1	Removed May 2024.
8	20481000-008DW	20481000-008DW25A	Behind Sliding Door Infront of Room 110 - Drinking Fountain	04/11/24	ND	None.
9	20481000-009OT	20481000-009OT25A	Behind Sliding Door Infront of Room 110 - Sink	04/11/24	0.5	None.
10	20481000-010DW	20481000-010DW25A	Room 114 - Drinking Fountain	04/11/24	ND	None.
11	20481000-011CF	20481000-011CF25A	Room 114 - Sink	04/11/24	ND	None.
12	20481000-012DW	20481000-012DW25A	Room 113 - Drinking Fountain	04/11/24	ND	None.
13	20481000-013CF	20481000-013CF25A	Room 113 - Sink	04/11/24	ND	None.
14	20481000-014DW	20481000-014DW25A	Room 112 - Drinking Fountain	04/11/24	ND	None.
15	20481000-015CF	20481000-015CF25A	Room 112 - Sink	04/11/24	ND	None.
16	20481000-016DW	20481000-016DW25A	Room 111 - Drinking Fountain	04/11/24	ND	None.
17	20481000-017CF	20481000-017CF25A	Room 111 - Sink	04/11/24	ND	None.
18	20481000-018NS	20481000-018NS25A	Health Room - Sink (Left Fixture)	04/11/24	1.6	None.
19	20481000-019NS	20481000-019NS25A	Health Room - Sink (Right Fixture)	04/11/24	ND	None.
20	20481000-020BF	20481000-020BF25A	Health Room Unisex Restroom - Sink	04/11/24	0.7	None.
21	20481000-021BF	20481000-021BF25A	Outside Main Office Unisex Restroom (Left) - Sink	04/11/24	1.5	None.
22	20481000-022BF	20481000-022BF25A	Outside Main Office Unisex Restroom (Right) - Sink	04/11/24	3.9	None.
23	20481000-023DW	20481000-023DW25A	Room 140 - West Drinking Fountain (A)	04/11/24	ND	None.
24	20481000-024CF	20481000-024CF25A	Room 140 - West Sink (A)	04/11/24	1.4	None.
25	20481000-025DW	20481000-025DW25A	Room 140 - East Drinking Fountain (B)	04/11/24	ND	None.
26	20481000-026CF	20481000-026CF25A	Room 140 - East Sink (B)	04/11/24	0.6	None.
27	20481000-027OT	20481000-027OT25A	Outside Room 140 In West Outdoor Storage Closet - Sink	04/11/24	5.7	Removed May 2024.
28	20481000-028DW	20481000-028DW25A	Room 141 - Drinking Fountain	04/11/24	ND	None.
29	20481000-029CF	20481000-029CF25A	Room 141 - Sink	04/11/24	1.0	None.
30	20481000-030DW	20481000-030DW25A	Room 142 - Drinking Fountain	04/11/24	ND	None.
31	20481000-031CF	20481000-031CF25A	Room 142 - Sink	04/11/24	0.8	None.
32	20481000-032DW	20481000-032DW25A	Room 143 - Drinking Fountain	04/11/24	ND	None.
33	20481000-033CF	20481000-033CF25A	Room 143 - Sink	04/11/24	1.1	None.
34	20481000-034BF	20481000-034BF25A	Room 140 Boys/Girl's Restroom - Trough Sink	04/11/24	4.4	None.
35	20481000-035DW	20481000-035DW25A	Room 130 - Drinking Fountain	04/11/24	ND	None.
36	20481000-036CF	20481000-036CF25A	Room 130 - Sink	04/11/24	1.3	None.
37	20481000-037BF	20481000-037BF25A	Next To Room 120 Boy's Restroom - Trough Sink	04/11/24	ND	None.
38	20481000-038BF	20481000-038BF25A	Next To Room 120 Girl's Restroom - Trough Sink	04/11/24	1.2	None.
39	20481000-039DW	20481000-039DW25A	Boys/Girl's Restroom Near 120 - Bottle Filler	04/11/24	ND	Elkay with Filter
40	20481000-040DW	20481000-040DW25A	Boys/Girl's Restroom Near 120 - Drinking Fountain	04/11/24	ND	Elkay with Filter
41	20481000-041DW	20481000-041DW25A	Room 120 - Drinking Fountain	04/11/24	ND	None.
42	20481000-042CF	20481000-042CF25A	Room 120 - Sink	04/11/24	0.5	None.
43	20481000-043DW	20481000-043DW25A	Room 121 - Drinking Fountain	04/11/24	ND	None.
44	20481000-044CF	20481000-044CF25A	Room 121 - Sink	04/11/24	0.7	None.
45	20481000-045DW	20481000-045DW25A	Room 122 - Drinking Fountain	04/11/24	ND	None.
46	20481000-046CF	20481000-046CF25A	Room 122 - Sink	04/11/24	0.9	None.
47	20481000-047BF	20481000-047BF25A	2nd Floor Near Elevator Boy's Restroom - Trough Sink	04/11/24	0.5	None.
48	20481000-048BF	20481000-048BF25A	2nd Floor Near Elevator Girl's Restroom - Trough Sink	04/11/24	0.8	None.
49	20481000-049WB	20481000-049WB25A	2nd Floor Outside Boy's Bathroom - Bottle Filler	04/11/24	ND	Elkay with Filter
50	20481000-050DW	20481000-050DW25A	2nd Floor Outside Boy's Bathroom - Drinking Fountain	04/11/24	ND	Elkay with Filter
51	20481000-051SF	20481000-051SF25A	Media Center - Sink	04/11/24	0.6	None.
52	20481000-052DW	20481000-052DW25A	Room 231 - Drinking Fountain	04/11/24	ND	None.
53	20481000-053CF	20481000-053CF25A	Room 231 - Sink	04/11/24	0.5	None.
54	20481000-054DW	20481000-054DW25A	Room 240 - West Drinking Fountain (A)	04/11/24	ND	None.
55	20481000-055CF	20481000-055CF25A	Room 240 - West Sink (A)	04/11/24	1.2	None.
56	20481000-056DW	20481000-056DW25A	Room 240 - East Drinking Fountain (B)	04/11/24	ND	None.
57	20481000-057CF	20481000-057CF25A	Room 240 - East Sink (B)	04/11/24	0.7	None.
58	20481000-058DW	20481000-058DW25A	Room 240 - SE Drinking Fountain (C)	04/11/24	ND	None.
59	20481000-059CF	20481000-059CF25A	Room 240 - SE Sink (C)	04/11/24	1.1	None.
60	20481000-060DW	20481000-060DW25A	Room 241 - Drinking Fountain	04/11/24	0.9	None.
61	20481000-061CF	20481000-061CF25A	Room 241 - Sink	04/11/24	1.0	None.
62	20481000-062DW	20481000-062DW25A	Room 242 - Drinking Fountain	04/11/24	ND	None.
63	20481000-063CF	20481000-063CF25A	Room 242 - Sink	04/11/24	ND	None.

64	20481000-064DW	20481000-064DW25A	Room 243 - Drinking Fountain	04/11/24	ND	None.
65	20481000-065CF	20481000-065CF25A	Room 243 - Sink	04/11/24	0.9	None.
66	20481000-066BF	20481000-066BF25A	Next To Room 203 Men's Restroom - Sink	04/11/24	9.8	None.
67	20481000-067BF	20481000-067BF25A	Next To Room 203 Women's Restroom - Sink	04/11/24	11.7	None.
68	20481000-068SF	20481000-068SF25A	Room 203 (Staff Work Room) - Sink	04/11/24	ND	None.
69	20481000-069SF	20481000-069SF25A	Room 204 (Staff Break Room) - Sink	04/11/24	ND	None.
70	20481000-070SF	20481000-070SF25A	Room 204 (Staff Break Room) - Insta Hot	04/11/24	ND	None.
71	20481000-071DW	20481000-071DW25A	Room 210 - South Drinking Fountain (A)	04/11/24	ND	None.
72	20481000-072CF	20481000-072CF25A	Room 210 - South Sink (A)	04/11/24	0.9	None.
73	20481000-073DW	20481000-073DW25A	Room 210 - NW Drinking Fountain (B)	04/11/24	ND	None.
74	20481000-074CF	20481000-074CF25A	Room 210 - NW Sink (B)	04/11/24	ND	None.
75	20481000-075DW	20481000-075DW25A	Room 210 - NE Drinking Fountain (C)	04/11/24	ND	None.
76	20481000-076CF	20481000-076CF25A	Room 210 - NE Sink (C)	04/11/24	1.6	None.
77	20481000-077DW	20481000-077DW25A	Room 211 - Drinking Fountain	04/11/24	ND	None.
78	20481000-078CF	20481000-078CF25A	Room 211 - Sink	04/11/24	ND	None.
79	20481000-079DW	20481000-079DW25A	Room 212 - Drinking Fountain	04/11/24	ND	None.
80	20481000-080CF	20481000-080CF25A	Room 212 - Sink	04/11/24	ND	None.
81	20481000-081DW	20481000-081DW25A	Room 213 - Drinking Fountain	04/11/24	ND	None.
82	20481000-082CF	20481000-082CF25A	Room 213 - Sink	04/11/24	ND	None.
83	20481000-083DW	20481000-083DW25A	Room 214 - Drinking Fountain	04/11/24	ND	None.
84	20481000-084CF	20481000-084CF25A	Room 214 - Sink	04/11/24	ND	None.

Lead Tests - Roosevelt Elementary School - Cafeteria Building - # 20481001

#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20481001-001DW	20481001-001DW25A	Cafeteria - Drinking Fountain (Upper)	04/11/24	0.8	This drinking fountain has a lead filter on it.
2	20481001-002DW	20481001-002DW25A	Cafeteria - Drinking Fountain (Lower)	04/11/24	0.6	This drinking fountain has a lead filter on it.
N/A	N/A	N/A	Cafeteria - Drinking Fountain (Lower - Bottle Filler)	08/08/16	16.7	The bottle filler was removed permanently.
3	20481001-003BF	20481001-003BF25A	Cafeteria - Women's Restroom - Sink (Left)	04/11/24	2.1	None.
4	20481001-004BF	20481001-004BF25A	Cafeteria - Women's Restroom - Sink (Right)	04/11/24	0.8	None.
5	20481001-005BF	20481001-005BF25A	Cafeteria - Men's Restroom - Sink (Left)	04/11/24	1.0	None.
6	20481001-006BF	20481001-006BF25A	Cafeteria - Men's Restroom - Sink (Right)	04/11/24	2.5	None.
7	20481001-007KF	20481001-007KF25A	Kitchen - Sink (Pre-rinse/Dishwasher)	04/11/24	0.7	None.
8	20481001-008KF	20481001-008KF25A	Kitchen (Double) - Sink (Food Prep - Left)	04/11/24	0.7	This sink has a lead filter on it.
9	20481001-009KF	20481001-009KF25A	Kitchen (Double) - Sink (Handwash - Right)	04/11/24	ND	None.
10	20481001-010KF	20481001-010KF25A	Kitchen - Sink (Hand Wash)	04/11/24	1.9	None.

Lead Tests - Roosevelt Elementary School - Gym Building - # 20481002

#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20481002-001BF	20481002-001BF25A	Gym Men's Restroom - Sink	04/11/24	0.5	None.
2	20481002-002BF	20481002-002BF25A	Gym Women's Restroom - Sink	04/11/24	ND	None.
3	20481002-003DW	20481002-003DW25A	Gym - Drinking Fountain (Upper)	04/11/24	ND	None.
4	20481002-004DW	20481002-004DW25A	Gym - Drinking Fountain (Lower)	04/11/24	ND	None.
5	20481002-005DW	20481002-005DW25A	Playground (Shade Structure) - Drinking Fountain	04/11/24	ND	None.

*None Detected (ND) = 0.10 Or Less PPB

= Fixture Where Water Has The Potential of Being Consumed (All of These Will Be Tested When Testing The Whole School)

*The E.P.A. action level for lead in schools is 20 PPB. Oregon's action level for schools is 15 PPB (Changed in 2019 in accordance with OAR 333-061-0400).

*The E.P.A. action level for copper is 1.30

*Lead test results will be posted on the MSD/Facilities website within 5 days.