

Hedrick Middle School

Lead Tests - Hedrick Middle School - Main Building - # 20481400

| # | Fixture ID # | Sample ID # | Location/Type | Date Tested | Lead Test Results | Remarks |
|-----|----------------|-------------------|---|-------------|-------------------|--|
| 1 | 20481400-001NS | 20481400-001NS21A | Health Room - Sink | 03/16/20 | 0.7 | None. |
| 2 | 20481400-002BF | 20481400-002BF21A | Health Room Unisex Restroom - Sink | 03/16/20 | 0.2 | None. |
| 3 | 20481400-003SF | 20481400-003SF21A | Main Office - Kitchenette | 03/16/20 | 0.2 | None. |
| 4 | 20481400-004DW | 20481400-004DW21A | By The Office - Drinking Fountain (Upper) | 03/16/20 | ND | Has Lead Filter. |
| 5 | 20481400-005WB | 20481400-005DW21A | By The Office - Drinking Fountain (Bottle Filler) | 03/16/20 | ND | Has Lead Filter. |
| 6 | 20481400-006BF | 20481400-006BF21A | Outside Office Staff Men's Restroom - Sink (Left) | 03/16/20 | 1.6 | None. |
| 7 | 20481400-007BF | 20481400-007BF21A | Outside Office Staff Men's Restroom - Sink (Right) | 03/16/20 | 0.2 | None. |
| 8 | 20481400-008BF | 20481400-008BF21A | Outside Office Staff Women's Restroom - Sink (Left) | 03/16/20 | 0.2 | None. |
| 9 | 20481400-009BF | 20481400-009BF21A | Outside Office Staff Women's Restroom - Sink (Right) | 03/16/20 | 1.9 | None. |
| 10 | 20481400-010DW | 20481400-010DW21A | Room 322 - Drinking Fountain | 03/16/20 | 0.2 | None. |
| 11 | 20481400-011CF | 20481400-011CF21A | Room 322 - Sink | 03/16/20 | 0.4 | None. |
| 12 | 20481400-012DW | 20481400-012DW21A | Room 323 - Drinking Fountain | 03/16/20 | 0.2 | None. |
| 13 | 20481400-013CF | 20481400-013CF21A | Room 323 - Sink | 03/16/20 | 0.3 | None. |
| 14 | 20481400-014DW | 20481400-014DW21A | Room 325 - Drinking Fountain | 03/16/20 | 0.3 | None. |
| 15 | 20481400-015CF | 20481400-015CF21A | Room 325 - Sink | 03/16/20 | 0.9 | None. |
| 16 | 20481400-016DW | 20481400-016DW21A | Room 324 - Drinking Fountain | 03/16/20 | 0.1 | None. |
| 17 | 20481400-017CF | 20481400-017CF21A | Room 324 - Sink | 03/16/20 | 0.4 | None. |
| 18 | 20481400-018SF | 20481400-018SF21A | Storage Room In-between (Science) 326/328 - Sink | 03/16/20 | 7.2 | None. |
| N/A | N/A | N/A | Room 326 (Science) - Sink (Island) | N/A | N/A | "Non-Potable Water" Sign Installed 12 Dec 2019. |
| N/A | N/A | N/A | Room 326 (Science) - Eyewash | N/A | N/A | The eyewash station is not for consuming water. |
| N/A | N/A | N/A | Room 326 (Science) - Sink (North Wall - Left) | N/A | N/A | "Non-Potable Water" Sign Installed 12 Dec 2019. |
| N/A | N/A | N/A | Room 326 (Science) - Sink (North Wall - Right) | N/A | N/A | "Non-Potable Water" Sign Installed 12 Dec 2019. |
| N/A | N/A | N/A | Room 326 (Science) - Sink (East Wall - Left) | N/A | N/A | "Non-Potable Water" Sign Installed 12 Dec 2019. |
| N/A | N/A | N/A | Room 326 (Science) - Sink (East Wall - Right) | N/A | N/A | "Non-Potable Water" Sign Installed 12 Dec 2019. |
| N/A | N/A | N/A | Room 328 (Science) - Sink (Island) | 05/16/08 | ND | "Non-Potable Water" Sign Installed 12 Dec 2019. |
| N/A | N/A | N/A | Room 328 (Science) - Eyewash | N/A | N/A | The eyewash station is not for consuming water. |
| N/A | N/A | N/A | Room 328 (Science) - Sink (North Wall - Left) | N/A | N/A | "Non-Potable Water" Sign Installed 12 Dec 2019. |
| N/A | N/A | N/A | Room 328 (Science) - Sink (North Wall - Right) | N/A | N/A | "Non-Potable Water" Sign Installed 12 Dec 2019. |
| N/A | N/A | N/A | Room 328 (Science) - Sink (West Wall - Left) | N/A | N/A | "Non-Potable Water" Sign Installed 12 Dec 2019. |
| N/A | N/A | N/A | Room 328 (Science) - Sink (West Wall - Right) | N/A | N/A | "Non-Potable Water" Sign Installed 12 Dec 2019. |
| 19 | 20481400-019DW | 20481400-019DW21A | Room 327 - Drinking Fountain | 03/16/20 | 0.1 | None. |
| 20 | 20481400-020CF | 20481400-020CF21A | Room 327 - Sink | 03/16/20 | 0.3 | None. |
| 21 | 20481400-021DW | 20481400-021DW21A | Room 329 - Drinking Fountain | 03/16/20 | 0.1 | None. |
| 22 | 20481400-022CF | 20481400-022CF21A | Room 329 - Sink | 03/16/20 | 0.9 | None. |
| 23 | 20481400-023DW | 20481400-023DW21A | Room 331 - Drinking Fountain | 03/16/20 | ND | None. |
| 24 | 20481400-024CF | 20481400-024CF21A | Room 331 - Sink | 03/16/20 | 0.6 | None. |
| 25 | 20481400-025BF | 20481400-025BF21A | Across From Room 331 Women's Restroom - Sink (Left) | 03/16/20 | 0.9 | None. |
| 26 | 20481400-026BF | 20481400-026BF21A | Across From Room 331 Women's Restroom - Sink (Center) | 03/16/20 | 2.7 | None. |
| 27 | 20481400-027BF | 20481400-027BF21A | Across From Room 331 Women's Restroom - Sink (Right) | 03/16/20 | 0.8 | None. |
| 28 | 20481400-028BF | 20481400-028BF21A | Across From Room 334 Men's Restroom - Sink (Left) | 03/16/20 | 1.2 | None. |
| 29 | 20481400-029BF | 20481400-029BF21A | Across From Room 334 Men's Restroom - Sink (Center) | 03/16/20 | 2.1 | None. |
| 30 | 20481400-030BF | 20481400-030BF21A | Across From Room 334 Men's Restroom - Sink (Right) | 03/16/20 | 2.6 | None. |
| 31 | 20481400-031DW | 20481400-031DW21A | In Hallway Between Rooms 331/334 - Drinking Fountain | 03/16/20 | 0.4 | None. |
| 32 | 20481400-032DW | 20481400-032DW21A | Room 334 - Drinking Fountain | 03/16/20 | 0.1 | None. |
| 33 | 20481400-033CF | 20481400-033CF21A | Room 334 - Sink | 03/16/20 | 0.6 | None. |
| 34 | 20481400-034DW | 20481400-034DW21A | Room 336 - Drinking Fountain | 03/16/20 | 0.2 | None. |
| 35 | 20481400-035CF | 20481400-035CF21A | Room 336 - Sink | 03/16/20 | 0.5 | None. |
| 36 | 20481400-036CF | 20481400-036CF21A | Room 335 (Storage Room) - Sink | 06/02/22 | 2.9 | Added to tracker 8/24/21. Replaced Faucet 5/19/22. Lead filter added 06/02/2022. |
| N/A | 20481400-172CF | N/A | Room 335 (Science) - Sink (North Wall - Right) | 05/02/19 | 1.4 | "Non-Potable Water" Sign Installed 12 Dec 2019. |
| N/A | N/A | N/A | Room 335 (Science) - Sink (North Wall - Left) | N/A | N/A | "Non-Potable Water" Sign Installed 12 Dec 2019. |
| N/A | N/A | N/A | Room 335 (Science) - Sink (West Wall) | N/A | N/A | "Non-Potable Water" Sign Installed 12 Dec 2019. |
| N/A | N/A | N/A | Room 335 (Science) - Sink (South Wall) | N/A | N/A | "Non-Potable Water" Sign Installed 12 Dec 2019. |
| N/A | 20481400-173CF | N/A | Room 335 (Science) - Sink (Island) | 05/02/19 | 9.7 | "Non-Potable Water" Sign Installed 12 Dec 2019. |
| N/A | N/A | N/A | Room 335 - Eyewash | N/A | N/A | The eyewash station is not for consuming water. |
| N/A | 20481400-174CF | N/A | Room 337 (Science) - Sink (East Wall) | 05/02/19 | 3.0 | "Non-Potable Water" Sign Installed 12 Dec 2019. |
| N/A | 20481400-175CF | N/A | Room 337 (Science) - Sink (North Wall - Left) | 05/02/19 | 1.7 | "Non-Potable Water" Sign Installed 12 Dec 2019. |
| N/A | 20481400-176CF | N/A | Room 337 (Science) - Sink (North Wall - Right) | 05/02/19 | 1.2 | "Non-Potable Water" Sign Installed 12 Dec 2019. |
| N/A | 20481400-177CF | N/A | Room 337 (Science) - Sink (South Wall) | 05/02/19 | 1.5 | "Non-Potable Water" Sign Installed 12 Dec 2019. |
| N/A | N/A | N/A | Room 337 - Eyewash | N/A | N/A | The eyewash station is not for consuming water. |
| N/A | 20481400-178CF | N/A | Room 337b (Science) - Sink (Island) | 05/02/19 | 1.2 | "Non-Potable Water" Sign Installed 12 Dec 2019. |
| 37 | 20481400-037SF | 20481400-037SF21A | Room 337 Storage Room - Sink | 03/16/20 | 0.5 | None. |
| 38 | 20481400-038DW | 20481400-038DW21A | Room 338 - Drinking Fountain | 03/16/20 | 0.3 | None. |
| 39 | 20481400-039CF | 20481400-039CF21A | Room 338 - Sink | 03/16/20 | 0.7 | None. |
| 40 | 20481400-040DW | 20481400-040DW21A | Wrestling Room - Drinking Fountain | 03/16/20 | 0.6 | None. |
| 41 | 20481400-041DW | 20481400-041DW21A | Room 216 - Drinking Fountain | 03/16/20 | 0.2 | None. |

| | | | | | | |
|-----|----------------|-------------------|--|----------|-----|---|
| 42 | 20481400-042CF | 20481400-042CF21A | Room 216 - Sink | 03/16/20 | 1.2 | None. |
| 43 | 20481400-043DW | 20481400-043DW21A | Room 215 - Drinking Fountain | 03/16/20 | 0.1 | None. |
| 44 | 20481400-044CF | 20481400-044CF21A | Room 215 - Sink | 03/16/20 | 0.8 | None. |
| 45 | 20481400-045DW | 20481400-045DW21A | Media Center Work Room - Drinking Fountain | 03/16/20 | 0.2 | None. |
| 46 | 20481400-046SF | 20481400-046SF21A | Media Center Work Room - Sink | 03/16/20 | 6.3 | None. |
| 47 | 20481400-047DW | 20481400-047DW21A | Media Center Office - Drinking Fountain | 03/16/20 | 0.3 | None. |
| 48 | 20481400-048SF | 20481400-048SF21A | Media Center Office - Sink | 03/16/20 | 0.8 | None. |
| 49 | 20481400-049CF | 20481400-049CF21A | Room 206 A - Sink (Near Washer/Dryer) | 03/16/20 | 3.9 | None. |
| 50 | 20481400-050CF | 20481400-050CF21A | Room 206 (Culinary) - Sink (North Wall - Left) | 03/16/20 | 1.4 | None. |
| 51 | 20481400-051CF | 20481400-051CF21A | Room 206 (Culinary) - Sink (North Wall - Center) | 03/16/20 | 1.1 | None. |
| 52 | 20481400-052CF | 20481400-052CF21A | Room 206 (Culinary) - Sink (North Wall - Right) | 03/16/20 | 1.8 | None. |
| 53 | 20481400-053CF | 20481400-053CF21A | Room 206 (Culinary) - Sink (South Wall - Left) | 03/16/20 | 4.4 | None. |
| 54 | 20481400-054CF | 20481400-054CF21A | Room 206 (Culinary) - Sink (South Wall - Center) | 03/16/20 | 1.5 | None. |
| 55 | 20481400-055CF | 20481400-055CF21A | Room 206 (Culinary) - Sink (South Wall - Right) | 03/16/20 | 1.0 | None. |
| 56 | 20481400-056DW | 20481400-056DW21A | Room 401 - Drinking Fountain | 03/16/20 | 0.4 | None. |
| 57 | 20481400-057CF | 20481400-057CF21A | Room 401 - Sink | 03/16/20 | 1.4 | None. |
| 58 | 20481400-058DW | 20481400-058DW21A | Room 402 - Drinking Fountain | 03/16/20 | 0.4 | None. |
| 59 | 20481400-059CF | 20481400-059CF21A | Room 402 - Sink | 03/16/20 | 1.2 | None. |
| N/A | N/A | N/A | Room 403 - Eye Wash | N/A | N/A | The eyewash station is not for consuming water. |
| N/A | 20481400-179CF | N/A | Room 403 (Science) - Sink (North Wall) | 05/02/19 | 1.8 | "Non-Potable Water" Sign Installed 12 Dec 2019. |
| N/A | 20481400-180CF | N/A | Room 403 (Science) - Sink (West Wall) | 05/02/19 | 1.1 | "Non-Potable Water" Sign Installed 12 Dec 2019. |
| N/A | 20481400-181CF | N/A | Room 403 (Science) - Sink (South Wall - Left) | 05/02/19 | 2.4 | "Non-Potable Water" Sign Installed 12 Dec 2019. |
| N/A | 20481400-182CF | N/A | Room 403 (Science) - Sink (South Wall - Right) | 05/02/19 | 1.8 | "Non-Potable Water" Sign Installed 12 Dec 2019. |
| N/A | 20481400-183CF | N/A | Room 403 (Science) - Sink (Island) | 05/02/19 | 2.1 | "Non-Potable Water" Sign Installed 12 Dec 2019. |
| 60 | 20481400-060DW | 20481400-060DW21A | Room 404 - Drinking Fountain | 03/16/20 | 0.4 | None. |
| 61 | 20481400-061CF | 20481400-061CF21A | Room 404 - Sink | 03/16/20 | 1.3 | None. |
| 62 | 20481400-062BF | 20481400-062BF21A | In-between Room 408/404 Men's Restroom - Sink (Left) | 03/16/20 | 1.9 | None. |
| 63 | 20481400-063BF | 20481400-063BF21A | In-between Room 408/404 Men's Restroom - Sink (Center) | 03/16/20 | 2.1 | None. |
| 64 | 20481400-064BF | 20481400-064BF21A | In-between Room 408/404 Men's Restroom - Sink (Right) | 03/16/20 | 0.4 | None. |
| 65 | 20481400-065BF | 20481400-065BF21A | In-between Room 408/404 Women's Restroom - Sink (Left) | 03/16/20 | 0.8 | None. |
| 66 | 20481400-066BF | 20481400-066BF21A | In-between Room 408/404 Women's Restroom - Sink (Center) | 03/16/20 | 0.6 | None. |
| 67 | 20481400-067BF | 20481400-067BF21A | In-between Room 408/404 Women's Restroom - Sink (Right) | 03/16/20 | 2.3 | None. |
| 68 | 20481400-068DW | 20481400-068DW21A | Room 408 - Drinking Fountain | 03/16/20 | 0.7 | None. |
| 69 | 20481400-069CF | 20481400-069CF21A | Room 408 - Sink | 03/16/20 | 1.8 | None. |
| 70 | 20481400-070DW | 20481400-070DW21A | Room 411 - Drinking Fountain | 03/16/20 | 0.4 | None. |
| 71 | 20481400-071CF | 20481400-071CF21A | Room 411 - Sink | 03/16/20 | 2.7 | None. |
| 72 | 20481400-072DW | 20481400-072DW21A | Room 410 - Drinking Fountain | 03/16/20 | 0.7 | None. |
| 73 | 20481400-073CF | 20481400-073CF21A | Room 410 - Sink | 03/16/20 | 1.0 | None. |
| 74 | 20481400-074DW | 20481400-074DW21A | Room 409 - Drinking Fountain (East Wall) | 03/16/20 | 1.2 | None. |
| N/A | 20481400-184CF | N/A | Room 409 (Science) - Sink (Island) | 05/02/19 | 1.0 | "Non-Potable Water" Sign Installed 12 Dec 2019. |
| N/A | N/A | N/A | Room 409 - Eye Wash | N/A | N/A | The eyewash station is not for consuming water. |
| N/A | 20481400-185CF | N/A | Room 409 (Science) - Sink (North Wall) | 05/02/19 | 2.6 | "Non-Potable Water" Sign Installed 12 Dec 2019. |
| N/A | 20481400-186CF | N/A | Room 409 (Science) - Sink (East Wall) | 05/02/19 | 1.6 | "Non-Potable Water" Sign Installed 12 Dec 2019. |
| N/A | 20481400-187CF | N/A | Room 409 (Science) - Sink (South Wall - Left) | 05/02/19 | 3.3 | "Non-Potable Water" Sign Installed 12 Dec 2019. |
| N/A | 20481400-188CF | N/A | Room 409 (Science) - Sink (South Wall - Right) | 05/02/19 | 1.7 | "Non-Potable Water" Sign Installed 12 Dec 2019. |
| 75 | 20481400-075SF | 20481400-075SF21A | Storage Room In-between 409/403 - Sink | 03/16/20 | 1.4 | None. |
| 76 | 20481400-076DW | 20481400-076DW21A | Room 204 - Drinking Fountain | 03/16/20 | 0.4 | None. |
| 77 | 20481400-077CF | 20481400-077CF21A | Room 204 - Sink | 03/16/20 | 1.1 | None. |
| 78 | 20481400-078DW | 20481400-078DW21A | Room 202 - Drinking Fountain | 03/16/20 | 0.3 | None. |
| 79 | 20481400-079CF | 20481400-079CF21A | Room 202 - Sink | 03/16/20 | 1.2 | None. |
| 80 | 20481400-080DW | 20481400-080DW21A | Room 303 - Drinking Fountain | 03/16/20 | 0.4 | None. |
| 81 | 20481400-081CF | 20481400-081CF21A | Room 303 - Sink | 03/16/20 | 1.9 | None. |
| 82 | 20481400-082DW | 20481400-082DW21A | Across From Room 303 - Drinking Fountain | 03/16/20 | 0.3 | None. |
| 83 | 20481400-083BF | 20481400-083BF21A | Across From Room 303 Men's Restroom - Sink (Left) | 03/16/20 | 2.5 | None. |
| 84 | 20481400-084BF | 20481400-084BF21A | Across From Room 303 Men's Restroom - Sink (Right) | 03/16/20 | 1.4 | None. |
| N/A | 20481400-189CF | N/A | Room 304 (Science) - Sink (Island) | 05/02/19 | 5.1 | "Non-Potable Water" Sign Installed 12 Dec 2019. |
| N/A | N/A | N/A | Room 304 - Eye Wash | N/A | N/A | The eyewash station is not for consuming water. |
| N/A | 20481400-190CF | N/A | Room 304 (Science) - Sink (South Wall) | 05/02/19 | 1.9 | "Non-Potable Water" Sign Installed 12 Dec 2019. |
| N/A | 20481400-191CF | N/A | Room 304 (Science) - Sink (East Wall) | 05/02/19 | 1.6 | "Non-Potable Water" Sign Installed 12 Dec 2019. |
| N/A | 20481400-192CF | N/A | Room 304 (Science) - Sink (North Wall - Left) | 05/02/19 | 4.3 | "Non-Potable Water" Sign Installed 12 Dec 2019. |
| N/A | 20481400-193CF | N/A | Room 304 (Science) - Sink (North Wall - Center) | 05/02/19 | 2.4 | "Non-Potable Water" Sign Installed 12 Dec 2019. |
| N/A | 20481400-194CF | N/A | Room 304 (Science) - Sink (North Wall - Right) | 05/02/19 | 2.9 | "Non-Potable Water" Sign Installed 12 Dec 2019. |
| 85 | 20481400-085SF | 20481400-085SF21A | Room In-between 304/306 Storage Room - Sink | 03/16/20 | 1.9 | None. |
| 86 | 20481400-086BF | 20481400-086BF21A | Across From Room 306 Women's Restroom - Sink (Left) | 03/16/20 | 0.3 | None. |
| 87 | 20481400-087BF | 20481400-087BF21A | Across From Room 306 Women's Restroom - Sink (Center) | 03/16/20 | 1.5 | None. |
| 88 | 20481400-088BF | 20481400-088BF21A | Across From Room 306 Women's Restroom - Sink (Right) | 03/16/20 | 1.3 | None. |
| N/A | 20481400-195CF | N/A | Room 306 (Science) - Sink (Island) | 05/02/19 | 6.4 | "Non-Potable Water" Sign Installed 12 Dec 2019. |
| N/A | 20481400-196CF | N/A | Room 306 (Science) - Sink (East Wall - Left) | 05/02/19 | 3.3 | "Non-Potable Water" Sign Installed 12 Dec 2019. |

| | | | | | | |
|-----|----------------|-------------------|---|----------|------|--|
| N/A | 20481400-197CF | N/A | Room 306 (Science) - Sink (East Wall - Right) | 05/02/19 | 3.3 | "Non-Potable Water" Sign Installed 12 Dec 2019. |
| N/A | 20481400-198CF | N/A | Room 306 (Science) - Sink (North Wall) | 05/02/19 | 3.5 | "Non-Potable Water" Sign Installed 12 Dec 2019. |
| N/A | 20481400-199CF | N/A | Room 306 (Science) - Sink (South Wall - Left) | 05/02/19 | 3.0 | "Non-Potable Water" Sign Installed 12 Dec 2019. |
| N/A | 20481400-200CF | N/A | Room 306 (Science) - Sink (South Wall - Right) | 05/02/19 | 6.2 | "Non-Potable Water" Sign Installed 12 Dec 2019. |
| N/A | N/A | N/A | Room 306 - Eye Wash | N/A | N/A | The eyewash station is not for consuming water. |
| 89 | 20481400-089DW | 20481400-089DW21A | Room 309 - Drinking Fountain | 03/16/20 | 0.5 | None. |
| 90 | 20481400-090CF | 20481400-090CF21A | Room 309 - Sink | 03/16/20 | 1.7 | None. |
| 91 | 20481400-091DW | 20481400-091DW21A | Room 310 - Drinking Fountain | 03/16/20 | 0.6 | None. |
| 92 | 20481400-092CF | 20481400-092CF21A | Room 310 - Sink | 03/16/20 | 1.3 | None. |
| 93 | 20481400-093DW | 20481400-093DW21A | Room 311 - Drinking Fountain | 03/16/20 | 0.6 | None. |
| 94 | 20481400-094CF | 20481400-094CF21A | Room 311 - Sink | 03/16/20 | 1.4 | None. |
| 95 | 20481400-095DW | 20481400-095DW21A | Room 314 - Drinking Fountain | 05/22/20 | 0.2 | This drinking fountain has a lead filter on it. |
| 96 | 20481400-096CF | 20481400-096CF21A | Room 314 - Sink | 05/22/20 | 0.3 | This sink has a lead filter on it. |
| 97 | 20481400-097BF | 20481400-097BF21A | Room 314 Unisex Restroom - Sink | 03/16/20 | 0.2 | None. |
| 98 | 20481400-098DW | 20481400-098DW21A | Room 315 - Drinking Fountain | 03/16/20 | 0.2 | None. |
| 99 | 20481400-099CF | 20481400-099CF21A | Room 315 - Sink | 03/16/20 | 0.9 | None. |
| 100 | 20481400-100DW | 20481400-100DW21A | Room 316 Staff Work Room - Drinking Fountain (North Wall) | 03/16/20 | 4.6 | None. |
| 101 | 20481400-101SF | 20481400-101SF21A | Room 316 Staff Work Room - Sink (North Wall) | 03/16/20 | 2.7 | None. |
| 102 | 20481400-102DW | 20481400-102DW21A | Room 316 Staff Work Room - Drinking Fountain (West Wall) | 03/16/20 | 0.4 | None. |
| 103 | 20481400-103SF | 20481400-103SF21A | Room 316 Staff Work Room - Sink (West Wall) | 03/16/20 | 1.8 | None. |
| 104 | 20481400-104DW | 20481400-104DW21A | Room 317 - Drinking Fountain | 03/16/20 | 0.3 | None. |
| 105 | 20481400-105CF | 20481400-105CF21A | Room 317 - Sink | 03/16/20 | 1.5 | None. |
| 106 | 20481400-106OT | 20481400-106OT21A | Room 119 (Store) - Sink (Utility) | 03/16/20 | 1.6 | None. |
| 107 | 20481400-107CF | 20481400-107CF21A | Room 122 - Sink (South Wall - Left) | 03/16/20 | 10.0 | None. |
| 108 | 20481400-108CF | 20481400-108CF21A | Room 122 - Sink (South Wall - Center) | 03/16/20 | 0.4 | None. |
| 109 | 20481400-109CF | 20481400-109CF21A | Room 122 - Sink (South Wall - Right) | 03/16/20 | 0.4 | None. |
| 110 | 20481400-110CF | 20481400-110CF21A | Room 122 - Sink (East Wall - Back Corner) | 03/16/20 | 1.1 | None. |
| 111 | 20481400-111CF | 20481400-111CF21A | Room 125 - Sink (North Wall - Left) | 03/16/20 | 3.3 | None. |
| 112 | 20481400-112CF | 20481400-112CF21A | Room 125 - Sink (North Wall - Right) | 03/16/20 | 1.5 | None. |
| 113 | 20481400-113CF | 20481400-113CF21A | Room 125 - Sink (South Wall - Left) | 03/16/20 | 0.3 | None. |
| 114 | 20481400-114CF | 20481400-114CF21A | Room 125 - Sink (South Wall - Right) | 03/16/20 | 5.3 | None. |
| 115 | 20481400-115BF | 20481400-115BF21A | Custodial Office Unisex Restroom - Sink | 03/16/20 | 0.7 | None. |
| 116 | 20481400-116DW | 20481400-116DW21A | Room 121 - Drinking Fountain | 03/16/20 | 0.3 | None. |
| 117 | 20481400-117CF | 20481400-117CF21A | Room 121 - Sink | 03/16/20 | 4.0 | None. |
| 118 | 20481400-118BF | 20481400-118BF21A | Room 124 (Staff Break Room) Men's Restroom - Sink (Left) | 03/16/20 | 2.0 | None. |
| 119 | 20481400-119BF | 20481400-119BF21A | Room 124 (Staff Break Room) Men's Restroom - Sink (Right) | 03/16/20 | 1.3 | None. |
| 120 | 20481400-120BF | 20481400-120BF21A | Room 124 (Staff Break Room) Women's Restroom - Sink (L) | 03/16/20 | 0.7 | None. |
| 121 | 20481400-121BF | 20481400-121BF21A | Room 124 (Staff Break Room) Women's Restroom - Sink (R) | 03/16/20 | 0.4 | None. |
| 122 | 20481400-122SF | 20481400-122SF21A | Room 124 (Staff Break Room) - Sink | 03/16/20 | 0.1 | None. |
| 123 | 20481400-123KF | 20481400-123KF21A | Kitchen Hand Wash - Sink (Near Serving Line) | 03/16/20 | 0.5 | None. |
| 124 | 20481400-124KF | 20481400-124KF21A | Kitchen Hand Wash - Sink (In Back Area That Serves Courtyard) | 03/16/20 | 0.4 | None. |
| 125 | 20481400-125KF | 20481400-125KF21A | Kitchen Pre-Rinse/Dishwasher - Sink (Single) | 03/16/20 | 2.5 | None. |
| 126 | 20481400-126KF | 20481400-126KF21A | Kitchen Pre-Rinse/Dishwasher - Sink (Double) | 03/16/20 | 6.2 | None. |
| 127 | 20481400-127KF | 20481400-127KF21A | Kitchen Food Prep - Sink (Double) | 03/16/20 | 0.6 | None. |
| 128 | 20481400-128DW | 20481400-128DW21A | Room 120 - Drinking Fountain | 03/16/20 | 0.6 | None. |
| 129 | 20481400-129CF | 20481400-129CF21A | Room 120 - Sink | 03/16/20 | 0.6 | None. |
| 130 | 20481400-130IM | 20481400-130IM21A | Room 118 - Ice Machine | 03/16/20 | 0.8 | None. |
| 131 | 20481400-131DW | 20481400-131DW21A | Hallway East Side of Gym Near Room 118 - Drinking Fountain | 03/16/20 | 6.0 | None. |
| 132 | 20481400-132BF | 20481400-132BF21A | Next To Room 117 Men's Restroom - Sink (Left) | 03/16/20 | 1.9 | None. |
| 133 | 20481400-133BF | 20481400-133BF21A | Next To Room 117 Men's Restroom - Sink (Center) | 03/16/20 | 2.1 | None. |
| 134 | 20481400-134BF | 20481400-134BF21A | Next To Room 117 Men's Restroom - Sink (Right) | 03/16/20 | 0.3 | None. |
| 135 | 20481400-135BF | 20481400-135BF21A | Next To Room 117 Women's Restroom - Sink (Left) | 03/16/20 | 1.5 | None. |
| 136 | 20481400-136BF | 20481400-136BF21A | Next To Room 117 Women's Restroom - Sink (Center) | 03/16/20 | 0.4 | None. |
| 137 | 20481400-137BF | 20481400-137BF21A | Next To Room 117 Women's Restroom - Sink (Right) | 03/16/20 | 0.4 | None. |
| 138 | 20481400-138BF | 20481400-138BF21A | North East Gym Entrance Unisex Restroom - Sink | 03/16/20 | 0.4 | None. |
| 139 | 20481400-139DW | 20481400-139DW21A | North East Gym Entrance - Drinking Fountain (Upper) | 03/16/20 | ND | This has lead/sediment filter. |
| 140 | 20481400-140DW | 20481400-140DW21A | North East Gym Entrance - Drinking Fountain (Bottle Filler) | 03/16/20 | ND | This has lead/sediment filter. |
| 141 | 20481400-141DW | 20481400-141DW21A | Inside Gym North West Corner - Drinking Fountain | 03/16/20 | 0.1 | This drinking fountain has a lead filter on it for iron. |
| 142 | 20481400-142DW | 20481400-142DW21A | Inside Gym South West Corner - Drinking Fountain | 03/16/20 | 0.2 | This drinking fountain has a lead filter on it. |
| 143 | 20481400-143DW | 20481400-143DW21A | Weight Room (Outside South Entrance) - Drinking Fountain | 03/16/20 | 0.7 | This drinking fountain has a lead filter on it. 1/24/2024 Uninstalled. |
| | | | Weight Room (Outside South Entrance) - Bottle Filler | 01/25/24 | ND | Installed 1/24/2024. Has lead filter. |
| | | | Weight Room (Outside South Entrance) - Drinking Fountain | 01/25/24 | ND | Installed 1/24/2024. Has lead filter. |
| 144 | 20481400-144BF | 20481400-144BF21A | Weight Room (Outside South Entrance) Unisex Restroom - Sink (Left) | 03/16/20 | 2.4 | None. |
| 145 | 20481400-145BF | 20481400-145BF21A | Weight Room (Outside South Entrance) Unisex Restroom - Sink (Right) | 03/16/20 | 4.4 | None. |
| 146 | 20481400-146OS | 20481400-146OS21A | Hose Bib Supplying Water Horse | 05/22/20 | 0.7 | None. |
| N/A | N/A | N/A | Boy's Locker Room - Shower Head (1) | N/A | N/A | Water should not be consumed out of the shower head. |
| N/A | N/A | N/A | Boy's Locker Room - Shower Head (2) | N/A | N/A | Water should not be consumed out of the shower head. |
| N/A | N/A | N/A | Boy's Locker Room - Shower Head (3) | N/A | N/A | Water should not be consumed out of the shower head. |

| | | | | | | |
|-----|----------------|-------------------|--|----------|------|--|
| N/A | N/A | N/A | Boy's Locker Room - Shower Head (4) | N/A | N/A | Water should not be consumed out of the shower head. |
| N/A | N/A | N/A | Boy's Locker Room - Shower Head (5) | N/A | N/A | Water should not be consumed out of the shower head. |
| N/A | N/A | N/A | Boy's Locker Room - Shower Head (6) | N/A | N/A | Water should not be consumed out of the shower head. |
| N/A | N/A | N/A | Boy's Locker Room - Shower Head (7) | N/A | N/A | Water should not be consumed out of the shower head. |
| N/A | N/A | N/A | Boy's Locker Room - Shower Head (8) | N/A | N/A | Water should not be consumed out of the shower head. |
| N/A | N/A | N/A | Boy's Locker Room - Shower Head (9) | N/A | N/A | Water should not be consumed out of the shower head. |
| N/A | N/A | N/A | Boy's Locker Room - Shower Head (10) | N/A | N/A | Water should not be consumed out of the shower head. |
| N/A | N/A | N/A | Boy's Locker Room - Shower Head (11) | N/A | N/A | Water should not be consumed out of the shower head. |
| N/A | N/A | N/A | Boy's Locker Room - Shower Head (12) | N/A | N/A | Water should not be consumed out of the shower head. |
| N/A | N/A | N/A | Boy's Locker Room - Shower Head (13) | N/A | N/A | Water should not be consumed out of the shower head. |
| N/A | N/A | N/A | Boy's Locker Room - Shower Head (14) | N/A | N/A | Water should not be consumed out of the shower head. |
| 147 | 20481400-147BF | 20481400-147BF21A | Boy's Locker Room - Sink (Left - Locker Area) | 03/16/20 | 3.7 | None. |
| 148 | 20481400-148BF | 20481400-148BF21A | Boy's Locker Room - Sink (Right - Locker Area) | 03/16/20 | 2.4 | None. |
| 149 | 20481400-149BF | 20481400-149BF21A | Boy's Locker Room - Sink (Urinal Area) | 03/16/20 | 7.1 | None. |
| 150 | 20481400-150SF | 20481400-150SF21A | Boy's Locker Room Coach - Sink | 03/16/20 | 11.0 | None. |
| 151 | 20481400-151BF | 20481400-151BF21A | Boy's Locker Room Coach Restroom - Sink | 03/16/20 | 2.5 | None. |
| N/A | N/A | N/A | Boy's Locker Room Coach Restroom - Shower | N/A | N/A | Water should not be consumed out of the shower head. |
| N/A | N/A | N/A | Girl's Locker Room - Shower Head (1) | N/A | N/A | Water should not be consumed out of the shower head. |
| N/A | N/A | N/A | Girl's Locker Room - Shower Head (2) | N/A | N/A | Water should not be consumed out of the shower head. |
| N/A | N/A | N/A | Girl's Locker Room - Shower Head (3) | N/A | N/A | Water should not be consumed out of the shower head. |
| N/A | N/A | N/A | Girl's Locker Room - Shower Head (4) | N/A | N/A | Water should not be consumed out of the shower head. |
| N/A | N/A | N/A | Girl's Locker Room - Shower Head (5) | N/A | N/A | Water should not be consumed out of the shower head. |
| N/A | N/A | N/A | Girl's Locker Room - Shower Head (6) | N/A | N/A | Water should not be consumed out of the shower head. |
| N/A | N/A | N/A | Girl's Locker Room - Shower Head (7) | N/A | N/A | Water should not be consumed out of the shower head. |
| N/A | N/A | N/A | Girl's Locker Room - Shower Head (8) | N/A | N/A | Water should not be consumed out of the shower head. |
| N/A | N/A | N/A | Girl's Locker Room - Shower Head (9) | N/A | N/A | Water should not be consumed out of the shower head. |
| N/A | N/A | N/A | Girl's Locker Room - Shower Head (10) | N/A | N/A | Water should not be consumed out of the shower head. |
| N/A | N/A | N/A | Girl's Locker Room - Shower Head (11) | N/A | N/A | Water should not be consumed out of the shower head. |
| N/A | N/A | N/A | Girl's Locker Room - Shower Head (12) | N/A | N/A | Water should not be consumed out of the shower head. |
| N/A | N/A | N/A | Girl's Locker Room - Individual Shower (Left) | N/A | N/A | Water should not be consumed out of the shower head. |
| N/A | N/A | N/A | Girl's Locker Room - Individual Shower (Right) | N/A | N/A | Water should not be consumed out of the shower head. |
| N/A | N/A | N/A | Girl's Locker Room Coach - Shower | N/A | N/A | Water should not be consumed out of the shower head. |
| 152 | 20481400-152DW | 20481400-152DW21A | Girl's Locker Room - Drinking Fountain (Left) | 03/16/20 | 0.5 | This drinking fountain has a lead filter on it for iron. |
| 153 | 20481400-153DW | 20481400-153DW21A | Girl's Locker Room - Drinking Fountain (Right) | 03/16/20 | 0.6 | This drinking fountain has a lead filter on it for iron. |
| 154 | 20481400-154BF | 20481400-154BF21A | Girl's Locker Room - Sink (Left - Locker Area) | 03/16/20 | 3.5 | None. |
| 155 | 20481400-155BF | 20481400-155BF21A | Girl's Locker Room - Sink (Right - Locker Area) | 03/16/20 | 3.2 | None. |
| 156 | 20481400-156BF | 20481400-156BF21A | Girl's Locker Room - Sink (Toilet Area - Left) | 05/22/20 | 0.1 | This sink has a lead filter on it. |
| 157 | 20481400-157BF | 20481400-157BF21A | Girl's Locker Room - Sink (Toilet Area - Center) | 03/16/20 | 1.7 | None. |
| 158 | 20481400-158BF | 20481400-158BF21A | Girl's Locker Room - Sink (Toilet Area - Right) | 03/16/20 | 9.0 | None. |
| 159 | 20481400-159SF | 20481400-159SF21A | Girl's Locker Room Coach - Sink | 03/16/20 | 0.8 | None. |
| 160 | 20481400-160DW | 20481400-160DW21A | Fitness Room (108) - Drinking Fountain | 03/16/20 | 0.2 | None. |
| 161 | 20481400-161DW | 20481400-161DW21A | Room 109 (Band Room) - Drinking Fountain | 03/16/20 | 0.4 | None. |
| 162 | 20481400-162CF | 20481400-162CF21A | Room 109 (Band Room) - Sink | 03/16/20 | 0.6 | None. |
| 163 | 20481400-163DW | 20481400-163DW21A | Room 107 - Drinking Fountain | 03/16/20 | 0.2 | None. |
| 164 | 20481400-164DW | 20481400-164DW21A | Room 106B - Drinking Fountain (West Wall) | 03/16/20 | 0.2 | None. |
| 165 | 20481400-165CF | 20481400-165CF21A | Room 106B - Sink (West Wall) | 03/16/20 | 1.1 | None. |
| 166 | 20481400-166CF | 20481400-166CF21A | Room 106A - Sink (South Wall) | 03/16/20 | 1.4 | None. |
| N/A | N/A | N/A | Room 102 - Eye Wash | N/A | N/A | The eyewash station is not for consuming water. |
| 167 | 20481400-167DW | 20481400-167DW21A | Room 102B - Drinking Fountain | 03/16/20 | 0.2 | None. |
| 168 | 20481400-168CF | 20481400-168CF21A | Room 102B - Sink | 03/16/20 | 1.2 | None. |
| 169 | 20481400-169CF | 20481400-169CF21A | Room 102A - Sink | 03/16/20 | 4.1 | None. |
| 170 | 20481400-170DW | 20481400-170DW21A | Room 103 - Drinking Fountain | 03/16/20 | 4.4 | None. |
| 171 | 20481400-171CF | 20481400-171CF21A | Room 103 - Sink | 03/16/20 | 2.7 | None. |

*None Detected (ND) = 0.10 Or Less PPB

= Fixture Where Water Has The Potential of Being Consumed (All of These Will Be Tested When Testing The Whole School)

*ODE's required action level is 15 parts per billion (PPB)

*The E.P.A.'s recommended action level for lead in schools is 20 PPB. Oregon's action level for schools changed to 15 PPB in 2019 in accordance with OAR 333-061-0400. In 2021, ODE changed the unit of measurement for reporting to parts per billion (PPB).

*The E.P.A. action level for copper is 1.30

*Lead test results will be posted on the MSD/Facilities website within 5 days minus the school map for security purposes.