Harrison ES – Preschool Classrooms Addition & HVAC Upgrades





Harrison ES – Preschool Classrooms Addition & HVAC Upgrades



Completed Work:

- Erosion control measures have been installed.
- > Initial work on the storm system has begun. Pipes and structures have been delivered.
- Existing playground fence has been demolished.
- Asphalt parking lot adjacent to Bruce Street has been demolished.
- Demolition of the existing ceiling has begun.

Upcoming Work / Look Ahead:

- Complete demolition of the existing ceiling.
- > Moving forward on storm main installation.
- Demolish concrete pavement.



Erosion control measures have been installed







Storm system in progress.





Demolition of existing soffit has begun.







Existing playground fence and equipment have been demolished.



