

Lead in School Drinking Water Report

Tumwater Middle School



Date(s) collected: 2023-03-31

Date(s) analyzed: 2023-04-10

Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Lead Test Result (ppb)
373313	Building A1	Sink	Health Room	Only sink	Tap	32
373309	Building A1	Sink - Multi-Compartment	Kitchen	To the right of dishwasher	Sprayer	26
373337	Building C	Sink	Room C1	Only sink	Tap	18
373353	Building B	Sink	Room B21	Sink on right when facing	Tap	17
373314	Building A1	Sink	Room A24	Only sink	Tap	15
373332	Building C	Sink	Only Sink	C7	Tap	15
373315	Building A1	Sink	Room A40	Smaller sink away from larger tub style sinks	Tap	12
373317	Building A1	Sink	Room A40	Middle of the larger sinks	Tap	12
373318	Building	Sink	Room A40	Sink closest to	Tap	11

Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Lead Test Result (ppb)
	A1			kiln		
373346	Building B	Sink	Room B9	Only sink	Tap	11
373316	Building A1	Sink	Room A40	Large sink closest to entrance/exit	Tap	9
373330	Building A1	Sink	Room A96	Only sink	Tap	9
373334	Building C	Sink	Room C8	Only sink	Tap	9
373336	Building C	Sink	Room C10	Only sink	Tap	9
373338	Building C	Sink	Room C2	Only sink	Tap	9
373350	Building B	Sink	Room B3	Only sink	Tap	7
373342	Building C	Sink	Room C4	Only sink	Tap	6
373312	Building A1	Fountain	Cafeteria	In between boys restroom and custodian closet	Water Fountain	5
373335	Building C	Sink	Room C9	Only sink	Tap	5
373339	Building C	Sink	Room C3	Only sink	Tap	5
373347	Building B	Sink	Room B	Only sink	Tap	5
373352	Building B	Sink	Room B21	Left sink when facing sinks	Tap	5
373344	Building B	Sink	Room B7	Only sink	Tap	4
373348	Building B	Sink	Room B1	Only sink	Tap	4
373351	Building B	Sink	Room B4	Only sink	Tap	4
373310	Building	Pot Filler	Kitchen	Next to ice	Other	3

Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Lead Test Result (ppb)
373328	Building A1	Fountain	Old Gymnasium	machine Facing fountains. Fountain on the right	Water Fountain	3
373331	Building A1	Sink	Room A100	Only sink	Tap	3
373345	Building B	Sink	Room B8	Only sink	Tap	3
373349	Building B	Sink	Room B2	Only sink	Tap	3
373306	Building A1	Sink - Multi-Compartment	Kitchen	3 tier sink by entrance/exit door	Tap	2
373307	Building A1	Sink - Multi-Compartment	Kitchen	Largest 3 tier sink next to entrance/exit door	Sprayer	2
373308	Building A1	Sink - Multi-Compartment	Kitchen	Sink closest to refrigerator	Tap	2
373341	Building C	Fountain - Multi-Level with Bottle Filler	Pod Area	Next to room C3	Water Bottle Filler	1
373343	Building B	Fountain	Pod Area	Next to room B7	Water Fountain	1
373311	Building A1	Ice Machine	Kitchen	Next to ovens	Other	<1
373319	Building A1	Fountain - Multi-Level	Outside Lgia	Next to restrooms. Higher fountain	Water Fountain	<1
373320	Building A1	Fountain - Multi-Level	Lgia Area	Next to restrooms	Water Fountain	<1
373321	Building A1	Fountain - Multi-Level with Bottle Filler	Girls Locker Room	Only fountain	Water Bottle Filler	<1
373322	Building	Fountain -	Girls Locker	Only fountain	Water	<1

Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Lead Test Result (ppb)
	A1	Multi-Level with Bottle Filler	Room		Fountain	
373323	Building A1	Fountain - Multi-Level with Bottle Filler	Boys Locker Room	Only fountain	Water Bottle Filler	<1
373324	Building A1	Fountain - Multi-Level with Bottle Filler	Boys Locker Room	Only fountain	Water Fountain	<1
373325	Building A1	Fountain - Multi-Level with Bottle Filler	Band Hallway	Next to family restroom. Higher fountain	Water Fountain	<1
373326	Building A1	Fountain - Multi-Level with Bottle Filler	Band Hallway	Next to family restroom Lower fountain	Water Fountain	<1
373327	Building A1	Fountain - Multi-Level with Bottle Filler	Band Hallway	Next to family restroom	Water Bottle Filler	<1
373329	Building A1	Fountain	Music Area	Next to room A96	Water Fountain	<1
373333	Building C	Fountain	Pod Area	Next to room C8	Water Fountain	<1
373340	Building C	Fountain - Multi-Level with Bottle Filler	Pod Area	Next to room C3	Water Fountain	<1

EXPLANATION OF TESTING AND RESULTS:

Results in this report represent sampling conducted by Washington State Department of Health. Per **RCW 28A.210.410** sampling and testing protocols, samples were collected as first-draw. Depending on size of the school(s) and number of drinking water fixtures, multiple dates for collecting samples may have been necessary to meet sampling and testing protocols. Above is information related to lead sampling for your school(s). For questions regarding testing and result, please email: leadfreekids@doh.wa.gov