

College Station ISD

2007 Bond Update

December 18, 2008

College Hills Elementary School

Masonry Work



Photo Taken 12/15/2008

Front Entrance



Photo Taken 12/15/2008

Cafetorium Area



Photo Taken 12/15/2008

Kitchen Area



Photo Taken 12/15/2008

Music Room



Photo Taken 12/15/2008

Gymnasium



Photo Taken 12/15/2008

Interior Corridor



Photo Taken 12/15/2008

Library Area



Photo Taken 12/15/2008

Ramp Area



Photo Taken 12/15/2008

Rough-In Plumbing



Photo Taken 12/15/2008

Rough-In Plumbing



Photo Taken 12/15/2008

Interior Corridor



Photo Taken 12/15/2008

Rough-In Plumbing



Photo Taken 12/15/2008

Rough-In Plumbing



Photo Taken 12/15/2008

Exterior Masonry Work



Photo Taken 12/15/2008

Exterior Masonry Work



Photo Taken 12/15/2008

Creek View Elementary School

Exterior View (looking to West)



Photo Taken 12/15/2008

Exterior View (looking to SW)



Photo Taken 12/15/2008

Entrance Canopy



Photo Taken 12/15/2008

Cafetorium Entrance



Photo Taken 12/15/2008

Forms for Concrete Placement



Photo Taken 12/15/2008

Forms for Concrete Placement



Photo Taken 12/15/2008

Exterior View from Rear of Building



Photo Taken 12/15/2008

Cabling Work



Photo Taken 12/15/2008

Electrical Conduit



Photo Taken 12/15/2008

Data Cable



Photo Taken 12/15/2008

Library Area



Photo Taken 12/15/2008

Library Area



Photo Taken 12/15/2008

Corridor



Photo Taken 12/15/2008

Door Frame to Cafetorium



Photo Taken 12/15/2008

Ceramic Tile in Restroom



Photo Taken 12/15/2008

Kitchen Area



Photo Taken 12/15/2008

Walk-In Refrigerator and Freezer



Photo Taken 12/15/2008

Cafetorium Area



Photo Taken 12/15/2008