

College Station ISD

2007 Bond Project Update

June 20, 2008

College Hills Elementary School

Photos taken 06-20-2008

Fence for Temporary Parking



Photos taken 06-20-2008

Asbestos Abatement



Photos taken 06-20-2008

Barrier Separating Construction from Campus



Photos taken 06-20-2008

Site Leveling



Photos taken 06-20-2008

Site Leveling



Photos taken 06-20-2008

Construction Office



Photos taken 06-20-2008

Site Leveling



Photos taken 06-20-2008

Site Leveling



Photos taken 06-20-2008

Creek View Elementary School

Photos taken 06-20-2008

Driveway Concrete Placement



Photos taken 06-20-2008

Driveway Concrete Placement



Photos taken 06-20-2008

Eagle Drive looking from East to West



Photos taken 06-20-2008

Eagle Drive Concrete Placement



Photos taken 06-20-2008

Gymnasium Walls



Photos taken 06-20-2008

Preparations for Carton Forms



Photos taken 06-20-2008

Finished Slab in Cafeteria Area



Photos taken 06-20-2008

Grounds Facility

Photos taken 06-20-2008

Grounds Equipment Storage Building



Photos taken 06-20-2008

Grounds Building Addition



Photos taken 06-20-2008

Athletics Renovation Project

Photos taken 06-20-2008

Stadium Field House Addition



Photos taken 06-20-2008

Track Surface Work



Photos taken 06-20-2008

Stadium Field House Painted Door Jambs



Photos taken 06-20-2008

Stadium Field House Locker Room



Photos taken 06-20-2008

Track Surface Work



Photos taken 06-20-2008

Track Surface Work



Photos taken 06-20-2008

Track Surface Work



Photos taken 06-20-2008

Stadium Home Side Rest Room



Photos taken 06-20-2008

Multi-Sport Field House Exterior Brick



Photos taken 06-20-2008

Multi-Sport Field House Overhead Plumbing



Photos taken 06-20-2008