

College Station ISD

2007 Bond Project Update

September 17, 2008

Creek View
Elementary School

Roof Joists and Decking Electrical Rough-In



Photo Taken 09/16/2008

Roof Joists and Decking Electrical Rough-In



Photo Taken 09/16/2008

Roof Joists and Decking Electrical Rough-In



Photo Taken 09/16/2008

Roof Joists and Decking Electrical Rough-In



Photo Taken 09/16/2008

Roof Joists and Decking Electrical Rough-In



Photo Taken 09/16/2008

Plumbing Rough-In



Photo Taken 09/16/2008

Plumbing Rough-In



Photo Taken 09/16/2008

Plumbing Rough-In



Photo Taken 09/16/2008

Plumbing Rough-In



Photo Taken 09/16/2008

Stage Area



Photo Taken 09/16/2008

Stage Area



Photo Taken 09/16/2008

HVAC Rough-In



Photo Taken 09/16/2008

HVAC Rough-In



Photo Taken 09/16/2008

HVAC Rough-In



Photo Taken 09/16/2008

HVAC Rough-In



Photo Taken 09/16/2008

Gym Interior and Partial Roof Deck



Photo Taken 09/16/2008

Exterior Walls



Photo Taken 09/16/2008

Exterior Walls



Photo Taken 09/16/2008

Kitchen Service Entrance



Photo Taken 09/16/2008

Gym Exterior



Photo Taken 09/16/2008

Masonry Work



Photo Taken 09/16/2008

Masonry Work



Photo Taken 09/16/2008

Masonry Work



Photo Taken 09/16/2008

College Hills
Elementary School

Gym Structural Masonry



Photo Taken 09/16/2008

Gym Structural Masonry



Photo Taken 09/16/2008

Grade Beams



Photo Taken 09/16/2008

Grade Beams



Photo Taken 09/16/2008

Grade Beams and Slab Transition Area



Photo Taken 09/16/2008

Grade Beam Forms



Photo Taken 09/16/2008

Grade Beam Forms



Photo Taken 09/16/2008

Slab Transition Area



Photo Taken 09/16/2008