

College Station ISD

2007 Bond Project Update

August 18, 2008

College Hills
Elementary School

Preparations for Slab Pour



Photo taken Friday, August 15, 2008

Preparations for Slab Pour



Photo taken Friday, August 15, 2008

Preparations for Slab Pour



Photo taken Friday, August 15, 2008

Grade Beams



Photo taken Friday, August 15, 2008

Preparations for Grade Beam Pour



Photo taken Friday, August 15, 2008

Grade Beam Forms at Floor Plate Transition Area



Photo taken Friday, August 15, 2008

Grade Beam Forms



Photo taken Friday, August 15, 2008

Grade Beam Forms



Photo taken Friday, August 15, 2008

Grade Beam Forms



Photo taken Friday, August 15, 2008

Slab in Kitchen Area



Photo taken Friday, August 15, 2008

Aftermath of Rain



Photo taken Saturday, August 16, 2008

Aftermath of Rain



Photo taken Saturday, August 16, 2008

Aftermath of Rain



Photo taken Saturday, August 16, 2008

Aftermath of Rain



Photo taken Saturday, August 16, 2008

Creek View
Elementary School

Structural Steel



Photo taken Friday, August 15, 2008

Interior Structural Steel



Photo taken Friday, August 15, 2008

Kitchen Area



Photo taken Friday, August 15, 2008

Interior Structural Steel



Photo taken Friday, August 15, 2008

Gymnasium



Photo taken Friday, August 15, 2008

Structural Steel



Photo taken Friday, August 15, 2008

Moisture Barrier – Exterior of Office Area



Photo taken Friday, August 15, 2008

Exterior of Cafetorium and Office



Photo taken Friday, August 15, 2008

Exterior of Gymnasium and Kitchen



Photo taken Friday, August 15, 2008

Exterior of Kitchen Area



Photo taken Friday, August 15, 2008

Exterior Looking to Southeast



Photo taken Friday, August 15, 2008

Structural Steel



Photo taken Friday, August 15, 2008

Structural Steel



Photo taken Friday, August 15, 2008

Athletics Complex Renovations

Open House Held 8/10/2008

