

College Station ISD

2007 Bond Project Update

July 15, 2008

Creek View
Elementary School

Gym and Cafeteria Area



Photo taken 07/11/2008

Masonry on Gymnasium



Photo taken 07/11/2008

Slab in Classroom Wing



Photo taken 07/11/2008

Grade Beams in Classroom Wing



Photo taken 07/11/2008

Grade Beam Forms and Steel in Classroom Wing



Photo taken 07/11/2008

Grade Beam Forms and Piers



Photo taken 07/11/2008

Eagle Drive Looking East



Photo taken 07/11/2008

Entrance to Creek View Elementary from Eagle Drive



Photo taken 07/11/2008

Eagle Drive Looking West



Photo taken 07/11/2008

College Hills
Elementary School

Temporary Parking Facility



Photo taken 07/11/2008

Temporary Parking Facility



Photo taken 07/11/2008

Temporary Parking Facility



Photo taken 07/11/2008

Drill Rig for Support Piers



Photo taken 07/11/2008

Steel for Support Piers



Photo taken 07/11/2008

Kitchen Rough-In Plumbing



Photo taken 07/11/2008

Kitchen Rough-In Plumbing



Photo taken 07/11/2008

Kitchen Rough-In Plumbing



Photo taken 07/11/2008

Kitchen Rough-In Plumbing



Photo taken 07/11/2008

Construction Site Looking South to North



Photo taken 07/11/2008

Athletics Complex Renovations

Multi-Sport Field House Exterior



Photo taken 07/11/2008

Multi-Sport Field House Interior



Photo taken 07/11/2008

Multi-Sport Field House Interior



Photo taken 07/11/2008

Multi-Sport Field House Interior



Photo taken 07/11/2008

Stadium Field House Weight Room Ceiling



Photo taken 07/11/2008

Stadium Field House Ceiling Grid



Photo taken 07/11/2008

Stadium Field House Electrical and Data Outlets



Photo taken 07/11/2008

Stadium Field House Casework



Photo taken 07/11/2008

Stadium Field House Casework



Photo taken 07/11/2008

Stadium Field House Casework



Photo taken 07/11/2008

Stadium Field House Painting



Photo taken 07/11/2008

Stadium Field House Painted Ceiling



Photo taken 07/11/2008

Stadium Field House Showers



Photo taken 07/11/2008

Elevator to Press Box



Photo taken 07/11/2008

Ground Floor Entrance to Press Box Elevator

(Plastic Protective Covering)



Photo taken 07/11/2008

Upper Level Entrance to Press Box Elevator

(Plastic Protective Covering)



Photo taken 07/11/2008

Stadium Home Side Men's Restroom



Photo taken 07/11/2008

Stadium Home Side Ladies Restroom



Photo taken 07/11/2008

Track Surface and Artificial Turf



Photo taken 07/11/2008

Track Surface and Artificial Turf



Photo taken 07/11/2008

Track Surface and Artificial Turf



Photo taken 07/11/2008

Grounds Department

Office And Restroom Building Addition



Photo taken 07/11/2008

Material Storage Bins



Photo taken 07/11/2008

Grounds Equipment Storage Building



Photo taken 07/11/2008