



Environmental Hazards Services, L.L.C.
 7469 Whitepine Rd
 Richmond, VA 23237
 Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Client: Stohl Environmental
 3860 California Road
 Orchard Park, NY 14127

Report Number: 21-02-00332

Received Date: 02/02/2021

Reported Date: 02/26/2021

Sampled By: Paul Nichols

Tech Certification #:

Project/Test Address: 2020L-159.1; Grand Island CSD; Grand Island Senior High School; 1100 Ransom Road; Grand Island, NY 14072

Client Number:
 33-5980

Laboratory Results

Fax Number:
 716-312-8092

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-02-00332-001	159.1-1A	01/26/2021	D.O. DF	<1.00	02/16/2021	
21-02-00332-002	159.1-1B	01/26/2021	D.O. DFB	<1.00	02/16/2021	
21-02-00332-003	159.1-2	01/26/2021	D.O. KITCHENETTE	1.04	02/17/2021	
21-02-00332-004	159.1-3	01/26/2021	D.O. GENDERLESS RESTROOM	2.88	02/16/2021	
21-02-00332-005	159.1-4	01/26/2021	D.O. WOMENS RESTROOM	<1.00	02/16/2021	
21-02-00332-006	159.1-5	01/26/2021	CONFRENCE ROOM	2.21	02/17/2021	
21-02-00332-007	159.1-7	01/26/2021	GYM HALLWAY ALL GENDER RESTROOM LEFT	4.88	02/17/2021	
21-02-00332-008	159.1-8	01/26/2021	GYM HALLWAY ALL GENDER RESTROOM RIGHT	4.83	02/17/2021	
21-02-00332-009	159.1-9	01/26/2021	GYM HALLWAY WOMENS RESTROOM	3.05	02/17/2021	
21-02-00332-010	159.1-10	01/26/2021	GYM HALLWAY WOMENS RESTROOM	3.71	02/17/2021	
21-02-00332-011	159.1-11	01/26/2021	PSYCHOLOGY LECTURE ROOM 110	13.6	02/17/2021	
21-02-00332-012	159.1-13	01/26/2021	BOYS TEAM ROOM SINK	14.3	02/17/2021	

Environmental Hazards Services, L.L.C

Client Number: 33-5980

Report Number: 21-02-00332

Project/Test Address: 2020L-159.1; Grand Island CSD; Grand Island Senior High School; 1100 Ransom Road; Grand Island, NY 14072

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-02-00332-013	159.1-14	01/26/2021	BOYS TEAM ROOM COACH'S OFFICE	15.6	02/17/2021	
21-02-00332-014	159.1-15	01/26/2021	TRAINERS ROOM SINK	20.6	02/17/2021	
21-02-00332-015	159.1-16	01/26/2021	TRAINERS ROOM ICE MACHINE	<1.00	02/17/2021	
21-02-00332-016	159.1-19	01/26/2021	BOYS TEAM ROOM 115	62.6	02/17/2021	
21-02-00332-017	159.1-22	01/26/2021	PRACTICE GYM WOMENS RESTROOM INSIDE	2.15	02/17/2021	
21-02-00332-018	159.1-23	01/26/2021	PRACTICE GYM WOMENS RESTROOM OUTSIDE	<1.00	02/17/2021	
21-02-00332-019	159.1-24	01/26/2021	PRATICE GYM MENS RESTROOM OUTSIDE	<1.00	02/17/2021	
21-02-00332-020	159.1-25	01/26/2021	GIRLS TEAM ROOM A SINK	<1.00	02/17/2021	
21-02-00332-021	159.1-26	01/26/2021	GIRLS TEAM ROOM D SINK	<1.00	02/17/2021	
21-02-00332-022	159.1-30	01/26/2021	GIRLS TEAM ROOM C SINK	1.49	02/17/2021	
21-02-00332-023	159.1-34	01/26/2021	GIRLS TEAM ROOM B SINK	6.03	02/17/2021	
21-02-00332-024	159.1-35	01/26/2021	ART 121A LEFT	5.35	02/17/2021	
21-02-00332-025	159.1-36	01/26/2021	ART 121A LEFT MIDDLE	4.93	02/17/2021	
21-02-00332-026	159.1-37	01/26/2021	ART 121A RIGH MIDDLE	3.47	02/17/2021	
21-02-00332-027	159.1-38	01/26/2021	ART 121A RIGHT	2.27	02/17/2021	
21-02-00332-028	159.1-39	01/26/2021	ART 121B	8.04	02/17/2021	
21-02-00332-029	159.1-40	01/26/2021	ART 121B	2.91	02/17/2021	
21-02-00332-030	159.1-41	01/26/2021	ART 121B	12.1	02/17/2021	
21-02-00332-031	159.1-43	01/26/2021	GIRLS POOL LOCKER ROOM SINK LEFT	1.10	02/17/2021	
21-02-00332-032	159.1-44	01/26/2021	GIRLS POOL LOCKER ROOM SINK RIGHT	<1.00	02/17/2021	

Environmental Hazards Services, L.L.C

Client Number: 33-5980

Report Number: 21-02-00332

Project/Test Address: 2020L-159.1; Grand Island CSD; Grand Island Senior High School; 1100 Ransom Road; Grand Island, NY 14072

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-02-00332-033	159.1-45	01/26/2021	GIRLS POOL COACH'S OFFICE	7.61	02/17/2021	
21-02-00332-034	159.1-49	01/26/2021	BOYS POOL LOCKER ROOM SINK LEFT	2.16	02/17/2021	
21-02-00332-035	159.1-50	01/26/2021	BOYS POOL LOCKER ROOM SINK RIGHT	2.25	02/17/2021	
21-02-00332-036	159.1-51	01/26/2021	BOYS POOL COACH'S OFFICE	2.14	02/17/2021	
21-02-00332-037	159.1-53	01/26/2021	122 ART ROOM LEFT WALL LEFT SINK	<1.00	02/17/2021	
21-02-00332-038	159.1-54	01/26/2021	122 ART ROOM LEFT WALL MIDDLE SINK	<1.00	02/17/2021	
21-02-00332-039	159.1-55	01/26/2021	122 ART ROOM LEFT WALL RIGHT SINK	<1.00	02/17/2021	
21-02-00332-040	159.1-56	01/26/2021	122 ART ROOM RIGHT WALL LEFT SINK	8.27	02/17/2021	
21-02-00332-041	159.1-57	01/26/2021	122 ART ROOM RIGHT WALL MIDDLE SINK	2.73	02/17/2021	
21-02-00332-042	159.1-58	01/26/2021	122 ART ROOM RIGHT WALL RIGHT SINK	2.97	02/19/2021	
21-02-00332-043	159.1-59	01/26/2021	122 ART ROOM RIGHT WALL BUBBLER	13.4	02/19/2021	
21-02-00332-044	159.1-61	01/26/2021	123B TECH ROOM LEFT SINK	23.2	02/19/2021	
21-02-00332-045	159.1-62	01/26/2021	123B TECH ROOM RIGHT SINK	3.88	02/19/2021	
21-02-00332-046	159.1-63	01/26/2021	124 PT ROOM MAIN	<1.00	02/19/2021	
21-02-00332-047	159.1-64	01/26/2021	124 PT ROOM RESTROOM	<1.00	02/19/2021	
21-02-00332-048	159.1-65	01/26/2021	INDOOR CONCESSION	<1.00	02/19/2021	
21-02-00332-049	159.1-66B	01/26/2021	DF NEAR CONCESSION	<1.00	02/19/2021	
21-02-00332-050	159.1-67	01/26/2021	GIRLS RESTROOM NEAR CONCESSION LEFTMOST	1.10	02/19/2021	
21-02-00332-051	159.1-68	01/26/2021	GIRLS RESTROOM NEAR CONCESSION 2ND FROM LEFT	1.15	02/19/2021	

Environmental Hazards Services, L.L.C

Client Number: 33-5980

Report Number: 21-02-00332

Project/Test Address: 2020L-159.1; Grand Island CSD; Grand Island Senior High School; 1100 Ransom Road; Grand Island, NY 14072

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-02-00332-052	159.1-69	01/26/2021	GIRLS RESTROOM NEAR CONCESSION 3RD FROM LEFT	<1.00	02/19/2021	
21-02-00332-053	159.1-70	01/26/2021	GIRLS RESTROOM NEAR CONCESSION 4TH FROM LEFT	7.38	02/19/2021	
21-02-00332-054	159.1-71	01/26/2021	GIRLS RESTROOM NEAR CONCESSION 5TH FROM LEFT	3.96	02/19/2021	
21-02-00332-055	159.1-72	01/26/2021	GIRLS RESTROOM NEAR CONCESSION 6TH FROM LEFT	2.75	02/19/2021	
21-02-00332-056	159.1-73	01/26/2021	GIRLS RESTROOM NEAR CONCESSION RIGHTMOST	4.00	02/19/2021	
21-02-00332-057	159.1-74	01/26/2021	BOYS RESTROOM NEAR CONCESSION LEFTMOST	2.08	02/19/2021	
21-02-00332-058	159.1-75	01/26/2021	BOYS RESTROOM NEAR CONCESSION 2ND FROM LEFT	<1.00	02/19/2021	
21-02-00332-059	159.1-76	01/26/2021	BOYS RESTROOM NEAR CONCESSION 3RD FROM LEFT	<1.00	02/19/2021	
21-02-00332-060	159.1-77	01/26/2021	BOYS RESTROOM NEAR CONCESSION 4TH FROM LEFT	<1.00	02/19/2021	
21-02-00332-061	159.1-78	01/26/2021	BOYS RESTROOM NEAR CONCESSION 5TH FROM LEFT	<1.00	02/19/2021	
21-02-00332-062	159.1-79	01/26/2021	BOYS RESTROOM NEAR CONCESSION RIGHTMOST	<1.00	02/19/2021	
21-02-00332-063	159.1-80	01/26/2021	CUSTODIAL STAFF RESTROOM	3.28	02/19/2021	
21-02-00332-064	159.1-81	01/26/2021	LEFT SINK DOUBLE	12.6	02/22/2021	

Environmental Hazards Services, L.L.C

Client Number: 33-5980

Report Number: 21-02-00332

Project/Test Address: 2020L-159.1; Grand Island CSD; Grand Island Senior High School; 1100 Ransom Road; Grand Island, NY 14072

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-02-00332-065	159.1-82	01/26/2021	RIGHT SINK DOUBLE	8.56	02/22/2021	
21-02-00332-066	159.1-83	01/26/2021	LARGE POT FILL	4.02	02/22/2021	
21-02-00332-067	159.1-84	01/26/2021	DISH WASH SPRAYER	<1.00	02/22/2021	
21-02-00332-068	159.1-85	01/26/2021	FOOD WASH SINK NEAR FREEZER	3.13	02/22/2021	
21-02-00332-069	159.1-86	01/26/2021	FOOD WASH SINK NEAR SMALL POT FILL	6.90	02/22/2021	
21-02-00332-070	159.1-87	01/26/2021	SMALL POT FILL	79.6	02/15/2021	
21-02-00332-071	159.1-88	01/26/2021	KITCHEN LOCKER ROOM	3.34	02/22/2021	
21-02-00332-072	159.1-89	01/26/2021	HANDWASH KITCHEN	<1.00	02/22/2021	
21-02-00332-073	159.1-90	01/26/2021	MENS RESTROOM NEAR CAFE	2.08	02/22/2021	
21-02-00332-074	159.1-91	01/26/2021	WOMENS RESTROOM NEAR CAFE	2.99	02/22/2021	
21-02-00332-075	159.1-92	01/26/2021	WHEELCHAIR ACCESSIBLE RESTROOM NEAR CAFE	<1.00	02/22/2021	
21-02-00332-076	159.1-94	01/26/2021	GUIDANCE OFFICE	<1.00	02/22/2021	
21-02-00332-077	159.1-95	01/26/2021	NURSES OFFICE MAIN	<1.00	02/22/2021	
21-02-00332-078	159.1-96	01/26/2021	NURSES OFFICE EXAM ROOM	<1.00	02/22/2021	
21-02-00332-079	159.1-97	01/26/2021	NURSES OFFICE STAFF RESTROOM	<1.00	02/22/2021	
21-02-00332-080	159.1-98	01/26/2021	NURSES OFFICE RESTROOM	<1.00	02/22/2021	
21-02-00332-081	159.1-99	01/26/2021	LIBRARY	17.2	02/22/2021	
21-02-00332-082	159.1-100	01/26/2021	ROOM 152	12.9	02/22/2021	
21-02-00332-083	159.1-102	01/26/2021	SCIENCE WOMEN'S RESTROOM LEFTMOST SINGLE SINK	8.83	02/22/2021	

Environmental Hazards Services, L.L.C

Client Number: 33-5980

Report Number: 21-02-00332

Project/Test Address: 2020L-159.1; Grand Island CSD; Grand Island Senior High School; 1100 Ransom Road; Grand Island, NY 14072

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-02-00332-084	159.1-103	01/26/2021	SCIENCE WOMEN'S RESTROOM 2ND FROM LEFT	2.10	02/22/2021	
21-02-00332-085	159.1-104	01/26/2021	SCIENCE WOMEN'S RESTROOM 3RD FROM LEFT	9.30	02/22/2021	
21-02-00332-086	159.1-105	01/26/2021	SCIENCE WOMEN'S RESTROOM RIGHTMOST SINGLE SINK	3.69	02/22/2021	
21-02-00332-087	159.1-107	01/26/2021	SCIENCE WOMEN'S RESTROOM LEFT MIDDLE BRADLEY SINK	1.98	02/22/2021	
21-02-00332-088	159.1-108	01/26/2021	SCIENCE WOMEN'S RESTROOM RIGHT MIDDLE BRADLEY SINK	2.04	02/22/2021	
21-02-00332-089	159.1-109	01/26/2021	SCIENCE WOMEN'S RESTROOM RIGHTMOST BRADLEY SINK	2.31	02/22/2021	
21-02-00332-090	159.1-110B	01/26/2021	SCIENCE HALL DF	<1.00	02/22/2021	
21-02-00332-091	159.1-111	01/26/2021	SCIENCE MEN'S RESTROOM LEFTMOST SINK	4.40	02/22/2021	
21-02-00332-092	159.1-112	01/26/2021	SCIENCE MEN'S RESTROOM 2ND FROM LEFT	2.43	02/22/2021	
21-02-00332-093	159.1-113	01/26/2021	SCIENCE MEN'S RESTROOM 3RD FROM LEFT	4.01	02/22/2021	
21-02-00332-094	159.1-114	01/26/2021	SCIENCE MEN'S RESTROOM 4TH FROM LEFT	2.36	02/22/2021	

Environmental Hazards Services, L.L.C

Client Number: 33-5980

Report Number: 21-02-00332

Project/Test Address: 2020L-159.1; Grand Island CSD; Grand Island Senior High School; 1100 Ransom Road; Grand Island, NY 14072

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-02-00332-095	159.1-115	01/26/2021	SCIENCE MEN'S RESTROOM 5TH FROM LEFT	2.16	02/22/2021	
21-02-00332-096	159.1-116	01/26/2021	SCIENCE MEN'S RESTROOM RIGHTMOST SINK	2.29	02/22/2021	
21-02-00332-097	159.1-117	01/26/2021	HOME EC LEFTMOST SINK	1.40	02/22/2021	
21-02-00332-098	159.1-118	01/26/2021	HOME EC 2ND FROM LEFT	8.48	02/22/2021	
21-02-00332-099	159.1-119	01/26/2021	HOME EC 3RD FROM LEFT	3.26	02/22/2021	
21-02-00332-100	159.1-120	01/26/2021	HOME EC RIGHTMOST	2.29	02/22/2021	
21-02-00332-101	159.1-122	01/26/2021	WOMENS RESTROOM NEAR HOME EC RIGHT SINK	<1.00	02/22/2021	
21-02-00332-102	159.1-126	01/26/2021	MENS RESTROOM NEAR HOME EC RIGHT SINK	<1.00	02/22/2021	
21-02-00332-103	159.1-127	01/26/2021	FACULTY RESTROOM NEAR TECH ROOMS	<1.00	02/22/2021	
21-02-00332-104	159.1-128	01/26/2021	TECH ROOM 66	<1.00	02/22/2021	
21-02-00332-105	159.1-129	01/26/2021	TECH ROOM 68	<1.00	02/22/2021	
21-02-00332-106	159.1-130	01/26/2021	TECH ROOM 69	<1.00	02/22/2021	
21-02-00332-107	159.1-131	01/26/2021	TECH ROOM 70	<1.00	02/22/2021	
21-02-00332-108	159.1-133	01/26/2021	MAIN OFFICE	<1.00	02/22/2021	
21-02-00332-109	159.1-134B	01/26/2021	MATH HALL DF	<1.00	02/22/2021	
21-02-00332-110	159.1-135	01/26/2021	MATH HALL WOMENS FACULTY	<1.00	02/22/2021	
21-02-00332-111	159.1-136	01/26/2021	MATH HALL MENS FACULTY	<1.00	02/22/2021	
21-02-00332-112	159.1-137	01/26/2021	ROOM 205	<1.00	02/22/2021	

Environmental Hazards Services, L.L.C

Client Number: 33-5980

Report Number: 21-02-00332

Project/Test Address: 2020L-159.1; Grand Island CSD; Grand Island Senior High School; 1100 Ransom Road; Grand Island, NY 14072

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-02-00332-113	159.1-138	01/26/2021	ROOM 218	9.07	02/22/2021	
21-02-00332-114	159.1-142	01/26/2021	MENS 2ND FLOOR SCIENCE RESTROOM LEFT OF QUAD SINK	3.17	02/22/2021	
21-02-00332-115	159.1-143	01/26/2021	MENS 2ND FLOOR SCIENCE RESTROOM LEFT MIDDLE OF QUAD SINK	2.05	02/22/2021	
21-02-00332-116	159.1-144	01/26/2021	MENS 2ND FLOOR SCIENCE RESTROOM RIGHT MIDDLE OF QUAD SINK	1.85	02/22/2021	
21-02-00332-117	159.1-145	01/26/2021	MENS 2ND FLOOR SCIENCE RESTROOM RIGHT OF QUAD SINK	2.30	02/22/2021	
21-02-00332-118	159.1-150	01/26/2021	WOMENS 2ND FLOOR SCIENCE RESTROOM LEFT OF QUAD SINK	<1.00	02/22/2021	
21-02-00332-119	159.1-152	01/26/2021	WOMENS 2ND FLOOR SCIENCE RESTROOM MIDDLE OF QUAD SINK	<1.00	02/22/2021	
21-02-00332-120	159.1-153	01/26/2021	WOMENS 2ND FLOOR SCIENCE RESTROOM RIGHT OF QUAD SINK	<1.00	02/22/2021	
21-02-00332-121	159.1-155B	01/26/2021	MUSIC WING DF	<1.00	02/22/2021	
21-02-00332-122	159.1-156A	01/26/2021	MUSIC WING HALL SINK	4.29	02/22/2021	
21-02-00332-123	159.1-156B	01/26/2021	MUSIC WING HALL SPRAYUER	<1.00	02/22/2021	
21-02-00332-124	159.1-157	01/26/2021	MUSIC WING RESTROOM	1.38	02/22/2021	
21-02-00332-125	159.1-158	01/26/2021	BASEMENT WOMENS RESTROOM	2.42	02/22/2021	
21-02-00332-126	159.1-159	01/26/2021	BASEMENT MENS RESTROOM	1.38	02/22/2021	

Environmental Hazards Services, L.L.C

Client Number: 33-5980

Report Number: 21-02-00332

Project/Test Address: 2020L-159.1; Grand Island CSD; Grand Island Senior High School; 1100 Ransom Road; Grand Island, NY 14072

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-02-00332-127	159.1.160	01/26/2021	BASEMENT BREAK ROOM	<1.00	02/22/2021	

Method: SM 3113B-2010
Analyst: Jennalee Hertzler
Accreditation #: NY 11714

Reviewed By Authorized Signatory:



Tasha Eaddy

QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion



Chain of Custody Document

3860 California Road, Orchard Park, New York 14127
 PHONE (716) 312-0070 FAX (716) 312-8092
 WWW.STOHLENVIRONMENTAL.COM

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-159.1

Client: Grand Island CSD

Contact: James Rozler

Building: Grand Island Senior High School

Location: 1100 Ransom Road

LEAD


Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
159.1-1A	D.O. DF	DF	1:00			
159.1-1B	D.O. DFB	DFB	1:01			
159.1-2	D.O. Kitchenette	S	1:02			
159.1-3	D.O. Genderless restroom	S	1:03			
159.1-4	D.O. Womens restroom	S	1:04			
159.1-5	Conference Room	S	1:05			
159.1-7	Gym hallway all gender restroom left	S	1:06			
159.1-8	Gym hallway all gender restroom right	S	1:07			
159.1-9	Gym Halway Womens restroom	S	1:08			
159.1-10	Gym Halway Womens restroom	S	1:09			
159.1-11	Psychology lecture room 110	S	1:10			
159.1-13	Boys team room sink	S	1:11			
159.1-14	Boys team room Coach's Office	S	1:12			
159.1-15	Trainers room sink	S	1:13			
159.1-16	Trainers room Ice Machine	IM	1:14			
159.1-19	Boys team room 115	S	1:15			
159.1-22	Practice Gym Womens restroom inside	S	1:16			
159.1-23	Practice Gym Womens restroom outside	S	1:17			

21-02-00332



Due Date:
 03/02/2021
 (Tuesday)
 AE

Notes:

Please e-mail lab results to labs@stohlenv.com If checked, also e-mail results to: Ehenderson@StohlEnv.com

Sampled By: Paul Nichols Print Name Paul Nichols Stohl Env: Paul Nichols Date: 1/28/2021

Relinquished By: Eric Henderson Jr. Print Name Eric Henderson Jr. Stohl Env: Eric Henderson Jr. Date: 1/28/2021

Received (Name / Lab): Amy Vejnar Date: 2/2/21 Time: 1:20 PM

Sample Login (Name / Lab): Amanda Cowley Date: 2/11/21 Time: 4:14 pm

Analysis (Name / Lab): J. Hertzler Date: 2/22/21 Time: 9:44 pm

QA/QC Review (Name / Lab): Trisha Fraddy Date: 2/26/21 Time: 9:28 am

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

332



Chain of Custody Document

3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-159.1

Client: Grand Island CSD

Contact: James Rozler

Building: Grand Island Senior High School

Location: 1100 Ransom Road

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround
20 Days

Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
159.1-24	Practice Gym Mens restroom outside	S	1:18			
159.1-25	Girls team room A sink	S	1:19			
159.1-26	Girls team room D sink	S	1:20			
159.1-30	Girls team room C sink	S	1:21			
159.1-34	Girls team room B sink	S	1:22			
159.1-35	Art 121A left	S	1:23			
159.1-36	Art 121A left middle	S	1:24			
159.1-37	Art 121A right middle	S	1:25			
159.1-38	Art 121A right	S	1:26			
159.1-39	Art 121B	S	1:27			
159.1-40	Art 121B	S	1:28			
159.1-41	Art 121B	S	1:29			
159.1-43	Girls Pool locker room sink left	S	1:30			
159.1-44	Girls Pool locker room sink right	S	1:31			
159.1-45	Girls pool Coach's office	S	1:32			
159.1-49	Boys pool locker room sink left	S	1:33			
159.1-50	Boys pool locker room sink right	S	1:34			
159.1-51	Boys pool Coach's office	S	1:35			

Notes:

Please e-mail lab results to labs@stohlenv.com

Sampled By: Paul Nichols Print Name Paul Nichols Stohl Env: Paul Nichols Date: 1/28/2021

Relinquished By: Eric Henderson Jr Print Name Eric Henderson Jr. Stohl Env: Eric Henderson Jr. Date: 1/28/2021

Received (Name / Lab): Ann Veinax Date: 2/2/21 Time: 1:20PM

Sample Login (Name / Lab): Trace Beem / Jean Beem Date: 2/15/21 Time: 8:00AM

Analysis (Name / Lab): J. Dentzler Date: 2/22/21 Time: 9:44 pm

QA/QC Review (Name / Lab): _____ Date: _____ Time: _____

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

332



Chain of Custody Document

3860 California Road, Orchard Park, New York 14127
 PHONE (716) 312-0070 FAX (716) 312-8092
 WWW.STOHLENVIRONMENTAL.COM

Submitted to: (Lab Name) EHS
 STOHL Job # 2020L-159.1

Client: Grand Island CSD Contact: James Rozler
 Building: Grand Island Senior High School Location: 1100 Ransom Road

LEAD
 Water by SM 19, 21 - 23 3113B (-04, -10) X Turnaround 20 Days

Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
159.1-53	122 art room left wall left sink	S	1:36			
159.1-54	122 art room left wall middle sink	S	1:37			
159.1-55	122 art room left wall right sink	S	1:38			
159.1-56	122 art room right wall left sink	S	1:39			
159.1-57	122 art room right wall middle sink	S	1:40			
159.1-58	122 art room right wall right sink	S	1:41			
159.1-59	122 art room right wall bubbler	Bub	1:42			
159.1-61	123B Tech room left sink	S	1:43			
159.1-62	123B Tech room right sink	S	1:44			
159.1-63	124 P.T. Room Main	S	1:45			
159.1-64	124 P.T. Room Restroom	S	1:46			
159.1-65	Indoor Concession	S	1:47			
159.1-66B	DF Near Concession	DFB	1:48			
159.1.67	Girls restroom near concession leftmost	S	1:49			
159.1.68	Girls restroom near concession 2nd from left	S	1:50			
159.1.69	Girls restroom near concession 3rd from left	S	1:51			
159.1.70	Girls restroom near concession 4th from left	S	1:52			
159.1.71	Girls restroom near concession 5th from left	S	1:53			

Notes:
 Please e-mail lab results to labs@stohlenv.com

Sampled By: Paul Nichols Print Name Paul Nichols Stohl Env: Paul Nichols Date: 1/25/2021
 Relinquished By: E. Henderson Jr. Print Name Eric Henderson Jr. Stohl Env: Eric Henderson Jr. Date: 1/28/2021
 Received (Name / Lab): Amy Vejnar Date: 2/2/21 Time: 1:20 PM
 Sample Login (Name / Lab): Traci Brown / Fran Blo Date: 2/15/21 Time: 8:05 AM
 Analysis (Name / Lab): G. Hertzler Date: 2/22/21 Time: 9:44 pm
 QA/QC Review (Name / Lab): _____ Date: _____ Time: _____
 Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

332



Chain of Custody Document

3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-159.1

Client: Grand Island CSD

Contact: James Rozler

Building: Grand Island Senior High School

Location: 1100 Ransom Road

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
159.1.72	Girls restroom near concession 6th from left	S	1:54			
159.1.73	Girls restroom near concession rightmost	S	1:55			
159.1.74	Boys restroom near concession leftmost	S	1:56			
159.1.75	Boys restroom near concession 2nd from left	S	1:57			
159.1.76	Boys restroom near concession 3rd from left	S	1:58			
159.1.77	Boys restroom near concession 4th from left	S	1:59			
159.1.78	Boys restroom near concession 5th from left	S	2:00			
159.1.79	Boys restroom near concession rightmost	S	2:01			
159.1.80	Custodial staff restroom	S	2:02			
159.1.81	Left sink double	S	2:03			
159.1.82	Right sink double	S	2:04			
159.1.83	Large Pot fill	S	2:05			
159.1.84	Dish wash sprayer	S	2:06			
159.1.85	Food wash sink near freezer	S	2:07			
159.1.86	Food wash sink near small pot fill	S	2:08			
159.1.87	Small pot fill	S	2:09			
159.1.88	Kitchen locker room	S	2:10			
159.1.89	Handwash kitchen	S	2:11			

Notes:

Please e-mail lab results to labs@stohlenv.com

Sampled By: Paul Nichols Print Name Paul Nichols Stohl Env: Paul Nichols Date: 1/25/2021

Relinquished By: E. Henderson Print Name Eric Henderson Jr. Stohl Env: Eric Henderson Jr. Date: 1/28/2021

Received (Name / Lab): Amy Vejnar Date: 2/2/21 Time: 1:20PM

Sample Login (Name / Lab): Traci Bloom / Tracy Bloom Date: 2/15/21 Time: 8:08 AM

Analysis (Name / Lab): J. Kertzyler Date: 2/22/21 Time: 9:44 pm

QA/QC Review (Name / Lab): _____ Date: _____ Time: _____

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

332



Chain of Custody Document

3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-159.1

Client: Grand Island CSD

Contact: James Rozler

Building: Grand Island Senior High School

Location: 1100 Ransom Road

LEAD
Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround
20 Days

Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
159.1.90	Mens restroom near cafe	S	2:12			
159.1.91	Womens restroom near cafe	S	2:13			
159.1.92	Wheelchair accessible restroom near cafe	S	2:14			
159.1.94	Guidance office	S	2:15			
159.1.95	Nurses office main	S	2:16			
159.1.96	Nurses office exam room	S	2:17			
159.1.97	Nurses office staff restroom	S	2:18			
159.1.98	Nurses office restroom	S	2:19			
159.1.99	Library	S	2:20			
159.1.100	Room 152	S	2:21			
159.1.102	Science women's restroom leftmost single sink	S	2:22			
159.1.103	Science women's restroom 2nd from left	S	2:23			
159.1.104	Science women's restroom 3rd from left	S	2:24			
159.1.105	Science women's restroom rightmost single sink	S	2:25			
159.1.107	Science women's restroom left middle Bradley sink	S	2:26			
159.1.108	Science women's restroom right middle bradley sink	S	2:27			
159.1.109	Science women's restroom rightmost bradley sink	S	2:28			
159.1.110B	Science hall DF	DFB	2:29			

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: Paul Nichols Print Name Paul Nichols Stohl Env: Paul Nichols Date: 1/28/2021

Relinquished By: Eric Henderson Jr. Print Name Eric Henderson Jr. Stohl Env: Eric Henderson Jr. Date: 1/28/2021

Received (Name / Lab): AMY VONAR Date: 2/2/21 Time: 1:23 PM

Sample Login (Name / Lab): Trace Bloom Place Bloom Date: 2/15/21 Time: 8:11 AM

Analysis (Name / Lab): G. Hertzyler Date: 2/22/21 Time: 9:44 pm

QA/QC Review (Name/Lab): _____ Date: _____ Time: _____

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

332



Chain of Custody Document

3860 California Road, Orchard Park, New York 14127
 PHONE (716) 312-0070 FAX (716) 312-8092
 WWW.STOHLENVIRONMENTAL.COM

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-159.1

Client: Grand Island CSD

Contact: James Rozler

Building: Grand Island Senior High School

Location: 1100 Ransom Road

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
159.1.111	Science men's restroom leftmost sink	S	2:30			
159.1.112	Science men's restroom 2nd from left	S	2:31			
159.1.113	Science men's restroom 3rd from left	S	2:32			
159.1.114	Science men's restroom 4th from left	S	2:33			
159.1.115	Science men's restroom 5th from left	S	2:34			
159.1.116	Science men's restroom rightmost sink	S	2:35			
159.1.117	Home Ec leftmost sink	S	2:36			
159.1.118	Home Ec 2nd from left	S	2:37			
159.1.119	Home Ec 3rd from left	S	2:38			
159.1.120	Home Ec rightmost	S	2:39			
159.1.122	Womens restroom near home Ec right sink	S	2:40			
159.1.126	Mens restroom near home ec right sink	S	2:41			
159.1.127	Faculty restroom near tech rooms	S	2:42			
159.1.128	Tech room 66	S	2:43			
159.1.129	Tech room 68	S	2:44			
159.1.130	Tech room 69	S	2:45			
159.1.131	Tech Room 70	S	2:46			
159.1.133	Main Office	S	2:47			

Notes:

Please e-mail lab results to labs@stohlenv.com

Sampled By: Paul Nichols Print Name Paul Nichols Stohl Env: Paul Nichols Date: 1/25/2021

Relinquished By: Eric Henderson Jr. Print Name Eric Henderson Jr. Stohl Env: Eric Henderson Jr. Date: 1/28/2021

Received (Name / Lab): Amy Veynar Date: 2/2/21 Time: 1:24 PM

Sample Login (Name / Lab): Tech Room / Paul B... Date: 2/15/21 Time: 8:54 PM

Analysis (Name / Lab): J. Hertzler Date: 2/22/21 Time: 9:44 pm

QA/QC Review (Name / Lab): _____ Date: _____ Time: _____

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

332



Chain of Custody Document

3860 California Road, Orchard Park, New York 14127
 PHONE (716) 312-0070 FAX (716) 312-8092
 WWW.STOHLENVIRONMENTAL.COM

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-159.1

Client: Grand Island CSD

Contact: James Rozler

Building: Grand Island Senior High School

Location: 1100 Ransom Road

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
159.1.134B	Math Hall DF	DFB	2:48			
159.1.135	Math Hall Womens faculty	S	2:49			
159.1.136	Math Hall Mens faculty	S	2:50			
159.1.137	Room 205	S	2:51			
159.1.138	Room 218	S	2:52			
159.1.142	Mens 2nd Floor Science Restroom left of quad sink	S	2:53			
159.1.143	Mens 2nd Floor Science Restroom left middle of quad sink	S	2:54			
159.1.144	Mens 2nd Floor Science Restroom right middle of quad sink	S	2:55			
159.1.145	Mens 2nd Floor Science Restroom right of quad sink	S	2:56			
159.1.150	Womens 2nd Floor science restroom left of quad sink	S	2:57			
159.1.152	Womens 2nd Floor science restroom middle of quad sink	S	2:58			
159.1.153	Womens 2nd Floor science restroom right of quad sink	S	2:59			
159.1.155B	Music Wing DF	DFB	3:00			
159.1.156A	Music Wing hall sink	S	3:01			
159.1.156B	Music Wing hall sprayer	S	3:02			
159.1.157	Music wing restroom	S	3:03			
159.1.158	Basement Womens restroom	S	3:04			
159.1.159	Basement mens restroom	S	3:05			

Notes:

Please e-mail lab results to labs@stohlenv.com

Sampled By: Paul Nichols Print Name Paul Nichols Stohl Env: Paul Nichols Date: 1/25/2021

Relinquished By: Eric Henderson Jr. Print Name Eric Henderson Jr. Stohl Env: Eric Henderson Jr. Date: 1/28/2021

Received (Name / Lab): Amy Vejnar Date: 2/2/21 Time: 1:25 PM

Sample Login (Name / Lab): Traoi Boon / Pau Ben Date: 2/15/21 Time: 8:20 AM

Analysis (Name / Lab): G. Hertigler Date: 2/22/21 Time: 9:44 pm

QA/QC Review (Name / Lab): _____ Date: _____ Time: _____

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

