



Environmental Hazards Services, L.L.C.
 7469 Whitepine Rd
 Richmond, VA 23237
 Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Report Number: 21-02-00313

Client: Stohl Environmental
 3860 California Road
 Orchard Park, NY 14127

Received Date: 02/02/2021
Reported Date: 02/26/2021
Sampled By: 1z5f600y9095157552
Tech Certification #:

Project/Test Address: Grand Island CSD; Veronica E Connors Middle School; 1100 Ransom Road,
 Grand Island, NY 14072

Client Number:
 33-5980

Laboratory Results

Fax Number:
 716-312-8092

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-02-00313-001	159.2-1	01/25/2021	MAIN OFFICE KITCHENETTE	5.00	02/25/2021	
21-02-00313-002	159.2-2	01/25/2021	MAIN OFFICE WATER FOUNTAIN	1.77	02/25/2021	
21-02-00313-003	159.2-3	01/25/2021	RESTROOM NEAR OFFICE RIGHT	3.09	02/25/2021	
21-02-00313-004	159.2-4B	01/25/2021	DFB NEAR OFFICE	<1.00	02/25/2021	
21-02-00313-005	159.2-5	01/25/2021	RESTROOM NEAR OFFICE LEFT	3.99	02/25/2021	
21-02-00313-006	159.2-6	01/25/2021	STAFF ROOM LADIES ROOM	2.34	02/25/2021	
21-02-00313-007	159.2-7	01/25/2021	STAFF ROOM MENS ROOM	1.69	02/25/2021	
21-02-00313-008	159.2-8	01/25/2021	NEW MAIN OFFICE SINK	7.22	02/25/2021	
21-02-00313-009	159.2-11	01/25/2021	GIRLS RESTROOM 6TH GRADE TRIPLE SINK MIDDLE	1.47	02/25/2021	
21-02-00313-010	159.2-12	01/25/2021	GIRLS RESTROOM 6TH GRADE TRIPLE SINK RIGHT	1.26	02/25/2021	
21-02-00313-011	159.2-13	01/25/2021	GIRLS RESTROOM 6TH GRADE 4TH FROM RIGHT	3.11	02/25/2021	

Environmental Hazards Services, L.L.C

Client Number: 33-5980

Report Number: 21-02-00313

Project/Test Address: Grand Island CSD; Veronica E Connors Middle School;
1100 Ransom Road, Grand Island, NY 14072

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-02-00313-012	159.2-14	01/25/2021	GIRLS RESTROOM 6TH GRADE 3RD FROM RIGHT	3.68	02/25/2021	
21-02-00313-013	159.2-15	01/25/2021	GIRLS RESTROOM 6TH GRADE 2ND FROM RIGHT	7.17	02/25/2021	
21-02-00313-014	159.2-16	01/25/2021	GIRLS RESTROOM 6TH GRADE RIGHTMOST SINK	4.85	02/25/2021	
21-02-00313-015	159.2-18	01/25/2021	BOYS RESTROOM 6TH GRADE LEFTMOST SINK	2.33	02/25/2021	
21-02-00313-016	159.2-19	01/25/2021	BOYS RESTROOM 6TH GRADE 2ND FROM LEFT	3.24	02/25/2021	
21-02-00313-017	159.2-20	01/25/2021	BOYS RESTROOM 6TH GRADE 3RD FROM LEFT	2.96	02/25/2021	
21-02-00313-018	159.2-21	01/25/2021	BOYS RESTROOM 6TH GRADE 4TH FROM LEFT	2.00	02/25/2021	
21-02-00313-019	159.2-22	01/25/2021	BOYS RESTROOM 6TH GRADE 5TH FROM LEFT	5.31	02/25/2021	
21-02-00313-020	159.2-23	01/25/2021	BOYS RESTROOM 6TH GRADE 6TH FROM LEFT	4.79	02/25/2021	
21-02-00313-021	159.2-24	01/25/2021	BOYS RESTROOM 6TH GRADE 7TH FROM LEFT	4.86	02/25/2021	
21-02-00313-022	159.2-25	01/25/2021	ROOM 115	18.5	02/26/2021	
21-02-00313-023	159.2-26	01/25/2021	LIBRARY MEDIA ROOM	6.01	02/25/2021	
21-02-00313-024	159.2-28	01/25/2021	GIRLS RESTROOM 8TH GRADE LEFTMOST BRADLEY	2.62	02/25/2021	
21-02-00313-025	159.2-29	01/25/2021	GIRLS RESTROOM 8TH GRADE LEFT MIDDLE OF BRADLEY	2.09	02/25/2021	
21-02-00313-026	159.2-30	01/25/2021	GIRLS RESTROOM 8TH GRADE RIGHT MIDDLE OF BRADLEY	1.93	02/25/2021	
21-02-00313-027	159.2-32	01/25/2021	GIRLS RESTROOM 8TH GRADE LEFT SINK NOT BRADLEY	3.08	02/25/2021	
21-02-00313-028	159.2-33	01/25/2021	GIRLS RESTROOM 8TH GRADE LEFT MIDDLE SINK	3.40	02/25/2021	

Environmental Hazards Services, L.L.C

Client Number: 33-5980

Report Number: 21-02-00313

Project/Test Address: Grand Island CSD; Veronica E Connors Middle School;
1100 Ransom Road, Grand Island, NY 14072

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-02-00313-029	159.2-34	01/25/2021	GIRLS RESTROOM 8TH GRADE RIGHT MIDDLE SINK	4.47	02/25/2021	
21-02-00313-030	159.2-35	01/25/2021	GIRLS RESTROOM 8TH GRADE RIGHTMOST SINK	18.4	02/26/2021	
21-02-00313-031	159.2-37	01/25/2021	BOYS RESTROOM 8TH GRADE LEFTMOST SINK	1.86	02/25/2021	
21-02-00313-032	159.2-38	01/25/2021	BOYS RESTROOM 8TH GRADE 2ND FROM LEFT	6.59	02/25/2021	
21-02-00313-033	159.2-39	01/25/2021	BOYS RESTROOM 8TH GRADE 3RD FROM LEFT	1.70	02/25/2021	
21-02-00313-034	159.2-40	01/25/2021	BOYS RESTROOM 8TH GRADE 4TH FROM LEFT	<1.00	02/25/2021	
21-02-00313-035	159.2-41	01/25/2021	BOYS RESTROOM 8TH GRADE 5TH FROM LEFT	<1.00	02/25/2021	
21-02-00313-036	159.2-42	01/25/2021	BOYS RESTROOM 8TH GRADE 6TH FROM LEFT	<1.00	02/25/2021	
21-02-00313-037	159.2-43	01/25/2021	BOYS RESTROOM 8TH GRADE 7TH FROM LEFT	<1.00	02/25/2021	
21-02-00313-038	159.2-45	01/25/2021	NURSES MAIN	4.10	02/25/2021	
21-02-00313-039	159.2-46	01/25/2021	NURSES EXAM	15.9	02/25/2021	
21-02-00313-040	159.2-47	01/25/2021	NURSES RESTROOM	<1.00	02/25/2021	
21-02-00313-041	159.2-48B	01/25/2021	DFB NEAR CAFE	<1.00	02/25/2021	
21-02-00313-042	159.2-49	01/25/2021	172 HOME EC LEFTMOST	3.90	02/25/2021	
21-02-00313-043	159.2-50	01/25/2021	172 HOME EC 2ND FROM LEFT	7.32	02/26/2021	
21-02-00313-044	159.2-51	01/25/2021	172 HOME EC LEFT SINK ON RIGHT WALL	6.77	02/26/2021	
21-02-00313-045	159.2-52	01/25/2021	172 HOME EC RIGHT SINK ON RIGHT WALL	7.28	02/26/2021	
21-02-00313-046	159.2-53	01/25/2021	174 HOME EC KITCHEN 3	5.85	02/26/2021	
21-02-00313-047	159.2-54	01/25/2021	174 HOME EC KITCHEN 4	6.12	02/26/2021	
21-02-00313-048	159.2-55	01/25/2021	174 HOME EC KITCHEN 1	13.6	02/26/2021	

Environmental Hazards Services, L.L.C

Client Number: 33-5980

Report Number: 21-02-00313

Project/Test Address: Grand Island CSD; Veronica E Connors Middle School;
1100 Ransom Road, Grand Island, NY 14072

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-02-00313-049	159.2-56	01/25/2021	174 HOME EC KITCHEN 2	5.62	02/26/2021	
21-02-00313-050	159.2-57	01/25/2021	KITCHEN HANDWASH	3.41	02/26/2021	
21-02-00313-051	159.2-58	01/25/2021	KITCHEN LEFT DOUBLE SINK	2.23	02/26/2021	
21-02-00313-052	159.2-59	01/25/2021	KITCHEN RIGHT DOUBLE SINK	3.31	02/26/2021	
21-02-00313-053	159.2-60	01/25/2021	KITCHEN SERVING LINE	2.03	02/26/2021	
21-02-00313-054	159.2-61	01/25/2021	DISHWASH SPRAYER	<1.00	02/26/2021	
21-02-00313-055	159.2-62	01/25/2021	POT FILL	5.82	02/26/2021	
21-02-00313-056	159.2-63	01/25/2021	LOCKER ROOM HANDWASH KITCHEN	3.32	02/26/2021	
21-02-00313-057	159.2-64	01/25/2021	LOCKER ROOM BOYS LEFT	2.30	02/26/2021	
21-02-00313-058	159.2-65	01/25/2021	LOCKER ROOM BOYS RIGHT	3.08	02/26/2021	
21-02-00313-059	159.2-66	01/25/2021	BOYS COACHES OFFICE	3.21	02/26/2021	
21-02-00313-060	159.2-67	01/25/2021	BOYS UPPER BATHROOMS LEFTMOST OF BRADLEY SINK	3.09	02/26/2021	
21-02-00313-061	159.2-70	01/25/2021	BOYS UPPER BATHROOMS RIGHTMOST OF BRADLEY SINK	1.37	02/26/2021	
21-02-00313-062	159.2-71	01/25/2021	GIRLS UPPER BATHROOMS LEFTMOST OF BRADLEY SINK	1.54	02/26/2021	
21-02-00313-063	159.2-72	01/25/2021	GIRLS UPPER BATHROOMS LEFT MIDDLE	1.23	02/26/2021	
21-02-00313-064	159.2-73	01/25/2021	GIRLS UPPER BATHROOMS RIGHT MIDDLE	1.14	02/26/2021	
21-02-00313-065	159.2-74	01/25/2021	GIRLS UPPER BATHROOMS RIGHTMOST	1.29	02/26/2021	
21-02-00313-066	159.2-75	01/25/2021	COACH'S OFFICE/TEAM LOCKER ROOM	<1.00	02/26/2021	

Environmental Hazards Services, L.L.C

Client Number: 33-5980

Report Number: 21-02-00313

Project/Test Address: Grand Island CSD; Veronica E Connors Middle School;
1100 Ransom Road, Grand Island, NY 14072

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-02-00313-067	159.2-76	01/25/2021	ROOM 191 TECH	7.50	02/26/2021	
21-02-00313-068	159.2-77	01/25/2021	ROOM 190 TECH	6.17	02/26/2021	
21-02-00313-069	159.2-78	01/25/2021	GIRLS LOCKER ROOM LEFT	2.05	02/26/2021	
21-02-00313-070	159.2-79	01/25/2021	GIRLS LOCKER ROOM RIGHT	2.30	02/26/2021	
21-02-00313-071	159.2-80	01/25/2021	GIRLS COACH'S OFFICE	7.07	02/26/2021	
21-02-00313-072	159.2-83	01/25/2021	189 ART WALL FAR LEFT	22.6	02/26/2021	
21-02-00313-073	159.2-84	01/25/2021	189 ART RIGHT WALL LEFT MIDDLE	5.87	02/26/2021	
21-02-00313-074	159.2-85	01/25/2021	189 ART RIGHT WALL RIGHT MIDDLE	1.55	02/26/2021	
21-02-00313-075	159.2-86	01/25/2021	189 ART LEFT WALL FAR RIGHT	2.39	02/26/2021	
21-02-00313-076	159.2-87	01/25/2021	188 ART LEFT WALL FAR LEFT	18.7	02/26/2021	
21-02-00313-077	159.2-88	01/25/2021	188 ART LEFT WALL LEFT MIDDLE	7.55	02/26/2021	

Method: SM 3113B-2010
Analyst: Jennalee Hertzler
Accreditation #: NY 11714

Reviewed By Authorized Signatory:



Tasha Eaddy
QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion

Stohl ENVIRONMENTAL

3860 California Road, Orchard Park, New York 14127
 PHONE (716) 312-0070 FAX (716) 312-8092
 WWW.STOHLENVIRONMENTAL.COM

Chain of Custody Document

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-159.2

Client: Grand Island CSD

Contact: James Rozler

Building: Veronica E. Connors Middle School

Location: 1100 Ransom Road Grand Island, NY 14072

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
159.2-1	Main Office Kitchenette	S	23:10			
159.2-2	Main Office Water fountain	DF	23:11			
159.2-3	Restroom near office right	S	23:12			
159.2-4B	DFB near office	DFB	23:13			
159.2-5	Restroom near office Left	S	23:14			
159.2-6	Staff room ladies room	S	23:15			
159.2-7	Staff room mens room	S	23:16			
159.2-8	New main office sink	S	23:17			
159.2-11	Girls Restroom 6th grade triple sink middle	S	23:18			
159.2-12	Girls restroom 6th grade triple sink right	S	23:19			
159.2-13	Girls restroom 6th grade 4th from right	S	23:20			
159.2-14	Girls restroom 6th grade 3rd from right	S	23:21			
159.2-15	Girls restroom 6th grade 2nd from right	S	23:22			
159.2-16	Girls restroom 6th grade rightmost sink	S	23:23			
159.2-18	Boys restroom 6th grade leftmost sink	S	23:24			
159.2-19	Boys restroom 6th grade 2nd from left	S	23:26			
159.2-20	Boys restroom 6th grade 3rd from left	S	23:27			
159.2-21	Boys restroom 6th grade 4th from left	S	23:28			

21-02-00313



Due Date:
03/02/2021
 (Tuesday)
 AE

Notes:

Please e-mail lab results to labs@stohlenv.com

If checked, also e-mail results to:

Ehenderson@StohlEnv.com

Sampled By: Paul Nichols Print Name Paul Nichols Stohl Env: Paul Nichols Date: 1/25/2021

Relinquished By: E. Henderson Jr. Print Name Eric Henderson Jr. Stohl Env: Eric Henderson Jr. Date: 1/28/2021

Received (Name / Lab): KTHARRIS Date: 2-2-21 Time: 12:07 PM

Sample Login (Name / Lab): Traci Bloom / Yaw Bo Date: 2/15/21 Time: 9:16 AM

Analysis (Name / Lab): J. Kerttyer Date: 2/24/21 Time: 1:58 PM

QA/QC Review (Name / Lab): Lisha Eady Date: 2/26/21 Time: 6:37 PM

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____



Chain of Custody Document

3860 California Road, Orchard Park, New York 14127
 PHONE (716) 312-0070 FAX (716) 312-8092
 WWW.STOHLENVIRONMENTAL.COM

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-159.2

Client: Grand Island CSD

Contact: James Rozler

Building: Veronica E. Connors Middle School

Location: 1100 Ransom Road Grand Island, NY 14072

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
159.2-22	Boys restroom 6th grade 5th from left	S	23:29			
159.2-23	Boys restroom 6th grade 6th from left	S	23:30			
159.2-24	Boys restroom 6th grade 7th from left	S	23:31			
159.2-25	Room 115	S	23:32			
159.2-26	Library media room	S	23:33			
159.2-28	Girls restroom 8th grade leftmost bradley	S	23:34			
159.2-29	Girls restroom 8th grade left middle of bradley	S	23:35			
159.2-30	Girls restroom 8th grade right middle of bradley	S	23:36			
159.2-32	Girls restroom 8th grade left sink not bradley	S	23:37			
159.2-33	Girls restroom 8th grade left middle sink	S	23:38			
159.2-34	Girls restroom 8th grade right middle sink	S	23:39			
159.2-35	Girls restroom 8th grade rightmost sink	S	23:40			
159.2-37	Boys restroom 8th grade leftmost sink	S	23:41			
159.2-38	Boys restroom 8th grade 2nd from left	S	23:42			
159.2-39	Boys restroom 8th grade 3rd from left	S	23:43			
159.2-40	Boys restroom 8th grade 4th from left	S	23:44			
159.2-41	Boys restroom 8th grade 5th from left	S	23:45			
159.2-42	Boys restroom 8th grade 6th from left	S	23:46			

Notes:

Please e-mail lab results to labs@stohlenv.com

Sampled By: Paul Nichols Print Name Paul Nichols Stohl Env: Paul Nichols Date: 1/25/2021

Relinquished By: E. Henderson Jr. Print Name Eric Henderson Jr. Stohl Env: Eric Henderson Jr. Date: 1/28/2021

Received (Name / Lab): K. Harris / K. Harris Date: 2-2-21 Time: 12:07 pm

Sample Login (Name / Lab): Traei Bloom / Grace Place Date: 2/15/21 Time: 9:14 am

Analysis (Name / Lab): J. Hertler Date: 2/26/21 Time: 1:58 pm

QA/QC Review (Name / Lab): J. Fialy Date: 2/26/21 Time: 6:37 pm

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____



Chain of Custody Document

3860 California Road, Orchard Park, New York 14127
 PHONE (716) 312-0070 FAX (716) 312-8092
 WWW.STOHLENVIRONMENTAL.COM

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-159.2

Client: Grand Island CSD

Contact: James Rozler

Building: Veronica E. Connors Middle School

Location: 1100 Ransom Road Grand Island, NY 14072

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
159.2-43	Boys restroom 8th grade 7th from left	S	23:47			
159.2-45	Nurses main	S	23:48			
159.2-46	Nurses exam	S	23:49			
159.2-47	Nurses restroom	S	23:50			
159.2-48B	DFB Near cafe	DFB	23:51			
159.2-49	172 Home Ec leftmost	S	23:52			
159.2-50	172 Home Ec 2nd from left	S	23:53			
159.2-51	172 Home Ec left sink on right wall	S	23:54			
159.2-52	172 Home Ec right sink on right wall	S	23:55			
159.2-53	174 Home Ec kitchen 3	S	23:56			
159.2-54	174 Home Ec kitchen 4	S	23:57			
159.2-55	174 Home Ec kitchen 1	S	23:58			
159.2-56	174 Home Ec kitchen 2	S	23:59			
159.2-57	Kitchen Handwash	S	0:00			
159.2-58	Kitchen Left Double sink	S	0:01			
159.2-59	Kitchen Right Double sink	S	0:02			
159.2-60	Kitchen Serving line	S	0:03			
159.2-61	Dishwash sprayer	S	0:04			

Notes:

Please e-mail lab results to labs@stohlenv.com

Sampled By: Paul Nichols Print Name Paul Nichols Stohl Env: Paul Nichols Date: 1/25/2021

Relinquished By: Eric Henderson Jr. Print Name Eric Henderson Jr. Stohl Env: Eric Henderson Jr. Date: 1/28/2021

Received (Name / Lab): RTHARRIS / R. Williams Date: 2-2-21 Time: 12:07 pm

Sample Login (Name / Lab): Traci Bloom / Grace Bloom Date: 2/15/21 Time: 9:17 AM

Analysis (Name / Lab): J. Hertigler Date: 2/26/21 Time: 1:58 pm

QA/QC Review (Name / Lab): Jade Coy Date: 2/26/21 Time: 2/26/21

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____



Chain of Custody Document

3860 California Road, Orchard Park, New York 14127
 PHONE (716) 312-0070 FAX (716) 312-8092
 WWW.STOHLENVIRONMENTAL.COM

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-159.2

Client: Grand Island CSD

Contact: James Rozler

Building: Veronica E. Connors Middle School

Location: 1100 Ransom Road Grand Island, NY 14072

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
159.2-62	Pot Fill	S	0:05			
159.2-63	Locker Room handwash Kitchen	S	0:06			
159.2-64	Locker Room boys left	S	0:07			
159.2-65	Locker room Boys right	S	0:08			
159.2-66	Boys Coaches office	S	0:09			
159.2-67	Boys upper bathrooms leftmost of bradley sink	S	0:10			
159.2-70	Boys upper bathrooms rightmost of bradley sink	S	0:11			
159.2-71	Girls upper bathrooms leftmost of bradley sink	S	0:12			
159.2-72	Girls upper bathrooms left middle	S	0:13			
159.2-73	Girls upper bathrooms right middle	S	0:14			
159.2-74	Girls upper bathrooms rightmost	S	0:15			
159.2-75	Coach's Office/Team Locker Room	S	0:16			
159.2-76	Room 191 Tech	S	0:17			
159.2-77	Room 190 tech	S	0:18			
159.2-78	Girls locker room left	S	0:19			
159.2-79	Girls locker room right	S	0:20			
159.2-80	Girls Coach's office	S	0:21			
159.2-83	189 Art right wall far left	S	0:22			

Notes:

Please e-mail lab results to labs@stohlenv.com

Sampled By: Paul Nichols Print Name Paul Nichols Stohl Env: Paul Nichols Date: 1/25/2021

Relinquished By: E. Henderson Jr. Print Name Eric Henderson Jr. Stohl Env: Eric Henderson Jr. Date: 1/28/2021

Received (Name / Lab): K. HARRIS Date: 2-2-21 Time: 12:07 PM

Sample Login (Name / Lab): Tina Bloom / Yau Bloom Date: 2/15/21 Time: 9:20 AM

Analysis (Name / Lab): J. Rozler Date: 2/26/21 Time: 1:58 pm

QA/QC Review (Name / Lab): _____ Date: _____ Time: _____

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____



Chain of Custody Document

3860 California Road, Orchard Park, New York 14127
 PHONE (716) 312-0070 FAX (716) 312-8092
 WWW.STOHLENVIRONMENTAL.COM

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-159.2

Client: Grand Island CSD Contact: James Rozler

Building: Veronica E. Connors Middle School Location: 1100 Ransom Road Grand Island, NY 14072

LEAD
 Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround
20 Days

Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
159.2-84	189 Art right wall left middle	S	0:23			
159.2-85	189 art right wall right middle	S	0:24			
159.2-86	189 art right wall far right	S	0:25			
159.2-87	188 art left wall far left	S	0:26			
159.2-88	188 art left wall left middle	S	0:27			

Notes:
 Please e-mail lab results to labs@stohlenv.com

Sampled By: Paul Nichols Print Name Paul Nichols Date: 1/25/2021

Relinquished By: E. Henderson Jr. Print Name Eric Henderson Jr. Date: 1/28/2021

Received (Name / Lab): KTHARRIS X [Signature] Date: 2.2.21 Time: 12:07 pm

Sample Login (Name / Lab): Tina Deon / [Signature] Date: 2/15/21 Time: 9:00 AM

Analysis (Name / Lab): G. Hertgen Date: 2/26/21 Time: 1:58 pm

QA/QC Review (Name/Lab): _____ Date: _____ Time: _____

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____