

**Centennial High School**

Sample ID	Sample Date	Sample Time	Fixture Type	Cadmium (ppb)	Copper (ppb)	Iron (ppb)	Lead (ppb)	Zinc (ppb)	Location	Action
CHS1	5/16/2018	5:48 AM	SC-1S	<1.00	1.93	<500	<1.00	2.04	Backflow #1	No Action Taken
CHS2	5/16/2018	5:52 AM	SC-1M	<1.00	1.75	<500	<1.00	1.52	Backflow #2	No Action Taken
CHS3	5/16/2018	5:55 AM	DFS	1.81	1370	<500	8.42	105	Hallway near Classroom #405	No Action Taken
CHS4	5/16/2018	5:56 AM	DFS	<1.00	217	<500	<1.00	1.72	Hallway near Classroom #309	No Action Taken
CHS5	5/16/2018	5:57 AM	DFS	<1.00	673	<500	1.23	6.79	Hallway near Classroom #414	No Action Taken
CHS6	5/16/2018	5:59 AM	DFS	<1.00	330	<500	<1.00	11.4	2nd Floor Hallway near Classroom #508	No Action Taken
CHS7	5/16/2018	6:01 AM	DFS	<1.00	102	<500	<1.00	302	2nd Floor Hallway near Classroom #502	No Action Taken
CHS8	5/16/2018	6:04 AM	DFS	<1.00	42.4	<500	<1.00	7.02	Hallway near Classroom #302	No Action Taken
CHS9	5/16/2018	6:06 AM	DFS	<1.00	163	<500	<1.00	10.7	Hallway near Kitchen	No Action Taken
CHS10-L	5/16/2018	6:07 AM	KSF	<1.00	455	<500	3.78	123	Kitchen	No Action Taken
CHS10-R	5/16/2018	6:07 AM	KSF	<1.00	319	<500	3.45	923	Kitchen	No Action Taken
CHS11	5/16/2018	6:08 AM	IM	<1.00	4.54	<500	<1.00	2.10	Kitchen	No Action Taken
CHS12	5/16/2018	6:10 AM	DFS	<1.00	85.1	<500	1.24	4.76	Hallway near Girls Locker Room	No Action Taken
CHS13	5/16/2018	6:11 AM	DFS	12.6	1070	<500	4.52	147	Hallway near Room #105	No Action Taken
CHS14	5/16/2018	6:12 AM	DFS	<1.00	199	<500	3.30	137	Hallway near Weight Lifting Room	No Action Taken
CHS15	5/16/2018	6:14 AM	DFS	<1.00	685	<500	7.39	108	Pool Area	No Action Taken
SL 15SEC*	5/8/2018	5:50 AM		<1.00	1.90	<500	<1.00	<1.00	Meter	
SL 45SEC*	5/8/2018	5:51 AM		<1.00	1.45	<500	<1.00	<1.00	Meter	

**Fixture Type: DFS - Drinking Fountain with single faucet, DFD - Drinking Fountain with double faucet, \*SC - Service Connection Tap; KS - Kitchen Sink; TL - Teachers Lounge Sink**

\* Service Connection Tap is not a point for consumption water