

**East High School**

Sample ID	Sample Date	Sample Time	Fixture Type	Cadmium (ppb)	Copper (ppb)	Iron (ppb)	Lead (ppb)	Zinc (ppb)	Location	Action
EHS-1	6/20/2018	6:01 AM	SC-1S	<.1	23.3	16	2.9	40	Backflow #1	No Action Taken
EHS-2	6/20/2018	6:06 AM	SC-1M	<.1	7.4	5	1.4	18	Backflow #2	No Action Taken
EHS-3	6/20/2018	6:15 AM	DFS	<.1	356.8	<5	6.6	118	Swimming Pool	No Action Taken
EHS-4	6/20/2018	6:16 AM	DFS	0.1	129.85	<5	4.5	2375	Hallway near Varsity Locker Room	No Action Taken
EHS-5	6/20/2018	6:17 AM	DFS	<.1	478.6	6	0.8	33	Hallway near Auxilary Gym	No Action Taken
EHS-6	6/20/2018	6:24 AM	DFS	<.1	504.5	14	8.0	30	Weightlifting Room	No Action Taken
EHS-8	6/20/2018	6:22 AM	DFS	<.1	139.8	5	7.2	82	Hallway Outside Gymnasium	No Action Taken
EHS-9	6/20/2018	6:24 AM	DFS	<.1	1104.6	5	1.4	253	Hallway Outside Gymnasium	No Action Taken
EHS-10	6/20/2018	6:25 AM	KSF	<.1	1780.5	<5	12.0	252	Hallway near Girls Locker Room	Filtration system installed
EHS-11L	6/20/2018	6:27 AM	KSF	<.1	116.3	36	6.70	1293	Kitchen	No Action Taken
EHS-11R	6/20/2018	6:28 AM	IM	<.1	58.7	140	2.8	226	Kitchen	No Action Taken
EHS-13	6/20/2018	6:31 AM	DFS	3.5	467.0	<5	60.4	363	Kitchen	Filtration system installed
EHS-14	6/20/2018	6:32 AM	DFS	9.4	658.8	<5	55.1	372	Cafeteria	Filtration system installed
EHS-15	6/20/2018	6:33 AM	DFS	<.1	1031.7	<5	95.7	136	Cafeteria	Filtration system installed
EHS-16	6/20/2018	6:34 AM	DFS	1.8	1010.3	<5	39.2	173	Cafeteria	Filtration system installed
EHS-17	6/20/2018	6:35 AM	DFS	0.4	982.0	<5	82.4	673	Cafeteria	Filtration system installed
EHS-18	6/20/2018	6:27 AM	DFS	0.2	472.3	<5	48.0	528	Hallway near Cafeteria	Filtration system installed
EHS-19	6/20/2018	6:38 AM	DFS	0.1	305.5	<5	38.0	390	Storage Room near Stage	Filtration system installed
EHS-20F	6/20/2018	6:39 AM	DFD	0.1	469.5	<5	2.50	152	Hallway near Activities Office	No Action Taken
EHS-21	6/20/2018	6:41 AM	DFD	0.1	967.1	<5	4.8	140	Hallway near Auditorium	No Action Taken
EHS-22	6/20/2018	6:43 AM	DFS	2.2	378.0	8	33.0	378	Hallway near Auditorium	Filtration system installed
EHS-23	6/20/2018	6:43 AM	DFS	0.1	334.9	5	26.2	165	Hallway near Auditorium	Filtration system installed
EHS-24	6/20/2018	6:45 AM	DFS	0.3	381.9	<5	31.6	616	Hallway near Classroom #39	Filtration system installed
EHS-25	6/20/2018	6:45 AM	DFS	0.1	416.0	<5	14.7	514	Hallway near Classroom #39	Filtration system installed
EHS-28	6/20/2018	6:47 AM	DFS	0.2	451.5	<5	40.1	418	Hallway near Classroom #39	Filtration system installed
EHS-29	6/20/2018	6:46 AM	DFS	1.5	585.8	<5	36.9	356	Hallway near Classroom #39	Filtration system installed
EHS-31	6/20/2018	6:50 AM	DFS	<0.1	235.5	10	24.7	164	Hallway near Science Wing	Filtration system installed
EHS-32	6/20/2018	6:51 AM	DFS	<0.1	190.3	6	6.1	83	Hallway near Science Wing	No Action Taken
EA31	6/20/2018	6:50 AM	DFS	<1.00	250	<500	6.88	155	Hallway near Media Center	No Action Taken
EA32	6/20/2018	6:51 AM	DFS	<1.00	219	<500	12.6	39.6	Hallway near Media Center	No Action Taken

**Fixture Type: DFS - Drinking Fountain with single faucet, DFD - Drinking Fountain with double faucet, \*SC - Service Connection Tap; KS - Kitchen Sink; TL - Teachers Lounge Sink**

\* Service Connection Tap is not a point for consumption water