

**Heaton Middle School**

Sample ID	Sample Date	Sample Time	Fixture Type	Cadmium (ppb)	Copper (ppb)	Iron (ppb)	Lead (ppb)	Zinc (ppb)	Location	Action
HT1	4/10/2018	6:03 AM	SC-1S	<1.00	27.7	<500	<1.00	3.61	Backflow #1	No Action Taken
HT2	4/10/2018	6:07 AM	SC-1M	<1.00	29.0	<500	<1.00	2.51	Backflow #2	No Action Taken
HT3	4/10/2018	6:34 AM	KSF	<1.00	14.5	<500	<1.00	14.2	Kitchen	No Action Taken
HT4	4/10/2018	6:20 AM	KSF	<1.00	43.8	<500	3.34	564	Kitchen	No Action Taken
HT5	4/10/2018	6:29 AM	DFS	<1.00	91.8	<500	5.32	29.0	Gymnasium	No Action Taken
HT6	4/10/2018	6:30 AM	DFS	<1.00	160	<500	9.63	117	Gymnasium	No Action Taken
HT7-L	4/10/2018	6:24 AM	DFD	<1.00	66.8	<500	5.42	423	Hallway near Auditorium	No Action Taken
HT7-R	4/10/2018	6:24 AM	DFD	<1.00	63.8	<500	4.42	109	Hallway near Auditorium	No Action Taken
HT8	4/10/2018	6:31 AM	DFS	<1.00	767	<500	45.3	885	Classroom #54	Disabled
HT9-L	4/10/2018	6:35 AM	DFD	<1.00	573	<500	12.6	430	Cafeteria	No Action Taken
HT10	4/10/2018	6:37 AM	DFS	<1.00	310	<500	6.08	93.5	Hallway near Classroom #12	No Action Taken
HT11	4/10/2018	6:40 AM	DFS	<1.00	88.6	<500	4.68	102	Hallway near Classroom #43	No Action Taken
H12	4/10/2018	6:42 AM	DFS	<1.00	151	<500	7.61	173	Hallway near Classroom #25	No Action Taken
HT13	4/10/2018	6:43 AM	DFS	<1.00	75.2	<500	5.10	90.9	Hallway near Classroom #32	No Action Taken
SL 15SEC	4/10/2018	6:20 AM		<1.00	102	<500	128	14.3	Meter	No Action Taken
SL 45SEC	4/10/2018	6:20 AM		<1.00	12.7	<500	1.18	12.1	Meter	No Action Taken

**Fixture Type: DFS - Drinking Fountain with single faucet, DFD - Drinking Fountain with double faucet, \*SC - Service Connection Tap; KS - Kitchen Sink; TL - Teachers Lounge Sink**

\* Service Connection Tap is not a point for consumption water