

Highland Park Elementary School

Sample ID	Sample Date	Sample Time	Fixture Type	Cadmium (ppb)	Copper (ppb)	Iron (ppb)	Lead (ppb)	Zinc (ppb)	Location	Action
HGHL1	2/13/2018	6:02 AM	SC-1S	<1.00	55.7	<500	1.16	11.6	Backflow #1	No Action Taken
HGHL2	2/13/2018	6:06 AM	SC-1M	<1.00	26.3	<500	<1.00	3.08	Backflow #2	No Action Taken
HGHL3-L	2/13/2018	6:08 AM	DFD	<1.00	42.9	<500	3.15	53.0	Hallway Near Gymnasium	No Action Taken
HGHL3-R	2/13/2018	6:09 AM	DFD	<1.00	50.9	<500	2.21	169	Hallway Near Gymnasium	No Action Taken
HGHL4-L	2/13/2018	6:09 AM	DFD	<1.00	119	<500	3.17	73.3	Gymnasium	No Action Taken
HGHL4-R	2/13/2018	6:10 AM	DFD	<1.00	121	<500	1.76	53.5	Gymnasium	No Action Taken
HGHL5-L	2/13/2018	6:10 AM	DFD	<1.00	170	<500	14.9	251	Cafeteria	Disabled
HGHL5-R	2/13/2018	6:11 AM	DFD	<1.00	155	<500	12.2	99.9	Cafeteria	Disabled
HGHL6	2/13/2018	6:12 AM	KSF	1.51	34.1	<500	1.05	673	Kitchen	No Action Taken
HGHL7	2/13/2018	6:13 AM	KSF	<1.00	248	<500	2.69	489	Nurses Office	No Action Taken
HGHL8	2/13/2018	6:14 AM	TL	<1.00	77.5	<500	<1.00	98.0	Teachers Lounge Sink	No Action Taken
HGHL9	2/13/2018	6:15 AM	DFS	<1.00	103	<500	3.11	59.4	Hallway Near Classroom #33	No Action Taken
SL 15SEC	2/13/2018	5:50 AM		<1.00	19.2	<500	1.63	30.9	Water Meter	No Action Taken
SL 45SEC	2/13/2018	5:50 AM		<1.00	15.7	<500	1.13	22.0	Water Meter	No Action Taken

Fixture Type: DFS - Drinking Fountain with single faucet, DFD - Drinking Fountain with double faucet, *SC - Service Connection Tap; KS - Kitchen Sink; TL - Teachers Lounge Sink

* Service Connection Tap is not a point for consumption water