

**Minnequa Elementary**

Sample ID	Sample Date	Sample Time	Fixture Type	Cadmium (ppb)	Copper (ppb)	Iron (ppb)	Lead (ppb)	Zinc (ppb)	Location	Action
MIN1	3/27/2018	5:57 AM	SC-1S	<1.00	29.9	<500	<1.00	7.61	Backflow #1	No Action Taken
MIN2	3/27/2018	6:01 AM	SC-1M	<1.00	19.3	<500	<1.00	3.73	Backflow #2	No Action Taken
MIN3-L	3/27/2018	6:01 AM	KSF	<1.00	69.4	<500	4.95	578	Kitchen Sink	No Action Taken
MIN3-R	3/27/2018	6:02 AM	KSF	<1.00	54.6	<500	4.02	259	Kitchen Sink	No Action Taken
MIN4-L	3/27/2018	6:04 AM	FF	<1.00	89.7	<500	3.61	93.5	Classroom #2	No Action Taken
MIN5-L	3/27/2018	6:06 AM	FF	<1.00	108	<500	2.21	285	Classroom #6	No Action Taken
MIN6-L	3/27/2018	6:10 AM	FF	<1.00	171	<500	4.84	365	Classroom #7	No Action Taken
MIN6-R	3/27/2018	6:10 AM	DFS	<1.00	63.4	<500	1.92	45.5	Classroom #7	No Action Taken
MIN7	3/27/2018	6:12 AM	DFS	<1.00	716	<500	<1.00	3.27	Classroom #23	No Action Taken
MIN8	3/27/2018	6:13 AM	DFS	<1.00	320	<500	<1.00	48.6	Hallway near Room #23	No Action Taken
MIN9	3/27/2018	6:14 AM	TL	<1.00	111	<500	1.10	527	Teachers Lounge Sink	No Action Taken
MIN10	3/27/2018	6:15 AM	FF	<1.00	97.3	<500	1.87	322	Nurses Office	No Action Taken
MIN11	3/27/2018	6:17 AM	DFS	<1.00	68.5	<500	<1.00	47.0	Hallway near Gymnasium	No Action Taken
SL 15SEC	3/27/2018	5:55 AM		<1.00	56.2	<500	13.3	19.5	Meter	No Action Taken
SL 45SEC	3/27/2018	5:55 AM		<1.00	8.92	<500	<1.00	5.78	Meter	No Action Taken

**Fixture Type: DFS - Drinking Fountain with single faucet, DFD - Drinking Fountain with double faucet, \*SC - Service Connection Tap; KS - Kitchen Sink; TL - Teachers Lounge Sink**

\* Service Connection Tap is not a point for consumption water