

Morton Elementary

Sample ID	Sample Date	Sample Time	Fixture Type	Cadmium (ppb)	Copper (ppb)	Iron (ppb)	Lead (ppb)	Zinc (ppb)	Location	Action
MRTN1	11/7/2017	5:56 AM	SC-1S	<1.00	119	<500	2.03	87.2	Service Connection Tap	No Action Taken
MRTN2	11/7/2017	6:01 AM	SC-1M	<1.00	224	<500	2.96	171	Service Connection Tap	No Action Taken
MRTN3	11/7/2017	6:06 AM	TL	<1.00	181	<500	1.16	449	Teachers Lounge	No Action Taken
MRTN4	11/7/2017	6:07 AM	DFS	<1.00	23.9	<500	<1.00	51.9	Cafeteria Hallway	No Action Taken
MRTN5-L	11/7/2017	6:08 AM	DFD	<1.00	204	<500	5.14	572	Cafeteria	No Action Taken
MRTN5-R	11/7/2017	6:09 AM	DFD	<1.00	91.0	<500	3.84	241	Cafeteria	No Action Taken
MRTN6-L	11/7/2017	6:10 AM	KSF	<1.00	194	<500	17.8	605	Kitchen	Replacing Faucet, Pipe & Shut Off Valves
MRTN6-R	11/7/2017	6:11 AM	KSF	<1.00	295	<500	36.8	444	Kitchen	Replacing Faucet, Pipe & Shut Off Valves
MRTN7	11/7/2017	6:13 AM	DFS	<1.00	77.8	<500	2.29	350	1st Floor East Hallway	No Action Taken
MRTN8	11/7/2017	6:15 AM	DFS	<1.00	202	<500	<1.00	42.1	2nd Floor near room 214	No Action Taken
MRTN9	11/7/2017	6:16 AM	DFS	<1.00	191	<500	<1.00	27.6	2nd Floor near room 214	No Action Taken
MRTN10	11/7/2017	6:18 AM	DFS	<1.00	96.9	<500	1.65	59.2	2nd East Hallway Vestibule	No Action Taken
SL 15SEC	11/7/2017	5:56 AM	SC	<1.00	49.7	<500	1.88	20.8	Service Connection	No Action Taken
SL 45SEC	11/7/2017	5:57 AM	SC	<1.00	17.6	<500	<1.00	13.4	Service Connection	No Action Taken

Fixture Type: DFS - Drinking Fountain with single faucet, DFD - Drinking Fountain with double faucet, *SC - Service Connection Tap; KS - Kitchen Sink; TL - Teachers Lounge Sink

* Service Connection Tap is not a point for consumption water