

Roncalli STEM Academy

Sample ID	Sample Date	Sample Time	Fixture Type	Cadmium (ppb)	Copper (ppb)	Iron (ppb)	Lead (ppb)	Zinc (ppb)	Location	Action
RMS1	4/17/2018	5:39 AM	SC-1S	<1.00	12.3	<500	<1.00	3.43	Backflow #1	No Action Taken
RMS2	4/17/2018	5:42 AM	SC-1M	<1.00	5.22	<500	<1.00	2.32	Backflow #2	No Action Taken
RMS3	4/17/2018	5:47 AM	DFS	<1.00	1150	<500	<1.00	65.6	Cafeteria	No Action Taken
RMS4-L	4/17/2018	5:49 AM	KSF	<1.00	173	<500	20.0	2150	Kitchen	Replace shut off, water lines & faucet
RMS4-R	4/17/2018	5:49 AM	KSF	<1.00	82.2	<500	3.76	860	Kitchen	No Action Taken
RMS5	4/17/2018	5:50 AM	DFS	<1.00	1220	<500	60.8	348	Cafeteria	Disabled
RMS6	4/17/2018	5:51 AM	DFS	<1.00	508	<500	26.6	147	Hallway near Classroom #31	Disabled
RMS7	4/17/2018	5:51 AM	DFS	<1.00	320	<500	6.35	59.1	Hallway near Classroom #30	No Action Taken
RMS8	4/17/2018	5:53 AM	DFS	<1.00	269	<500	1.22	63.6	Hallway near Classroom #47	No Action Taken
RMS9	4/17/2018	5:58 AM	DFS	4.88	1790	<500	5.92	962	Nurses Office	No Action Taken
RMS10	4/17/2018	5:59 AM	DFS	<1.00	1670	<500	26.2	76.7	Northside Hallway near Main Office	Disabled
RMS11	4/17/2018	6:00 AM	DFS	<1.00	301	<500	5.25	61.5	Southside Hallway near Main Office	No Action Taken
RMS13	4/17/2018	6:02 AM	DFS	<1.00	212	<500	13.4	60.9	Cafeteria	Disabled
SL 15SEC*	4/17/2018	5:44 AM		<1.00	21.1	<500	7.31	10.6	Meter	No Action Taken
SL 45SEC*	4/17/2018	5:45 AM		<1.00	10.5	<500	2.48	5.59	Meter	No Action Taken

Fixture Type: DFS - Drinking Fountain with single faucet, DFD - Drinking Fountain with double faucet, *SC - Service Connection Tap; KS - Kitchen Sink; TL - Teachers Lounge Sink

* Service Connection Tap is not a point for consumption water