

South Park Elementary

Sample ID	Sample Date	Sample Time	Fixture Type	Cadmium (ppb)	Copper (ppb)	Iron (ppb)	Lead (ppb)	Zinc (ppb)	Location	Action
SP1	3/13/2018	6:01 AM	SC-1S	<1.00	17.4	<500	<1.00	5.06	Backflow #1	No Action Taken
SP2	3/13/2018	6:05 AM	SC-1M	<1.00	9.25	<500	<1.00	3.26	Backflow #2	No Action Taken
SP3	3/13/2018	6:07 AM	DFS	<1.00	196	<500	<1.00	7.84	Hallway near Classroom #10	No Action Taken
SP4	3/13/2018	6:09 AM	DFS	<1.00	275	<500	<1.00	26.3	Hallway near Classroom #18	No Action Taken
SP5	3/13/2018	6:12 AM	TL	<1.00	73.6	<500	6.37	154	Teachers Lounge	No Action Taken
SP6	3/13/2018	6:13 AM	KSF	<1.00	490	<500	3.63	1520	Main Office	No Action Taken
SP7-L	3/13/2018	6:14 AM	DFD	<1.00	106	<500	4.97	89.1	Hallway near Gymnasium	No Action Taken
SP7-R	3/13/2018	6:14 AM	DFD	<1.00	88.9	<500	4.93	94.5	Hallway near Gymnasium	No Action Taken
SP8-L	3/13/2018	6:16 AM	DFD	<1.00	174	<500	9.12	286	Cafeteria	No Action Taken
SP8-R	3/13/2018	6:16 AM	DFD	<1.00	336	<500	11.2	225	Cafeteria	No Action Taken
SP9-L	3/13/2018	6:17 AM	KSF	<1.00	41.8	<500	1.09	634	Kitchen Sink	No Action Taken
SP9-R	3/13/2018	6:17 AM	KSF	<1.00	33.2	<500	11.2	229	Kitchen Sink	No Action Taken
SP10-L	3/13/2018	6:18 AM	DFD	<1.00	26.1	<500	2.21	40.5	Gymnasium	No Action Taken
SP10-R	3/13/2018	6:18 AM	DFD	<1.00	36.5	<500	2.22	104	Gymnasium	No Action Taken
SP11	3/13/2018	6:20 AM	KSF	<1.00	47.2	<500	1.32	229	Classroom #125	No Action Taken
SP12	3/13/2018	6:21 AM	DFS	<1.00	1030	<500	1.66	382	Hallway near Classroom #131	No Action Taken
SL 15SEC	3/13/2018	5:56 AM		<1.00	47.2	<500	2.98	25.5	Meter	No Action Taken
SL 45SEC	3/13/2018	5:56 AM		<1.00	12.8	<500	<1.00	7.88	Meter	No Action Taken

Fixture Type: DFS - Drinking Fountain with single faucet, DFD - Drinking Fountain with double faucet, *SC - Service Connection Tap; KS - Kitchen Sink; TL - Teachers Lounge Sink

* Service Connection Tap is not a point for consumption water