

| Lead Tests - Wilson Elementary School - Main Building - # 20481300 | | | | | | |
|---|----------------|-------------------|--|-------------|-------------------|--|
| # | Fixture ID # | Sample ID # | Location/Type | Date Tested | Lead Test Results | Remarks |
| 1 | 20481300-001NS | 20481300-001NS25A | Health Room - Sink | 04/12/24 | 3.1 | None. |
| 2 | 20481300-002DW | 20481300-002DW25A | Staff Work Room - Drinking Fountain | 04/12/24 | 1.6 | None. |
| 3 | 20481300-003SF | 20481300-003SF25A | Staff Work Room - Sink | 04/12/24 | 3.2 | None. |
| 4 | 20481300-004SF | 20481300-004SF25A | Conference/AP Office Near Main Office - Sink | 04/12/24 | 1.4 | Lead Filter removed 8/20/2021 - (connectors still in place.) |
| Lead Tests - Wilson Elementary School - Rooms 26-28 Modular Building - # 20481301 | | | | | | |
| # | Fixture ID # | Sample ID # | Location/Type | Date Tested | Lead Test Results | Remarks |
| 1 | 20481301-001DW | 20481301-001DW25A | Room 26 - Drinking Fountain | 04/12/24 | 0.7 | None. |
| 2 | 20481301-002CF | 20481301-002CF25A | Room 26 - Sink | 04/12/24 | 0.9 | None. |
| 3 | 20481301-003DW | 20481301-003DW25A | Room 27 - Drinking Fountain | 04/12/24 | 0.7 | None. |
| 4 | 20481301-004CF | 20481301-004CF25A | Room 27 - Sink | 04/12/24 | 0.6 | None. |
| 5 | 20481301-005DW | 20481301-005DW25A | Room 28 - Drinking Fountain | 04/12/24 | 0.7 | None. |
| 6 | 20481301-006CF | 20481301-006CF25A | Room 28 - Sink | 04/12/24 | 0.7 | None. |
| Lead Tests - Wilson Elementary School - E Wing Building - # 20481302 | | | | | | |
| # | Fixture ID # | Sample ID # | Location/Type | Date Tested | Lead Test Results | Remarks |
| 1 | 20481302-001BF | 20481302-001BF25A | Girl's Restroom Across From Room 21 - Sink (Left) | 04/12/24 | 4.0 | None. |
| 2 | 20481302-002BF | 20481302-002BF25A | Girl's Restroom Across From Room 21 - Sink (Right) | 04/12/24 | ND | None. |
| 3 | 20481302-003BF | 20481302-003BF25A | Boy's Restroom Across From Room 21 - Sink (Left) | 04/12/24 | 0.5 | None. |
| 4 | 20481302-004BF | 20481302-004BF25A | Boy's Restroom Across From Room 21 - Sink (Right) | 04/12/24 | 3.1 | None. |
| N/A | N/A | N/A | Room 21 - Drinking Fountain | 10/03/06 | ND | John Jessen removed this drinking fountain on 7/7/2016. |
| 5 | 20481302-005CF | 20481302-005CF25A | Room 21 - Sink | 04/12/24 | 7.9 | None. |
| 6 | 20481302-006DW | 20481302-006DW25A | Room 22 - Drinking Fountain | 04/12/24 | ND | None. |
| 7 | 20481302-007CF | 20481302-007CF25A | Room 22 - Sink | 04/12/24 | 4.0 | None. |
| 8 | 20481302-008DW | 20481302-008DW25A | Room 23 - Drinking Fountain | 04/12/24 | 2.5 | None. |
| 9 | 20481302-009CF | 20481302-009CF25A | Room 23 - Sink | 04/12/24 | ND | None. |
| 10 | 20481302-010DW | 20481302-010DW25A | Room 24 - Drinking Fountain | 04/12/24 | 0.8 | None. |
| 11 | 20481302-011CF | 20481302-011CF25A | Room 24 - Sink | 04/12/24 | ND | None. |
| 12 | 20481302-012DW | 20481302-012DW25A | Room 25 - Drinking Fountain | 04/12/24 | 4.2 | None. |
| 13 | 20481302-013CF | 20481302-013CF25A | Room 25 - Sink | 04/12/24 | 8.7 | None. |
| Lead Tests - Wilson Elementary School - A Wing Building - # 20481303 | | | | | | |
| # | Fixture ID # | Sample ID # | Location/Type | Date Tested | Lead Test Results | Remarks |
| 1 | 20481303-001DW | 20481303-001DW25A | Room 1 - Drinking Fountain | 04/12/24 | 6.8 | This drinking fountain has a sediment filter on it. |
| 2 | 20481303-002CF | 20481303-002CF25A | Room 1 - Sink | 04/12/24 | 10.0 | None. |
| 3 | 20481303-003DW | 20481303-003DW25A | Room 2 - Drinking Fountain | 04/12/24 | 2.4 | None. |
| 4 | 20481303-004CF | 20481303-004CF25A | Room 2 - Sink | 04/12/24 | 7.9 | None. |
| 5 | 20481303-005DW | 20481303-005DW25A | Room 3 - Drinking Fountain | 04/12/24 | 1.5 | None. |
| 6 | 20481303-006CF | 20481303-006CF25A | Room 3 - Sink | 04/12/24 | 6.6 | None. |
| 7 | 20481303-007DW | 20481303-007DW25A | Room 4 - Drinking Fountain | 04/12/24 | 1.7 | None. |
| 8 | 20481303-008CF | 20481303-008CF25A | Room 4 - Sink | 04/12/24 | 5.8 | None. |
| 9 | 20481303-009DW | 20481303-009DW25A | Room 5 - Drinking Fountain | 04/12/24 | 4.8 | This drinking fountain has a sediment filter on it. |
| 10 | 20481303-010CF | 20481303-010CF25A | Room 5 - Sink | 04/12/24 | 2.9 | None. |
| 11 | 20481303-011DW | 20481303-011DW25A | East A Wing/Outside Girls Restroom - Drinking Fountain | 04/12/24 | 0.7 | None. |
| 12 | 20481303-012BF | 20481303-012BF25A | East End of A Wing Girl's Restroom - Sink (Left) | 04/12/24 | 6.5 | None. |
| 13 | 20481303-013BF | 20481303-013BF25A | East End of A Wing Girl's Restroom - Sink (Right) | 04/12/24 | 6.9 | None. |
| 14 | 20481303-014BF | 20481303-014BF25A | East End of A Wing Boy's Restroom - Sink (Left) | 04/12/24 | 0.7 | None. |
| 15 | 20481303-015BF | 20481303-015BF25A | East End of A Wing Boy's Restroom - Sink (Right) | 04/12/24 | 4.6 | None. |
| Lead Tests - Wilson Elementary School - B Wing Building - # 20481304 | | | | | | |
| # | Fixture ID # | Sample ID # | Location/Type | Date Tested | Lead Test Results | Remarks |
| 1 | 20481304-001BF | 20481304-001BF25A | West End of B Wing Girl's Restroom - Sink (Left) | 04/12/24 | 5.8 | None. |
| 2 | 20481304-002BF | 20481304-002BF25A | West End of B Wing Girl's Restroom - Sink (Right) | 04/12/24 | 1.0 | None. |
| 3 | 20481304-003BF | 20481304-003BF25A | West End of B Wing Boy's Restroom - Sink (Left) | 04/12/24 | 2.9 | None. |
| 4 | 20481304-004BF | 20481304-004BF25A | West End of B Wing Boy's Restroom - Sink (Right) | 04/12/24 | 1.6 | None. |
| 5 | 20481304-005DW | 20481304-005DW25A | Room 6 - Drinking Fountain | 04/12/24 | 2.8 | None. |
| 6 | 20481304-006CF | 20481304-006CF25A | Room 6 - Sink | 04/12/24 | 5.7 | None. |
| 7 | 20481304-007DW | 20481304-007DW25A | Room 7 - Drinking Fountain | 04/12/24 | 1.3 | None. |
| 8 | 20481304-008CF | 20481304-008CF25A | Room 7 - Sink | 04/12/24 | 5.3 | None. |
| 9 | 20481304-009DW | 20481304-009DW25A | Room 8 - Drinking Fountain | 04/12/24 | 1.5 | None. |
| 10 | 20481304-010CF | 20481304-010CF25A | Room 8 - Sink | 04/12/24 | 4.5 | None. |
| 11 | 20481304-011DW | 20481304-011DW25A | Room 9 - Drinking Fountain | 04/12/24 | 1.6 | None. |
| 12 | 20481304-012CF | 20481304-012CF25A | Room 9 - Sink | 04/12/24 | 4.5 | None. |
| 13 | 20481304-013DW | 20481304-013DW25A | Room 10 - Drinking Fountain | 04/12/24 | 8.5 | None. |
| 14 | 20481304-014CF | 20481304-014CF25A | Room 10 - Sink | 04/12/24 | 8.1 | None. |
| Lead Tests - Wilson Elementary School - Cafeteria Building - # 20481305 | | | | | | |
| # | Fixture ID # | Sample ID # | Location/Type | Date Tested | Lead Test Results | Remarks |
| 1 | 20481305-001KF | 20481305-001KF25A | Kitchen - Sink (Pre-rinse/Dishwasher) | 04/12/24 | 1.2 | None. |
| 2 | 20481305-002KF | 20481305-002KF25A | Kitchen - Sink (Food Prep - East Wall) | 04/12/24 | ND | None. |
| 3 | 20481305-003KF | 20481305-003KF25A | Kitchen - Sink (Food Prep - North Wall) | 04/12/24 | ND | None. |
| 4 | 20481305-004DW | 20481305-004DW25A | Cafeteria - Drinking Fountain (Upper) | N/A | ND | Removed 2023. |
| 5 | 20481305-005DW | 20481305-005DW25A | Cafeteria - Drinking Fountain | 04/12/24 | ND | Elkay with Filter installed in 2023 |
| 6 | 20481305-006WB | 20481305-006WB25A | Cafeteria - Drinking Fountain (Bottle Filler) | 04/12/24 | ND | Elkay with Filter installed in 2023 |
| 7 | 20481305-007BF | 20481305-007BF25A | Cafeteria Men's Restroom - Sink | 04/12/24 | 2.8 | None. |
| 8 | 20481305-008BF | 20481305-008BF25A | Cafeteria Women's Restroom - Sink | 04/12/24 | ND | None. |
| Lead Tests - Wilson Elementary School - C Wing Building - # 20481306 | | | | | | |
| # | Fixture ID # | Sample ID # | Location/Type | Date Tested | Lead Test Results | Remarks |
| 1 | 20481306-001DW | 20481306-001DW25A | Room 11 - Drinking Fountain | 04/12/24 | 1.6 | None. |
| 2 | 20481306-002CF | 20481306-002CF25A | Room 11 - Sink | 04/12/24 | 7.7 | None. |

| 3 | 20481306-003DW | 20481306-003DW25A | Room 12 - Drinking Fountain | 04/12/24 | 5.0 | None. |
|---|----------------|-------------------|---|-------------|-------------------|--|
| 4 | 20481306-004CF | 20481306-004CF25A | Room 12 - Sink | 04/12/24 | 10.1 | None. |
| 5 | 20481306-005DW | 20481306-005DW25A | Room 13 - Drinking Fountain | 04/12/24 | 1.1 | None. |
| 6 | 20481306-006CF | 20481306-006CF25A | Room 13 - Sink | 04/12/24 | 3.0 | None. |
| 7 | 20481306-007DW | 20481306-007DW25A | Room 14 - Drinking Fountain | 04/12/24 | 1.3 | None. |
| 8 | 20481306-008CF | 20481306-008CF25A | Room 14 - Sink | 04/12/24 | 4.7 | None. |
| 9 | 20481306-009DW | 20481306-009DW25A | Room 15 - Drinking Fountain | 04/12/24 | 11.1 | None. |
| 10 | 20481306-010CF | 20481306-010CF25A | Room 15 - Sink | 04/12/24 | 6.9 | None. |
| 11 | 20481306-011BF | 20481306-011BF25A | West End of C Wing Girl's Restroom - Sink (Left) | 04/12/24 | 13.1 | None. |
| 12 | 20481306-012BF | 20481306-012BF25A | West End of C Wing Girl's Restroom - Sink (Right) | 04/12/24 | 2.9 | None. |
| 13 | 20481306-013BF | 20481306-013BF25A | West End of C Wing Boy's Restroom - Sink (Left) | 04/12/24 | 7.1 | None. |
| 14 | 20481306-014BF | 20481306-014BF25A | West End of C Wing Boy's Restroom - Sink (Right) | 04/12/24 | 3.2 | None. |
| Lead Tests - Wilson Elementary School - Gymnasium/Media Center Building - # 20481307 | | | | | | |
| # | Fixture ID # | Sample ID # | Location/Type | Date Tested | Lead Test Results | Remarks |
| 1 | 20481307-001SF | 20481307-001SF25A | Pass Room (Old Staff Break Room) - Sink | 05/21/24 | ND | Installed lead filter 05/20/2024. |
| 2 | 20481307-002BF | 20481307-002BF25A | Men's Restroom East Side of Staff Break Room - Sink | 04/30/24 | 2.9 | None. |
| 3 | 20481307-003BF | 20481307-003BF25A | Women's Restroom East Side of Staff Break Room - Sink | 04/12/24 | 8.8 | None. |
| N/A | N/A | N/A | Bolier Room - Sink | N/A | 7.7 | Water should not be consumed out of this sink |
| N/A | N/A | N/A | Old Shower/Storage Room - Drinking Fountain (East Gym) | N/A | N/A | This drinking fountain is not utilized and disconnected. |
| N/A | N/A | N/A | Old Shower/Storage Room - Drinking Fountain (West Gym) | N/A | N/A | This drinking fountain is not utilized and disconnected. |
| 4 | 20481307-004DW | 20481307-004DW25A | West Side of Gym (Outside) - Drinking Fountain (Left) | 04/12/24 | ND | This drinking fountain has a lead filter on it. |
| 5 | 20481307-005DW | 20481307-005DW25A | West Side of Gym (Outside) - Drinking Fountain (Right) | 04/12/24 | ND | This drinking fountain has a lead filter on it. |
| 6 | N/A | N/A | Baseball Field Drinking Fountain | N/A | N/A | Added to Tracker 08/23/21. Removed from Site 05/13/22. |
| Lead Tests - Wilson Elementary School - D Wing Building - # 20481308 | | | | | | |
| # | Fixture ID # | Sample ID # | Location/Type | Date Tested | Lead Test Results | Remarks |
| 1 | 20481308-001BF | 20481308-001BF25A | East End of D Wing Girl's Restroom - Sink (Left) | 04/12/24 | 5.8 | None. |
| 2 | 20481308-002BF | 20481308-002BF25A | East End of D Wing Girl's Restroom - Sink (Right) | 04/12/24 | 2.5 | None. |
| 3 | 20481308-003BF | 20481308-003BF25A | East End of D Wing Girl's Restroom - Sink (Separate Room) | 04/12/24 | 0.9 | None. |
| 4 | 20481308-004BF | 20481308-004BF25A | East End of D Wing Boy's Restroom - Sink (Left) | 04/12/24 | 1.1 | None. |
| 5 | 20481308-005BF | 20481308-005BF25A | East End of D Wing Boy's Restroom - Sink (Right) | 04/12/24 | 9.6 | None. |
| 6 | 20481308-006DW | 20481308-006DW25A | Room 16 (Staff Break) - Drinking Fountain | 04/12/24 | 6.9 | None. |
| 7 | 20481308-007CF | 20481308-007CF25A | Room 16 (Staff Break) - Sink | 04/12/24 | 1.6 | None. |
| 8 | 20481308-008DW | 20481308-008DW25A | Room 17 - Drinking Fountain | 04/12/24 | 1.0 | None. |
| 9 | 20481308-009CF | 20481308-009CF25A | Room 17 - Sink | 04/12/24 | 4.0 | None. |
| 10 | 20481308-010CF | 20481308-010CF25A | Room 18 - Sink | 04/12/24 | 3.7 | None. |
| 11 | 20481308-011SF | 20481308-011SF25A | Small Kitchenette Space In-between Rooms 18/19 - Sink | 04/12/24 | 2.1 | None. |
| 12 | 20481308-012DW | 20481308-012DW25A | Room 19 - Drinking Fountain | 04/12/24 | 0.6 | None. |
| 13 | 20481308-013CF | 20481308-013CF25A | Room 19 - Sink | 04/12/24 | 1.3 | None. |
| 14 | 20481308-014DW | 20481308-014DW25A | Room 20 - Drinking Fountain | 04/12/24 | ND | None. |
| 15 | 20481308-015CF | 20481308-015CF25A | Room 20 - Sink | 04/12/24 | 1.0 | None. |

*None Detected (ND) = 0.10 Or Less PPB

 = Fixture Where Water Has The Potential of Being Consumed (All of These Will Be Tested When Testing The Whole School)

*ODE's required action level is 15 parts per billion (PPB)

*The E.P.A.'s recommended action level for lead in schools is 20 PPB. Oregon's action level for schools changed to 15 PPB in 2019 in accordance with OAR 333-061-0400. In 2021, ODE changed the unit of measurement for reporting to parts per billion (PPB).

*The E.P.A. action level for copper is 1.30

*Lead test results will be posted on the MSD/Facilities website within 5 days minus the school map for security purposes.