

J.C. Broderick & Associates, Inc.

Environmental / Construction Consulting & Testing



1775 Expressway Drive North
Hauppauge, NY 11788
631.584.5492
Fax: 631.584.3395
www.jcbroderick.com

April 6, 2021

Mr. Frank Fiorino
Middle Country Central School District
25 N. Bicycle Path Suite B
Selden, New York 11784

Re: **Lead Testing in School Drinking Water
2020 Compliance 10 NYCRR Subpart 67-4**

JCB#: **19-45366**

Dear Mr. Fiorino:

J.C. Broderick & Associates, Inc. (JCB) was retained to perform lead testing and analysis of the outlets which service the above referenced school district in accordance with 10 NYCRR Subpart 67-4 (Subpart 67-4).

The outlets servicing each of the school buildings were inventoried and assigned unique identification numbers. The use and location of each outlet was reviewed to determine its applicability for testing under Subpart 67-4.

An initial first-draw sample was collected from each applicable outlet after the minimum 8-hour stagnation period. Samples were logged into a chain of custody document and delivered to an Environmental Laboratory Approval Program (ELAP) accredited laboratory for analysis.

Results from the laboratory analysis were compared with the Action Level as defined by Subpart 67-4 of 15 parts per billion (ppb). Any outlet which exceeded this level requires a remediation action plan be implemented (i.e. removal from service, placarding for non-drinking uses). Outlets which did not exceed the action level do not require further testing or remediation.

Please see the following attachments which detail the sampling and analysis performed and remediation actions taken to date.

Attachment 1: Lead Testing Results for Applicable Outlets
Attachment 2: Laboratory Analytical Reports
Attachment 3: Laboratory Certifications

If you have any questions, or if more information is needed, please contact our office.


Sincerely,

A handwritten signature in cursive script, appearing to read 'George Greve', written in black ink.

George Greve
J C Broderick & Associates, Inc.

Attachment 1:

Lead Testing Results
for Applicable Outlets



J.C. Broderick & Associates, Inc.
Environmental Consulting & Testing
1775 Expressway Drive North
Hauppauge, New York 11788
631.584.5492 fax 631.584.3395



Laboratory Lead in Water Results

J. C. BRODERICK AND ASSOCIATES, INC.

1775 Expressway North Hauppauge, NY 11788

TEL: (631) 584-5492 FAX: (631) 584-3395

JCB #: 19-45366

Middle Country Central School District

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
---------------	----------	------------------	-------------	----------------------	-------------	--------------	------------------------------------

Administrative Office

MCCSD-0783	1011	Women's Bathroom	Bathroom Faucet	Non-Potable	12/4/2020	1.2	Result Below Action Level Continue O&M
MCCSD-0785	1013	Restroom Adjacent Custodial Closet	Bathroom Faucet	Non-Potable	12/4/2020	14	Result Below Action Level Continue O&M
MCCSD-0786	1014	Corridor from Personnel to Main Entrance Lobby	Water Fountain-No Chiller	Potable	12/4/2020	2.8	Result Below Action Level Continue O&M
MCCSD-0788	2008	Women's Bathroom	Bathroom Faucet	Non-Potable	12/4/2020	2.5	Result Below Action Level Continue O&M
MCCSD-0789	2004	Men's Bathroom	Bathroom Faucet	Non-Potable	12/4/2020	3.7	Result Below Action Level Continue O&M
MCCSD-0790	2010	Kitchen	Sports Cooler	Potable	12/4/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0791	2010	Kitchen	Kitchen Faucet (Cold)	Potable	12/4/2020	1.4	Result Below Action Level Continue O&M
MCCSD-0792	1024	New Construction Classroom	Classroom Faucet	Non-Potable	1/21/2021	42	Placarded for Non-Drinking Use Until Remediated

Bicycle Path Kindergarten Center

MCCSD-1756	1000	Room 101	Classroom Faucet	Non-Potable	11/20/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1757	1000	Room 101	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1758	1001	Room 102	Classroom Faucet	Non-Potable	11/20/2020	<3.0 ND	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-1759	1001	Room 102	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1760	1002	Room 103	Classroom Faucet	Non-Potable	11/20/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1761	1002	Room 103	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1762	1003	Room 105	Classroom Faucet	Non-Potable	11/20/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1763	1003	Room 105	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1764	1005	Room 107	Classroom Faucet	Non-Potable	11/20/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1765	1005	Room 107	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1766	1006	Room 108	Classroom Faucet	Non-Potable	11/20/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1767	1006	Room 108	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1768	1009A	Room 109	Classroom Faucet	Non-Potable	11/20/2020	6.8	Result Below Action Level Continue O&M
MCCSD-1769	1010	Room 110	Classroom Faucet	Non-Potable	11/20/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1770	1010	Room 110	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1771	1011	Bathroom	Bathroom Faucet	Non-Potable	11/20/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1772	1011	Bathroom	Bathroom Faucet	Non-Potable	11/20/2020	OOS	Testing Required Before Return to Service
MCCSD-1773	1011	Bathroom	Bathroom Faucet	Non-Potable	11/20/2020	OOS	Testing Required Before Return to Service

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-1774	1011	Bathroom	Bathroom Faucet	Non-Potable	11/20/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1775	1014	Hallway	Bottled Water Dispenser	Potable	11/20/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1776	1014	Hallway	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1778	1013	Bathroom	Bathroom Faucet	Non-Potable	11/20/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1779	1013	Bathroom	Bathroom Faucet	Non-Potable	11/20/2020	OOS	Testing Required Before Return to Service
MCCSD-1780	1013	Bathroom	Bathroom Faucet	Non-Potable	11/20/2020	OOS	Testing Required Before Return to Service
MCCSD-1781	1013	Bathroom	Bathroom Faucet	Non-Potable	11/20/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1782	1015	Room 111	Classroom Faucet	Non-Potable	11/20/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1783	1015	Room 111	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1784	1016	Room 112	Classroom Faucet	Non-Potable	11/20/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1785	1016	Room 112	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1786	1017	Room 113	Classroom Faucet	Non-Potable	11/20/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1787	1017	Room 113	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1788	1018	Room 114	Classroom Faucet	Non-Potable	11/20/2020	1.3	Result Below Action Level Continue O&M
MCCSD-1789	1018	Room 114	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-1790	1019	Faculty	Classroom Faucet	Potable	11/20/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1791	1020	Room 117	Classroom Faucet	Non-Potable	11/20/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1792	1020	Room 117	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1793	1021	Room 118	Classroom Faucet	Non-Potable	11/20/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1794	1021	Room 118	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1795	1022	Cafeteria	Classroom Faucet	Non-Potable	11/20/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1796	1022	Cafeteria	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1797	1024	Kitchen	Kitchen Faucet (Cold)	Potable	11/20/2020	3.6	Result Below Action Level Continue O&M
MCCSD-1798	1024	Kitchen	Hand Wash Only	Non-Potable	11/20/2020	1	Result Below Action Level Continue O&M
MCCSD-1799	1024	Kitchen	Kitchen Faucet (Cold)	Potable	11/20/2020	1.9	Result Below Action Level Continue O&M
MCCSD-1800	1024	Kitchen	Spray Nozzle	Potable	11/20/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1801	1024	Kitchen	Kitchen Service Area	Potable	11/20/2020	1.6	Result Below Action Level Continue O&M
MCCSD-1802	1024A	Kitchen Bathroom	Bathroom Faucet	Non-Potable	11/20/2020	3.2	Result Below Action Level Continue O&M
MCCSD-1804	1025	Room 119	Classroom Faucet	Non-Potable	11/20/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1805	1025	Room 119	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-1806	1026	Office	Bottled Water Dispenser	Potable	11/20/2020	OOS	Testing Required Before Return to Service
MCCSD-1807	1027	Room 123	Classroom Faucet	Non-Potable	11/20/2020	7.6	Result Below Action Level Continue O&M
MCCSD-1810	1031	Room 125	Classroom Faucet	Non-Potable	11/20/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1811	1031	Room 125	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1812	1034C	Office Bathroom	Bathroom Faucet	Non-Potable	11/20/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1813	1049	Hallway	Bottled Water Dispenser	Potable	11/20/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1814	1049	Hallway	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1815	1035	Bathroom	Bathroom Faucet	Non-Potable	11/20/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1816	1036	Bathroom	Bathroom Faucet	Non-Potable	11/20/2020	1.2	Result Below Action Level Continue O&M
MCCSD-1817	1037	Nurse	Nurse's Office Sink	Potable	11/20/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1818	1037A	Nurse Bathroom	Bathroom Faucet	Non-Potable	11/20/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1819	1038	Bathroom	Bathroom Faucet	Non-Potable	11/20/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1820	1038	Bathroom	Bathroom Faucet	Non-Potable	11/20/2020	OOS	Testing Required Before Return to Service
MCCSD-1821	1038	Bathroom	Bathroom Faucet	Non-Potable	11/20/2020	OOS	Testing Required Before Return to Service
MCCSD-1822	1038	Bathroom	Bathroom Faucet	Non-Potable	11/20/2020	<3.0 ND	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-1823	1039	Bathroom	Bathroom Faucet	Non-Potable	11/20/2020	1.3	Result Below Action Level Continue O&M
MCCSD-1824	1039	Bathroom	Bathroom Faucet	Non-Potable	11/20/2020	OOS	Testing Required Before Return to Service
MCCSD-1825	1039	Bathroom	Bathroom Faucet	Non-Potable	11/20/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1827	1040	Room 131	Classroom Faucet	Non-Potable	11/20/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1828	1040	Room 131	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1829	1041	Room 132	Classroom Faucet	Non-Potable	11/20/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1830	1041	Room 132	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1831	1042	Room 133	Classroom Faucet	Non-Potable	11/20/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1832	1042	Room 133	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1833	1043	Room 134	Classroom Faucet	Non-Potable	11/20/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1834	1043	Room 134	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1835	1044	Room 135	Classroom Faucet	Non-Potable	11/20/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1836	1044	Room 135	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1837	1045	Room 136	Classroom Faucet	Non-Potable	11/20/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1838	1045	Room 136	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-1839	1046	Room 137	Classroom Faucet	Non-Potable	11/20/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1840	1046	Room 137	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1841	1048	Room 139	Classroom Faucet	Non-Potable	11/20/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1842	1048	Room 139	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service

Centereach High School

MCCSD-0816	1000B	Music Vestibule Band Room	Classroom Faucet	Non-Potable	12/5/2020	2.3	Result Below Action Level Continue O&M
MCCSD-0817	1004	Room 133	Home Economics Faucet (Cold)	Potable	12/5/2020	2.5	Result Below Action Level Continue O&M
MCCSD-0818	1004	Room 133	Home Economics Faucet (Cold)	Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0819	1004	Room 133	Home Economics Faucet (Cold)	Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0820	1004	Room 133	Home Economics Faucet (Cold)	Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0821	1004	Room 133	Home Economics Faucet (Cold)	Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0824	1004B	Room 133 Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0825	1005	Room 131	Spray Nozzle	Potable	12/5/2020	1.4	Result Below Action Level Continue O&M
MCCSD-0826	1005	Room 131	Spray Nozzle	Potable	12/5/2020	2.7	Result Below Action Level Continue O&M
MCCSD-0827	1005	Room 131	Spray Nozzle	Potable	12/5/2020	3.7	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0828	1005	Room 131	Spray Nozzle	Potable	12/5/2020	1.7	Result Below Action Level Continue O&M
MCCSD-0829	1005	Room 131	Spray Nozzle	Potable	12/5/2020	1.4	Result Below Action Level Continue O&M
MCCSD-0830	1005	Room 131	Spray Nozzle	Potable	12/5/2020	1.1	Result Below Action Level Continue O&M
MCCSD-0831	1005C	Room 131 Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0833	1008B1	Planetarium Office Exit Vestibule Boys Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	16	Placarded for Non-Drinking Use Until Remediated
MCCSD-0834	1008B2	Planetarium Office Exit Vestibule Girls Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	360 D	Placarded for Non-Drinking Use Until Remediated
MCCSD-0835	1010A	Auditorium Stage	Bathroom Faucet	Non-Potable	12/5/2020	3.2	Result Below Action Level Continue O&M
MCCSD-0837	1012	Girls Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	1.1	Result Below Action Level Continue O&M
MCCSD-0838	1012	Girls Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	7.1	Result Below Action Level Continue O&M
MCCSD-0839	1012	Girls Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	9.2	Result Below Action Level Continue O&M
MCCSD-0840	1012	Girls Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	5.7	Result Below Action Level Continue O&M
MCCSD-0842	1016	Faculty Cafeteria	Classroom Faucet	Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0844	1017A1	Custodial Receiving Room Locker Room Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0846	1019	Kitchen	Hand Wash Only	Non-Potable	12/5/2020	1	Result Below Action Level Continue O&M
MCCSD-0847	1019	Kitchen	Kitchen Faucet (Cold)	Potable	12/5/2020	22	Removed From Service, Pending Remediation

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0848	1019	Kitchen	Kitchen Faucet (Cold)	Potable	12/5/2020	33	Removed From Service, Pending Remediation
MCCSD-0849	1019	Kitchen	Spray Nozzle	Potable	12/5/2020	1.1	Result Below Action Level Continue O&M
MCCSD-0850	1019	Kitchen	Hand Wash Only	Non-Potable	12/5/2020	3.7	Result Below Action Level Continue O&M
MCCSD-0851	1019	Kitchen	Pasta Pot/Steam Kettle	Potable	12/5/2020	3.9	Result Below Action Level Continue O&M
MCCSD-0852	1019	Kitchen	Pasta Pot/Steam Kettle	Potable	12/5/2020	OOS	Testing Required Before Return to Service
MCCSD-0853	1019	Kitchen	Kitchen Faucet (Cold)	Potable	12/5/2020	16	Removed From Service, Pending Remediation
MCCSD-0854	1019	Kitchen	Kitchen Faucet (Cold)	Potable	12/5/2020	2.9	Result Below Action Level Continue O&M
MCCSD-0855	1019	Kitchen	Spray Nozzle	Potable	12/5/2020	1	Result Below Action Level Continue O&M
MCCSD-0856	1019	Kitchen	Kitchen Faucet (Cold)	Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0857	1019	Kitchen	Hand Wash Only	Non-Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0858	1019	Kitchen	Spray Nozzle	Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0861	0004B1	Women's Locker Room Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	50	Placarded for Non-Drinking Use Until Remediated
MCCSD-0862	0004B1	Women's Locker Room Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	9.3	Result Below Action Level Continue O&M
MCCSD-0863	0004B1	Women's Locker Room Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	4.2	Result Below Action Level Continue O&M
MCCSD-0864	0004C	Men's Locker Room	Bathroom Faucet	Non-Potable	12/5/2020	65	Placarded for Non-Drinking Use Until Remediated

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0865	1040	Corridor from PTSA Office to Room 126	Bottled Water Dispenser	Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0866	1040	Corridor from PTSA Office to Room 126	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0868	1029	Boys Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	5.3	Result Below Action Level Continue O&M
MCCSD-0870	1032A	Girls Locker Room Vestibule	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0871	1032A1A	Girls Locker Room Vestibule Office Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	8.1	Result Below Action Level Continue O&M
MCCSD-0872	1032A2	Girls Locker Room	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0873	1032A2A	Girls Locker Room Team Room	Bathroom Faucet	Non-Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0874	1032A2A	Girls Locker Room Team Room	Bathroom Faucet	Non-Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0875	1032A2B	Girls Locker Room Showers	Bathroom Faucet	Non-Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0876	1032A2B	Girls Locker Room Showers	Bathroom Faucet	Non-Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0879	1032D2B	Boys Locker Room Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0880	1032D2B	Boys Locker Room Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	3.2	Result Below Action Level Continue O&M
MCCSD-0881	1032D2A1	Boys Locker Room Showers Storage Room	Bathroom Faucet	Non-Potable	12/5/2020	1.7	Result Below Action Level Continue O&M
MCCSD-0882	1032D2A1	Boys Locker Room Showers Storage Room	Bathroom Faucet	Non-Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0883	1032D	Boys Locker Room Vestibule	Water Fountain-No Chiller	Non-Potable	12/5/2020	OOS	Testing Required Before Return to Service

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0884	1032D1A	Boys Locker Room Vestibule Office Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	3.3	Result Below Action Level Continue O&M
MCCSD-0885	1033A1	Wrestling Room Exit Vestibule Girls Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0886	1033A1	Wrestling Room Exit Vestibule Girls Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0887	1033A1	Wrestling Room Exit Vestibule Girls Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	1.2	Result Below Action Level Continue O&M
MCCSD-0888	1033C1A	Wrestling Room Exit Vestibule 2 Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0889	1033C1A	Wrestling Room Exit Vestibule 2 Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0890	1034A	Fitness Room Storage Room 1	Ice Machine	Potable	12/5/2020	5.1	Result Below Action Level Continue O&M
MCCSD-0892	1047A	Room 95 Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0897	1047	Room 95	Home Economics Faucet (Cold)	Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0898	1047	Room 95	Spray Nozzle	Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0899	1047	Room 95	Home Economics Faucet (Cold)	Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0900	1047	Room 95	Spray Nozzle	Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0901	1047	Room 95	Home Economics Faucet (Cold)	Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0902	1047	Room 95	Spray Nozzle	Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0903	1047	Room 95	Home Economics Faucet (Cold)	Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0904	1047	Room 95	Spray Nozzle	Potable	12/5/2020	2.5	Result Below Action Level Continue O&M
MCCSD-0905	1047	Room 95	Ice Machine	Potable	12/5/2020	OOS	Testing Required Before Return to Service
MCCSD-0906	1050	Room 102	Classroom Faucet	Non-Potable	12/5/2020	OOS	Testing Required Before Return to Service
MCCSD-0907	1051	Room 104	Classroom Faucet	Non-Potable	12/5/2020	22	Placarded for Non-Drinking Use Until Remediated
MCCSD-0909	1063	Corridor from Main Entrance Lobby to Room 102	Bottled Water Dispenser	Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0910	1063	Corridor from Main Entrance Lobby to Room 102	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0912	1068	Room 113	Classroom Faucet	Non-Potable	12/5/2020	2.5	Result Below Action Level Continue O&M
MCCSD-0913	1066A	Main Office Mail Room	Classroom Faucet	Non-Potable	12/5/2020	8.1	Result Below Action Level Continue O&M
MCCSD-0914	1076B	Nurses Office Exam Room	Nurse's Office Sink	Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0915	1076	Nurses Office	Nurse's Office Sink	Potable	12/5/2020	4.1	Result Below Action Level Continue O&M
MCCSD-0916	1076	Nurses Office	Nurse's Office Sink	Potable	12/5/2020	9.9	Result Below Action Level Continue O&M
MCCSD-0917	1076B1	Nurses Office Exam Room Coat Closet	Bathroom Faucet	Non-Potable	12/5/2020	9.4	Result Below Action Level Continue O&M
MCCSD-0918	1076C	Nurses Office Back Exam Room	Bathroom Faucet	Non-Potable	12/5/2020	2.5	Result Below Action Level Continue O&M
MCCSD-0919	1069	Men's Faculty Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0920	1070	Women's Faculty Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	1.2	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0921	1070	Women's Faculty Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	12	Result Below Action Level Continue O&M
MCCSD-0923	1072D	Faculty Center Men's Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	1.1	Result Below Action Level Continue O&M
MCCSD-0924	1072E	Faculty Center "Rest" Room	Kitchen Faucet (Cold)	Potable	12/5/2020	7.3	Result Below Action Level Continue O&M
MCCSD-0925	1072F	Faculty Center Women's Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0926	1077	Corridor from Nurses Office to Main Entrance Lobby	Bottled Water Dispenser	Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0927	1077	Corridor from Nurses Office to Main Entrance Lobby	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0929	1081	Room 118	Tempered Water Outlet	Non-Potable	12/5/2020	6.5	Result Below Action Level Continue O&M
MCCSD-0930	1081	Room 118	Classroom Faucet	Non-Potable	12/5/2020	58	Placarded for Non-Drinking Use Until Remediated
MCCSD-0931	1081	Room 118	Classroom Faucet	Non-Potable	12/5/2020	6.8	Result Below Action Level Continue O&M
MCCSD-0932	1081	Room 118	Tempered Water Outlet	Non-Potable	12/5/2020	14	Result Below Action Level Continue O&M
MCCSD-0937	1083	Room 120	Classroom Faucet	Non-Potable	12/5/2020	5.1	Result Below Action Level Continue O&M
MCCSD-0939	1089	Corridor from A.P. Office to Stairwell	Bottled Water Dispenser	Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0940	1089	Corridor from A.P. Office to Stairwell	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0941	1085	Men's Bathroom	Bathroom Faucet	Non-Potable	2/23/2021	16	Placarded for Non-Drinking Use Until Remediated
MCCSD-0942	1085	Men's Bathroom	Bathroom Faucet	Non-Potable	2/23/2021	OOS	Testing Required Before Return to Service

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0943	1085	Men's Bathroom	Bathroom Faucet	Non-Potable	2/23/2021	840 D	Placarded for Non-Drinking Use Until Remediated
MCCSD-0944	1085	Men's Bathroom	Bathroom Faucet	Non-Potable	2/23/2021	120	Placarded for Non-Drinking Use Until Remediated
MCCSD-0946	1085	Men's Bathroom	Bathroom Faucet	Non-Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0947	1085	Men's Bathroom	Bathroom Faucet	Non-Potable	2/23/2021	84	Placarded for Non-Drinking Use Until Remediated
MCCSD-0948	1085	Men's Bathroom	Bathroom Faucet	Non-Potable	2/23/2021	610 D	Placarded for Non-Drinking Use Until Remediated
MCCSD-0949	1087	Room 122	Classroom Faucet	Non-Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0951	1088E	AP Office Kitchen	Kitchen Faucet (Cold)	Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0952	1088E	AP Office Kitchen	Spray Nozzle	Potable	12/5/2020	1.9	Result Below Action Level Continue O&M
MCCSD-1011	2008E	Faculty Office Cluster Men's Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	1.6	Result Below Action Level Continue O&M
MCCSD-1012	2008F	Faculty Office Cluster Break Room	Kitchen Faucet (Cold)	Potable	12/5/2020	1.9	Result Below Action Level Continue O&M
MCCSD-1013	2008G	Faculty Office Cluster Women's Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1071	2030	Corridor from Storage Closet to Room 200	Bottled Water Dispenser	Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1072	2030	Corridor from Storage Closet to Room 200	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1073	2023	Girls Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	6.0	Result Below Action Level Continue O&M
MCCSD-1074	2023	Girls Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	7.9	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-1075	2023	Girls Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	6.7	Result Below Action Level Continue O&M
MCCSD-1076	2023	Girls Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1077	2023	Girls Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	16	Placarded for Non-Drinking Use Until Remediated
MCCSD-1078	2023	Girls Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	2.6	Result Below Action Level Continue O&M
MCCSD-1079	2023	Girls Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	4.3	Result Below Action Level Continue O&M
MCCSD-1118	2046	Boys Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	29	Placarded for Non-Drinking Use Until Remediated
MCCSD-1119	2046	Boys Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	21	Placarded for Non-Drinking Use Until Remediated
MCCSD-1120	2046	Boys Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	7.9	Result Below Action Level Continue O&M
MCCSD-1121	2046	Boys Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	5.3	Result Below Action Level Continue O&M
MCCSD-1122	2046	Boys Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	7.8	Result Below Action Level Continue O&M
MCCSD-1123	2046	Boys Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	40	Placarded for Non-Drinking Use Until Remediated
MCCSD-1124	2046	Boys Bathroom	Hose Bib	Non-Potable	12/5/2020	26	Placarded for Non-Drinking Use Until Remediated
MCCSD-1126	2046	Boys Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	62	Placarded for Non-Drinking Use Until Remediated
MCCSD-1127	2046	Boys Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	14	Result Below Action Level Continue O&M
MCCSD-1128	2046	Boys Bathroom	Bathroom Faucet	Non-Potable	12/5/2020	93	Placarded for Non-Drinking Use Until Remediated

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-1148	2051	Corridor from Room 225 to Stairwell	Bottled Water Dispenser	Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1149	2051	Corridor from Room 225 to Stairwell	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1190	1093D	New Construction	Bathroom Faucet	Non-Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1191	1093D	New Construction	Bathroom Faucet	Non-Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1192	1093B1	New Construction	Bathroom Faucet	Non-Potable	12/5/2020	1.3	Result Below Action Level Continue O&M
MCCSD-1193	1096	New Construction	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1194	1096	New Construction	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1195	1096	New Construction	Bottled Water Dispenser	Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1196	1096	New Construction	Bottled Water Dispenser	Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1197	1096	New Construction	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1198	1096	New Construction	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1199	1095B1	New Construction	Bathroom Faucet	Non-Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1200	1095D	New Construction	Bathroom Faucet	Non-Potable	12/5/2020	3.2	Result Below Action Level Continue O&M
MCCSD-1201	1095D	New Construction	Bathroom Faucet	Non-Potable	12/5/2020	1.7	Result Below Action Level Continue O&M
MCCSD-1202	1099	New Construction	Bottled Water Dispenser	Potable	12/5/2020	<3.0 ND	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-1203	1099	New Construction	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1204	1099	New Construction	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1206	1098A	New Construction	Classroom Faucet	Non-Potable	12/5/2020	2.3	Result Below Action Level Continue O&M
MCCSD-1217	Exterior	Exterior	Bathroom Faucet	Non-Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1220	Exterior	Exterior	Bathroom Faucet	Non-Potable	2/23/2021	OOS	Testing Required Before Return to Service

Dawnwood Middle School

MCCSD-0612	1028	Corridor from Auditorium to Room 128	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0613	1011	Nurses Office	Nurse's Office Sink	Potable	1/21/2021	2.4	Result Below Action Level Continue O&M
MCCSD-0614	1011A	Nurses Office Bathroom	Bathroom Faucet	Non-Potable	1/21/2021	2.2	Result Below Action Level Continue O&M
MCCSD-0615	1013	Faculty Lounge	Classroom Faucet	Non-Potable	1/21/2021	1.5	Result Below Action Level Continue O&M
MCCSD-0616	1013A	Faculty Lounge Women's Bathroom	Bathroom Faucet	Non-Potable	1/21/2021	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0617	1013B	Faculty Lounge Men's Bathroom	Bathroom Faucet	Non-Potable	1/21/2021	2.2	Result Below Action Level Continue O&M
MCCSD-0618	1014	Girls Bathroom	Bathroom Faucet	Non-Potable	1/21/2021	3.2	Result Below Action Level Continue O&M
MCCSD-0619	1014	Girls Bathroom	Bathroom Faucet	Non-Potable	1/21/2021	1.6	Result Below Action Level Continue O&M
MCCSD-0620	1014	Girls Bathroom	Bathroom Faucet	Non-Potable	1/21/2021	3.1	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0621	1014	Girls Bathroom	Bathroom Faucet	Non-Potable	1/21/2021	3.1	Result Below Action Level Continue O&M
MCCSD-0622	1014	Girls Bathroom	Bathroom Faucet	Non-Potable	1/21/2021	2.3	Result Below Action Level Continue O&M
MCCSD-0623	1036F	Boys Locker Room Showers	Bathroom Faucet	Non-Potable	1/21/2021	14	Result Below Action Level Continue O&M
MCCSD-0624	1036F	Boys Locker Room Showers	Bathroom Faucet	Non-Potable	1/21/2021	2.1	Result Below Action Level Continue O&M
MCCSD-0626	1016	Boys Bathroom	Bathroom Faucet	Non-Potable	1/21/2021	4.1	Result Below Action Level Continue O&M
MCCSD-0627	1016	Boys Bathroom	Bathroom Faucet	Non-Potable	1/21/2021	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0628	1016	Boys Bathroom	Bathroom Faucet	Non-Potable	1/21/2021	3	Result Below Action Level Continue O&M
MCCSD-0629	1016	Boys Bathroom	Bathroom Faucet	Non-Potable	1/21/2021	2.1	Result Below Action Level Continue O&M
MCCSD-0630	1016	Boys Bathroom	Bathroom Faucet	Non-Potable	1/21/2021	1.7	Result Below Action Level Continue O&M
MCCSD-0632	1020	Room 119	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0638	1037	Gym Corridor	Bottled Water Dispenser	Potable	1/21/2021	1.9	Result Below Action Level Continue O&M
MCCSD-0639	1037	Gym Corridor	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0640	1031	Men's Bathroom	Bathroom Faucet	Non-Potable	1/21/2021	1.3	Result Below Action Level Continue O&M
MCCSD-0641	1031	Men's Bathroom	Bathroom Faucet	Non-Potable	1/21/2021	1.4	Result Below Action Level Continue O&M
MCCSD-0642	1032	Women's Bathroom	Bathroom Faucet	Non-Potable	1/21/2021	<3.0 ND	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0643	1033A	Girls Locker Room Bathroom	Bathroom Faucet	Non-Potable	1/21/2021	4.4	Result Below Action Level Continue O&M
MCCSD-0644	1033A	Girls Locker Room Bathroom	Bathroom Faucet	Non-Potable	1/21/2021	2.5	Result Below Action Level Continue O&M
MCCSD-0645	1037	Gym Corridor	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0646	1036E	Locker Room Bathroom 1	Bathroom Faucet	Non-Potable	1/21/2021	3.5	Result Below Action Level Continue O&M
MCCSD-0647	1036E	Locker Room Bathroom 2	Bathroom Faucet	Non-Potable	1/21/2021	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0649	1042	Music Vestibule	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0651	1049	Girls Bathroom	Bathroom Faucet	Non-Potable	12/4/2020	1.7	Result Below Action Level Continue O&M
MCCSD-0652	1049	Girls Bathroom	Bathroom Faucet	Non-Potable	12/4/2020	1.7	Result Below Action Level Continue O&M
MCCSD-0653	1049	Girls Bathroom	Bathroom Faucet	Non-Potable	12/4/2020	3.4	Result Below Action Level Continue O&M
MCCSD-0654	1050A	Room 94 Vestibule 1 Closet	Bathroom Faucet	Non-Potable	1/21/2021	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0655	1051	Room 94	Classroom Faucet	Non-Potable	12/4/2020	1.2	Result Below Action Level Continue O&M
MCCSD-0656	1053A	Room 94 Vestibule 2 Faculty Bathroom	Bathroom Faucet	Non-Potable	12/4/2020	2.6	Result Below Action Level Continue O&M
MCCSD-0657	1052	Boys Bathroom	Bathroom Faucet	Non-Potable	12/4/2020	1.4	Result Below Action Level Continue O&M
MCCSD-0658	1052	Boys Bathroom	Bathroom Faucet	Non-Potable	12/4/2020	1.6	Result Below Action Level Continue O&M
MCCSD-0659	1052	Boys Bathroom	Bathroom Faucet	Non-Potable	12/4/2020	2.4	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0660	1067	Corridor from Orchestra Room to Room 100	Bottled Water Dispenser	Potable	12/4/2020	1.8	Result Below Action Level Continue O&M
MCCSD-0661	1067	Corridor from Orchestra Room to Room 100	Bottled Water Dispenser	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0662	1054A	Room 95	Classroom Faucet	Non-Potable	12/4/2020	2	Result Below Action Level Continue O&M
MCCSD-0664	1057A	Room 97B (Interior Wall Removed)	Bathroom Faucet	Non-Potable	12/4/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0665	1062	Room 100	Classroom Faucet	Non-Potable	12/4/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0666	1069	Room 102	Classroom Faucet	Non-Potable	12/4/2020	1.2	Result Below Action Level Continue O&M
MCCSD-0667	1069	Room 102	Classroom Faucet	Non-Potable	12/4/2020	3	Result Below Action Level Continue O&M
MCCSD-0668	1069	Room 102	Classroom Faucet	Non-Potable	12/4/2020	OOS	Testing Required Before Return to Service
MCCSD-0689	1072	Room 104	Classroom Faucet	Non-Potable	12/4/2020	2.9	Result Below Action Level Continue O&M
MCCSD-0690	1072	Room 104	Classroom Faucet	Non-Potable	12/4/2020	1.4	Result Below Action Level Continue O&M
MCCSD-0701	1075	Room 106	Home Economics Faucet (Cold)	Potable	12/4/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0702	1075	Room 106	Home Economics Faucet (Cold)	Potable	12/4/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0703	1075	Room 106	Home Economics Faucet (Cold)	Potable	12/4/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0704	1075	Room 106	Home Economics Faucet (Cold)	Potable	12/4/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0707	1080	Room 108	Home Economics Faucet (Cold)	Non-Potable	12/4/2020	<3.0 ND	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0708	1080	Room 108	Home Economics Faucet (Cold)	Non-Potable	12/4/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0709	1080	Room 108	Home Economics Faucet (Cold)	Non-Potable	12/4/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0710	1080	Room 108	Home Economics Faucet (Cold)	Non-Potable	12/4/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0713	1101	Main Corridor Cafeteria to Room 102	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0715	1083	Boys Bathroom	Bathroom Faucet	Non-Potable	12/4/2020	2.4	Result Below Action Level Continue O&M
MCCSD-0716	1083	Boys Bathroom	Bathroom Faucet	Non-Potable	12/4/2020	1.4	Result Below Action Level Continue O&M
MCCSD-0717	1083	Boys Bathroom	Bathroom Faucet	Non-Potable	12/4/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0718	1083	Boys Bathroom	Bathroom Faucet	Non-Potable	12/4/2020	1.7	Result Below Action Level Continue O&M
MCCSD-0721	1085	Girls Bathroom	Bathroom Faucet	Non-Potable	12/4/2020	1.7	Result Below Action Level Continue O&M
MCCSD-0722	1085	Girls Bathroom	Bathroom Faucet	Non-Potable	12/4/2020	1.6	Result Below Action Level Continue O&M
MCCSD-0723	1085	Girls Bathroom	Bathroom Faucet	Non-Potable	12/4/2020	2.1	Result Below Action Level Continue O&M
MCCSD-0724	1085	Girls Bathroom	Bathroom Faucet	Non-Potable	12/4/2020	1.4	Result Below Action Level Continue O&M
MCCSD-0725	1086	Technology Room 111	Classroom Faucet	Non-Potable	12/4/2020	2.8	Result Below Action Level Continue O&M
MCCSD-0726	1086	Technology Room 111	Classroom Faucet	Non-Potable	12/4/2020	9.5	Result Below Action Level Continue O&M
MCCSD-0727	1086	Technology Room 111	Classroom Faucet	Non-Potable	12/4/2020	6.0	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0728	1090	Room 113	Classroom Faucet	Non-Potable	12/4/2020	5.4	Result Below Action Level Continue O&M
MCCSD-0729	1090	Room 113	Classroom Faucet	Non-Potable	12/4/2020	8.8	Result Below Action Level Continue O&M
MCCSD-0730	1090	Room 113	Classroom Faucet	Non-Potable	12/4/2020	3.3	Result Below Action Level Continue O&M
MCCSD-0731	1101	Main Corridor Cafeteria to Room 102	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0732	1092	Kitchen	Hand Wash Only	Non-Potable	12/4/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0733	1092	Kitchen	Kitchen Faucet (Cold)	Potable	1/21/2021	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0734	1092	Kitchen	Spray Nozzle	Potable	1/21/2021	1.2	Result Below Action Level Continue O&M
MCCSD-0735	1092	Kitchen	Kitchen Faucet (Cold)	Potable	1/21/2021	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0736	1092E	Kitchen Bathroom	Bathroom Faucet	Non-Potable	12/4/2020	1.8	Result Below Action Level Continue O&M
MCCSD-0737	1092	Kitchen	Hand Wash Only	Non-Potable	1/21/2021	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0738	1092	Kitchen	Kitchen Service Area	Potable	1/21/2021	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0739	1092	Kitchen	Hand Wash Only	Non-Potable	12/4/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0740	1092	Kitchen	Kitchen Faucet (Cold)	Potable	12/4/2020	1.1	Result Below Action Level Continue O&M
MCCSD-0741	1101	Main Corridor Cafeteria to Room 102	Bottled Water Dispenser	Potable	12/4/2020	1.3	Result Below Action Level Continue O&M
MCCSD-0742	1101	Main Corridor Cafeteria to Room 102	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0743	1100	Main Lobby Vestibule	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0744	1096	Women's Faculty Bathroom	Bathroom Faucet	Non-Potable	12/4/2020	1.8	Result Below Action Level Continue O&M
MCCSD-0745	1097	Men's Faculty Bathroom	Bathroom Faucet	Non-Potable	12/4/2020	1.4	Result Below Action Level Continue O&M
MCCSD-0746	1098B	Library Storage Room	Kitchen Faucet (Cold)	Potable	12/4/2020	2.1	Result Below Action Level Continue O&M
MCCSD-0747	2029	Second Floor Main Corridor	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0759	2012	Girls Bathroom	Bathroom Faucet	Non-Potable	1/21/2021	7.2	Result Below Action Level Continue O&M
MCCSD-0760	2012	Girls Bathroom	Bathroom Faucet	Non-Potable	1/21/2021	3.6	Result Below Action Level Continue O&M
MCCSD-0761	2012	Girls Bathroom	Bathroom Faucet	Non-Potable	1/21/2021	9.5	Result Below Action Level Continue O&M
MCCSD-0762	2012	Girls Bathroom	Bathroom Faucet	Non-Potable	1/21/2021	12	Result Below Action Level Continue O&M
MCCSD-0764	2015	Boys Bathroom	Bathroom Faucet	Non-Potable	1/21/2021	4.8	Result Below Action Level Continue O&M
MCCSD-0765	2015	Boys Bathroom	Bathroom Faucet	Non-Potable	1/21/2021	4.7	Result Below Action Level Continue O&M
MCCSD-0766	2015	Boys Bathroom	Bathroom Faucet	Non-Potable	1/21/2021	3.5	Result Below Action Level Continue O&M
MCCSD-0767	2015	Boys Bathroom	Bathroom Faucet	Non-Potable	1/21/2021	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0768	2015	Boys Bathroom	Bathroom Faucet	Non-Potable	1/21/2021	5.4	Result Below Action Level Continue O&M
MCCSD-0770	2029	Second Floor Main Corridor	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0772	2016	Room 209	Classroom Faucet	Non-Potable	1/21/2021	45	Placarded for Non-Drinking Use Until Remediated
MCCSD-0782	2029	Second Floor Main Corridor	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service

Eugene Auer Memorial Elementary School

MCCSD-0506	1005	Nurses Office	Nurse's Office Sink	Potable	12/2/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0507	1005A	Nurses Office Bathroom	Bathroom Faucet	Non-Potable	12/2/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0508	1000A	Main Office Bathroom	Bathroom Faucet	Non-Potable	12/2/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0509	1000B1	Main Office Principals Office Bathroom	Bathroom Faucet	Non-Potable	12/2/2020	5.6	Result Below Action Level Continue O&M
MCCSD-0510	1016	Room 202	Classroom Faucet	Non-Potable	12/2/2020	3.4	Result Below Action Level Continue O&M
MCCSD-0511	1016	Room 202	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0512	1017	Room 203	Tempered Water Outlet	Non-Potable	12/2/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0513	1017	Room 203	Tempered Water Outlet	Non-Potable	12/2/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0514	1018	Girls Bathroom	Bathroom Faucet	Non-Potable	12/2/2020	1.8	Result Below Action Level Continue O&M
MCCSD-0515	1018	Girls Bathroom	Bathroom Faucet	Non-Potable	12/2/2020	OOS	Testing Required Before Return to Service
MCCSD-0516	1018	Girls Bathroom	Bathroom Faucet	Non-Potable	12/2/2020	5.5	Result Below Action Level Continue O&M
MCCSD-0518	1030	Corridor from Room 201 to 211	Bottled Water Dispenser	Potable	12/2/2020	<3.0 ND	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0519	1030	Corridor from Room 201 to 212	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0520	1020	Boys Bathroom	Bathroom Faucet	Non-Potable	12/2/2020	5.9	Result Below Action Level Continue O&M
MCCSD-0521	1020	Boys Bathroom	Bathroom Faucet	Non-Potable	12/2/2020	OOS	Testing Required Before Return to Service
MCCSD-0522	1020	Boys Bathroom	Bathroom Faucet	Non-Potable	12/2/2020	OOS	Testing Required Before Return to Service
MCCSD-0523	1020	Boys Bathroom	Bathroom Faucet	Non-Potable	12/2/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0524	1021	Room 204	Classroom Faucet	Non-Potable	12/2/2020	2.5	Result Below Action Level Continue O&M
MCCSD-0525	1021	Room 204	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0526	1022	Room 206	Classroom Faucet	Non-Potable	12/2/2020	3.2	Result Below Action Level Continue O&M
MCCSD-0527	1022	Room 206	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0528	1023	Room 205	Classroom Faucet	Non-Potable	12/2/2020	2	Result Below Action Level Continue O&M
MCCSD-0529	1023	Room 205	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0530	1024	Room 208	Classroom Faucet	Non-Potable	12/2/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0531	1024	Room 208	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0532	1025	Room 207	Classroom Faucet	Non-Potable	12/2/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0533	1025	Room 207	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0534	1026	Room 210	Classroom Faucet	Non-Potable	12/2/2020	3.1	Result Below Action Level Continue O&M
MCCSD-0535	1026	Room 210	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0536	1027	Room 209	Classroom Faucet	Non-Potable	12/2/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0537	1027	Room 209	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0538	1028	Room 212	Classroom Faucet	Non-Potable	12/2/2020	27	Placarded for Non-Drinking Use Until Remediated
MCCSD-0539	1028	Room 212	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0540	1029	Room 211	Classroom Faucet	Non-Potable	12/2/2020	17	Placarded for Non-Drinking Use Until Remediated
MCCSD-0541	1029	Room 211	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0542	1031	Cafeteria	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0543	1032	Kitchen	Kitchen Faucet (Cold)	Potable	12/2/2020	2.6	Result Below Action Level Continue O&M
MCCSD-0544	1032	Kitchen	Kitchen Faucet (Cold)	Potable	12/2/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0545	1032A	Kitchen Bathroom	Bathroom Faucet	Non-Potable	12/2/2020	1.9	Result Below Action Level Continue O&M
MCCSD-0547	1036	Faculty Room	Classroom Faucet	Non-Potable	12/2/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0548	1040	Corridor from Cafeteria to Art Storage Room	Water Fountain-No Chiller	Non-Potable	12/2/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0549	1039	Women's Bathroom	Bathroom Faucet	Non-Potable	12/2/2020	<3.0 ND	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0550	1038	Men's Bathroom	Bathroom Faucet	Non-Potable	12/2/2020	1.5	Result Below Action Level Continue O&M
MCCSD-0551	1037A2	Gym Physical Therapy Room Bathroom	Bathroom Faucet	Non-Potable	12/2/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0552	1037A1A	Gym Physical Therapy Room Office Bathroom	Bathroom Faucet	Non-Potable	12/2/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0553	1037C1	Gym Boys Locker Room Bathroom	Bathroom Faucet	Non-Potable	12/2/2020	1.2	Result Below Action Level Continue O&M
MCCSD-0554	1037C3	Gym Boys Locker Room Office Bathroom	Bathroom Faucet	Non-Potable	12/2/2020	14	Result Below Action Level Continue O&M
MCCSD-0555	1040	Corridor from Cafeteria to Art Storage Room	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0556	1041	Art Storage Room	Classroom Faucet	Non-Potable	12/2/2020	OOS	Testing Required Before Return to Service
MCCSD-0557	1042	Room 117	Classroom Faucet	Non-Potable	12/2/2020	7.1	Result Below Action Level Continue O&M
MCCSD-0558	1042	Room 117	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0559	1043	Room 114	Classroom Faucet	Non-Potable	12/2/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0560	1043	Room 114	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0561	1044	Room 115	Classroom Faucet	Non-Potable	12/2/2020	3.8	Result Below Action Level Continue O&M
MCCSD-0562	1044	Room 115	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0563	1045	Room 112	Classroom Faucet	Non-Potable	12/2/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0564	1045	Room 112	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0565	1046	Room 113	Classroom Faucet	Non-Potable	12/2/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0566	1046	Room 113	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0567	1047	Room 110	Classroom Faucet	Non-Potable	12/2/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0568	1047	Room 110	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0569	1048	Room 111	Classroom Faucet	Non-Potable	12/2/2020	16	Placarded for Non-Drinking Use Until Remediated
MCCSD-0570	1048	Room 111	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0571	1049	Room 108	Classroom Faucet	Non-Potable	12/2/2020	3.5	Result Below Action Level Continue O&M
MCCSD-0572	1049	Room 108	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0573	1051	Boys Bathroom	Bathroom Faucet	Non-Potable	12/2/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0574	1051	Boys Bathroom	Bathroom Faucet	Non-Potable	12/2/2020	OOS	Testing Required Before Return to Service
MCCSD-0575	1051	Boys Bathroom	Bathroom Faucet	Non-Potable	12/2/2020	OOS	Testing Required Before Return to Service
MCCSD-0576	1051	Boys Bathroom	Bathroom Faucet	Non-Potable	12/2/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0577	1065	Corridor from Room 104 to 117	Bottled Water Dispenser	Potable	12/2/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0578	1065	Corridor from Room 104 to 117	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0580	1053	Girls Bathroom	Bathroom Faucet	Non-Potable	12/2/2020	<3.0 ND	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0581	1053	Girls Bathroom	Bathroom Faucet	Non-Potable	12/2/2020	OOS	Testing Required Before Return to Service
MCCSD-0582	1053	Girls Bathroom	Bathroom Faucet	Non-Potable	12/2/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0583	1050	Room 109	Classroom Faucet	Non-Potable	12/2/2020	1.3	Result Below Action Level Continue O&M
MCCSD-0584	1050	Room 109	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0585	1054	Room 107	Classroom Faucet	Non-Potable	12/2/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0586	1054	Room 107	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0587	1055	Room 106	Classroom Faucet	Non-Potable	12/2/2020	4.4	Result Below Action Level Continue O&M
MCCSD-0588	1055	Room 106	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0589	1058	Room 104	Classroom Faucet	Non-Potable	12/2/2020	1.1	Result Below Action Level Continue O&M
MCCSD-0590	1058	Room 104	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0592	1059	Room 105	Classroom Faucet	Non-Potable	12/2/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0593	1059	Room 105	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0594	1060	Room 103	Classroom Faucet	Non-Potable	12/2/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0595	1060	Room 103	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0596	1061	Room 102	Kitchen Faucet (Cold)	Potable	12/2/2020	<3.0 ND	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0597	1061	Room 102	Spray Nozzle	Potable	12/2/2020	11	Result Below Action Level Continue O&M
MCCSD-0600	1062	Room 101	Classroom Faucet	Non-Potable	12/2/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0601	1062	Room 101	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0602	1010	Front Lobby/Corridor	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service

Hawkins Path Elementary School

MCCSD-0001	1003A	Room 115 Server Room	Bathroom Faucet	Non-Potable	11/18/2020	OOS	Testing Required Before Return to Service
MCCSD-0002	1005	Nurses Office	Nurse's Office Sink	Potable	11/18/2020	5.0	Result Below Action Level Continue O&M
MCCSD-0003	1005A	Nurses Office Bathroom	Bathroom Faucet	Non-Potable	11/18/2020	1.3	Result Below Action Level Continue O&M
MCCSD-0004	1021	Corridor from Resource Room to Cafeteria	Bottled Water Dispenser	Potable	11/18/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0005	1021	Corridor from Resource Room to Cafeteria	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0006	1007	Girls Bathroom	Bathroom Faucet	Non-Potable	11/18/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0007	1007	Girls Bathroom	Bathroom Faucet	Non-Potable	11/18/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0008	1007	Girls Bathroom	Bathroom Faucet	Non-Potable	11/18/2020	3.7	Result Below Action Level Continue O&M
MCCSD-0010	1009	Boys Bathroom	Bathroom Faucet	Non-Potable	11/18/2020	2.6	Result Below Action Level Continue O&M
MCCSD-0011	1009	Boys Bathroom	Bathroom Faucet	Non-Potable	11/18/2020	1.6	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0012	1009	Boys Bathroom	Bathroom Faucet	Non-Potable	11/18/2020	3.1	Result Below Action Level Continue O&M
MCCSD-0013	1010	Room 108	Classroom Faucet	Non-Potable	11/18/2020	3.0	Result Below Action Level Continue O&M
MCCSD-0014	1010	Room 108	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0015	1021	Corridor from Resource Room to Cafeteria	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0016	1012	Room 106	Classroom Faucet	Non-Potable	11/18/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0017	1012	Room 106	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0018	1014	Room 104	Classroom Faucet	Non-Potable	11/18/2020	1.7	Result Below Action Level Continue O&M
MCCSD-0019	1014	Room 104	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0020	1021	Corridor from Resource Room to Cafeteria	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0021	1017	Room 101	Classroom Faucet	Non-Potable	11/18/2020	4.1	Result Below Action Level Continue O&M
MCCSD-0022	1017	Room 101	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0023	1018	Room 102	Classroom Faucet	Non-Potable	11/18/2020	2.4	Result Below Action Level Continue O&M
MCCSD-0024	1018	Room 102	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0025	1019	Room 103	Classroom Faucet	Non-Potable	11/18/2020	6.1	Result Below Action Level Continue O&M
MCCSD-0026	1024	Womens Bathroom	Bathroom Faucet	Non-Potable	11/18/2020	<3.0 ND	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0027	1021	Corridor from Resource Room to Cafeteria	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0028	1025	Women's Bathroom	Bathroom Faucet	Non-Potable	11/18/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0029	1025	Women's Bathroom	Bathroom Faucet	Non-Potable	11/18/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0030	1029C	Room 118 Bathroom	Bathroom Faucet	Non-Potable	11/18/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0031	1034	Corridor from Boys Locker Room to Room 118	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0032	1033	Orchestra Room	Classroom Faucet	Non-Potable	11/18/2020	8.9	Result Below Action Level Continue O&M
MCCSD-0034	1031	Storage Room/Office	Bottled Water Dispenser	Potable	11/18/2020	OOS	Testing Required Before Return to Service
MCCSD-0038	1037	Kitchen	Kitchen Faucet (Cold)	Potable	11/18/2020	15	Result Below Action Level Continue O&M
MCCSD-0039	1037	Kitchen	Kitchen Faucet (Cold)	Potable	11/18/2020	3.2	Result Below Action Level Continue O&M
MCCSD-0040	1037	Kitchen	Kitchen Faucet (Cold)	Potable	11/18/2020	7.8	Result Below Action Level Continue O&M
MCCSD-0041	1037	Kitchen	Kitchen Faucet (Cold)	Potable	11/18/2020	24	Removed From Service, Pending Remediation
MCCSD-0042	1037	Kitchen	Ice Machine	Potable	11/18/2020	OOS	Testing Required Before Return to Service
MCCSD-0043	1037A	Kitchen Bathroom	Bathroom Faucet	Non-Potable	11/18/2020	22	Placarded for Non-Drinking Use Until Remediated
MCCSD-0044	2017	2nd Floor Corridor	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0045	2017	2nd Floor Corridor	Bottled Water Dispenser	Potable	11/18/2020	<3.0 ND	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0046	2017	2nd Floor Corridor	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0047	2006	Girls Bathroom	Bathroom Faucet	Non-Potable	11/18/2020	2.8	Result Below Action Level Continue O&M
MCCSD-0048	2006	Girls Bathroom	Bathroom Faucet	Non-Potable	11/18/2020	3.2	Result Below Action Level Continue O&M
MCCSD-0049	2006	Girls Bathroom	Bathroom Faucet	Non-Potable	11/18/2020	3	Result Below Action Level Continue O&M
MCCSD-0051	2008	Boys Bathroom	Bathroom Faucet	Non-Potable	11/18/2020	3.5	Result Below Action Level Continue O&M
MCCSD-0052	2008	Boys Bathroom	Bathroom Faucet	Non-Potable	11/18/2020	5.3	Result Below Action Level Continue O&M
MCCSD-0053	2008	Boys Bathroom	Bathroom Faucet	Non-Potable	11/18/2020	6.2	Result Below Action Level Continue O&M
MCCSD-0054	2017	2nd Floor Corridor	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0055	2017	2nd Floor Corridor	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service

Holbrook Road Elementary School

MCCSD-0355	1010	Gym Corridor	Bottled Water Dispenser	Potable	11/25/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0356	1010	Gym Corridor	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0357	1009B	Music Band Room Bathroom	Bathroom Faucet	Non-Potable	11/25/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0358	1006	Kitchen/Serving Area	Kitchen Faucet (Cold)	Potable	11/25/2020	2.1	Result Below Action Level Continue O&M
MCCSD-0359	1006	Kitchen/Serving Area	Spray Nozzle	Potable	11/25/2020	<3.0 ND	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0361	1006A	Kitchen Bathroom	Bathroom Faucet	Non-Potable	11/25/2020	18	Placarded for Non-Drinking Use Until Remediated
MCCSD-0363	1013	Women's Bathroom Outside Cafeteria	Bathroom Faucet	Non-Potable	11/25/2020	1.6	Result Below Action Level Continue O&M
MCCSD-0364	1038	First Floor Main Corridor	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0365	1014	Men's Bathroom Outside Cafeteria	Bathroom Faucet	Non-Potable	11/25/2020	5.2	Result Below Action Level Continue O&M
MCCSD-0366	1015	Faculty Lounge	Classroom Faucet	Non-Potable	11/25/2020	2.1	Result Below Action Level Continue O&M
MCCSD-0367	1021A	Copy Room Stamp Room	Classroom Faucet	Non-Potable	11/25/2020	190	Placarded for Non-Drinking Use Until Remediated
MCCSD-0368	1038	First Floor Main Corridor	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0369	1023	Room 111 Nurses Office	Nurse's Office Sink	Potable	11/25/2020	3.8	Result Below Action Level Continue O&M
MCCSD-0370	1023A	Room 111 Nurses Office Bathroom	Bathroom Faucet	Non-Potable	11/25/2020	65	Placarded for Non-Drinking Use Until Remediated
MCCSD-0371	1038	First Floor Main Corridor	Bottled Water Dispenser	Potable	11/25/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0372	1038	First Floor Main Corridor	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0373	1025	Girls Bathroom	Bathroom Faucet	Non-Potable	11/25/2020	2.2	Result Below Action Level Continue O&M
MCCSD-0374	1025	Girls Bathroom	Bathroom Faucet	Non-Potable	11/25/2020	1.6	Result Below Action Level Continue O&M
MCCSD-0375	1025	Girls Bathroom	Bathroom Faucet	Non-Potable	11/25/2020	5.6	Result Below Action Level Continue O&M
MCCSD-0377	1027	Boys Bathroom	Bathroom Faucet	Non-Potable	11/25/2020	1.5	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0378	1027	Boys Bathroom	Bathroom Faucet	Non-Potable	11/25/2020	3.2	Result Below Action Level Continue O&M
MCCSD-0379	1027	Boys Bathroom	Bathroom Faucet	Non-Potable	11/25/2020	2	Result Below Action Level Continue O&M
MCCSD-0380	1038	First Floor Main Corridor	Bottled Water Dispenser	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0381	1038	First Floor Main Corridor	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0382	1035	Kindergarten Room 101	Classroom Faucet	Non-Potable	11/25/2020	7.5	Result Below Action Level Continue O&M
MCCSD-0383	1035	Kindergarten Room 101	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0384	1036	Kindergarten Room 102	Classroom Faucet	Non-Potable	11/25/2020	4.5	Result Below Action Level Continue O&M
MCCSD-0385	2017	Second Floor Main Corridor	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0386	2017	Second Floor Main Corridor	Bottled Water Dispenser	Potable	11/25/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0387	2017	Second Floor Main Corridor	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0388	2007	Girls Bathroom	Bathroom Faucet	Non-Potable	11/25/2020	2.5	Result Below Action Level Continue O&M
MCCSD-0389	2007	Girls Bathroom	Bathroom Faucet	Non-Potable	11/25/2020	5.3	Result Below Action Level Continue O&M
MCCSD-0390	2007	Girls Bathroom	Bathroom Faucet	Non-Potable	11/25/2020	9.8	Result Below Action Level Continue O&M
MCCSD-0393	2009	Boys Bathroom	Bathroom Faucet	Non-Potable	11/25/2020	1.8	Result Below Action Level Continue O&M
MCCSD-0394	2009	Boys Bathroom	Bathroom Faucet	Non-Potable	11/25/2020	1.5	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0396	2017	Second Floor Main Corridor	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0397	2017	Second Floor Main Corridor	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service

Jericho Elementary School

MCCSD-0167	1001	Girls Bathroom	Bathroom Faucet	Non-Potable	11/19/2020	9.7	Result Below Action Level Continue O&M
MCCSD-0168	1011	Art Gallery/Resource Room Hallway	Classroom Faucet	Non-Potable	11/19/2020	2.8	Result Below Action Level Continue O&M
MCCSD-0169	1011	Art Gallery/Resource Room Hallway	Classroom Faucet	Non-Potable	11/19/2020	2.5	Result Below Action Level Continue O&M
MCCSD-0170	1005	Room D6	Bathroom Faucet	Non-Potable	11/19/2020	6.1	Result Below Action Level Continue O&M
MCCSD-0171	1011	Art Gallery/Resource Room Hallway	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0172	1011	Art Gallery/Resource Room Hallway	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0173	1082C	Main Office Principal Office	Bathroom Faucet	Non-Potable	11/19/2020	2.6	Result Below Action Level Continue O&M
MCCSD-0175	1014A	Receiving Room Bathroom 1	Bathroom Faucet	Non-Potable	11/19/2020	3.2	Result Below Action Level Continue O&M
MCCSD-0176	1014B	Receiving Room Bathroom 2	Bathroom Faucet	Non-Potable	11/19/2020	8.8	Result Below Action Level Continue O&M
MCCSD-0178	1022B	Kitchen	Kitchen Faucet (Cold)	Potable	11/19/2020	11	Result Below Action Level Continue O&M
MCCSD-0179	1022B	Kitchen	Kitchen Faucet (Cold)	Potable	11/19/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0180	1022	Cafeteria	Bottled Water Dispenser	Potable	11/19/2020	<3.0 ND	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0181	1022	Cafeteria	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0182	1018	Faculty Lounge	Bottled Water Dispenser	Potable	11/19/2020	OOS	Testing Required Before Return to Service
MCCSD-0183	1018	Faculty Lounge	Classroom Faucet	Non-Potable	11/19/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0184	1024	Corridor From Faculty Room to Art Room	Classroom Faucet	Non-Potable	11/19/2020	1.3	Result Below Action Level Continue O&M
MCCSD-0185	1024	Corridor From Faculty Room to Art Room	Classroom Faucet	Non-Potable	11/19/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0186	1019A	Women's Bathroom	Bathroom Faucet	Non-Potable	11/19/2020	5.6	Result Below Action Level Continue O&M
MCCSD-0187	1020	Men's Bathroom	Bathroom Faucet	Non-Potable	11/19/2020	2.9	Result Below Action Level Continue O&M
MCCSD-0188	1025	Boys Bathroom	Bathroom Faucet	Non-Potable	11/19/2020	OOS	Testing Required Before Return to Service
MCCSD-0189	1025	Boys Bathroom	Bathroom Faucet	Non-Potable	11/19/2020	OOS	Testing Required Before Return to Service
MCCSD-0190	1032	Corridor Outside Resource Room	Classroom Faucet	Non-Potable	11/19/2020	1	Result Below Action Level Continue O&M
MCCSD-0191	1026	Girls Bathroom	Bathroom Faucet	Non-Potable	11/19/2020	1.5	Result Below Action Level Continue O&M
MCCSD-0193	1032	Corridor Outside Resource Room	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0194	1032	Corridor Outside Resource Room	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0195	1023	Art Room	Classroom Faucet	Non-Potable	11/19/2020	7.1	Result Below Action Level Continue O&M
MCCSD-0196	1023	Art Room	Classroom Faucet	Non-Potable	11/19/2020	1.7	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0197	1041	Girls Locker Room	Bathroom Faucet	Non-Potable	11/19/2020	8.8	Result Below Action Level Continue O&M
MCCSD-0198	1041	Girls Locker Room	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0199	1041B1	Girls Locker Room Coach Office Bathroom	Bathroom Faucet	Non-Potable	11/19/2020	1.7	Result Below Action Level Continue O&M
MCCSD-0200	1039B2	Boys Locker Room Coaches Office Bathroom	Bathroom Faucet	Non-Potable	11/19/2020	OOS	Testing Required Before Return to Service
MCCSD-0201	1039	Old Boys Locker Room (Mass Storage)	Bathroom Faucet	Non-Potable	11/19/2020	OOS	Testing Required Before Return to Service
MCCSD-0202	1057	Corridor from OT Room to Girls Bathroom	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0203	1057	Corridor from OT Room to Girls Bathroom	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0204	1055	Boys Bathroom	Bathroom Faucet	Non-Potable	11/19/2020	7.0	Result Below Action Level Continue O&M
MCCSD-0205	1055	Boys Bathroom	Bathroom Faucet	Non-Potable	11/19/2020	35	Placarded for Non-Drinking Use Until Remediated
MCCSD-0206	1057	Corridor from OT Room to Girls Bathroom	Classroom Faucet	Non-Potable	11/19/2020	3.2	Result Below Action Level Continue O&M
MCCSD-0207	1057	Corridor from OT Room to Girls Bathroom	Classroom Faucet	Non-Potable	11/19/2020	2.3	Result Below Action Level Continue O&M
MCCSD-0208	1056	Girls Bathroom	Bathroom Faucet	Non-Potable	11/19/2020	4.9	Result Below Action Level Continue O&M
MCCSD-0209	1056	Girls Bathroom	Bathroom Faucet	Non-Potable	11/19/2020	6.2	Result Below Action Level Continue O&M
MCCSD-0210	1058	Room K4	Classroom Faucet	Non-Potable	11/19/2020	12	Result Below Action Level Continue O&M
MCCSD-0212	1060	Room K3	Classroom Faucet	Non-Potable	11/19/2020	1.4	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0213	1060	Room K3	Classroom Faucet	Non-Potable	11/19/2020	1.3	Result Below Action Level Continue O&M
MCCSD-0214	1062	Room K2	Classroom Faucet	Non-Potable	11/19/2020	7.3	Result Below Action Level Continue O&M
MCCSD-0216	1064	Room K1	Classroom Faucet	Non-Potable	11/19/2020	3.6	Result Below Action Level Continue O&M
MCCSD-0217	1072	Corridor from Room A6 to Elevator	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0218	1072	Corridor from Room A6 to Elevator	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0219	1069	Boys Bathroom	Bathroom Faucet	Non-Potable	11/19/2020	2.8	Result Below Action Level Continue O&M
MCCSD-0220	1072	Corridor from Room A6 to Elevator	Classroom Faucet	Non-Potable	11/19/2020	1.3	Result Below Action Level Continue O&M
MCCSD-0221	1072	Corridor from Room A6 to Elevator	Classroom Faucet	Non-Potable	11/19/2020	1.2	Result Below Action Level Continue O&M
MCCSD-0223	1070	Girls Bathroom	Bathroom Faucet	Non-Potable	11/19/2020	6.6	Result Below Action Level Continue O&M
MCCSD-0224	1083	Main Corridor	Bottled Water Dispenser	Potable	11/19/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0225	1083	Main Corridor	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0226	1080	Nurses Office	Nurse's Office Sink	Potable	11/19/2020	6.9	Result Below Action Level Continue O&M
MCCSD-0227	1080A	Nurses Office Bathroom	Bathroom Faucet	Non-Potable	11/19/2020	9.3	Result Below Action Level Continue O&M
MCCSD-0229	2000B	Library Bathroom	Bathroom Faucet	Non-Potable	11/19/2020	3.4	Result Below Action Level Continue O&M
MCCSD-0230	2001	Computer Room	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0231	2001C	Computer Room Girls Bathroom	Bathroom Faucet	Non-Potable	11/19/2020	8.1	Result Below Action Level Continue O&M
MCCSD-0232	2001C	Computer Room Girls Bathroom	Bathroom Faucet	Non-Potable	11/19/2020	11	Result Below Action Level Continue O&M

New Lane Memorial Elementary School

MCCSD-1850	1000A	Yellow Gym Entrance Vestibule	Bottled Water Dispenser	Potable	12/8/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1851	1000A	Yellow Gym Entrance Vestibule	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1852	1004A	Blue Gym Office Bathroom	Bathroom Faucet	Non-Potable	12/8/2020	31	Placarded for Non-Drinking Use Until Remediated
MCCSD-1853	1002A	Yellow Gym Office Bathroom	Bathroom Faucet	Non-Potable	12/8/2020	22	Placarded for Non-Drinking Use Until Remediated
MCCSD-1855	1006	Girls Bathroom Adjacent Yellow Gym	Bathroom Faucet	Non-Potable	12/8/2020	10	Result Below Action Level Continue O&M
MCCSD-1856	1006	Girls Bathroom Adjacent Yellow Gym	Bathroom Faucet	Non-Potable	12/8/2020	14	Result Below Action Level Continue O&M
MCCSD-1857	1007	Boys Bathroom Adjacent Blue Gym	Bathroom Faucet	Non-Potable	12/8/2020	120	Placarded for Non-Drinking Use Until Remediated
MCCSD-1858	1007	Boys Bathroom Adjacent Blue Gym	Bathroom Faucet	Non-Potable	12/8/2020	450	Placarded for Non-Drinking Use Until Remediated
MCCSD-1859	1007	Boys Bathroom Adjacent Blue Gym	Bathroom Faucet	Non-Potable	12/8/2020	19	Placarded for Non-Drinking Use Until Remediated
MCCSD-1862	1011A	Blue Gym Entrance Vestibule	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1863	2007	Room 500	Classroom Faucet	Non-Potable	12/8/2020	18	Placarded for Non-Drinking Use Until Remediated
MCCSD-1864	2006	Boys Bathroom Right Adjacent 500 Cluster	Bathroom Faucet	Non-Potable	12/8/2020	14	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-1865	2001A	Right Entrance Vestibule to 500 Cluster	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1866	2005	Girls Bathroom Right Adjacent 500 Cluster	Bathroom Faucet	Non-Potable	12/8/2020	1.2	Result Below Action Level Continue O&M
MCCSD-1867	2001	500 Cluster	Classroom Faucet	Non-Potable	12/8/2020	8.2	Result Below Action Level Continue O&M
MCCSD-1868	2001	500 Cluster	Classroom Faucet	Non-Potable	12/8/2020	3.7	Result Below Action Level Continue O&M
MCCSD-1869	2001	500 Cluster	Classroom Faucet	Non-Potable	12/8/2020	4.0	Result Below Action Level Continue O&M
MCCSD-1870	2004	Room 509	Classroom Faucet	Non-Potable	12/8/2020	13	Result Below Action Level Continue O&M
MCCSD-1872	2003	Boys Bathroom Left Adjacent 500 Cluster	Bathroom Faucet	Non-Potable	12/8/2020	15	Result Below Action Level Continue O&M
MCCSD-1873	2001B	Left Entrance Vestibule to 500 Cluster	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1874	2002	Girls Bathroom Left Adjacent 500 Cluster	Bathroom Faucet	Non-Potable	12/8/2020	9.2	Result Below Action Level Continue O&M
MCCSD-1875	2002	Girls Bathroom Left Adjacent 500 Cluster	Bathroom Faucet	Non-Potable	12/8/2020	13	Result Below Action Level Continue O&M
MCCSD-1877	2001	500 Cluster	Classroom Faucet	Non-Potable	12/8/2020	27	Placarded for Non-Drinking Use Until Remediated
MCCSD-1878	2001	500 Cluster	Classroom Faucet	Non-Potable	12/8/2020	8.0	Result Below Action Level Continue O&M
MCCSD-1879	2001	500 Cluster	Classroom Faucet	Non-Potable	12/8/2020	18	Placarded for Non-Drinking Use Until Remediated
MCCSD-1880	2009	Copy Room	Classroom Faucet	Non-Potable	12/8/2020	23	Placarded for Non-Drinking Use Until Remediated
MCCSD-1881	2010	Cafeteria	Bottled Water Dispenser	Potable	12/8/2020	<3.0 ND	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-1882	2010	Cafeteria	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1883	2010	Cafeteria	Hand Wash Only	Non-Potable	12/8/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1885	2010	Cafeteria	Kitchen Faucet (Cold)	Potable	12/8/2020	2	Result Below Action Level Continue O&M
MCCSD-1886	2010	Cafeteria	Kitchen Faucet (Cold)	Potable	12/8/2020	3.8	Result Below Action Level Continue O&M
MCCSD-1887	2010	Cafeteria	Hand Wash Only	Non-Potable	12/8/2020	1	Result Below Action Level Continue O&M
MCCSD-1888	2013	Nurses Office Sick Room	Nurse's Office Sink	Potable	12/8/2020	1	Result Below Action Level Continue O&M
MCCSD-1889	2012A1	Nurses Office Bathroom	Bathroom Faucet	Non-Potable	12/8/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1890	2012A	Nurses Office	Nurse's Office Sink	Potable	12/8/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1892	2014	Boys Bathroom Adjacent Library	Bathroom Faucet	Non-Potable	12/8/2020	1.2	Result Below Action Level Continue O&M
MCCSD-1893	2014	Boys Bathroom Adjacent Library	Bathroom Faucet	Non-Potable	12/8/2020	1.3	Result Below Action Level Continue O&M
MCCSD-1895	2015	Girls Bathroom Adjacent Library	Bathroom Faucet	Non-Potable	12/8/2020	3.1	Result Below Action Level Continue O&M
MCCSD-1896	2015	Girls Bathroom Adjacent Library	Bathroom Faucet	Non-Potable	12/8/2020	2.8	Result Below Action Level Continue O&M
MCCSD-1897	2028	Corridor Adjacent Library	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1898	2017	Library	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1900	4029	Third Floor Corridor	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-1901	4029	Third Floor Corridor	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1902	4024	Third Floor Girls Bathroom	Bathroom Faucet	Non-Potable	12/8/2020	2.1	Result Below Action Level Continue O&M
MCCSD-1903	4024	Third Floor Girls Bathroom	Bathroom Faucet	Non-Potable	12/8/2020	1.2	Result Below Action Level Continue O&M
MCCSD-1904	4024	Third Floor Girls Bathroom	Bathroom Faucet	Non-Potable	12/8/2020	1.6	Result Below Action Level Continue O&M
MCCSD-1905	4021	Third Floor Boys Bathroom	Bathroom Faucet	Non-Potable	12/8/2020	1.3	Result Below Action Level Continue O&M
MCCSD-1906	4021	Third Floor Boys Bathroom	Bathroom Faucet	Non-Potable	12/8/2020	1.9	Result Below Action Level Continue O&M
MCCSD-1907	4021	Third Floor Boys Bathroom	Bathroom Faucet	Non-Potable	12/8/2020	3.7	Result Below Action Level Continue O&M
MCCSD-1909	4014	Room 713A/B Faculty Room	Kitchen Faucet (Cold)	Potable	12/8/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1910	4014	Room 713A/B Faculty Room	Spray Nozzle	Potable	12/8/2020	2.8	Result Below Action Level Continue O&M
MCCSD-1912	4007	Third Floor Womens Bathroom	Bathroom Faucet	Non-Potable	12/8/2020	2.8	Result Below Action Level Continue O&M
MCCSD-1913	4007	Third Floor Womens Bathroom	Bathroom Faucet	Non-Potable	12/8/2020	3.5	Result Below Action Level Continue O&M
MCCSD-1914	4007	Third Floor Womens Bathroom	Bathroom Faucet	Non-Potable	12/8/2020	8.5	Result Below Action Level Continue O&M
MCCSD-1915	4004	Third Floor Mens Bathroom	Bathroom Faucet	Non-Potable	12/8/2020	2	Result Below Action Level Continue O&M
MCCSD-1916	4004	Third Floor Mens Bathroom	Bathroom Faucet	Non-Potable	12/8/2020	1.3	Result Below Action Level Continue O&M
MCCSD-1917	4004	Third Floor Mens Bathroom	Bathroom Faucet	Non-Potable	12/8/2020	4.5	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-1918	4029	Third Floor Corridor	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1919	4000	Room 722	Art Faucet	Non-Potable	12/8/2020	3.7	Result Below Action Level Continue O&M
MCCSD-1920	4000	Room 722	Art Faucet	Non-Potable	12/8/2020	2.1	Result Below Action Level Continue O&M
MCCSD-1921	3002	Boys Bathroom Adjacent 100 Cluster	Bathroom Faucet	Non-Potable	12/8/2020	23	Placarded for Non-Drinking Use Until Remediated
MCCSD-1922	3002	Boys Bathroom Adjacent 100 Cluster	Bathroom Faucet	Non-Potable	12/8/2020	55	Placarded for Non-Drinking Use Until Remediated
MCCSD-1923	3002	Boys Bathroom Adjacent 100 Cluster	Bathroom Faucet	Non-Potable	12/8/2020	18	Placarded for Non-Drinking Use Until Remediated
MCCSD-1925	3011	Corridor from 100 Cluster to 200 Cluster	Classroom Faucet	Non-Potable	12/8/2020	5.5	Result Below Action Level Continue O&M
MCCSD-1926	3011	Corridor from 100 Cluster to 200 Cluster	Classroom Faucet	Non-Potable	12/8/2020	9.4	Result Below Action Level Continue O&M
MCCSD-1927	3011	Corridor from 100 Cluster to 200 Cluster	Classroom Faucet	Non-Potable	12/8/2020	6.9	Result Below Action Level Continue O&M
MCCSD-1928	3011	Corridor from 100 Cluster to 200 Cluster	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1930	3003	Girls Bathroom Adjacent 100 Cluster	Bathroom Faucet	Non-Potable	12/8/2020	17	Placarded for Non-Drinking Use Until Remediated
MCCSD-1931	3003	Girls Bathroom Adjacent 100 Cluster	Bathroom Faucet	Non-Potable	12/8/2020	9.5	Result Below Action Level Continue O&M
MCCSD-1932	3003	Girls Bathroom Adjacent 100 Cluster	Bathroom Faucet	Non-Potable	12/8/2020	9.5	Result Below Action Level Continue O&M
MCCSD-1933	3005	Womens Bathroom Left Adjacent 100 Cluster	Bathroom Faucet	Non-Potable	12/8/2020	3.1	Result Below Action Level Continue O&M
MCCSD-1934	3011	Corridor from 100 Cluster to 200 Cluster	Classroom Faucet	Non-Potable	12/8/2020	6.2	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-1935	3011	Corridor from 100 Cluster to 200 Cluster	Classroom Faucet	Non-Potable	12/8/2020	3.8	Result Below Action Level Continue O&M
MCCSD-1936	3011	Corridor from 100 Cluster to 200 Cluster	Classroom Faucet	Non-Potable	12/8/2020	3.9	Result Below Action Level Continue O&M
MCCSD-1937	3006	Womens Bathroom Right Adjacent 100 Cluster	Bathroom Faucet	Non-Potable	12/8/2020	3.4	Result Below Action Level Continue O&M
MCCSD-1938	3006	Womens Bathroom Right Adjacent 100 Cluster	Bathroom Faucet	Non-Potable	12/8/2020	2.9	Result Below Action Level Continue O&M
MCCSD-1940	3011	Corridor from 100 Cluster to 200 Cluster	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1942	3008	Third Grade Boys Bathroom	Bathroom Faucet	Non-Potable	12/8/2020	2.6	Result Below Action Level Continue O&M
MCCSD-1943	3008	Third Grade Boys Bathroom	Bathroom Faucet	Non-Potable	12/8/2020	8.5	Result Below Action Level Continue O&M
MCCSD-1944	3008	Third Grade Boys Bathroom	Bathroom Faucet	Non-Potable	12/8/2020	8.8	Result Below Action Level Continue O&M
MCCSD-1945	3011	Corridor from 100 Cluster to 200 Cluster	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1946	3009	Third Grade Girls Bathroom	Bathroom Faucet	Non-Potable	12/8/2020	4.4	Result Below Action Level Continue O&M
MCCSD-1947	3099	Third Grade Girls Bathroom	Bathroom Faucet	Non-Potable	12/8/2020	6.7	Result Below Action Level Continue O&M
MCCSD-1948	3009	Third Grade Girls Bathroom	Bathroom Faucet	Non-Potable	12/8/2020	7.8	Result Below Action Level Continue O&M
MCCSD-1950	3011	Corridor from 100 Cluster to 200 Cluster	Classroom Faucet	Non-Potable	12/8/2020	3.5	Result Below Action Level Continue O&M
MCCSD-1951	3011	Corridor from 100 Cluster to 200 Cluster	Classroom Faucet	Non-Potable	12/8/2020	1.8	Result Below Action Level Continue O&M
MCCSD-1952	3011	Corridor from 100 Cluster to 200 Cluster	Classroom Faucet	Non-Potable	12/8/2020	6.2	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-1953	3013A1	Main Office Principals Bathroom	Bathroom Faucet	Non-Potable	12/8/2020	20	Placarded for Non-Drinking Use Until Remediated
MCCSD-1954	3026	Corridor from 300 Cluster to 400 Cluster	Classroom Faucet	Non-Potable	12/8/2020	1.5	Result Below Action Level Continue O&M
MCCSD-1955	3026	Corridor from 300 Cluster to 400 Cluster	Classroom Faucet	Non-Potable	12/8/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1956	3026	Corridor from 300 Cluster to 400 Cluster	Classroom Faucet	Non-Potable	12/8/2020	1.5	Result Below Action Level Continue O&M
MCCSD-1958	3017	Fourth Grade Girls Bathroom	Bathroom Faucet	Non-Potable	12/8/2020	2	Result Below Action Level Continue O&M
MCCSD-1959	3017	Fourth Grade Girls Bathroom	Bathroom Faucet	Non-Potable	12/8/2020	2.3	Result Below Action Level Continue O&M
MCCSD-1960	3017	Fourth Grade Girls Bathroom	Bathroom Faucet	Non-Potable	12/8/2020	8.5	Result Below Action Level Continue O&M
MCCSD-1961	3026	Corridor from 300 Cluster to 400 Cluster	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1962	3018	Fourth Grade Boys Bathroom	Bathroom Faucet	Non-Potable	12/8/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1963	3018	Fourth Grade Boys Bathroom	Bathroom Faucet	Non-Potable	12/8/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1964	3018	Fourth Grade Boys Bathroom	Bathroom Faucet	Non-Potable	12/8/2020	1.8	Result Below Action Level Continue O&M
MCCSD-1967	3026	Corridor from 300 Cluster to 400 Cluster	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1969	3020	Womens Bathroom Adjacent 400 Cluster	Bathroom Faucet	Non-Potable	12/8/2020	13	Result Below Action Level Continue O&M
MCCSD-1970	3020	Womens Bathroom Adjacent 400 Cluster	Bathroom Faucet	Non-Potable	12/8/2020	10	Result Below Action Level Continue O&M
MCCSD-1971	3026	Corridor from 300 Cluster to 400 Cluster	Classroom Faucet	Non-Potable	12/8/2020	300	Placarded for Non-Drinking Use Until Remediated

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-1972	3026	Corridor from 300 Cluster to 400 Cluster	Classroom Faucet	Non-Potable	12/8/2020	5.0	Result Below Action Level Continue O&M
MCCSD-1973	3026	Corridor from 300 Cluster to 400 Cluster	Classroom Faucet	Non-Potable	12/8/2020	16	Placarded for Non-Drinking Use Until Remediated
MCCSD-1974	3021	Mens Bathroom Adjacent 400 Cluster	Bathroom Faucet	Non-Potable	12/8/2020	8.3	Result Below Action Level Continue O&M
MCCSD-1975	3021	Mens Bathroom Adjacent 400 Cluster	Bathroom Faucet	Non-Potable	12/8/2020	19	Placarded for Non-Drinking Use Until Remediated
MCCSD-1977	3023	Fifth Grade Girls Bathroom	Bathroom Faucet	Non-Potable	12/8/2020	16	Placarded for Non-Drinking Use Until Remediated
MCCSD-1978	3023	Fifth Grade Girls Bathroom	Bathroom Faucet	Non-Potable	12/8/2020	16	Placarded for Non-Drinking Use Until Remediated
MCCSD-1979	3023	Fifth Grade Girls Bathroom	Bathroom Faucet	Non-Potable	12/8/2020	21	Placarded for Non-Drinking Use Until Remediated
MCCSD-1981	3026	Corridor from 300 Cluster to 400 Cluster	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1982	3026	Corridor from 300 Cluster to 400 Cluster	Classroom Faucet	Non-Potable	12/8/2020	17	Placarded for Non-Drinking Use Until Remediated
MCCSD-1983	3026	Corridor from 300 Cluster to 400 Cluster	Classroom Faucet	Non-Potable	12/8/2020	16	Placarded for Non-Drinking Use Until Remediated
MCCSD-1984	3026	Corridor from 300 Cluster to 400 Cluster	Classroom Faucet	Non-Potable	12/8/2020	14	Result Below Action Level Continue O&M
MCCSD-1985	3026	Corridor from 300 Cluster to 400 Cluster	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1987	3024	Fifth Grade Boys Bathroom	Bathroom Faucet	Non-Potable	12/8/2020	23	Placarded for Non-Drinking Use Until Remediated
MCCSD-1988	3024	Fifth Grade Boys Bathroom	Bathroom Faucet	Non-Potable	12/8/2020	17	Placarded for Non-Drinking Use Until Remediated
MCCSD-1989	3024	Fifth Grade Boys Bathroom	Bathroom Faucet	Non-Potable	12/8/2020	13	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-1990	2021	Kitchen	Kitchen Faucet (Cold)	Potable	12/8/2020	2.7	Result Below Action Level Continue O&M
MCCSD-1991	2021	Kitchen	Spray Nozzle	Potable	12/8/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1992	2021	Kitchen	Kitchen Faucet (Cold)	Potable	12/8/2020	4.8	Result Below Action Level Continue O&M
MCCSD-1993	2021	Kitchen	Spray Nozzle	Potable	12/8/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1994	2021	Kitchen	Kitchen Faucet (Cold)	Potable	12/8/2020	1.3	Result Below Action Level Continue O&M
MCCSD-1996	2021	Kitchen	Pasta Pot/Steam Kettle	Potable	12/8/2020	51	Removed From Service, Pending Remediation
MCCSD-1997	2021B	Kitchen Bathroom	Bathroom Faucet	Non-Potable	12/8/2020	4.7	Result Below Action Level Continue O&M
MCCSD-1999	2023A	Custodial Office Bathroom	Bathroom Faucet	Non-Potable	12/8/2020	1.8	Result Below Action Level Continue O&M

Newfield High School

MCCSD-1222	1026	Corridor from Room 130 to 140	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1223	1008	Room 137/139 Vestibule	Classroom Faucet	Non-Potable	11/21/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1224	1026	Corridor from Room 130 to 140	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1225	1013	Room 138	Spray Nozzle	Potable	11/21/2020	2	Result Below Action Level Continue O&M
MCCSD-1226	1013	Room 138	Spray Nozzle	Potable	11/21/2020	14	Result Below Action Level Continue O&M
MCCSD-1227	1013	Room 138	Spray Nozzle	Potable	11/21/2020	2	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-1228	1013	Room 138	Spray Nozzle	Potable	11/21/2020	1.3	Result Below Action Level Continue O&M
MCCSD-1229	1013	Room 138	Spray Nozzle	Potable	11/21/2020	1.3	Result Below Action Level Continue O&M
MCCSD-1232	1013A	Room 138 Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	2.9	Result Below Action Level Continue O&M
MCCSD-1233	1014	Room 140	Classroom Faucet	Non-Potable	11/21/2020	2.8	Result Below Action Level Continue O&M
MCCSD-1234	1014B	Room 140 Storage Room(Interior Walls Removed)	Bathroom Faucet	Non-Potable	11/21/2020	3.2	Result Below Action Level Continue O&M
MCCSD-1235	1022	Bathroom 49	Bathroom Faucet	Non-Potable	11/21/2020	13	Result Below Action Level Continue O&M
MCCSD-1236	1027	Women's Faculty Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	1.9	Result Below Action Level Continue O&M
MCCSD-1237	1058	Corridor from Room 135 to Intersection	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1238	1029	Men's Faculty Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	3.7	Result Below Action Level Continue O&M
MCCSD-1239	1029	Men's Faculty Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	2.5	Result Below Action Level Continue O&M
MCCSD-1242	1031B	Boys Locker Room Showers	Bathroom Faucet	Non-Potable	11/21/2020	OOS	Testing Required Before Return to Service
MCCSD-1243	1031B	Boys Locker Room Showers	Bathroom Faucet	Non-Potable	11/21/2020	OOS	Testing Required Before Return to Service
MCCSD-1244	1031B	Boys Locker Room Showers	Bathroom Faucet	Non-Potable	11/21/2020	OOS	Testing Required Before Return to Service
MCCSD-1245	1031B	Boys Locker Room Showers	Bathroom Faucet	Non-Potable	11/21/2020	OOS	Testing Required Before Return to Service
MCCSD-1246	1031C	Boys Locker Room Rear Vestibule	Ice Machine	Potable	11/21/2020	<3.0 ND	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-1247	1035A	Boys Varsity Team Room Showers	Bathroom Faucet	Non-Potable	11/21/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1248	1035A	Boys Varsity Team Room Showers	Bathroom Faucet	Non-Potable	11/21/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1249	1045B2	Vestibule Locker Room Showers	Bathroom Faucet	Non-Potable	11/21/2020	12	Result Below Action Level Continue O&M
MCCSD-1250	1045B2	Vestibule Locker Room Showers	Bathroom Faucet	Non-Potable	11/21/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1251	1045B2	Vestibule Locker Room Showers	Bathroom Faucet	Non-Potable	11/21/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1252	1047	Vestibule	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1253	1047	Vestibule	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1254	1047A1	Vestibule Office Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	15	Result Below Action Level Continue O&M
MCCSD-1255	1041	Fitness Room	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1256	1041	Fitness Room	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1257	1040	Stairwell	Classroom Faucet	Non-Potable	11/21/2020	8.0	Result Below Action Level Continue O&M
MCCSD-1258	1036	Rear Right Gymnasium Corridor	Bottled Water Dispenser	Potable	11/21/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1259	1036	Rear Right Gymnasium Corridor	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1260	1036	Rear Right Gymnasium Corridor	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1261	1030	Boys Locker Room Vestibule	Classroom Faucet	Potable	11/21/2020	2.2	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-1262	N/A	New Construction Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1263	N/A	New Construction Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1264	N/A	New Construction Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	1.2	Result Below Action Level Continue O&M
MCCSD-1265	N/A	New Construction Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	1.2	Result Below Action Level Continue O&M
MCCSD-1266	N/A	New Construction Hallway	Bottled Water Dispenser	Potable	11/21/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1267	N/A	New Construction Hallway	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1268	N/A	New Construction Hallway	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1269	N/A	New Construction Boys Coach Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	1.2	Result Below Action Level Continue O&M
MCCSD-1270	N/A	New Construction Boys Locker Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1271	N/A	New Construction Boys Locker Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1272	N/A	New Construction Girls Locker Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1273	N/A	New Construction Girls Locker Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1274	N/A	New Construction Girls Coach Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1275	N/A	New Construction Hallway	Bottled Water Dispenser	Potable	11/21/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1276	N/A	New Construction Hallway	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-1277	N/A	New Construction Hallway	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1278	1039B	Girls Locker Room Sport Lounge	Bathroom Faucet	Non-Potable	11/21/2020	OOS	Testing Required Before Return to Service
MCCSD-1279	1039B	Girls Locker Room Sport Lounge	Bathroom Faucet	Non-Potable	11/21/2020	OOS	Testing Required Before Return to Service
MCCSD-1280	1039B	Girls Locker Room Sport Lounge	Bathroom Faucet	Non-Potable	11/21/2020	OOS	Testing Required Before Return to Service
MCCSD-1281	1039B	Girls Locker Room Sport Lounge	Bathroom Faucet	Non-Potable	11/21/2020	OOS	Testing Required Before Return to Service
MCCSD-1282	1049B	Girls Locker Room Vestibule Office Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	3	Result Below Action Level Continue O&M
MCCSD-1283	1052	Boys Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	5.3	Result Below Action Level Continue O&M
MCCSD-1285	1074	Corridor from Room 99 to Gymnasium	Bottled Water Dispenser	Potable	11/21/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1286	1074	Corridor from Room 99 to Gymnasium	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1287	1097	Library	Bottled Water Dispenser	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1288	1097	Library	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1289	1097	Bathroom Left Library	Bathroom Faucet	Non-Potable	11/21/2020	OOS	Testing Required Before Return to Service
MCCSD-1290	1097	Bathroom Right Library	Kitchen Faucet (Cold)	Potable	11/21/2020	OOS	Testing Required Before Return to Service
MCCSD-1291	1063	School Store	Kitchen Faucet (Cold)	Potable	11/21/2020	6.8	Result Below Action Level Continue O&M
MCCSD-1292	1061	Kitchen	Hand Wash Only	Non-Potable	11/21/2020	<3.0 ND	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-1293	1061	Kitchen	Hand Wash Only	Non-Potable	11/21/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1294	1061	Kitchen	Hand Wash Only	Non-Potable	11/21/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1295	1061	Kitchen	Hand Wash Only	Non-Potable	11/21/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1296	1061	Kitchen	Hand Wash Only	Non-Potable	11/21/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1297	1061	Kitchen	Kitchen Faucet (Cold)	Potable	11/21/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1298	1061	Kitchen	Kitchen Faucet (Cold)	Potable	11/21/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1299	1061	Kitchen	Spray Nozzle	Potable	11/21/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1300	1061	Kitchen	Hand Wash Only	Non-Potable	11/21/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1301	1061	Kitchen	Kitchen Faucet (Cold)	Potable	11/21/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1302	1061A	Kitchen Locker Room	Bathroom Faucet	Non-Potable	11/21/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1303	1067	Women's Faculty Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	2.3	Result Below Action Level Continue O&M
MCCSD-1304	1067	Women's Faculty Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	5.0	Result Below Action Level Continue O&M
MCCSD-1306	1074	Corridor from Room 99 to Gymnasium	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1307	1075	Men's Faculty Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	2.9	Result Below Action Level Continue O&M
MCCSD-1308	1075	Men's Faculty Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	2.7	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-1310	1077A	Custodial Office Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1312	1080	Band Room	Classroom Faucet	Non-Potable	11/21/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1313	1081	Corridor from Band Room to Room 98	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1314	1086	Girls Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	5.7	Result Below Action Level Continue O&M
MCCSD-1315	1086	Girls Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	13	Result Below Action Level Continue O&M
MCCSD-1316	1087	Boys Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	5.0	Result Below Action Level Continue O&M
MCCSD-1317	N/A	Principal Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	OOS	Testing Required Before Return to Service
MCCSD-1318	1100	Room 115	Classroom Faucet	Non-Potable	11/21/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1319	1100	Room 115	Classroom Faucet	Non-Potable	11/21/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1320	1100	Room 115	Classroom Faucet	Non-Potable	11/21/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1321	1101	Room 113	Classroom Faucet	Non-Potable	11/21/2020	OOS	Testing Required Before Return to Service
MCCSD-1322	1101	Room 113	Classroom Faucet	Non-Potable	11/21/2020	32	Placarded for Non-Drinking Use Until Remediated
MCCSD-1323	1101	Room 113	Classroom Faucet	Non-Potable	11/21/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1324	1101	Room 113	Classroom Faucet	Non-Potable	11/21/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1325	1101	Room 113	Classroom Faucet	Non-Potable	11/21/2020	<3.0 ND	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-1326	1102	Room 111	Classroom Faucet	Non-Potable	11/21/2020	OOS	Testing Required Before Return to Service
MCCSD-1327	1102	Room 111	Classroom Faucet	Non-Potable	11/21/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1328	1102C	Room 111 Dark Room	Classroom Faucet	Non-Potable	11/21/2020	OOS	Testing Required Before Return to Service
MCCSD-1329	1102C	Room 111 Dark Room	Classroom Faucet	Non-Potable	11/21/2020	OOS	Testing Required Before Return to Service
MCCSD-1330	1102C	Room 111 Dark Room	Classroom Faucet	Non-Potable	11/21/2020	OOS	Testing Required Before Return to Service
MCCSD-1331	1102C	Room 111 Dark Room	Classroom Faucet	Non-Potable	11/21/2020	OOS	Testing Required Before Return to Service
MCCSD-1332	1116	Corridor from Room 113 to 123A	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1344	1107	Science Prep Room	Bottled Water Dispenser	Potable	11/21/2020	OOS	Testing Required Before Return to Service
MCCSD-1353	1057	Girls Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	3.2	Result Below Action Level Continue O&M
MCCSD-1356	1055	Nurses Office	Nurse's Office Sink	Potable	11/21/2020	1.2	Result Below Action Level Continue O&M
MCCSD-1357	1055B	Nurses Office Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	2.3	Result Below Action Level Continue O&M
MCCSD-1358	1055C	Nurses Office Bathroom 2	Bathroom Faucet	Non-Potable	11/21/2020	5.2	Result Below Action Level Continue O&M
MCCSD-1359	1116	Corridor from Room 113 to 123A	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1360	1111	Girls Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	4.0	Result Below Action Level Continue O&M
MCCSD-1361	1112	Women's Faculty Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	3.7	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-1362	1113	Men's Faculty Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	13	Result Below Action Level Continue O&M
MCCSD-1363	1116	Corridor from Room 113 to 123A	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1374	1119	Boys Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	7.7	Result Below Action Level Continue O&M
MCCSD-1454	N/A	New Construction Hallway	Bottled Water Dispenser	Potable	11/21/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1455	N/A	New Construction Hallway	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1497	1140	Room 104	Home Economics Faucet (Cold)	Potable	11/21/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1500	1140	Room 104	Home Economics Faucet (Cold)	Potable	11/21/2020	2.7	Result Below Action Level Continue O&M
MCCSD-1501	1140	Room 104	Home Economics Faucet (Cold)	Potable	11/21/2020	1.6	Result Below Action Level Continue O&M
MCCSD-1502	1140	Room 104	Home Economics Faucet (Cold)	Potable	11/21/2020	1.2	Result Below Action Level Continue O&M
MCCSD-1503	1140	Room 104	Home Economics Faucet (Cold)	Potable	11/21/2020	2	Result Below Action Level Continue O&M
MCCSD-1504	1138A	Room 106 Bathroom	Classroom Faucet	Non-Potable	11/21/2020	1.5	Result Below Action Level Continue O&M
MCCSD-1505	1134	Girls Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	12	Result Below Action Level Continue O&M
MCCSD-1506	1134	Girls Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	3.9	Result Below Action Level Continue O&M
MCCSD-1507	1134	Girls Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	3.4	Result Below Action Level Continue O&M
MCCSD-1509	1131	Men's Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	7.2	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-1510	1131	Men's Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	7.2	Result Below Action Level Continue O&M
MCCSD-1512	2013	Boys Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	3.9	Result Below Action Level Continue O&M
MCCSD-1513	2013	Boys Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	6.3	Result Below Action Level Continue O&M
MCCSD-1514	2013	Boys Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	5.0	Result Below Action Level Continue O&M
MCCSD-1515	2013	Boys Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	5.8	Result Below Action Level Continue O&M
MCCSD-1516	2013	Boys Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	14	Result Below Action Level Continue O&M
MCCSD-1519	2009	Girls Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	6.2	Result Below Action Level Continue O&M
MCCSD-1520	2009	Girls Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	10	Result Below Action Level Continue O&M
MCCSD-1521	2009	Girls Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	13	Result Below Action Level Continue O&M
MCCSD-1522	2009	Girls Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	4.3	Result Below Action Level Continue O&M
MCCSD-1523	2016	Corridor from Room 201 to Stairwell	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1524	2017B2	Faculty Room Copy Room Kitchen	Kitchen Faucet (Cold)	Potable	11/21/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1526	2020	Women's Faculty Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	1.1	Result Below Action Level Continue O&M
MCCSD-1527	2020	Women's Faculty Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	3.4	Result Below Action Level Continue O&M
MCCSD-1528	2035	Corridor from Room 223 to Faculty Room	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-1529	2022	Men's Faculty Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	2.6	Result Below Action Level Continue O&M
MCCSD-1530	2022	Men's Faculty Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	7.6	Result Below Action Level Continue O&M
MCCSD-1532	2017B2	Faculty Room Copy Room Kitchen	Spray Nozzle	Potable	11/21/2020	18	Removed From Service, Pending Remediation
MCCSD-1533	2033	Girls Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	6.6	Result Below Action Level Continue O&M
MCCSD-1534	2033	Girls Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	3.2	Result Below Action Level Continue O&M
MCCSD-1535	2033	Girls Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	11	Result Below Action Level Continue O&M
MCCSD-1536	2033	Girls Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	3.2	Result Below Action Level Continue O&M
MCCSD-1537	2035	Corridor from Room 223 to Faculty Room	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1539	2038	Boys Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	1.8	Result Below Action Level Continue O&M
MCCSD-1540	2038	Boys Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	2.6	Result Below Action Level Continue O&M
MCCSD-1541	2038	Boys Bathroom	Bathroom Faucet	Non-Potable	11/21/2020	3.5	Result Below Action Level Continue O&M
MCCSD-1542	2050	Corridor From 223 To 228	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service

North Coleman Road Elementary School

MCCSD-0064	1005	Room 202	Classroom Faucet	Non-Potable	11/24/2020	2.1	Result Below Action Level Continue O&M
MCCSD-0065	1005	Room 202	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0066	1006	Room 203	Classroom Faucet	Non-Potable	11/24/2020	25	Placarded for Non-Drinking Use Until Remediated
MCCSD-0067	1006	Room 203	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0068	1007	Girls Bathroom	Bathroom Faucet	Non-Potable	11/24/2020	4.0	Result Below Action Level Continue O&M
MCCSD-0069	1007	Girls Bathroom	Bathroom Faucet	Non-Potable	11/24/2020	1.7	Result Below Action Level Continue O&M
MCCSD-0070	1007	Girls Bathroom	Bathroom Faucet	Non-Potable	11/24/2020	5.0	Result Below Action Level Continue O&M
MCCSD-0072	1019	Corridor Room 201 to 211	Bottled Water Dispenser	Potable	11/24/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0073	1019	Corridor Room 201 to 211	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0074	1009	Boys Bathroom	Bathroom Faucet	Non-Potable	11/24/2020	3.4	Result Below Action Level Continue O&M
MCCSD-0075	1009	Boys Bathroom	Bathroom Faucet	Non-Potable	11/24/2020	6.8	Result Below Action Level Continue O&M
MCCSD-0076	1009	Boys Bathroom	Bathroom Faucet	Non-Potable	11/24/2020	4.0	Result Below Action Level Continue O&M
MCCSD-0077	1009	Boys Bathroom	Bathroom Faucet	Non-Potable	11/24/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0078	1010	Room 204	Classroom Faucet	Non-Potable	11/24/2020	4.0	Result Below Action Level Continue O&M
MCCSD-0079	1010	Room 204	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0080	1011	Room 206	Classroom Faucet	Non-Potable	11/24/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0081	1011	Room 206	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0082	1012	Room 205	Classroom Faucet	Non-Potable	11/24/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0083	1012	Room 205	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0084	1013	Room 208	Classroom Faucet	Non-Potable	11/24/2020	2	Result Below Action Level Continue O&M
MCCSD-0085	1013	Room 208	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0086	1014	Room 207	Classroom Faucet	Non-Potable	11/24/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0087	1014	Room 207	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0088	1015	Room 210	Classroom Faucet	Non-Potable	11/24/2020	1.8	Result Below Action Level Continue O&M
MCCSD-0089	1015	Room 210	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0090	1016	Room 209	Classroom Faucet	Non-Potable	11/24/2020	4.7	Result Below Action Level Continue O&M
MCCSD-0091	1016	Room 209	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0092	1017	Room 212	Classroom Faucet	Non-Potable	11/24/2020	2.1	Result Below Action Level Continue O&M
MCCSD-0093	1017	Room 212	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0094	1018	Room 211	Classroom Faucet	Non-Potable	11/24/2020	4.4	Result Below Action Level Continue O&M
MCCSD-0095	1018	Room 211	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0096	1020	Cafeteria/Auditorium	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0097	1020B	Cafeteria/Auditorium Fan Room	Sports Cooler	Potable	11/24/2020	OOS	Testing Required Before Return to Service
MCCSD-0099	1021	Kitchen	Kitchen Faucet (Cold)	Potable	11/24/2020	2.6	Result Below Action Level Continue O&M
MCCSD-0100	1021A1	Kitchen Office Bathroom	Bathroom Faucet	Non-Potable	11/24/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0102	1022A	Custodial Room Storage	Classroom Faucet	Non-Potable	11/24/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0104	1030	Corridor Room 117 to 212	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0105	1026	Women's Faculty Bathroom	Bathroom Faucet	Non-Potable	11/24/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0106	1028	Men's Faculty Bathroom	Bathroom Faucet	Non-Potable	11/24/2020	1.4	Result Below Action Level Continue O&M
MCCSD-0107	1027A1	Gym Faculty Office Bathroom	Bathroom Faucet	Non-Potable	11/24/2020	2.2	Result Below Action Level Continue O&M
MCCSD-0108	1027A2A	Gym Faculty Office Storage Room Bathroom	Bathroom Faucet	Non-Potable	11/24/2020	1.1	Result Below Action Level Continue O&M
MCCSD-0109	1027C2	Boys Locker Room Bathroom	Bathroom Faucet	Non-Potable	11/24/2020	9.2	Result Below Action Level Continue O&M
MCCSD-0110	1027C1A	Boys Locker Room Office Bathroom	Bathroom Faucet	Non-Potable	11/24/2020	1.3	Result Below Action Level Continue O&M
MCCSD-0111	1030	Corridor Room 117 to 212	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0112	1031	Room 117	Classroom Faucet	Non-Potable	11/24/2020	64	Placarded for Non-Drinking Use Until Remediated
MCCSD-0113	1031	Room 117	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0114	1032	Room 114	Classroom Faucet	Non-Potable	11/24/2020	18	Placarded for Non-Drinking Use Until Remediated

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0115	1032	Room 114	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0116	1033	Room 115	Classroom Faucet	Non-Potable	11/24/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0117	1033	Room 115	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0118	1034	Room 112	Classroom Faucet	Non-Potable	11/24/2020	8.8	Result Below Action Level Continue O&M
MCCSD-0119	1034	Room 112	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0120	1035	Room 113	Classroom Faucet	Non-Potable	11/24/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0121	1035	Room 113	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0122	1036	Room 110	Classroom Faucet	Non-Potable	11/24/2020	9.1	Result Below Action Level Continue O&M
MCCSD-0123	1036	Room 110	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0124	1037	Room 111	Classroom Faucet	Non-Potable	11/24/2020	12	Result Below Action Level Continue O&M
MCCSD-0125	1037	Room 111	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0126	1038	Room 108	Classroom Faucet	Non-Potable	11/24/2020	2.4	Result Below Action Level Continue O&M
MCCSD-0127	1038	Room 108	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0128	1039	Boys Bathroom	Bathroom Faucet	Non-Potable	11/24/2020	1.4	Result Below Action Level Continue O&M
MCCSD-0129	1039	Boys Bathroom	Bathroom Faucet	Non-Potable	11/24/2020	1.9	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0130	1039	Boys Bathroom	Bathroom Faucet	Non-Potable	11/24/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0131	1039	Boys Bathroom	Bathroom Faucet	Non-Potable	11/24/2020	3.2	Result Below Action Level Continue O&M
MCCSD-0132	1048	Corridor Room 104 to 117	Bottled Water Dispenser	Potable	11/24/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0133	1048	Corridor Room 104 to 117	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0135	1041	Girls Bathroom	Bathroom Faucet	Non-Potable	11/24/2020	1.3	Result Below Action Level Continue O&M
MCCSD-0136	1041	Girls Bathroom	Bathroom Faucet	Non-Potable	11/24/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0137	1041	Girls Bathroom	Bathroom Faucet	Non-Potable	11/24/2020	1.6	Result Below Action Level Continue O&M
MCCSD-0138	1042	Room 109	Classroom Faucet	Non-Potable	11/24/2020	6.0	Result Below Action Level Continue O&M
MCCSD-0139	1042	Room 109	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0142	1043	Room 107	Bottled Water Dispenser	Potable	11/24/2020	OOS	Testing Required Before Return to Service
MCCSD-0143	1044	Room 106	Classroom Faucet	Non-Potable	11/24/2020	4.6	Result Below Action Level Continue O&M
MCCSD-0144	1044	Room 106	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0145	1047	Room 104	Classroom Faucet	Non-Potable	11/24/2020	4.5	Result Below Action Level Continue O&M
MCCSD-0146	1047	Room 104	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0147	1049	Room 105	Classroom Faucet	Non-Potable	11/24/2020	2.3	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0148	1049	Room 105	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0149	1050	Room 103	Classroom Faucet	Non-Potable	11/24/2020	11	Result Below Action Level Continue O&M
MCCSD-0150	1050	Room 103	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0151	1051	Room 102 (Interior Wall Removed)	Classroom Faucet	Non-Potable	11/24/2020	3.9	Result Below Action Level Continue O&M
MCCSD-0152	1051	Room 102 (Interior Wall Removed)	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0153	1052	Room 101	Classroom Faucet	Non-Potable	11/24/2020	7.1	Result Below Action Level Continue O&M
MCCSD-0154	1052	Room 101	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0155	1059	Health Office Suite	Nurse's Office Sink	Potable	11/24/2020	2.1	Result Below Action Level Continue O&M
MCCSD-0156	1059A	Healthy Office Suite Bathroom	Bathroom Faucet	Non-Potable	11/24/2020	6.3	Result Below Action Level Continue O&M
MCCSD-0157	1063A	Main Office Bathroom	Bathroom Faucet	Non-Potable	11/24/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0158	1063B	Main Office Principals Office	Bathroom Faucet	Non-Potable	11/24/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0159	1064	Main Lobby/Corridor	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service

Oxhead Road Elementary School

MCCSD-0402	1000	Room 102	Classroom Faucet	Non-Potable	12/1/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0403	1000	Room 102	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0404	1000B	Room 102 Bathroom	Bathroom Faucet	Non-Potable	12/1/2020	4.6	Result Below Action Level Continue O&M
MCCSD-0405	1001	Room 103	Classroom Faucet	Non-Potable	12/1/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0406	1001	Room 103	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0407	1001B	Room 103 Bathroom	Bathroom Faucet	Non-Potable	12/1/2020	4.3	Result Below Action Level Continue O&M
MCCSD-0408	1002	Room 101	Classroom Faucet	Non-Potable	12/1/2020	17	Placarded for Non-Drinking Use Until Remediated
MCCSD-0409	1002	Room 101	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0410	1003	Room 104	Classroom Faucet	Non-Potable	12/1/2020	3.6	Result Below Action Level Continue O&M
MCCSD-0411	1003	Room 104	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0412	1003B	Room 104 Bathroom	Bathroom Faucet	Non-Potable	12/1/2020	9.1	Result Below Action Level Continue O&M
MCCSD-0414	1005	Room 105	Classroom Faucet	Non-Potable	12/1/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0415	1005	Room 105	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0416	1007	Faculty Room	Classroom Faucet	Non-Potable	12/1/2020	1.2	Result Below Action Level Continue O&M
MCCSD-0417	1008	Nurses Office	Nurse's Office Sink	Potable	12/1/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0418	1008B	Nurses Bathroom	Bathroom Faucet	Non-Potable	12/1/2020	3.8	Result Below Action Level Continue O&M
MCCSD-0419	1009	Room 106	Classroom Faucet	Non-Potable	12/1/2020	<3.0 ND	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0420	1009	Room 106	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0421	1010	Room 107	Classroom Faucet	Non-Potable	12/1/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0422	1010	Room 107	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0423	1013A	Bathroom	Bathroom Faucet	Non-Potable	12/1/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0424	1025	1st Floor Main Corridor	Bottled Water Dispenser	Potable	12/1/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0425	1025	1st Floor Main Corridor	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0426	1012C1	Gym Locker Room Storage Room	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0427	1012C2A	Gym Locker Room Vestibule Bathroom	Bathroom Faucet	Non-Potable	12/1/2020	OOS	Testing Required Before Return to Service
MCCSD-0428	1016	Cafeteria	Bottled Water Dispenser	Potable	12/1/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0429	1016	Cafeteria	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0430	1017B	Music Room Bathroom	Bathroom Faucet	Non-Potable	12/1/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0431	1020A	Storage Room Bathroom	Bathroom Faucet	Non-Potable	12/1/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0432	1024	Kitchen	Kitchen Faucet (Cold)	Potable	12/1/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0433	1024	Kitchen	Spray Nozzle	Potable	12/1/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0434	1024	Kitchen	Ice Machine	Potable	12/1/2020	OOS	Testing Required Before Return to Service

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0435	1024	Kitchen	Kitchen Faucet (Cold)	Potable	12/1/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0438	1029	Girls Bathroom	Bathroom Faucet	Non-Potable	12/1/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0439	1029	Girls Bathroom	Bathroom Faucet	Non-Potable	12/1/2020	OOS	Testing Required Before Return to Service
MCCSD-0440	1029	Girls Bathroom	Bathroom Faucet	Non-Potable	12/1/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0442	1032	Boys Bathroom	Bathroom Faucet	Non-Potable	12/1/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0443	1032	Boys Bathroom	Bathroom Faucet	Non-Potable	12/1/2020	OOS	Testing Required Before Return to Service
MCCSD-0444	1032	Boys Bathroom	Bathroom Faucet	Non-Potable	12/1/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0446	1033	Room 110	Classroom Faucet	Non-Potable	12/1/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0447	1033	Room 110	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0448	1034	Room 109	Classroom Faucet	Non-Potable	12/1/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0449	1034	Room 109	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0450	1035	Room 112	Classroom Faucet	Non-Potable	12/1/2020	8.4	Result Below Action Level Continue O&M
MCCSD-0451	1035	Room 112	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0452	1036	Room 111	Classroom Faucet	Non-Potable	12/1/2020	1.3	Result Below Action Level Continue O&M
MCCSD-0453	1036	Room 111	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0454	1037	Room 114	Classroom Faucet	Non-Potable	12/1/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0455	1037	Room 114	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0456	1038	Room 113	Classroom Faucet	Non-Potable	12/1/2020	2.2	Result Below Action Level Continue O&M
MCCSD-0457	1038	Room 113	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0458	1039	Room 116	Classroom Faucet	Non-Potable	12/1/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0459	1039	Room 116	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0460	1040	Room 115	Classroom Faucet	Non-Potable	12/1/2020	1.4	Result Below Action Level Continue O&M
MCCSD-0461	1040	Room 115	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0462	1041	Corridor Room 115 to Storage Room	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0463	1042	Room 118	Classroom Faucet	Non-Potable	12/1/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0464	1042	Room 118	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0465	1042B	Room 118 Bathroom	Bathroom Faucet	Non-Potable	12/1/2020	6.2	Result Below Action Level Continue O&M
MCCSD-0466	1043	Room 117	Classroom Faucet	Non-Potable	12/1/2020	1.3	Result Below Action Level Continue O&M
MCCSD-0467	1043	Room 117	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0468	1043A	Room 117 Bathroom	Bathroom Faucet	Non-Potable	12/1/2020	6.3	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0469	2001	Room 210	Classroom Faucet	Non-Potable	12/1/2020	1.1	Result Below Action Level Continue O&M
MCCSD-0470	2001	Room 210	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0471	2008	Room 209	Classroom Faucet	Non-Potable	12/1/2020	2.6	Result Below Action Level Continue O&M
MCCSD-0472	2008	Room 209	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0473	2009	Room 208	Classroom Faucet	Non-Potable	12/1/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0474	2009	Room 208	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0475	2010	Room 207	Classroom Faucet	Non-Potable	12/1/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0476	2010	Room 207	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0477	2011	Room 206	Classroom Faucet	Non-Potable	12/1/2020	7.3	Result Below Action Level Continue O&M
MCCSD-0478	2011	Room 206	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0479	2012	Room 205	Classroom Faucet	Non-Potable	12/1/2020	1.3	Result Below Action Level Continue O&M
MCCSD-0480	2012	Room 205	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0481	2013	Room 204	Classroom Faucet	Non-Potable	12/1/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0482	2013	Room 204	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0483	2014	Room 203	Classroom Faucet	Non-Potable	12/1/2020	2.8	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0484	2014	Room 203	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0485	2015	Room 202	Classroom Faucet	Non-Potable	12/1/2020	5.0	Result Below Action Level Continue O&M
MCCSD-0486	2015	Room 202	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0487	2017	Boys Bathroom	Bathroom Faucet	Non-Potable	12/1/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0488	2017	Boys Bathroom	Bathroom Faucet	Non-Potable	12/1/2020	OOS	Testing Required Before Return to Service
MCCSD-0489	2017	Boys Bathroom	Bathroom Faucet	Non-Potable	12/1/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0492	2019	Girls Bathroom	Bathroom Faucet	Non-Potable	12/1/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0493	2019	Girls Bathroom	Bathroom Faucet	Non-Potable	12/1/2020	OOS	Testing Required Before Return to Service
MCCSD-0494	2019	Girls Bathroom	Bathroom Faucet	Non-Potable	12/1/2020	1.3	Result Below Action Level Continue O&M
MCCSD-0496	2020	Room 201	Classroom Faucet	Non-Potable	12/1/2020	4.2	Result Below Action Level Continue O&M
MCCSD-0497	2020	Room 201	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0498	2021B	Library Storage Room	Classroom Faucet	Non-Potable	12/1/2020	28	Placarded for Non-Drinking Use Until Remediated
MCCSD-0499	2022	Women's Bathroom	Bathroom Faucet	Non-Potable	12/1/2020	4.3	Result Below Action Level Continue O&M
MCCSD-0500	2022	Women's Bathroom	Bathroom Faucet	Non-Potable	12/1/2020	4.0	Result Below Action Level Continue O&M
MCCSD-0501	2023	Men's Bathroom	Bathroom Faucet	Non-Potable	12/1/2020	6.1	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
---------------	----------	------------------	-------------	----------------------	-------------	--------------	------------------------------------

Selden Middle School

MCCSD-1561	1026	Nurses Office	Nurse's Office Sink	Potable	12/3/2020	2.6	Result Below Action Level Continue O&M
MCCSD-1562	1026A	Nurses Office Bathroom	Bathroom Faucet	Non-Potable	12/3/2020	1.2	Result Below Action Level Continue O&M
MCCSD-1563	1001	Men's Faculty Bathroom	Bathroom Faucet	Non-Potable	12/3/2020	13	Result Below Action Level Continue O&M
MCCSD-1564	1001	Men's Faculty Bathroom	Bathroom Faucet	Non-Potable	12/3/2020	8.2	Result Below Action Level Continue O&M
MCCSD-1566	1002	Women's Faculty Bathroom	Bathroom Faucet	Non-Potable	12/3/2020	3.1	Result Below Action Level Continue O&M
MCCSD-1567	1002	Women's Faculty Bathroom	Bathroom Faucet	Non-Potable	12/3/2020	13	Result Below Action Level Continue O&M
MCCSD-1569	1006	Band Room 148	Classroom Faucet	Non-Potable	12/4/2020	13	Result Below Action Level Continue O&M
MCCSD-1581	1046	Corridor from Elevator to Xerox Room	Bottled Water Dispenser	Potable	12/3/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1582	1046	Corridor from Elevator to Xerox Room	Sports Cooler	Potable	12/3/2020	OOS	Testing Required Before Return to Service
MCCSD-1583	1027	Room 102	Classroom Faucet	Non-Potable	12/4/2020	2.2	Result Below Action Level Continue O&M
MCCSD-1584	1032	Room 106	Classroom Faucet	Non-Potable	12/4/2020	1.4	Result Below Action Level Continue O&M
MCCSD-1585	1037	Room 110	Classroom Faucet	Non-Potable	12/4/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1586	1038	Boys Bathroom	Bathroom Faucet	Non-Potable	12/3/2020	2.5	Result Below Action Level Continue O&M
MCCSD-1587	1038	Boys Bathroom	Bathroom Faucet	Non-Potable	12/3/2020	5.9	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-1588	1038	Boys Bathroom	Bathroom Faucet	Non-Potable	12/3/2020	6.7	Result Below Action Level Continue O&M
MCCSD-1591	1040	Girls Bathroom	Bathroom Faucet	Non-Potable	12/3/2020	1.5	Result Below Action Level Continue O&M
MCCSD-1592	1040	Girls Bathroom	Bathroom Faucet	Non-Potable	12/3/2020	4.5	Result Below Action Level Continue O&M
MCCSD-1593	1040	Girls Bathroom	Bathroom Faucet	Non-Potable	12/3/2020	4.5	Result Below Action Level Continue O&M
MCCSD-1595	1042	Room 109	Classroom Faucet	Non-Potable	12/4/2020	19	Placarded for Non-Drinking Use Until Remediated
MCCSD-1596	1043	Room 114	Classroom Faucet	Non-Potable	12/4/2020	4.0	Result Below Action Level Continue O&M
MCCSD-1597	1046	Corridor from Elevator to Xerox Room	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1598	1051I	Bathroom	Bathroom Faucet	Non-Potable	12/4/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1599	1051J	Bathroom	Bathroom Faucet	Non-Potable	12/3/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1600	1051D	New Construction Classroom	Classroom Faucet	Non-Potable	12/4/2020	230	Placarded for Non-Drinking Use Until Remediated
MCCSD-1601	1051E	New Construction Classroom	Classroom Faucet	Non-Potable	12/4/2020	51	Placarded for Non-Drinking Use Until Remediated
MCCSD-1602	1048	Faculty Lounge	Kitchen Faucet (Cold)	Potable	12/3/2020	3	Result Below Action Level Continue O&M
MCCSD-1603	1052A3	Boys Locker Room Equipment Room	Bathroom Faucet	Non-Potable	12/3/2020	96	Placarded for Non-Drinking Use Until Remediated
MCCSD-1604	1052A4	Boys Locker Room Bathroom	Bathroom Faucet	Non-Potable	12/3/2020	5.6	Result Below Action Level Continue O&M
MCCSD-1605	1052A	Boys Locker Room	Bottled Water Dispenser	Potable	12/3/2020	<3.0 ND	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-1606	1052A	Boys Locker Room	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1608	1052E	Girls Locker Room	Bottled Water Dispenser	Potable	12/3/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1609	1052E	Girls Locker Room	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1610	1052E3	Girls Locker Room Bathroom	Bathroom Faucet	Non-Potable	12/3/2020	160	Placarded for Non-Drinking Use Until Remediated
MCCSD-1611	1052E3	Girls Locker Room Bathroom	Bathroom Faucet	Non-Potable	12/3/2020	47	Placarded for Non-Drinking Use Until Remediated
MCCSD-1613	1052E2	Girls Locker Room Showers	Bathroom Faucet	Non-Potable	12/3/2020	5.6	Result Below Action Level Continue O&M
MCCSD-1614	1057A	Kitchen	Kitchen Faucet (Cold)	Potable	12/3/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1615	1057A	Kitchen	Kitchen Faucet (Cold)	Potable	12/3/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1616	1057A	Kitchen	Kitchen Faucet (Cold)	Potable	12/3/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1617	1057A	Kitchen	Spray Nozzle	Potable	12/3/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1618	1057A	Kitchen	Kitchen Faucet (Cold)	Potable	12/3/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1619	1057A	Kitchen	Ice Machine	Potable	12/3/2020	OOS	Testing Required Before Return to Service
MCCSD-1620	1057A	Kitchen	Kitchen Faucet (Cold)	Potable	12/3/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1621	1057A	Kitchen	Kitchen Faucet (Cold)	Potable	12/3/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1622	1057A	Kitchen	Kitchen Faucet (Cold)	Potable	12/3/2020	<3.0 ND	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-1623	1057A2A	Kitchen Locker Room Bathroom	Bathroom Faucet	Non-Potable	12/3/2020	7.0	Result Below Action Level Continue O&M
MCCSD-1625	1054	Custodial Receiving Room	Ice Machine	Potable	12/3/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1626	1054A	Custodial Receiving Room Bathroom	Bathroom Faucet	Non-Potable	12/4/2020	4.0	Result Below Action Level Continue O&M
MCCSD-1627	1057	Cafeteria	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1628	1057	Cafeteria	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1629	1058	Handicap Bathroom	Bathroom Faucet	Potable	12/3/2020	8.1	Result Below Action Level Continue O&M
MCCSD-1633	1078	Corridor Room 104 to 138	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1637	1063A	Faculty Bathroom	Bathroom Faucet	Non-Potable	12/3/2020	48	Placarded for Non-Drinking Use Until Remediated
MCCSD-1638	1063A	Faculty Bathroom	Bathroom Faucet	Non-Potable	12/3/2020	9.2	Result Below Action Level Continue O&M
MCCSD-1643	1067	Boys Bathroom	Bathroom Faucet	Non-Potable	12/3/2020	4.3	Result Below Action Level Continue O&M
MCCSD-1644	1067	Boys Bathroom	Bathroom Faucet	Non-Potable	12/3/2020	12	Result Below Action Level Continue O&M
MCCSD-1645	1067	Boys Bathroom	Bathroom Faucet	Non-Potable	12/3/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1648	1069	Girls Bathroom	Bathroom Faucet	Non-Potable	12/3/2020	7.6	Result Below Action Level Continue O&M
MCCSD-1649	1069	Girls Bathroom	Bathroom Faucet	Non-Potable	12/3/2020	5.7	Result Below Action Level Continue O&M
MCCSD-1650	1069	Girls Bathroom	Bathroom Faucet	Non-Potable	12/3/2020	6.1	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-1654	1072	Room 129	Classroom Faucet	Non-Potable	12/3/2020	130	Placarded for Non-Drinking Use Until Remediated
MCCSD-1655	1073	Room 134	Home Economics Faucet (Cold)	Potable	12/3/2020	5.8	Result Below Action Level Continue O&M
MCCSD-1656	1073	Room 134	Home Economics Faucet (Cold)	Potable	12/3/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1657	1073	Room 134	Home Economics Faucet (Cold)	Potable	12/3/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1658	1075	Room 136	Home Economics Faucet (Cold)	Potable	12/3/2020	1	Result Below Action Level Continue O&M
MCCSD-1659	1075	Room 136	Home Economics Faucet (Cold)	Potable	12/3/2020	12	Result Below Action Level Continue O&M
MCCSD-1660	1075	Room 136	Home Economics Faucet (Cold)	Potable	12/3/2020	3.3	Result Below Action Level Continue O&M
MCCSD-1661	1075	Room 136	Home Economics Faucet (Cold)	Potable	12/3/2020	9.4	Result Below Action Level Continue O&M
MCCSD-1662	1078	Corridor Room 104 to 138	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1670	2018	Corridor Room 224 to 236	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1692	2007	Room 240 Prep Room (now a Bathroom)	Bathroom Faucet	Non-Potable	12/3/2020	1.1	Result Below Action Level Continue O&M
MCCSD-1694	2009	Girls Bathroom	Bathroom Faucet	Non-Potable	12/3/2020	10	Result Below Action Level Continue O&M
MCCSD-1695	2009	Girls Bathroom	Bathroom Faucet	Non-Potable	12/3/2020	7.2	Result Below Action Level Continue O&M
MCCSD-1696	2009	Girls Bathroom	Bathroom Faucet	Non-Potable	12/3/2020	8.6	Result Below Action Level Continue O&M
MCCSD-1698	2011	Boys Bathroom	Bathroom Faucet	Non-Potable	12/3/2020	3.4	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-1699	2011	Boys Bathroom	Bathroom Faucet	Non-Potable	12/3/2020	8.7	Result Below Action Level Continue O&M
MCCSD-1700	2011	Boys Bathroom	Bathroom Faucet	Non-Potable	12/3/2020	4.3	Result Below Action Level Continue O&M
MCCSD-1730	2018	Corridor Room 224 to 236	Bottled Water Dispenser	Potable	12/3/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1731	2018	Corridor Room 224 to 236	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1732	2043	Corridor Elevator to Room 200	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-1734	2028	Girls Bathroom	Bathroom Faucet	Non-Potable	12/3/2020	4.0	Result Below Action Level Continue O&M
MCCSD-1735	2028	Girls Bathroom	Bathroom Faucet	Non-Potable	12/3/2020	4.4	Result Below Action Level Continue O&M
MCCSD-1736	2028	Girls Bathroom	Bathroom Faucet	Non-Potable	12/3/2020	8.7	Result Below Action Level Continue O&M
MCCSD-1738	2030	Boys Bathroom	Bathroom Faucet	Non-Potable	12/3/2020	16	Placarded for Non-Drinking Use Until Remediated
MCCSD-1739	2030	Boys Bathroom	Bathroom Faucet	Non-Potable	12/3/2020	13	Result Below Action Level Continue O&M
MCCSD-1740	2030	Boys Bathroom	Bathroom Faucet	Non-Potable	12/3/2020	4.7	Result Below Action Level Continue O&M
MCCSD-1742	2032	Room 209	Bathroom Faucet	Non-Potable	12/3/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-1743	2043	Corridor Elevator to Room 200	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service

Stagecoach Elementary School

MCCSD-2008	1001	Kitchen	Kitchen Faucet (Cold)	Potable	12/11/2020	7.0	Result Below Action Level Continue O&M
------------	------	---------	-----------------------	---------	------------	-----	--

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-2009	1001	Kitchen	Spray Nozzle	Potable	12/11/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-2010	1001	Kitchen	Hand Wash Only	Non-Potable	12/11/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-2011	1001A	Kitchen Bathroom	Bathroom Faucet	Non-Potable	12/11/2020	1.9	Result Below Action Level Continue O&M
MCCSD-2013	1000A	Custodial Office Bathroom	Bathroom Faucet	Non-Potable	12/11/2020	2.1	Result Below Action Level Continue O&M
MCCSD-2016	1005	Girl's Toilet	Bathroom Faucet	Non-Potable	12/11/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-2017	1005	Girl's Toilet	Bathroom Faucet	Non-Potable	12/11/2020	1.8	Result Below Action Level Continue O&M
MCCSD-2018	1007	Near Room A5	Classroom Faucet	Non-Potable	12/11/2020	1	Result Below Action Level Continue O&M
MCCSD-2019	1007	Near Room A5	Classroom Faucet	Non-Potable	12/11/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-2020	1004	Boy's Toilet	Bathroom Faucet	Non-Potable	12/11/2020	2	Result Below Action Level Continue O&M
MCCSD-2021	1004	Boy's Toilet	Bathroom Faucet	Non-Potable	12/11/2020	4.7	Result Below Action Level Continue O&M
MCCSD-2022	1007	Near Room A5	Water Fountain-No Chiller	Potable	12/11/2020	OOS	Testing Required Before Return to Service
MCCSD-2023	1018B	Main Office Kitchenette	Kitchen Faucet (Cold)	Potable	12/11/2020	6.4	Result Below Action Level Continue O&M
MCCSD-2024	1015A	Principal's Office Bathroom	Bathroom Faucet	Non-Potable	12/11/2020	13	Result Below Action Level Continue O&M
MCCSD-2025	1019	Nurse's Office	Nurse's Office Sink	Potable	12/11/2020	1.2	Result Below Action Level Continue O&M
MCCSD-2026	1019B	Nurse's Office Bathroom	Bathroom Faucet	Non-Potable	12/11/2020	<3.0 ND	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-2027	1021	Near Music Room	Bottled Water Dispenser	Potable	12/11/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-2028	1021	Near Music Room	Water Fountain-No Chiller	Potable	12/11/2020	OOS	Testing Required Before Return to Service
MCCSD-2029	1026	Near Room B7	Water Fountain-No Chiller	Potable	12/11/2020	OOS	Testing Required Before Return to Service
MCCSD-2030	1024	Boy's Toilet	Bathroom Faucet	Non-Potable	12/11/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-2031	1026	Hallway	Classroom Faucet	Non-Potable	12/11/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-2032	1026	Hallway	Classroom Faucet	Non-Potable	12/11/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-2033	1025	Girl's Toilet	Bathroom Faucet	Non-Potable	12/11/2020	2.1	Result Below Action Level Continue O&M
MCCSD-2034	1025	Girl's Toilet	Bathroom Faucet	Non-Potable	12/11/2020	1.7	Result Below Action Level Continue O&M
MCCSD-2038	1036	Room B8	Classroom Faucet	Non-Potable	12/11/2020	2	Result Below Action Level Continue O&M
MCCSD-2039	1036	Room B8	Water Fountain-No Chiller	Potable	12/11/2020	OOS	Testing Required Before Return to Service
MCCSD-2040	1038	Room B9	Classroom Faucet	Non-Potable	12/11/2020	1.7	Result Below Action Level Continue O&M
MCCSD-2041	1038	Room B9	Water Fountain-No Chiller	Potable	12/11/2020	OOS	Testing Required Before Return to Service
MCCSD-2042	1040	Room B10	Classroom Faucet	Non-Potable	12/11/2020	2.2	Result Below Action Level Continue O&M
MCCSD-2043	1040	Room B10	Water Fountain-No Chiller	Potable	12/11/2020	OOS	Testing Required Before Return to Service
MCCSD-2044	1047	Near Social Worker's Office	Water Fountain-No Chiller	Potable	12/11/2020	OOS	Testing Required Before Return to Service

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-2045	1047	Near Social Worker Office	Water Fountain-No Chiller	Potable	12/11/2020	OOS	Testing Required Before Return to Service
MCCSD-2046	1045	Boy's Toilet	Bathroom Faucet	Non-Potable	12/11/2020	1.9	Result Below Action Level Continue O&M
MCCSD-2047	1047	Near Social Worker's Office	Classroom Faucet	Non-Potable	12/11/2020	1.5	Result Below Action Level Continue O&M
MCCSD-2048	1047	Near Social Worker's Office	Classroom Faucet	Non-Potable	12/11/2020	2	Result Below Action Level Continue O&M
MCCSD-2049	1046	Girl's Toilet	Bathroom Faucet	Non-Potable	12/11/2020	1.6	Result Below Action Level Continue O&M
MCCSD-2050	1046	Girl's Toilet	Bathroom Faucet	Non-Potable	12/11/2020	2.1	Result Below Action Level Continue O&M
MCCSD-2051	1057A2	Music Room Bathroom	Bathroom Faucet	Non-Potable	12/11/2020	2.3	Result Below Action Level Continue O&M
MCCSD-2052	1060	Men's Bathroom	Bathroom Faucet	Non-Potable	12/11/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-2053	1061	Women's Bathroom	Bathroom Faucet	Non-Potable	12/11/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-2054	1058	Women's Bathroom	Bathroom Faucet	Non-Potable	12/11/2020	2.7	Result Below Action Level Continue O&M
MCCSD-2055	1062	Girl's Toilet	Bathroom Faucet	Non-Potable	12/11/2020	1.3	Result Below Action Level Continue O&M
MCCSD-2056	1062	Girl's Toilet	Bathroom Faucet	Non-Potable	12/11/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-2057	1066	Near Faculty Lounge	Classroom Faucet	Non-Potable	12/11/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-2058	1066	Near Faculty Lounge	Classroom Faucet	Non-Potable	12/11/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-2059	1063	Boy's Toilet	Bathroom Faucet	Non-Potable	12/11/2020	<3.0 ND	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-2060	1063	Boy's Toilet	Bathroom Faucet	Non-Potable	12/11/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-2061	1066	Across From Room D1	Water Fountain-No Chiller	Potable	12/11/2020	OOS	Testing Required Before Return to Service
MCCSD-2062	1066	Across From Room D1	Water Fountain-No Chiller	Potable	12/11/2020	OOS	Testing Required Before Return to Service
MCCSD-2063	1058	Women's Bathroom	Water Fountain-No Chiller	Potable	12/11/2020	200	Removed From Service, Pending Remediation
MCCSD-2064	1075B	Faculty	Kitchen Faucet (Cold)	Potable	12/11/2020	11	Result Below Action Level Continue O&M
MCCSD-2065	1075	Cafeteria Auditorium	Bottled Water Dispenser	Potable	12/11/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-2066	1075	Cafeteria Auditorium	Water Fountain-No Chiller	Potable	12/11/2020	OOS	Testing Required Before Return to Service
MCCSD-2067	1059B	P.E. Coach's Office Bathroom	Bathroom Faucet	Non-Potable	12/11/2020	16	Placarded for Non-Drinking Use Until Remediated
MCCSD-2068	1080	Near Cafeteria Auditorium	Classroom Faucet	Non-Potable	12/11/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-2069	1080	Near Cafeteria Auditorium	Classroom Faucet	Non-Potable	12/11/2020	1.1	Result Below Action Level Continue O&M
MCCSD-2070	1080	Near Cafeteria Auditorium	Classroom Faucet	Non-Potable	12/11/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-2085	1075B	Faculty Lounge	Bottle Fill Station	Potable	12/11/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-2086	1075B	Faculty Lounge	Ice Machine	Potable	12/11/2020	<3.0 ND	Result Below Action Level Continue O&M

Unity Drive Elementary School

MCCSD-0251	1000	Room 116	Classroom Faucet	Non-Potable	11/25/2020	8.4	Result Below Action Level Continue O&M
------------	------	----------	------------------	-------------	------------	-----	--

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0252	1000	Room 116	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0253	1000B	Room 116 Bathroom	Bathroom Faucet	Non-Potable	11/25/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0254	1001	Room 117	Classroom Faucet	Non-Potable	11/25/2020	14	Result Below Action Level Continue O&M
MCCSD-0255	1001	Room 117	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0256	1001B	Room 117 Bathroom	Bathroom Faucet	Non-Potable	11/25/2020	1.8	Result Below Action Level Continue O&M
MCCSD-0257	1004	Room 115	Classroom Faucet	Non-Potable	11/25/2020	8.8	Result Below Action Level Continue O&M
MCCSD-0258	1004	Room 115	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0259	1005	Room 114	Classroom Faucet	Non-Potable	11/25/2020	6.6	Result Below Action Level Continue O&M
MCCSD-0260	1005	Room 114	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0261	1006	Room 113	Classroom Faucet	Non-Potable	11/25/2020	18	Placarded for Non-Drinking Use Until Remediated
MCCSD-0262	1006	Room 113	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0263	1007	Room 112	Classroom Faucet	Non-Potable	11/25/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0264	1007	Room 113	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0265	1008	Room 111	Classroom Faucet	Non-Potable	11/25/2020	1.7	Result Below Action Level Continue O&M
MCCSD-0266	1008	Room 111	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0267	1009	Room 108/110 Conference Room	Classroom Faucet	Non-Potable	11/25/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0268	1009	Room 108/110 Conference Room	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0269	1009	Room 108/110 Conference Room	Classroom Faucet	Non-Potable	11/25/2020	3.2	Result Below Action Level Continue O&M
MCCSD-0270	1010	Room 109	Classroom Faucet	Non-Potable	11/25/2020	3.3	Result Below Action Level Continue O&M
MCCSD-0271	1010	Room 109	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0273	1012	Boys Bathroom	Bathroom Faucet	Non-Potable	11/25/2020	2.1	Result Below Action Level Continue O&M
MCCSD-0274	1012	Boys Bathroom	Bathroom Faucet	Non-Potable	11/25/2020	OOS	Testing Required Before Return to Service
MCCSD-0275	1012	Boys Bathroom	Bathroom Faucet	Non-Potable	11/25/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0276	1014	Girls Bathroom	Bathroom Faucet	Non-Potable	11/25/2020	7.3	Result Below Action Level Continue O&M
MCCSD-0277	1014	Girls Bathroom	Bathroom Faucet	Non-Potable	11/25/2020	OOS	Testing Required Before Return to Service
MCCSD-0278	1014	Girls Bathroom	Bathroom Faucet	Non-Potable	11/25/2020	2	Result Below Action Level Continue O&M
MCCSD-0279	1018	Men's Faculty Bathroom	Bathroom Faucet	Non-Potable	11/25/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0280	1019	Women's Faculty Bathroom	Bathroom Faucet	Non-Potable	11/25/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0281	1020	Room 107	Classroom Faucet	Non-Potable	11/25/2020	1.6	Result Below Action Level Continue O&M
MCCSD-0282	1020	Room 107	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service


Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0283	1022	Cafeteria	Bottled Water Dispenser	Potable	11/25/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0284	1022	Cafeteria	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0285	1022B	Cafeteria Kitchen	Kitchen Faucet (Cold)	Potable	11/25/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0286	1022B	Cafeteria Kitchen	Kitchen Faucet (Cold)	Potable	11/25/2020	4.6	Result Below Action Level Continue O&M
MCCSD-0287	1022B	Cafeteria Kitchen	Spray Nozzle	Potable	11/25/2020	2.3	Result Below Action Level Continue O&M
MCCSD-0288	1022B	Cafeteria Kitchen	Hand Wash Only	Non-Potable	11/25/2020	3.0	Result Below Action Level Continue O&M
MCCSD-0290	1023B1	Corridor Bathroom	Bathroom Faucet	Non-Potable	11/25/2020	OOS	Testing Required Before Return to Service
MCCSD-0291	1023D1	Head Custodian Office Bathroom	Bathroom Faucet	Non-Potable	11/25/2020	1.2	Result Below Action Level Continue O&M
MCCSD-0292	1023E	Art Room	Classroom Faucet	Non-Potable	11/25/2020	5.1	Result Below Action Level Continue O&M
MCCSD-0293	1023E1	Art Room Bathroom	Bathroom Faucet	Non-Potable	11/25/2020	OOS	Testing Required Before Return to Service
MCCSD-0294	1027A	Pre K Music Room Bathroom	Bathroom Faucet	Non-Potable	11/25/2020	2.9	Result Below Action Level Continue O&M
MCCSD-0295	1028A	Physical Education Office Bathroom	Bathroom Faucet	Non-Potable	11/25/2020	4.2	Result Below Action Level Continue O&M
MCCSD-0296	1033	Corridor from Gymnasium to Main Entrance	Bottled Water Dispenser	Potable	11/25/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0297	1033	Corridor from Gymnasium to Main Entrance	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0298	1031	Main Office	Classroom Faucet	Non-Potable	11/25/2020	2.9	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0299	1031A	Main Office Faculty Lounge	Classroom Faucet	Non-Potable	11/25/2020	1	Result Below Action Level Continue O&M
MCCSD-0300	1032	Health Office	Nurse's Office Sink	Potable	11/25/2020	7.9	Result Below Action Level Continue O&M
MCCSD-0301	1032A	Health Office Bathroom	Bathroom Faucet	Non-Potable	11/25/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0302	1035	Room 106	Classroom Faucet	Non-Potable	11/25/2020	2.7	Result Below Action Level Continue O&M
MCCSD-0303	1036	Room 105	Classroom Faucet	Non-Potable	11/25/2020	1.9	Result Below Action Level Continue O&M
MCCSD-0304	1038A	Room 104A Closet	Bathroom Faucet	Non-Potable	11/25/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0305	1039	Room 104	Classroom Faucet	Non-Potable	11/25/2020	3.2	Result Below Action Level Continue O&M
MCCSD-0306	1039	Room 104	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0307	1041	Room 103	Classroom Faucet	Non-Potable	11/25/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0308	1041	Room 103	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0309	1041A	Room 103 Bathroom	Bathroom Faucet	Non-Potable	11/25/2020	3.7	Result Below Action Level Continue O&M
MCCSD-0310	1042	Room 102	Classroom Faucet	Non-Potable	11/25/2020	1.3	Result Below Action Level Continue O&M
MCCSD-0311	1042B	Room 102 Bathroom	Bathroom Faucet	Non-Potable	11/25/2020	1.5	Result Below Action Level Continue O&M
MCCSD-0312	1043B	Room 101 Bathroom	Bathroom Faucet	Non-Potable	11/25/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0313	2001A1	Women's Bathroom	Bathroom Faucet	Non-Potable	11/25/2020	7.9	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0314	2001B1	Men's Bathroom	Bathroom Faucet	Non-Potable	11/25/2020	7.4	Result Below Action Level Continue O&M
MCCSD-0315	2003	Girls Bathroom	Bathroom Faucet	Non-Potable	11/25/2020	11	Result Below Action Level Continue O&M
MCCSD-0316	2003	Girls Bathroom	Bathroom Faucet	Non-Potable	11/25/2020	OOS	Testing Required Before Return to Service
MCCSD-0317	2003	Girls Bathroom	Bathroom Faucet	Non-Potable	11/25/2020	4.6	Result Below Action Level Continue O&M
MCCSD-0319	2002	Library	Classroom Faucet	Non-Potable	11/25/2020	11	Result Below Action Level Continue O&M
MCCSD-0320	2006	Boys Bathroom	Bathroom Faucet	Non-Potable	11/25/2020	7.5	Result Below Action Level Continue O&M
MCCSD-0321	2006	Boys Bathroom	Bathroom Faucet	Non-Potable	11/25/2020	OOS	Testing Required Before Return to Service
MCCSD-0322	2006	Boys Bathroom	Bathroom Faucet	Non-Potable	11/25/2020	10	Result Below Action Level Continue O&M
MCCSD-0323	2007	Room 202	Classroom Faucet	Non-Potable	11/25/2020	2.3	Result Below Action Level Continue O&M
MCCSD-0324	2007	Room 202	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0325	2008	Room 203	Classroom Faucet	Non-Potable	11/25/2020	15	Result Below Action Level Continue O&M
MCCSD-0326	2008	Room 203	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0327	2009	Room 204	Classroom Faucet	Non-Potable	11/25/2020	<3.0 ND	Result Below Action Level Continue O&M
MCCSD-0328	2009	Room 204	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0329	2010	Room 205	Classroom Faucet	Non-Potable	11/25/2020	6.3	Result Below Action Level Continue O&M

Outlet Number	Space ID	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result (ppb)	Remediation Actions/Current Status
MCCSD-0330	2010	Room 205	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0331	2011	Room 206	Classroom Faucet	Non-Potable	11/25/2020	4.4	Result Below Action Level Continue O&M
MCCSD-0332	2011	Room 206	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0333	2012	Room 207	Classroom Faucet	Non-Potable	11/25/2020	4.3	Result Below Action Level Continue O&M
MCCSD-0334	2012	Room 207	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0335	2013	Room 208	Classroom Faucet	Non-Potable	11/25/2020	13	Result Below Action Level Continue O&M
MCCSD-0336	2013	Room 208	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0337	2014	Room 209	Classroom Faucet	Non-Potable	11/25/2020	6.3	Result Below Action Level Continue O&M
MCCSD-0338	2014	Room 209	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0339	2017	Room 211	Classroom Faucet	Non-Potable	11/25/2020	2.7	Result Below Action Level Continue O&M
MCCSD-0340	2017	Room 211	Water Fountain-No Chiller	Potable	2/23/2021	OOS	Testing Required Before Return to Service
MCCSD-0341	2017B2A	Room 211 Vestibule Publishing Center Bathroom	Bathroom Faucet	Non-Potable	11/25/2020	7.5	Result Below Action Level Continue O&M
MCCSD-0342	2018	Room 210	Classroom Faucet	Non-Potable	11/25/2020	8.8	Result Below Action Level Continue O&M
MCCSD-0343	2018	Room 210	Water Fountain-No Chiller	Non-Potable	11/25/2020	OOS	Testing Required Before Return to Service

Attachment 2:
Chain of Custody
&
Laboratory Analysis



J.C. Broderick & Associates, Inc.

Environmental Consulting & Testing


1775 Expressway Drive North

Hauppauge, New York 11788

631.584.5492 fax 631.584.3395

Attachment 3:

Laboratory Certifications



J.C. Broderick & Associates, Inc.

Environmental Consulting & Testing

1775 Expressway Drive North

Hauppauge, New York 11788

631.584.5492 fax 631.584.3395

NEW YORK STATE DEPARTMENT OF HEALTH
WADSWORTH CENTER



Expires 12:01 AM April 01, 2021
Issued April 01, 2020

CERTIFICATE OF APPROVAL FOR LABORATORY SERVICE

Issued in accordance with and pursuant to section 502 Public Health Law of New York State

MR. DANIEL CLARKE
EMSL ANALYTICAL, INC.
528 MINEOLA AVE.
CARLE PLACE, NY 11514

NY Lab Id No: 11469

*is hereby APPROVED as an Environmental Laboratory in conformance with the
National Environmental Laboratory Accreditation Conference Standards (2003) for the category
ENVIRONMENTAL ANALYSES POTABLE WATER
All approved analytes are listed below:*

Bacteriology

Coliform, Total / E. coli (Qualitative)	SM 21, 23 9222A,B,C SM 20, 21-23 9223B (-04) (Colilert)
E. coli (Enumeration)	SM 21, 23 9222A,B,C
Enterococci	SM 20, 23 9230C (Budnick 1996)
Heterotrophic Plate Count	SimPlate SM 20, 21-23 9215B (-04)

Metals I

Lead, Total	EPA 200.5
-------------	-----------

Miscellaneous

Asbestos	EPA 100.2
----------	-----------

Serial No.: 61397

Property of the New York State Department of Health. Certificates are valid only at the address shown, must be conspicuously posted, and are printed on secure paper. Continued accreditation depends on successful ongoing participation in the Program. Consumers are urged to call (518) 485-5570 to verify the laboratory's accreditation status.

